

CAM FOLLOWERS

Sep 2016

Fits	Part#	Alt#	Solid/Hyd	Stock	Price
Bedford CF, Vauxhall 1600, 2000, 2300 OHC	VBR02	VCF142	Solid	✓	\$ 10
BMC "O" series 1700, 2000	BLR04	VCF155	Solid	✓	\$ 10
BMC 1500-1622 "B" series	BLR01	VCF113	Solid	x	\$ 18
BMC 1800?	20.6 x 60mm		Solid	✓	\$ 18
BMC 848 - 1275cc & late 1800 (20.6 x 38mm)	BLR05	VCF110	Solid	✓	\$ 8
BMC Maxi, Allegro 1500, 1750	BLR02	VCF117	Solid	✓	\$ 8
Chev 2.8 V6	HT2095		Hydraulic	✓	\$ 35
Chev/Holden V8	VL73		Hydraulic	8	
Chrysler Valiant 245, 265, V8 318, Jeep Cherokee 4.0	HT2011	VL89CT	Hydraulic	15	\$ 8
Datsun A12, A14, A15	NIR01	AT2067	Solid	✓	\$ 8
Falcon 200-250 (Non crossflow)	HT -949		Hydraulic	✓	\$ 8
Falcon 200-250 (Non crossflow)	HT -949R		Hydraulic	4	\$ 10
Falcon C/F	VL35		Hydraulic	✓	\$ 8
Falcon V8 302, 351	HT -900		Hydraulic	4	\$ 8
Ford 240, 300	HT -914		Hydraulic	10?	\$ 15
Ford 81-87 1.6L 98CID, 2.3L 140	HT2102		Hydraulic	✓	\$ 12
Ford Commercial (1.25" head, .608" stem, 2.45" long)	ACF103		solid	8	\$ 25
Ford Cortina 1600, 2000 OHC	CFR09	VCF104	Solid	✓	\$ 11
Ford Cortina C/F (13mm stem)	CF1498		Solid	✓	\$ 12
Ford Cortina NCF, Anglia (11mm stem)	CF1477	CFR02,VCF10	Solid	✓	\$ 13
Ford Cortina OHC ball stud adjuster	VBS249		Stud adjuster	rusty	\$ 2
Ford V4, V6	CFR04	VCF106	Solid	x	
Ford Zephyr 6 & 4, Consul (.005" O/S stem)	211E 6489B		Solid	✓	\$ 10
Ford Zephyr 6 & 4, Consul (Std stem)	211E 6489		Solid	5	\$ 25
GMC (.990" x 2.312")	AT874		Solid	12	
GMC Pass78-84 15leng.AMC/jee	HT -2077		Hydraulic	8	\$
GMC truck 1956-79 235, 261, 305C, 279,	AT864		Solid	✓	\$
Hillman 1500, 1600, 1725 (22.2 x 49.5mm)	MCF1149		Solid	x	\$ 15
Hillman Avenger 1250, 1300, 1500, 1600 (23.8 x 49.5mm)	CRR05	VCF116	Solid	✓	\$ 11
Holden 149, 161, 179, 186, 202, 253, 308	HT -969	VL73CT	Hydraulic	✓	\$ 8
Holden 149, 161, 179, 186, 202, 253, 308 Performance.	HT -969R		Hydraulic	✓	\$ 10
Holden Camira	RHT-2056		Hydraulic	8	\$ 15
Holden Commodore (RB30?)	HT -2148		Hydraulic	6	\$ 15
IHC 4-152, 4-196, 4-196E, V266, V3	HT-855		Hydraulic	✓	\$
Nissan A12, A14, A15	NIR01	AT2067	Solid	✓	\$ 8
Rover 2.6 SD1 -Rocker arm	BLR23	DAS511	R/Arm	✓	\$ 30
Rover V8 3500, Buick V6 225	HT -896		Hydraulic	8?	\$ 15
Rover SD1??? over valve lifter .875" x 1.960" (extended)	DAS520		Hydraulic	12	
Standard Vanguard .9365" x 1.950"	B2284		Solid	3	\$ 16
Toyota K, 3K, 4K (20 x 44.5mm)	AT2069		Solid	✓	\$ 8
Vaux/Bed 1600, 2000, 2300 OHC	VBR02	VCF142	Solid	✓	\$ 10
Vauxhall Viva and Chevette	VBR01	VCF107	Solid	✓	\$ 7
Wisconsin all VG4D engs	AT2013		Solid	✓	\$
Zephyr/Consul o/s stem (.503")	BFS	211E 6489B	Solid	✓	\$ 9

Bowden Engine Parts, 37 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: +64 9 4061388

Email: chris@bowdenengineparts.co.nz

CAM FOLLOWERS

Sep 2016

M/Spares retails 1994			
DAS508	\$ 20.49		
DAS057	\$ 8.45		
	\$ 12.03	sege's \$6.51	
HT900	\$ 8.42	sege's \$5.07	
HT900	\$ 8.42		
DAS572	\$ 12.45		
DAS056			
13/7/16\$11		ACL\$6.00	
was \$8			
DAS512	\$ 4.56		
DAS058	\$ 12.45		
.503"			
.499"			
DAS053	\$ 15.23		
DAS506	\$ 12.76		
	\$ 8.42		
DAS580	\$ 24.36		
	47.35	\$ 47.35	
DAS502	\$ 22.70	Buick V8 225	
Bareco retail	\$15.75+		
DAS054	\$ 8.58		