

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|-----------------------------|-------------------|------------------------|------------------------------------|-------|----------|
| IN PART NUMBER ORDER | | | | | |
| 229 | | O ring | O RING | 17 | |
| 4235 | BMC "O"? | Oil seal | 35x62x7 (for 8MM wide see C12527) | 1 | |
| 10719 | | (main cap side seal?) | | 1 | |
| 23128 | Filter seal? | Rubber ring | | 43 | |
| 29838 | Simca | (rear seal plate gsk?) | | 1 | |
| 30136 | Ford (6D?) | Oil seal -rear crank | Neoprene (for rope type see KT638) | | \$ 50.00 |
| 48724 | | Oil seal | 48x70x12 | 1 | |
| 50211 | Flavell Wave Seal | Oil seal | 2.750x3.625x.5 | 5 | |
| 97051 | | Oil seal | 2"x2.623"x.280" | 1 | |
| 97066 | | Oil seal | | 2 | |
| 97071 | | Oil seal (PR6350) | 1.875"x3.141x2.562x.6 | 1 | |
| 97076 | | Oil seal | 35x64x9 | 1 | |
| 97083 | | Oil seal | | 2 | |
| 97087 | | Oil seal | | 1 | |
| 97090 | | Oil seal | | 2 | |
| 97091 | | Oil seal | | 2 | |
| 97092 | Vauxhall Viva? | Oil seal | Viva? | 0 | |
| 97096 | | Oil seal | 42x65x13.9x16.4 | 22 | |
| 97099 | | Oil seal | 45x75x8 | 4 | |
| 97112 | | Oil seal | | 1 | |
| 97120 | | Oil seal | | 2 | |
| 97125 | | Oil seal | | 1 | |
| 97126 | | Oil seal | 1.575"x2.047x.339 | 1 | |
| 97132 | | Oil seal | 1.500"x1.990x.250 | 3 | |
| 97133 | | Oil seal (PR0767) | 55/6x82x10 | 1 | |
| 97139 | | Oil seal | 48x62x10 | 2 | |
| 97140 | | Oil seal | | 2 | |
| 97143 | | Oil seal | | 2 | |
| 97149 | | Oil seal -rear crank | Wick type | 2 | |
| 97151 | | Oil seal (97364) | 15x32x7 | 1 | |
| 97153 | | Oil seal | | 1 | |
| 97164 | | Oil seal | 71x96x9 | 3 | |
| 97167 | | Oil seal | | 2 | |
| 97169 | | Oil seal | | 2 | |
| 97172 | | Oil seal | | 2 | |
| 97183 | | Oil seal | big | 2 | |
| 97184 | | Oil seal | | 2 | |
| 97194 | 48x70x9 | Oil seal | 48x70x9 (PR0178) | 10 | |
| 97195 | Holden? | Oil seal | 2 piece (Holden?) | 1 | |
| 97199 | Holden 202? | Oil seal | 2 piece (Holden?) 2.430x3.020x.320 | 4 | |
| 97202 | | Oil seal | | | |
| 97208 | | Oil seal | 85x105x13 | 1 | |
| 97209 | | Oil seal | | | |
| 97219 | | Oil seal | 45x72.2x7.5x8.5 | 2 | |
| 97226 | | Oil seal (PR0736) | 40x75x9 | 1 | |
| 97239 | | Oil seal (PR0177) | 48x62x8 | 3 | |
| 97240 | | Oil seal | | 2 | |
| 97245 | | Oil seal | | 2 | |
| 97248 | | Oil seal | 3.687x5.125x.5 | 2 | |
| 97249 | | Oil seal (PR0969) | 60x68x11x17.5 | 3 | |
| 97250 | | Oil seal -rear crank | Wick type | 2 | |
| 97262 | | Oil seal | | 2 | |
| 97263 | | Oil seal | | 2 | |
| 97275 | | Oil seal | | 2 | |
| 97277 | | Oil seal | 65x88x11.5 | 2 | |
| 97284 | | Oil seal | | 1 | |
| 97288 | | Oil seal (PR0098) | 32x44x9 | 1 | |
| 97304 | | Oil seal (mower?) | 28x36x8 | 1 | |
| 97305 | | Oil seal | 52x68x13 | 1 | |
| 97308 | | Oil seal | | 2 | |
| 97311 | | Oil seal (PR0081) | | 1 | |
| 97320 | | Oil seal | 34x44x8 | 1 | |
| 97323 | | Oil seal | 35x54x9x15 | 3 | |
| 97327 | | Oil seal (PR0604) | 52x72x7.5 | 1 | |
| 97333 | | Oil seal | | 2 | |
| 97340 | | Oil seal | | 2 | |
| 97345 | | Oil seal | 32x58x8 | 2 | |
| 97346 | | Oil seal | | 1 | |
| 97350 | | Oil seal | | 1 | |
| 97357 | | Oil seal | | 2 | |
| 97358 | | Oil seal (PR0902?) | 32x48x8 | 2,3 | |
| 97359 | | Oil seal | | 2 | |
| 97361 | | Oil seal | 38x65x9 | 2 | |
| 97362 | | Oil seal | 35x55x11 | 1 | |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|---------------|-------------------------------------|----------------------------------|--------------------------------------------|-------|----------|
| 97367 | | Oil seal | | 2 | |
| 97368 | | Oil seal | | 2 | |
| 97370 | | Oil seal | big | 1 | |
| 97373 | | Oil seal (PR0209) | | 3 | |
| 97375 | | Oil seal | | 2 | |
| 97376 | | Oil seal (PR0141) | 65x88x12 | 2 | |
| 97377 | | Oil seal | | 2 | |
| 97381 | | Oil seal | big | 2 | |
| 97382 | | Oil seal | 48x74x10 | 1 | |
| 97390 | | Oil seal | | 1 | |
| 97515 | | Oil seal | 35x56x15 | 2 | |
| 102743 | Mitsubishi Heavy | Oil seal plus wear sleeve | 97x115x12 | 1 | |
| 160819 | Cummins | R/C or side plate? | | 1 | |
| 233473 | | Oil seal retainer gsk | Oil seal retainer gsk | 16 | |
| 305356 | | Copper washer | | 200 | |
| 393225 | GM | Seal | 1.5"x2.375"x0.5" GM | 1 | |
| 546063 | Leyland | Oil seal | 1.500x2.375x.500" | 1 | |
| 948483 | Volvo | Oil seal | | 1 | |
| 3832961 | Chev | Mani inl end seal | CHEV IN MAN END SEAL | 29 | |
| 3927109 | Chev | Mani inl end seal | CHEV IN MAN END SEAL | 102 | |
| 4068617 | Chrysler V8 | Mani gsk Inlet set | | 1 | |
| 7206309 | Bedford CF | Distr. Gsk | | 20 | |
| 7405144 | | Copper ring | | 79 | |
| 7405147 | | Fibre washer 11 x 17 x 1 | | 202 | |
| 14146069 | Isuzu G150 | Mani gsk round/square ports | (round ports gsk is JA016) | 0 | \$ 30.00 |
| 2004650030 | For oil seal? | Spring | | 4 | |
| 0.8x4x8 | | Fibre washer 4 x 8 x 0.8 | | 11 | |
| 044.598 | | Oil seal | 92x110x10 | 1 | |
| 06-08-201-900 | | Misc gsk | On Deletion 2237 | 13 | |
| 08930041 | | Front cover gsk | On Deletion 2237 | 4 | |
| 08930042 | | Front cover gsk | On Deletion 2237 | 12 | |
| 09729 | | Alloy washer | | 300 | |
| 1-11367100-1 | Isuzu 6BD1-T | Sump gasket | | 1 | |
| 11493-45010 | Toyo | Misc gsk | Misc gsk Toyota | 7 | |
| 12279-58000 | Nissan | Oil seal - rear (rope type pair) | | 2 | |
| 13119-84360 | Suzuki | Mani gsk Inlet | INLET MANIFOLD GSK SUZUKI | 2 | |
| 13207-97063 | Nissan | Valve seal | | 2 | |
| 17105-PE3-000 | | | | 1 | |
| 2418F475 | Perkins | Oil seal | 134?x159x10.5/14.5 | 1 | |
| 304012R1 | IHC? | Copper washer, large IHC? | | 20 | |
| 3138042R1 | IHC | T/C or side gsk | | 5 | |
| 31397-X0101 | Nissan | Sump gsk | OIL PAN GSK NISSAN | 3 | |
| 3681 M015 | Perkins (6.354?) | Sump gsk set | | 1 | |
| 369984R1 | IHC | Sump gsk | Misc gsk Int. truck | 3 | |
| 38320-18010 | Nissan | Diff gsk | Diff gsk Nissan | 7 | |
| 48x4B | | O ring 48x56x4 | | 39 | |
| 5091/249 | Leyland Nuffield tractor | Oil seal - front hub | 2.437x3.250x.375" | 3 | |
| 5x10x1.5 | | Fibre washer 5 x 10 x 1.5 | | 8 | |
| 6212-41-4540 | Komatsu | Valve seal | for 9 or 9.5mm stem? | 12 | |
| 678527-C1 | IHC | Oil seal plus wear sleeve | 5.125"x6.125"x.437" | 1 | |
| 6D22LS | Mitsubishi 6D22 | Liner seal set (18) | 6 x black, 6 x thin red, 6 x thick red | 1 | |
| 714GB3113A | Mack | Valve seal | for 6.5 or 7mm stem? | 16 | |
| 76HF9447AA | Ford | Carb insulator | | 5 | |
| 897148M3 | Norwood | Water gsk? | Misc gsk Norwood | 45 | |
| 9/1213/58 | Lombardini | Oil seal | 55x72x10 | 1 | |
| 90215-18011 | | Copper washer with locate tab | | 19 | |
| 90311-38035 | Toyota Landcruiser 1988-97 | Oil seal -differential lock | 38x74x11/18 | 5 | \$ 10.00 |
| 90313-48001 | Toyota | Seal special | | 1 | |
| 90430-72114 | Toyo | Cork ring | MISC GSK TOYOTA | 4 | |
| 90923-05004 | Toyo | Fuel pump gsk | Fuel pump gsk Toyota | 16 | |
| 90923-06007 | Toyo | Fuel pump insul block | TOYOTA | 6 | |
| 9613-S | 1.500x2.550x2.375x.480 | Oil seal | 1.500x2.550x2.375x.480 approx dims. | 1 | |
| A225 | BMC 1100, 1300 | Filter hsg to block gsk | | 1 | \$ 5.00 |
| A317 | Bedford 466, 500 | Front cover gsk plus | JR178,KT145,KT477,KT491,KT492,KT494 | 5 | |
| A327 | Bedford 466, 500 | Water pump gsk | | 5 | \$ 10.00 |
| A377 | Mitsubishi 4G32 | Front cover gsk | TCG690 | 1 | |
| ATCS13 | Toyota 4M | Front cover oil seal & gsk set | 1971-76 (possibly later too?) (Seal NL243) | 1 | |
| ATJ5628 | Leyland Tractor 270 | Transfer housing gsk | | 10 | \$ 15.00 |
| ATJ5630 | Leyland Tractor 270 | Rear PTO housing gsk | | | |
| AUC4900 | | Fibre washer 17 x 22.5 x 1.5 | | 15 | |
| AYB420 | Austin Kimberley 70-72, Ley P76 6 | Exhaust flange (2 rqd) | | 0 | |
| AYH3202 | BMC? | Oil seal | 1.375"x2"x.437" | 1 | |
| AYH451 | Austin Kimberley, Aus Marina | Therm gsk | NZ338 (also use WG6) | | |
| B069 | Use KG378 or KJ481 | O ring | | | |
| B23285 | 2.375 x 1.625 x .500 | Oil Seal | 2.375 x 1.625 x .500 | 1 | |
| B2384 | Massey Fergusson 35, 135, 148, 240, | Oil Seal | Outer axle seal | 2 | |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|-------------|----------------------------|---------------------------------|------------------------------------|-------|----------|
| B326 | | Rubber ring | approx 37x46x4 sq section | 6 | |
| B3906 | Fordson Major/Trader | Liner seal (3/16") | For single O ring liners | 8 | \$ 7.00 |
| B3907 | Fordson Super Major/Trader | Liner seal thin, upper (3/32") | For double O ring liners | 3 | \$ 7.00 |
| B3908 | Fordson Super Major/Trader | Liner seal thick, lower (3/16") | For double O ring liners | 4 | \$ 8.00 |
| B3909 | Ford Tractor New World | Oil seal -front crank | | 1 | \$ 8.00 |
| B4000 | Ford Tractor New World | Oil seal -rear crank | | 2 | \$ 35.00 |
| B546 | Ford V4, V6 | Fuel pump block | also KS969 | | |
| B730 | Leyland P76 V8 | Oil seal -front crank | 2"x2.625"x.375" | | \$ 15.00 |
| B730W | | Oil seal | 2"x2.687"x.375" | 3 | |
| BA1 | Mitsubishi 4G42, KE46 | Front cover gsk -9 hole | | 2 | \$ 10.00 |
| BA2 | Mitsubishi 4G42, KE46 | Front cover gsk -10 hole | | 2 | \$ 10.00 |
| BG3988E | 50x67x7 | Oil Seal -special | 50x67x7 approx dims. | 1 | |
| BH4649F | Sub? | Oil seal | 86x103x7.5 | 1 | |
| BH5644G | Sub? | Oil seal | 86x103x8 | 1 | |
| BH634 | | Fibre washer 14 x 20.5 x 2.5 | 14mm (for sump plugs?) | 5 | |
| BIG1 | 4.750x5.562x.460 | Oil seal | 4.750"x5.562"x.460" | 1 | |
| BRF1 | | Brass Ferrule | BRASS FERRULE FOR KV384 | 145 | |
| BW45 | Borg Warner | Oilpan gsk? | | 1 | \$ 8.00 |
| BW679A | | Valve seal | | 13 | |
| C12527 | BMC "O"? | Oil seal | 35x62x8 (for 7MM wide see C12527) | 1 | |
| C2806789 | Mitsu | | MISC GSK. MITSUBISHI | 9 | |
| C3681438 | Mitsu | Sump gsk | Sump gsk Mits | 11 | |
| C6490 | 1.562x2.625x.625 | Oil seal | 1.562"x2.625"x.625" | 1 | |
| C7AZ-6571-B | Ford 11/32", 7/8"OD | Valve seal -umbrella | FORD | 302 | \$ 3.00 |
| CFT1 | Bedford CF | Aux. thrust plate | | 3 | |
| CR17190 | | Oil seal | 1.739"x2.812"(+flange)x.594" | 3 | |
| DMG762/2S | Rover 216, 416 1995 on | Mani gsk Inlet | | 9 | \$ 8.00 |
| DMS4301 | Ford V8 351C 70-74 | MGI valley cover | | 1 | |
| DOVWP | Ford Trader 380 Dover etc | Water Pump gsk | | 1 | |
| DR720VCBS | Holden V6 VN | Valve cover bolt seal set | | 1 | \$ 20.00 |
| DSF27 | See PNZ267 | | | | |
| EM1111 | Perkins 6.354 Turbo | Oil seal -front crank | plus few exh gaskets & valve seals | 1 | |
| FMX | Ford FMX | Oilpan gsk? | | 1 | \$ 10.00 |
| GJ106-1 | Ford Falcon | Shim 1/32" | | 15 | |
| GJ106-2 | Ford Falcon | Shim 1/16" | | 10 | |
| GJ106-3 | Ford Falcon | Shim 1/8" | | 12 | |
| GJ225-5 | | Washers brass | 1/2" OD x 7/8" ID | 28 | |
| GT105 | | | | 1 | |
| GT106 | | | | 1 | |
| GT108 | Toyota 6R | front plate or cover + 3 | 15691/15193/16271-33010,11312- | 16 | \$ 10.00 |
| GT110 | Nissan J13, J15? | | JH007 & 13044 | 16 | |
| GT116 | Nissan | | KA440,KV651/834 | 43 | |
| GT120 | | | | 1 | |
| GT122 | | | | 1 | |
| GT128 | | | KT500, KT501, KT259 | 1 | |
| GT129 | Triumph | | JA705, JA706 | 1 | |
| GT133 | Mits | | JB904, JB905, JCMD020622 | nil | |
| GT145 | Mazda TC | | | 3 | |
| GT158 | Simca | | | 1 | |
| GT165 | | | | 1 | |
| GT174 | | | | 1 | |
| GT177 | Mits? | | E301-15-116/162NZ,E301-12502NZ | 9 | |
| GT185 | Toyota 3K | | KV402,11383-22010,16124-22011 | 3 | |
| GT186 | Hillman | | KR831,KR859,KS684, MITSUBISHI | 5 | |
| GT187 | BMC "A" | Oil pump & fuel pump gsks. | FUEL PUMP GSK | 13 | |
| GT188 | Toyota 3K | | KA443,JR450,20846,16343-22011 | 7 | |
| GT189 | Ford | | | 1 | |
| GT190 | Bedford 300 | | KR615,KT478,KT370 GM | 7 | |
| GT191 | BMC 1800 | | KD136,KT329,KD205 NZMC | 19 | |
| GT192 | BMC 1800 | | KT312,KT293 NZMC | 11 | |
| GT193 | Vaux Viva | Carb gsks | 2 x KD243, 1 x KT092, 2 x KD082 GM | 0 | |
| GT194 | Vaux Viva | Water hsg gsks | KT478, KA170 GM | 1 | \$ 6.00 |
| GT195 | BMC | | KG134,KD153,KD157,KD007,KD111 | 7 | |
| GT196 | Hillman Avenger | | KT327,KD258,PNZ061 MITSUBISHI | 25 | |
| GT197 | Hillman Avenger | | KD668,KD215 MITSUBISHI | 3 | |
| GT200 | Ford Cortina C/F | | JH488/9,JH415/6 FORD | 4 | |
| GT201 | Hillman Hunter | | KA081,KR859,KT191,KT192 MITS | 5 | |
| GT203 | Hillman Hunter | | KT071,KR831,KA205 MITSUBISHI | 30 | |
| GT204 | Mitsubishi 4G32 | Front cover & waterpump gsk | 1X JCMD009043,1X JCMD009006 | 50 | |
| GT205 | Mitsubishi 4G32 | Rear seal plate etc | 1X LT273,LT274,LT275,2X LT276 | 6 | |
| GT207 | Mitsubishi 4G15 carb | Mani gsk inl set | use JC629 plus LA251 | | |
| GT214 | | Front cover + 7 | KS014/15/16/17/KA087/KR993/379 | 19 | |
| GT215 | Jaguar | | LS550,LS551,LS549,LS548 JAGUAR | 8 | |
| GT217 | Vaux 2.6, 3.3 | Mani gsk inl set | JB503 x 2 plus JB502 | 4 | \$ 20.00 |
| GT219 | Nissan RB30 | | 15066-42L01,16175-V5200,13017- | 6 | |
| GT220 | Niss? | Mani gsk exh set | Cont:17170/3-87302 | 2 | |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|---------|----------------------------------|----------------------------|-----------------------------------------------|-------|----------|
| GT230 | Ford Cortina OHC | Mani gsk exh set | CONT:JA768/770 EX.MAN.GSK.SET | 21 | \$ 10.00 |
| GT231 | | Mani gsk exh set | JA963 = 1 + 2 PIECES | 6 | |
| GT232 | JC653 x 6 | Mani gsk exh group | CONT:JC653 X 6 EX.MAN.GROUP | 12 | |
| GT233 | BMC "A" | Carb gsks? (6) | CONT:KD153 X 6 OFF | 16 | |
| GT234 | KD177 x 6 | Carb gsks | CONT:KD177 X 6 | 9 | |
| GT235 | Bedford 466, 500 | Cork ring | CONT:KG756 X 10 | 1 | |
| GT237 | KG033 x 6 | V/seals felt | CONTAINS KG033 X 6 | 3 | |
| GT241 | | Mani gsk exh set | | 1 | |
| GT242 | | Mani gsk inl, carb etc | | 2 | |
| GT244 | Holden Barina | Water pump gsk. Etc | BARINA/SWIFT W/p, f/cover, rear seal pla | 4 | |
| GT245 | | Carb gsks? | KD241A X 4 | 1 | |
| GT249 | | | KD260,KD082,KD242,KD243X2,KT09 | 2 | |
| GT251 | | Mani gsk exh set | EX.MANIFOLD GSK. | 7 | |
| GT252 | Mazda F8 carb | Mani gsk set | JC401+PNZ408 | 194 | \$ 5.00 |
| GT258 | Toyota 3K, 4K | W/p, therm gsks. | MISC GSKS (KA443,LA131,LT220) | 181 | |
| GT259 | Jaguar 2.4, 3.4 to 1959 | | CAM.COVER GSKS. | 6 | |
| GT260 | Bedford 214 | Mani gsk set (2 ends only) | JA219/20 (G 1033949/51) (part HA003) | 10 | |
| GT34 | Diesel? | | | 1 | |
| GT39 | BMC "B"? | W/p, O/pickup | KS235,KA079 NZMC | 2 | |
| GT46 | | | | 1 | |
| GT52 | | | | 1 | |
| GT53 | | | | 1 | |
| GT58 | Leyland 400 | | | 10 | |
| GT58 | Leyland 400 | | JR097,KR591/296,KS340,KS065,KS | 10 | |
| GT59 | Leyland 400 | | | 3 | |
| GT59 | Leyland 400 | | BMC "C"? comb. | | |
| GT74 | Ford V4 | Sump set | HC067 | 1 | \$ 20.00 |
| GT78 | Ford V6 | Sump set | JH401,JH439,JH440,JH441 FORD HC066 | 6 | |
| GT97 | Nissan H20 | Group | 1X21074-69200,22179/1307932200 | 10 | |
| GT98 | Nissan A12, A14, A15 | | F/cover, W/pumpLR104, oil pump&pickup | 14 | |
| GT99 | | | | 1 | |
| HA001 | Chrysler SV 6 (short engine) | Mani gsk set | (head gsk 23.5" long) | 1 | \$ 35.00 |
| HA002 | Bedford 214 early | Mani gsk set | 1 x JA223, 2 x JA224 (or Chev?) | 4 | \$ 30.00 |
| HA003 | Bedford 214 | Mani gsk set+hot box | exh ends GT260, centre JA218/9 | 1 | |
| HA004 | Chev 6 216, 235 1937-52 | Mani gsk set | JA223 + 2 x JA224 | 1 | |
| HA009 | Ford Major petrol 1952-57 | Mani gsk set | use HA021 | | |
| HA010 | Ford Trader 4 cyl diesel 1952-57 | Mani gsk set | | 3 | \$ 25.00 |
| HA016 | BMC "C" | Mani gsk set | 2xJE363 twin ro port & 2xJE364 single sq port | | \$ 30.00 |
| HA017 | Bedford 300 | Mani gsk set | | | \$ 40.00 |
| HA021 | Ford Major petrol 1952-57 | Mani gsk set | set = 2 gaskets | 1 | \$ 30.00 |
| HA024 | Rover | Mani gsk set -exh | 4 cyl "F" head to 1958 | lots | \$ 20.00 |
| HA025 | Rover | Mani gsk set -exh | 6 cyl "F" (JA424/5/6?) | lots | \$ 25.00 |
| HA033 | Hillman | Mani gsk | | 2 | |
| HA039 | Mits 4 | Mani gsk Exh | | 1 | |
| HA043 | Mitsubishi 4G54 | Mani gsk Exh | | 2 | \$ 18.00 |
| HA044 | Mits 4 | Mani gsk Inlet | | 3 | |
| HA045 | Mits 4 | Mani gsk Inlet | | 2 | |
| HA048 | Ford Falcon CIH X/F | Mani gsk Exh | (PNZ239) | 2 | \$ - |
| HA054 | Toyo 4 | Mani gsk | | 1 | |
| HA154 | Chev V8 S/B | Mani gsk Inlet set | | 1 | \$ 20.00 |
| HA172 | Vaux Viva | Mani gsk set | JA730, JA484, JE251, KD082 | yes | \$ 30.00 |
| HA178 | Ford V8 | Mani gsk set | (MS253) | 1 | |
| HA180 | Toyo 4 | Mani gsk set | | 1 | |
| HA185 | Chrysler SV 6 (long engine) | Mani gsk set | (head gsk 25.5" long) (MSM4405 or ACL#J | 1? | \$ 35.00 |
| HA190 | Chrysler Valiant slant 6 | Mani gsk | | 3 | \$ 15.00 |
| HA191 | Holden 186, 202 | Mani gsk set | | 6 | \$ 20.00 |
| HA208 | Mazda 4 | Mani gsk set | | 3 | |
| HA238 | Ford Cortina OHC | Mani gsk set | JA769 + GT230 | 1 | \$ 15.00 |
| HA264 | Bedford CF | Mani gsk exh set | | | |
| HA265 | Holden V8 253, 308 red | Mani gsk Inlet set | | 3 | \$ 15.00 |
| HA271 | Mazda NA, UB, VB, VC | Mani gsk set | JE057 inl plus 2 x JB802 sq exh | 12 | \$ 8.00 |
| HA278 | Bedford CF | Mani gsk Inlet pair | (JA608 + JA609) | | \$ - |
| HA285 | Ford V8 289,302W | Mani gsk Inlet set | | 7 | |
| HA294 | | Mani gsk pr | | 1 | \$ 15.00 |
| HA295 | Ford V8 302C, 351C 2V | Mani gsk Inlet set | | 1 | |
| HA295EX | Ford V8 302C, 351C 2V | Mani gsk exh set | | 2 | |
| HA295LP | Ford V8 -large port | Mani gsk Inlet set | | 2 | |
| HA297 | Ford Cortina 2.0 | Mani gsk Inlet | now JA769 | 1 | |
| HA303 | Ford Falcon CIH X/F -use NZ268 | Mani gsk Inlet | (see NZ268) | | |
| HA305 | Holden 1900 | Mani gsk exh | | 3 | |
| HA309 | Holden V8 | Mani gsk exh set | 2 x NZ320 plus exh fla (KK009, DSF9A) | 2 | \$ 10.00 |
| HA310 | Chev V8 S/B 1955-74 | Mani gsk exh set | | 1 | |
| HA313 | Isuzu G161Z | Mani gsk exh set | | 1 | |
| HA331 | Ford V8 | Mani gsk Inlet set | | 5 | |
| HA336 | Mazda 4 | Mani gsk set | | 3 | |
| HA345 | Isuzu G161Z, G180Z, G200Z | Mani gsk Inlet pair | (2 x NZ626) | 2 | |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|--------|-----------------------------------------|----------------------------|-------------------------------------|-------|----------|
| HA346 | Isuzu 4 | Mani gsk exh set | | 2 | |
| HA347 | Nissan 4 | Mani gsk | | 1 | |
| HA349 | Holden V8 253, 308 blue/black | Mani gsk Inlet set | (also JC285?) | 2 | \$ 50.00 |
| HA350 | Mazda 4 | Mani gsk set | | 1 | |
| HA353 | Ford Falcon | Mani gsk Exh | Also JC158 | 3 | \$ 20.00 |
| HA366 | Nissan E13 | Mani gsk Inlet -small port | | 2 | |
| HA368 | Holden | Mani gsk set | | 2 | |
| HA372 | Nissan E16 | Mani gsk exh -big port | | 1 | |
| HA373 | Falcon EFI 85-88 | Mani gsk Inlet | | 1+5 | |
| HA383 | Honda | Mani gsk exh set | | 1 | |
| HA391 | Mits 4 | Mani gsk Exh | | 0 | \$ 10.00 |
| HA393 | Falcon 4.1 | Mani gsk Inlet | | 1 | |
| HA399 | Ford 4 | Mani gsk set | | 1 | |
| HA405 | Nissan RB30E | Mani gsk Inlet set | | 2 | \$ 16.00 |
| HA413 | Honda 4 | Mani gsk set | | 1 | |
| HA416 | Holden V6 VN, VR | Mani gsk Inlet set | | | |
| HA417 | Holden V6 VN, VR | Mani gsk Exhaust set | | | \$ 20.00 |
| HA420 | Toyo 4 | Mani gsk | | 1 | |
| HA424 | Holden V8 304, 348 | Mani gsk Inlet | | 1 | \$ 25.00 |
| HC001 | Chrysler SV 6 (short engine) | Sump set | rails are 615mm long | | \$ 35.00 |
| HC002 | Chrysler SV 6 (long engine) | Sump set | | | \$ 35.00 |
| HC006 | Jaguar | Sump set | | | |
| HC009 | Ford Trader 6 cyl 1957-61 | Sump set | Rails JH481,front KS754, rear KT638 | 1 | |
| HC010 | Bedford 214 | Sump set | | 1 | \$ 20.00 |
| HC015 | Morris Series E, MM Minor | Sump set | | 1 | \$ 30.00 |
| HC016 | Standard Vanguard | Sump set | | 3 | \$ 25.00 |
| HC017 | Morris MO Oxford 1952-54 | Sump set | | 1 | |
| HC020 | Ford Consul | Sump set | | 1 | \$ 25.00 |
| HC021 | Ford Zephyr 6 mk1,2,3 | Sump set | | 3 | \$ 20.00 |
| HC022 | Vauxhall EIP | Sump set | | | \$ - |
| HC023 | Vaux Wyvern 1952-56 | Sump set | | 6 | \$ 25.00 |
| HC024 | Ford Trader 1952-61 | Sump set | JH277/8, KS754, KT638 | 1 | \$ 40.00 |
| HC025 | Ford 100E | Sump set | | 1 | \$ 25.00 |
| HC027 | Fiat 850 1964-72 | Sump set | | 1 | \$ 15.00 |
| HC028 | Chev 285-350 V8 small block to 1980 | Sump set | | | \$ 25.00 |
| HC028L | Chev 350, 400 V8 small block 1980 on | Sump set | dipstick hole on RH sump rail | 1 | \$ 20.00 |
| HC031 | BMC "A" transverse | Sump set | | | |
| HC034 | Ford Falcon 144, 170, 200 | Sump set | | | |
| HC035 | Chrysler Valiant slant 6 | Sump set | | 8 | \$ 35.00 |
| HC037 | | Sump set | | 1 | |
| HC039 | Ford Trader 1961-65 4 cyl | Sump set | JH277/8, KS754, KT638 | | \$ 35.00 |
| HC043 | Holden 149-202 | Sump set | | 6 | \$ 25.00 |
| HC045 | Ford Truck 240, 300 petrol | Sump set | | 2 | \$ 60.00 |
| HC047 | Hillman 1400, 1500, 1600 | Sump set | | | |
| HC048 | BMC "A" in line | Sump set | sides = JH378/9, ends KT331 | 2 | |
| HC052 | Perkins 3.152 | Sump set | | 1 | |
| HC056 | Ford Trader 4D | Sump set | KT048, KT049, JH405pr | 4 | \$ 40.00 |
| HC057 | Ford Trader 6D | Sump set | KT048, KT049, JH406/417 | 5 | \$ 40.00 |
| HC059 | Vaux Viva | Sump set | | 3 | \$ 30.00 |
| HC060 | Ford Cortina C/F to 4/70 | Sump set | Cork end seals | 3 | \$ 30.00 |
| HC065 | Bedford CF, Victor FC | Sump set | | | |
| HC066 | Ford V6 | Sump set | Also GT78 | 3 | |
| HC067 | Ford V4 | Sump set | Also GT74 | 7 | \$ 20.00 |
| HC068 | Ford Cortina NCF | Sump set | | 3 | |
| HC069 | BMC Maxi, Allegro, Marina FWD | Sump set | | 7 | \$ 15.00 |
| HC070 | Ford Cortina C/F 1970 on | Sump set | With rubber end seals | 1 | \$ 30.00 |
| HC072 | Hillman Hunter -steel sump | Sump set | | 2 | \$ 30.00 |
| HC074 | Hillman Hunter -alloy sump | Sump set | | 5 | \$ 40.00 |
| HC084 | Toyota | Sump set | | 2 | |
| HC206 | Hino Contessa | Sump set | | 1 | |
| HC209 | Toyota Landcruiser | Sump set | | 1 | |
| HC210 | Nissan A10, A12, A14, A15 | Sump set | JJ329+KV420+KV421 (NZG SS130) | 1 | |
| HC215 | Holden 4 | Sump set | | 3 | |
| HC220 | Ford V8 | Sump set | | 1 | |
| HC223 | Nissan | Sump set | | 10 | |
| HC226 | Ford Falcon | Sump set | Same as HC235? | 2 | \$ 30.00 |
| HC234 | | Sump set | | 2 | |
| HC235 | Ford Falcon (1 x small, 1 x large ends) | Sump set | NZ177+KT620+KT621 Same as HC226? | 3 | \$ 30.00 |
| HC242 | Chrysler V8 273, 318 | Sump set | | 1 | \$ 20.00 |
| HC252 | Chrysler Valiant 245, 265 Hemi | Sump set | | 5 | \$ 45.00 |
| HC253 | BMC Maxi, Marina RWD | Sump set | | 4 | \$ 15.00 |
| HC257 | Ford Falcon | Sump set | | 6 | \$ 25.00 |
| HC285 | Ford Cort 2.0 | Sump set | | 1 | \$ 17.00 |
| HC291 | Holden Opel | Sump set | | 12 | |
| HC311 | Holden V8 253, 308 | Sump set | | 1 | \$ 25.00 |
| HC323 | Ford V8 Cleveland | Sump set | | 1 | |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|----------|----------------------------------------|------------------------------|------------------------------------------|-------|----------|
| HC369 | Ford Falcon XC 1971-76 | Sump set | | 1 | |
| HC371 | Mitsubishi/Chrysler 4 | Sump set | | 4 | |
| HC382 | Mitsubishi/Chrysler 4 | Sump set | | 5 | |
| HC394 | Mazda/Ford 4 | Sump set | | 1 | |
| HC403 | Toyo 5K | Sump gsk | | 3 | \$ 20.00 |
| HC420 | Holden Torana UC | Sump gsk | | 5 | \$ 25.00 |
| HC424 | Jaguar 2.8 68-79, 3.4 75-86, 4.2 68-86 | Sump set | | 1 | \$ 20.00 |
| HC431 | Mazda HA | Sump set | | 1 | |
| HC435 | Mazda R2, S2 | Sump gsk | | 4 | \$ 11.00 |
| HC436 | Mazda/Ford 4 | Sump set | (2 gsks in set) | 9 | |
| HC440 | | Sump set | SS440 | 1 | |
| HC442 | Nissan E13, E15, E16 | Sump gsk | | 3 | \$ 20.00 |
| HC453 | Mazda | Sump gsk | | 1 | |
| HC454 | Mazda/Ford 4 | Sump gsk | | 12 | |
| HC457 | Ford Falcon EA - EL | Sump gsk | | 6 | \$ 15.00 |
| HC460 | Nissan RB20, RB30, RB33 | Sump end pr -rubber | | 3 | \$ 25.00 |
| HC462 | Mazda B3, B5, B6, BP 89- | Sump end pr -rubber | Silicon sides | 1 | \$ 10.00 |
| HC473 | Mazda SL diesl | Sump set | Upper (Lower = JJ386) | 1 | |
| HJ217 | | Gearbox gsk set | | 14 | |
| HJ219 | GM manual | Gearbox gsk set | | 15 | |
| HM5200 | Subaru EJ20G -shim tappets | Rocker cover gsk R/H | 96- uses S/P sealsKK5061, 93-96 KK5083 | 1 | |
| HM5210 | Subaru EJ20G -shim tappets | Rocker cover gsk L/H | 96- uses S/P sealsKK5061, 93-96 KK5083 | 1 | |
| HN014 | Ford Falcon | Rear seal - rope | 2 piece Rope type (KT571) | 1pr | |
| HN016 | Chrysler Valiant slant 6 | Rear seal + cap seals set | (KS634 rope seals + KS633 cap sides) | | \$ 58.00 |
| HN016N | Chrysler Valiant slant 6? | Rear seal + cap seals set | (Neoprene rear seals + KS633? cap sides) | | |
| HN017 | Holden 149-186 | Rear seal | KS690L + KS690U | yes | \$ 20.00 |
| HN022 | Holden 202, 253, 308, Bedford | Rear seal - rope (pair) | (was KT632) | 2 | \$ 30.00 |
| HN039 | | | Misc gsk Toyota 11553-31010 | 16 | |
| HN040 | Holden 202-308 | Rear seal - rubber | Use KV517 | | |
| HN055 | Ford Falcon 6 NCF, V8 Cleveland | Rear seal - rope (pair) | Later models have rubber seals | | |
| HN056 | Ford V8 Windsor | Rear seal - rubber | | 10pr | |
| HN065 | Chrysler Valiant slant 6 | Rear seal - rope | pair (KS634) | | |
| HR103 | Rover | Valve seal | | lots | |
| HR106 | Ford Trader | Valve seal | | 8 | |
| HR501 | Nissan inlet | Valve seal | | 6 | |
| HR5065 | Mazda WL | Valve seal | | 12 | |
| HR5070 | Mazda FS | Valve seal | | 8 | |
| HR5071 | Mazda FS | Valve seal | | 8 | |
| HR569 | Lada, BMW | Valve seal (for 11mm? guide) | FIAT 4174355(1 BAG = 8 PIECES) | 8 | |
| HR625 | BMC "O" | Valve seal 7? x 11.3 | NZMC PRINCESS AHU1626 | 66 | |
| HR662 | BMW | Valve seal (for 10mm guide) | | 11 | \$ 3.00 |
| HSC | BMC Princess | Oil seal g/box | 0.875x1.125x0.375 | 1 | |
| HSK010? | Nissan L18? | Camshaft shim set | "020" crossed out & "010" written | 1 | |
| HSK020 | Nissan L18 | Camshaft shim set | | 3 | |
| HSM27 | See PNZ267 | | | | |
| HYP64 | | | | | |
| JA007 | Nissan L16, L18, L20B | Mani gsk | | 4 | \$ 10.00 |
| JA009 | Nissan J15, J16 | Mani gsk | | 4 | \$ 15.00 |
| JA010 | Nissan A10, A12 | Mani gsk | | 2 | \$ 15.00 |
| JA011 | | Mani gsk | | 7 | \$ 10.00 |
| JA013 | Nissan H20 | Mani gsk | | 0 | |
| JA016 | Isuzu G150 | Mani gsk round ports | (round/square ports gsk is 14146069) | 0 | \$ 30.00 |
| JA021 | Mazda NA, VB etc | Mani gsk Inlet | (Also use JE057) | 1 | |
| JA024 | Mitsubishi 4G41 etc | Mani gsk | | 2 | |
| JA025 | Mitsubishi 4G32 | Mani gsk Exh | EXH.MANIFOLD GSK JCMD002565 | 4 | \$ 2.00 |
| JA030 | Toyota 2R | Mani gsk | MANIFOLD GSK 17172-31012 | 8+1 | \$ 15.00 |
| JA031 | Toyo 12R? | Mani gsk | | 5 | |
| JA032 | Toyo 3R, 5R to 1977 | Mani gsk | | 2 | \$ 10.00 |
| JA033 | Toyota Crown 4M | Mani gsk set | | 6 | |
| JA039 | Mazda | Mani gsk | | 2 | |
| JA052 | Mazda S2, XA, ZB | Mani gsk Exh | S2, XA requires 4, ZB 6. | 8 | \$ 3.00 |
| JA053 | Toyota 2T, 3T etc | Mani gsk Exh | | 1 | |
| JA063 | Toyota 12R | Mani gsk | 6 bolt | 1 | |
| JA064 | Toyota 12R | Mani gsk (hotbox?) | MANIFOLD GSK 17171-44010 | 3 | |
| JA074 | Toyo 5R 1971-77 | Mani gsk | | 1 | |
| JA075 | Toyota B/2B 72-80 | Mani gsk Exh | | 4 | |
| JA077 | Honda EB1, EB2, EB3, EN | Mani gsk exh set | | 44 | \$ 8.00 |
| JA078 | Mitsubishi 4G51, 4G52 | Mani gsk Exh square port | (Round port is JB912) | 1 | \$ 40.00 |
| JA086 | Mazda 4 | Mani gsk Inlet | | 1 | |
| JA093 | Isuzu (G150 or 161?) | Mani gsk | Round inlet and square exhaust ports | 2 | |
| JA094 | Lada | Mani gsk | part of CX660 | 1 | |
| JA206 | Chrysler SV | Mani gsk | part of HA001 (4 reqd) | | |
| JA208 | Hillman SV | Mani gsk | | 1 | |
| JA214 | | Mani gsk | | 2 | \$ 15.00 |
| JA218 | Bedford 214 | Mani gsk centre | G 1033950 (part of HA003) | 0 | |
| JA219/20 | Bedford 214 | Mani gsk ends -see GT260 | (part of HA003) | 0 | |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|---------|----------------------------------------|-------------------------------|-------------------------------------|-------|-----------|
| JA223 | Chev 216 | Mani gsk -centre | MANIFOLD CENTRE 838287 GM (HA002?) | 4 | |
| JA224 | Chev 216 | Mani gsk -ends | MANIFOLD ENDS 838288 GM (HA002?) | 4 | |
| JA249 | Austin A70 | Mani gsk | | 0 | \$ 25.00 |
| JA256 | Austin A40 Devon, Somerset 1948-54 | Mani gsk | | 0 | \$ 18.00 |
| JA258 | Fergusson | Mani gsk each | | 2 | \$ 8.00 |
| JA259 | Standard Vanguard -2 required | Mani gsk each | | 10 | \$ 10.00 |
| JA260 | Jowett | Mani? | | 1 | |
| JA264 | Austin 4 litre petrol | Mani gsk -44mm inlet holes | (Gsk with 37mm inet ports is JA307) | 2 | \$ 30.00 |
| JA266 | Nuffield tractor | Mani gsk set | B L M C AAA4460 | 3 | |
| JA269 | | Exh gsk | | 6 | |
| JA272 | Jaguar 6 cyl | Mani gsk exh (2 reqd.) | | 14 | \$ 10.00 |
| JA275 | IHC trucks BD,SD 220/240/264 vertica | Mani gsk | 69752R1 | | \$ 20.00 |
| JA279 | Ford 100E | Mani gsk | Manifold gsk F 100E-9448 | 7 | |
| JA281 | BMC 3.4, 3.8, 5.1, 5.7 diesels | Mani gsk exh single | 3 for 4 cyl, 4 for 6 cyl | 22 | \$ 4.00 |
| JA282 | BMC "B" | Mani gsk | | 3 | \$ 8.00 |
| JA285 | Triumph 1200, Std 8, 10 | Mani gsk | | 3 | |
| JA286 | Hillman | Mani gsk | | | |
| JA290 | Jaguar | Mani gsk | MANIFOLD GSK. JAGUAR C7619 | 5 | \$ 15.00 |
| JA295 | BMC 2.2 diesel | Mani gsk | | | \$ 15.00 |
| JA296 | IHC BD264 | Mani gsk | IHC 700830R2 | 6 | \$ 12.00 |
| JA296 | IHC BD264 -2 reqd | Mani gsk | | 0 | \$ 12.00 |
| JA299 | Chev V8 350, | Mani gsk Inlet | G 373196 | 6 | |
| JA306 | Triumph TR4 | Mani gsk pr | | 1 | \$ 30.00 |
| JA307 | Austin 4 litre petrol | Mani gsk -37mm inlet holes | (Gsk with 44mm inet ports is JA264) | | \$ 30.00 |
| JA308 | Triumph TR2 | Mani gsk pr | | 1 | \$ 30.00 |
| JA315 | Ford (Trader?) | Mani gsk | | 3 | |
| JA316 | Ford Trader 6 cyl diesel 1957-66 | Mani gsk | 2 reqd | 3 | \$30/pair |
| JA317 | Ford Trader 4 cyl diesel 1957-65 | Mani gsk | 2 reqd | 6 | \$25/pair |
| JA318 | Rover 2 1/4 litre diesel | Mani gsk | MANIFOLD GSK N GEG685 Also JC882 | 3 | |
| JA319 | Bedford 214 | Mani gsk Inlet | Not required if HA003 set used | 0 | |
| JA322 | Austin Healey 3000 | Mani gsk | MANIFOLD GSK N GEG624 | | \$ 20.00 |
| JA323 | Rover 2 1/4 litre petrol | Mani gsk | | 1 | \$ 25.00 |
| JA324 | Rover 2 1/4 litre petrol | hot box | HOT BOX GASKET L/ROVER 57-PET | 4 | \$ 10.00 |
| JA328 | IHC | Mani gsk exh single | Manifold gsk I. 704165R2 | 6 | |
| JA329 | Humber Super Snipe | Mani gsk Exh | MANIFOLD GSK T R5220308 | 0 | |
| JA330 | Bedford 300 | Mani gsk Inlet | | 1 | |
| JA345 | GM? | Mani gsk exh ends | MANIFOLD ENDS G 3835503 | 15 | |
| JA359 | | Mani gsk Exh | Part of GT86 | 1 | |
| JA360 | | Mani gsk Exh | Part of GT86 | 2 | |
| JA361 | | Mani gsk Exh | Part of GT86 | 2 | |
| JA363/4 | BMC "C" | Mani gsk Exh set | See HA016 | | |
| JA367 | Bedford | Mani gsk -centre | not 214 | 1 | |
| JA371 | | Mani gsk exh -centre | EXH.MANIFOLD CENTRE G 3704836 | 4 | |
| JA372 | | Mani gsk Exh | EXH.MANIFOLD G 3704835 | 13 | |
| JA380 | Jaguar | Mani gsk Inlet | INLET MANIFOLD J C14127/1 (3 reqd) | 2 | \$ 10.00 |
| JA381 | Skoda 1089 & 1221cc 1953-71 | Mani gsk | | 1? | \$ 25.00 |
| JA390 | BMC 1.5 diesel | Mani gsk | | 1 | \$ 13.00 |
| JA391 | Chrysler Valiant 225 | Mani gsk | TODD 1947762 | 3 | \$ 30.00 |
| JA394 | Leyland 400 late -6 reqd | Mani gsk exh single | Studs 92mm apart | 1 | \$ 5.00 |
| JA395 | Leyland 400 late -1 reqd | Mani gsk Inlet | INLET MANIFOLD GSK N 601286 | 1 | \$ 16.00 |
| JA396 | Ford? | Mani gsk Inlet | | 3 | |
| JA397 | Ford Zephyr 6 & 4 mk3 | Mani gsk Inlet -big port | FORD 211E-9441 | 124- | \$ 5.00 |
| JA408 | Ford Cortina | Mani gsk small port | | 1 | |
| JA419 | Hillman Imp | Mani gsk | MANIFOLD TO CYL.HD T R7100313 | 2 | \$ 25.00 |
| JA424 | Rover part of HA024/5 sets | Mani gsk exh part | Rover 3 litre | 10 | \$ 3.00 |
| JA425 | Rover part of HA024/5 sets | Mani gsk exh part | (sets HA024/5) | 13 | |
| JA426 | Rover part of HA024/5 sets | Mani gsk exh part | | 12 | |
| JA426 | | | Mani gsk N 534102 | 12 | |
| JA432 | Ford Cortina | Mani gsk big port | | 3 | |
| JA439 | BMC 1300 | Mani gsk | | 7 | \$ 10.00 |
| JA444 | Perkins | Mani gsk exh single | | 21 | |
| JA457 | | Mani gsk | S 110-095840 | 1 | |
| JA464 | | Mani gsk exh single | EXH.MANIFOLD GSK PN 36862143 | 11 | |
| JA466 | Ford V6, V4 | Mani gsk exh single | | 6 | \$ 4.00 |
| JA467 | Ford Trader 240-255 | Mani gsk -exh | (pair) | 5 | \$ 30.00 |
| JA468 | Ford Trader 330-380 | Mani gsk -exh | (pair) | 3 | \$ 26.00 |
| JA469 | Triumph 1300 | Mani gsk | 8 port. Also JA502 | 30 | |
| JA476 | Ford | Inf mani gsk steel (101?) | Ford EIADKN-6053 | 186 | |
| JA478 | Leyland 600/680 | Mani gsk -exh | (4 rqd) | | \$ 8.00 |
| JA480 | Chev/Bed 6 | Mani gsk | | 1 | |
| JA482 | Ford Tractor 4 cyl 5000, 6600 | MGI -steel 4 port (JA482K9 24 | Mani gsk Ford C5NE-9448-B | 15+16 | |
| JA484 | Vaux Viva | Mani gsk Inlet | MANIFOLD GSK. G 9966621 | 4 | \$ 5.00 |
| JA486 | Ford Tractor 3 cyl 2000, 3000, 4000, 4 | Mani gsk -exh (tin) | Mani gsk Ford C5NE-9448-A | 8 | \$ 15.00 |
| JA486C | Ford Tractor 3 cyl 2000, 3000, 4000, 4 | Mani gsk -exh (composite) | | 2 | \$ 15.00 |
| JA488 | Hillman Hunter A/H | Mani gsk -exh | TODD 1238426 | 36 | |
| JA493 | Leyland 400 early -2 reqd | Mani gsk exh single | Studs 73/77mm apart LEYLAND 602827 | 53 | \$ 5.00 |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|---------|----------------------------------------|-------------------------------|--------------------------------------|--------|----------|
| JA494 | Leyland 400 early -2 reqd | Mani gsk exh single | Studs 73/77mm apart LEYLAND 602828 | 32 | \$ 5.00 |
| JA495 | Leyland 400 early -2 reqd | Mani gsk exh single | Studs 73/77mm apart | 36 | \$ 5.00 |
| JA496 | Leyland 400 early -1 reqd | Mani gsk inl twin | | 20 | |
| JA497 | Leyland 400 early -4 reqd | Mani gsk inl single | MISC GSK LEYLAND 602832 | 44 | |
| JA500 | Rover 2 1/4 litre petrol | Mani gsk Inlet | | | \$ 8.00 |
| JA502 | Triumph 1300,1500 | Mani gsk | 8 port (also JA469 for Triumph 1300) | 4 | \$ 15.00 |
| JA5047 | Mitsubishi 4G15 1989 on ECI | Mani gsk Inlet | | 1 | \$ 12.00 |
| JA5059 | Toyota 5VZ-FE 1995 on | Mani gsk Exh | | 1 | \$ 35.00 |
| JA5073 | Mitsubishi 6A11-12 1992 on | Mani gsk Exh | | 1 | \$ 50.00 |
| JA508 | Rover 3500 | MGI valley cover | Includes 2 x KT232 rubber end seals | 2+1 | \$ 60.00 |
| JA510 | Triumph 2000, 2500 | Mani gsk | | | \$ 10.00 |
| JA512 | Fiat | Mani gsk | MANIFOLD GSK FIAT 4127971 | 5 | |
| JA516 | BMC Marina 1500, 1750 | Mani gsk | MANIFOLD GSK N GEG621/32H93 | 2 | \$ - |
| JA520 | Hillman Avenger | Mani gsk | | 1 | \$ 12.00 |
| JA545 | Perkins | Mani gsk Inlet | MANIFOLD GSK PERKINS 0490738 | 5 | |
| JA550 | BMC | hot box | HOT SPOT GSK NZMC AEC950 | 53 | |
| JA567 | Leyland 400 | | Misc gsk Leyland 601304 | 5 | |
| JA585 | Humber Super Snipe | Mani gsk Inlet | INDUC.MANIFOLD GSK T 1228053 | 4 | \$ 15.00 |
| JA599 | Ford Tractor 3 cyl 2000, 3000, 4000, 4 | Mani gsk Inlet | | | \$ 15.00 |
| JA608 | Bedford CF | Mani gsk Inlet -front | Set = HA278 | 27 | \$ - |
| JA609 | Bedford CF | Mani gsk Inlet -rear | Set = HA278 | | \$ - |
| JA628 | | Exh fla - flat 2 bolt 1.27"ID | | 2 | |
| JA635 | IHC | Mani gsk exh single | Mani gsk Int. Trucks 704162R1 | 4 | |
| JA694 | Hillman Hunter A/H | Mani gsk -steel | MANIFOLD GSK.TODD 1238427 | 39 | |
| JA699 | Fiat | Mani gsk Exh | | 1 | |
| JA704 | Bedford 466 | Mani gsk Inlet | INDUC.MANIFOLD GSK G 8825524 | 146 | \$ 15.00 |
| JA705 | Triumph | | see GT129 | | |
| JA706 | Triumph | | see GT129 | | |
| JA719 | BMC | Mani gsk? | B L M C NT5072 | 3 | |
| JA721 | Leyland 600/680 | Mani gsk Inlet | (2 reqd) | | |
| JA722 | Leyland 600/680 | Mani gsk Inlet | (2 reqd) | | |
| JA726 | Ford Zephyr | Mani gsk Inlet | | 3 | |
| JA730 | Vaux Viva | Mani gsk Exh | | | \$ 20.00 |
| JA737 | IHC BD264 -4 reqd | Exh fla gsk | Mani gsk I. 700832R2 | 10 | \$ 10.00 |
| JA742 | Rootes? | Mani gsk Inlet | Inl mani gsk P 36867153 | 15 | |
| JA745 | | | | | |
| JA747 | Ford V4 | Mani inlet gsk | (PNZ379+NZ204+NZ205+PNZ195+PNZ19 | 4 | \$ 30.00 |
| JA748 | Ford V6 (individual items) | Mani inlet gsk "D" ports | (PNZ378+NZ204+NZ205+PNZ195+PNZ19 | 7 | \$ 25.00 |
| JA754 | Fiat | Mani gsk Exh | EXH.MANIFOLD GSK FIAT 4048457 | 5 | |
| JA765 | Austin Kimberley? | Mani gsk | | 1 | \$ 30.00 |
| JA769 | Ford Cortina OHC | Mani gsk Inlet | (exh =GT230, both =HA238) | 1 | \$ 9.00 |
| JA782 | Holden 179 etc | Mani gsk | | 10 | \$ 10.00 |
| JA791 | | | IN & EX MAN GSK N GEG664 | | |
| JA793 | Jaguar | Mani gsk | | 4 | |
| JA796 | Vaux 1600 OHC | Inl mani rear | | | \$ 8.00 |
| JA935 | IHC 6 ABD, AGD240/264/282 | Mani gsk | | | \$ 35.00 |
| JA961 | Chrysler 245, 265 Hemi | Mani gsk | | 1 | \$ 15.00 |
| JA963 | Ford Falcon NCF | Mani gsk Exh set | | 2 | \$ 25.00 |
| JAGBS1 | | | On Deletion 2237 | 7 | |
| JB310 | Holden 4 | Mani gsk | | 2+3 | |
| JB408 | Austin Kimberley | Mani gsk | Mani gsk N. AYB2172 | 46 | \$ 20.00 |
| JB502 | Vaux 3.3, 2.6 | Mani gsk Inlet (1 reqd) | Old# JA392 | 20 | \$ 6.00 |
| JB503 | Vaux 3.3, 2.6 | Mani gsk Inlet (2 reqd) | Old# JA379 | 20 | \$ 7.00 |
| JB553 | IHC | Mani gsk joints | | lots | |
| JB568 | | Mani gsk | MANIFOLD GSK D 14035-H7200 | 2 | |
| JB581 | Renault | Mani gsk | | 2 | |
| JB682 | Bedford 500 | Mani gsk Exh (6 reqd) | | 18 | \$ 5.00 |
| JB683 | Vaux Viva HC | Exh fla -twin pipe | | 0 | \$ 12.00 |
| JB757 | Toyota F | Mani gsk | | 1 | |
| JB766 | Honda 4 | Mani gsk | | 1 | |
| JB802 | Mazda MA, NA (square port) | Mani gsk Exh | also in HA271 (round port is JC046) | 1 | |
| JB857 | Renault | Mani gsk | | 2 | |
| JB903 | Ford 6 | Mani gsk Inlet | | 3 | |
| JB904 | Mits | | see GT133 | | |
| JB905 | Mits | | see GT133 | | |
| JB906 | | | T. JCMD020624 | 77 | |
| JB907 | Chrysler V8 318 | Mani gsk Inlet set | | 1 | |
| JB908 | Mits | Mani gsk Inlet | IN MAN GSK T JCMD000561 | 6 | |
| JB909 | Mits | Mani gsk Inlet | IN MAN GSK T JCMD000560 | 2 | |
| JB910/1 | Toyo 3K, 4K, 5K | Mani gsk set | | 2 | \$ 9.00 |
| JB912 | Mitsubishi 4G51, 4G52 | Mani gsk Exh round port | (Square port is JA078) | 11 | \$ 12.00 |
| JB913 | Mitsubishi 4G32,36 | Mani gsk Exh | | 73+1 | |
| JB949 | Toyota 2T, 3T etc | Mani gsk Inlet | | 1 | \$ 10.00 |
| JB971 | Mitsubishi 4G51/2/3/4 -84 | Mani gsk Inlet | | 1 | \$ 15.00 |
| JB975 | Toyota 2F | Mani gsk | delaminated | 1? | |
| JB977 | Ford Trader 330-380 | Mani gsk -steel | MAN GSK FORD 2704E-6K698A | 30, 43 | |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|-----------|--------------------------------------|---------------------------|--------------------------------------------|-------|----------|
| JB980 | Toyota 12R | Mani gsk Exh | 8 bolt | 1 | |
| JB983 | Toyota M-EU, 4M, 5M | Mani gsk Exh | | 1 | |
| JB984 | Toyo 6 | Mani gsk Inlet | | 1 | |
| JB989 | Bedford 500 | Side plate gsk | SIDE PLATE GSK G 91010432 | 5 | \$ 15.00 |
| JB998 | Mits | Mani gsk Exh | | 1 | |
| JB999 | Mitsubishi 4G52 | Mani gsk Exh | | 50 | |
| JC004 | Mitsubishi 4G52 | Mani gsk Exh | | 9 | |
| JC010 | Nissan SD22 | Mani gsk | | 1 | \$ 25.00 |
| JC024 | | Mani gsk | | 1 | |
| JC025 | Honda EK/ED 6 hole in/ex | Mani gsk | EX.MAN.HONDA EK,EF | 11 | \$ 15.00 |
| JC038 | Mazda 626 | Ex fla? | | 4 | |
| JC040 | Holden Comodore 4 | Mani gsk | MANIFOLD GSK.G 9940097 | 10 | \$ 25.00 |
| JC043 | Nissan L28 | Mani gsk | | 1 | |
| JC046 | Mazda MA, NA (round port) | Mani gsk Exh | Ford 0459-20-745ANZ (square port is JB802) | 7 | |
| JC048 | | Mani gsk | | 4 | |
| JC057 | Nissan A14 (round inl) | Mani gsk | Round inl ports (Oval = JC214) | 1 | \$ 15.00 |
| JC060 | Isuzu Gemini | Mani gsk | 2 = GT239 | 2 | |
| JC088 | Daihatsu G11 | Mani gsk | | 1 | |
| JC092 | Mazda VC etc | Mani gsk Exh | MANIFOLD GSK. M 3607-13-462NZ | 14 | |
| JC107 | Bed | | GM 91056334 | 1 | |
| JC108 | Bed 8.2 litre diesel | Adaptor to induction mani | | 1 | |
| JC116 | Toyota 2AL, 4AL | Mani gsk | | 1 | \$ 10.00 |
| JC118 | Honda EC, EG, EL | Mani gsk | | 3 | \$ 5.00 |
| JC119 | Honda EL, EJ, EK, EM, EP | Mani gsk | | 7 | \$ 20.00 |
| JC121 | BMC "O" | Mani gsk | | 1 | \$ 20.00 |
| JC123 | | Mani gsk Inlet -twin | ON DELETION 2238 | 47 | |
| JC124 | Mitsubishi 4G32 | Mani gsk Inlet | 14mm centre hole -see also JC606 | 8 | |
| JC125 | Mitsubishi 4G54 | Mani gsk Exh | | 0 | \$ 12.00 |
| JC126 | Nissan Z20, Z22 | Mani gsk Inlet | | 4 | \$ 10.00 |
| JC128 | Nissan L20A/S injected 1981 on | Mani gsk | | 1? | |
| JC156 | Ford 6 | Mani gsk Inlet | | 1 | |
| JC157 | Ford Falcon AH C/F | Mani gsk Inlet | | 2 | |
| JC158 | Ford Falcon AH C/F | Mani gsk Exh | Also HA353 | 3 | |
| JC159 (B) | GM | Mani gsk | | 2 | |
| JC160 | Holden V8 red | Mani gsk Inlet pair | | 1 | |
| JC163 | Ford Laser 1980-87 | Mani gsk Exh | | 6 | |
| JC169 | Ford Truck 240, 300 petrol | Mani gsk | | 1 | \$ 30.00 |
| JC183 | Mazda E5 | Mani gsk Inlet | | 1 | \$ 14.00 |
| JC185 | Toyota 2L 1982-88 non-turbo | Mani gsk Exh | Staggered centre studs | 2 | \$ 8.00 |
| JC214 | Nissan A15 | Mani gsk | Oval inl ports (Round = JC057) | 2 | \$ 15.00 |
| JC215 | Toyota 21R, 2R | Mani gsk Inlet | (round port) | 2 | |
| JC222 | Suzuki F10A | Mani gsk Exh | | 1 | |
| JC224 | Mitsubishi 4D56T | Mani gsk | | 1 | |
| JC225 | Mitsubishi 4G32 | Mani gsk Inlet | | 13 | \$ 9.00 |
| JC242 | Suzuki F5A | Mani gsk Exh | | lots | \$ 10.00 |
| JC253 | Honda EK | Mani gsk | | 3 | \$ 12.00 |
| JC272 | Mitsubishi 4G32 | Mani gsk Exh | | 2 | \$ 14.00 |
| JC283 | Holden 1600, 1800 | Mani gsk Inlet | | 2 | \$ 6.00 |
| JC284 | Isuzu 4FB1,FC1,FD1 | Mani gsk Exh | | 2 | \$ 6.00 |
| JC285 | Holden V8 253, 308 blue/black beaded | Mani gsk Inlet pair | (also HA349?) | 1 | \$ 50.00 |
| JC317 | Nissan CA16, CA18, CA20 | Mani gsk Inlet | | 2 | \$ 4.00 |
| JC319 | Mitsubishi 8DC6, 8DC8 | Mani gsk exh | On Deletion 2232 | 210 | \$ 4.00 |
| JC324 | Mitsubishi 6DS7 1973 on | Mani gsk -exh | | 9 | \$ 15.00 |
| JC336 | Isuzu 4B/6B diesels | Mani gsk Exh -2 port | 4B requires 2, 6B 3. | 3 | |
| JC337 | Isuzu 4BA1 to 4BD1 | Mani gsk Inlet | | 1 | |
| JC344 | Toyota "H" 1972 on | Mani gsk exh set | | 3 | \$ 24.00 |
| JC356 | Ford Falcon AH C/F | Mani gsk Inlet | | 1 | |
| JC397 | Nissan CD17 | Mani gsk | | 1 | |
| JC400 | Mazda FE, F8 | Mani gsk exh set | Is this same as JC777? | 4 | |
| JC401 | Mazda FE, F8 8V | Mani gsk Inlet | plus PNZ408 = GT252 | | |
| JC403 | Toyo 2SEL 81-88 | Mani gsk Exh | | 2 | |
| JC404 | | Mani gsk | | 1 | |
| JC405 | | Mani gsk | | 1 | |
| JC408 | Mitsubishi 4G62/3 | Mani gsk | | 1 | \$ 25.00 |
| JC410 | Toyota 21R, 2R | Mani gsk -exh | (Carb. For Inj use JC584) | 2 | |
| JC414 | Honda EB, EN | Mani gsk Inlet | 2 required | 2 | |
| JC427 | Mazda Rotary | Mani gsk | | 2? | |
| JC429 | Isuzu 4FG1 | Mani gsk Inlet | | 1 | \$ 6.00 |
| JC438 | Toyota 3Y? | Mani gsk | Replaced by JC615 | 1 | |
| JC439 | Toyota B, 2B, 3B | Mani gsk -exh set | | 2 | |
| JC443-4 | Mazda HA | Mani gsk -exh | | 2 | \$ 20.00 |
| JC444 | Toyo 1C diesel 85 on (.2CT,3CT) | Mani gsk -exh | laminated steel | 1 | \$ 30.00 |
| JC445 | Toyota 2LT 1982-88 | Mani gsk -exh | Centre studs same level | 3 | \$ 10.00 |
| JC446 | Rover | Mani gsk | MANIFOLD GASKET ROVER | 5 | |
| JC447 | | | | 2 | |
| JC449 | Holden Camira | Mani gsk Inlet | | 5 | |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|---------|---------------------------------------|------------------------|-----------------------------------------|--------|----------|
| JC457 | | | | | |
| JC471 | Nissan VG30E | Mani gsk singles | 3 = JC472 | 3 | |
| JC472 | Nissan VG30E | Mani gsk | | 1 | |
| JC473 | Nissan SD23,25 | Mani gsk | | 1 | \$ 15.00 |
| JC475 | Nissan B/bird | Mani gsk -exh | | 2 | |
| JC493 | Mitsubishi 4G62, 4G63 | Mani gsk Inlet | | 3 | \$ 9.00 |
| JC494 | Mitsubishi | Mani gsk -exh | 4 pieces | 1 | |
| JC511 | Mitsubishi 4G52, 4G54 | Mani gsk Inlet | large retangle hole between ports 3 & 4 | 3 | |
| JC512 | Mits | Mani gsk Inlet | JCMD026528 | 9 | |
| JC514 | Suzuki G10 | Mani gsk -exh | EX.MAN.SUZUKI G10 | 2 | \$ 13.00 |
| JC516 | Honda ES, ET | Mani gsk Inlet | | 3 | \$ 5.00 |
| JC526 | | Mani gsk Inlet | IN.MANIFOLD HH17116-PE2-000 | 3 | |
| JC530 | Falcon? | Mani gsk Inlet | | 3 | |
| JC532 | Suzuki G10 | Mani gsk Inlet | IN.MAN.SUZUKI G10 | 5 | \$ 8.00 |
| JC534 | Honda EV, EW | Mani gsk -exh set | | 1 | |
| JC536 | HA393 use | Mani gsk Inlet | WSN USE HA393 | 4 | |
| JC537 | HA393 use | | WSN USE HA393 | 16 | |
| JC557 | Honda ER | Mani gsk | | 1 | \$ 15.00 |
| JC558 | Toyota 2E | Mani gsk -exh | | 1 | |
| JC579 | Toyota 4A | Mani gsk -exh | | 1 | |
| JC588 | Suzuki G13A, B | Mani gsk Inlet | | 1 | |
| JC589 | Suzuki G13A, B | Mani gsk -exh | | 1 | |
| JC595 | Subaru | Mani gsk Inlet | only 1 in set? | 1 | |
| JC606 | Mitsubishi 4G32 | Mani gsk Inlet | 12mm centre hole -see also JC124 | 2 | |
| JC611 | Mitsubishi 4G63 | Mani gsk -exh | | 2 | \$ 10.00 |
| JC614 | Mitsu | Mani gsk Inlet single | INLET MANIFOLD REAR MITSUBISHI | 12 | |
| JC615 | Toyota 3Y | Mani gsk | also JC438 | 1 | |
| JC623 | Toyota 3F | Mani gsk | | 1 | \$ 13.00 |
| JC627 | Mitsubishi 4G32 | Mani gsk Exh | | 19 | \$ 15.00 |
| JC628 | Mitsubishi 4G12T | Mani gsk Exh | EX MAN GSK MITSU JCMD013795 | 52 | \$ 20.00 |
| JC629 | Mitsubishi 4G12 | Mani gsk Inlet | | 3 | \$ 5.00 |
| JC632 | Mitsubishi 4D68T 92- | Mani gsk Exh | | 7 | \$ 30.00 |
| JC637 | | | | | |
| JC640 | Toyota 2L up to 1988 (mk 1) | Mani gsk Inlet | | 1 | |
| JC641 | | Mani gsk Exh | EX.MANIFOLD | 3 | |
| JC643 | Isuzu C190 etc | Mani gsk | | 1 | |
| JC644 | Mitsubishi 4G52, 4G54 | Mani gsk Inlet | slotted hole between ports 3 & 4 | 1 | |
| JC645 | Mits Magna | Mani gsk Exh | | 3 | |
| JC646 | Mits?) | Mani gsk Exh | | 5 | |
| JC652 | Honda A20, B20 | Mani gsk Inlet | | 1 | |
| JC653 | Nissan RB20E, RB30E | Mani gsk Exh | Also GT232 | 2 | \$ 10.00 |
| JC657 | Toyota 4M | Mani gsk Inlet | | 2 | |
| JC664 | Mazda B3, B6 | Mani gsk Exh | | 3? | \$ 9.00 |
| JC665 | Mazda | Mani gsk Inlet | | 10 | |
| JC668 | Nissan SD23,25 | Mani gsk | | 3 | \$ 15.00 |
| JC670 | Isuzu 4ZB1 | Mani gsk Inlet | | 5 | |
| JC674 | Honda | Mani gsk Exh | | 1 | |
| JC675 | Nissan | Mani gsk | Niss 14005-J2001 | 1 | |
| JC683 | Isuzu | Mani gsk Exh | | 4 | |
| JC686 | Honda | Mani gsk Inlet | | 2 | \$ 9.00 |
| JC700 | Subaru EF12 | Mani gsk Exh | EX.MAN.SUBARU EF12 | 6 | |
| JC719 | Mits | Mani gsk | | 2 | \$ 30.00 |
| JC727 | Ford 6 | Mani gsk Inlet | | 2 | \$ 5.00 |
| JC728 | Ford 6 | Mani gsk Inlet | | 3 | \$ 18.00 |
| JC730 | Falcon EA multi-point | Mani gsk | | | \$ 12.00 |
| JC740 | Toyota 7MGTEU | Mani gsk Exh | | 1 | |
| JC744 | Nissan | Mani gsk exh part | In HA372 | | |
| JC745 | Nissan E13, E15 | Mani gsk exh part | WSN USE HA372 | 10 | |
| JC749 | Nissan E13, E15 | Mani gsk Exh | EX.MAN.GSK.NISSAN 14036-01M02 | 2 | |
| JC751 | Mitsubishi 6G72MLS | Mani gsk | | 1 | |
| JC752 | Mits | Mani gsk | | 1 | |
| JC757 | Holden Astra 1.6 87-90 | Mani gsk Inlet | | 2 | |
| JC776 | Daihatsu | Mani gsk Exh | | 2 | |
| JC777 | Ford Telstar 12v 1987 | Mani gsk exh set | Is this same as JC400? | 2+ | |
| JC777A | Ford Telstar 12v | Mani gsk exh set | Is this same as JC400? | 1 | |
| JC779 | Mazda FE 12v | Mani gsk Inlet | | 1 | |
| JC781/2 | Mazda B6 16v DOHC Tur | Mani gsk exh pr | | 1 | |
| JC793 | Mitsubishi 4G15 multi-point injection | Mani gsk Inlet | | 1 | \$ 5.00 |
| JC797 | | Mani gsk Exh -singles | | 3 | |
| JC798 | Nissan E13, E15 | | FRONT INTAKE GSK.D 14035-01M00 | 1 | |
| JC799 | Nissan E13, E15 | Mani gsk Inlet -centre | CENTRE INTAKE GSK D14035-01M01 | 383 | |
| JC805 | Nissan TD | Mani gsk Inlet | | 1 | |
| JC841 | Toyota 3SGE, 3SGELU | Mani gsk Inlet | | 1 | |
| JC870 | | Mani gsk Exh | | 1(+1?) | |
| JC875 | Niss Micra CG13DE 95-97 | Mani gsk Inlet | | 1 | |
| JC880 | Toyo 4AF, 4AFE | Mani gsk Inlet | | 1 | \$ 8.00 |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|------------|-------------------------------|--------------------------|--------------------------------|--------|----------|
| JC881 | Toyo 4AF, 4AFE, 5AFE | Mani gsk Exh | | 1 | \$ 12.00 |
| JC882 | Rover 2 1/4 litre diesel | Mani gsk | Also JA318 | 2 | \$ 25.00 |
| JC920 | Honda B18A | Mani gsk Inlet | | 3 | |
| JC931 | Mazda | Mani gsk Exh | | 1 | |
| JC938 | Daihatsu CB | Mani gsk Inlet | | 2 | \$ 9.00 |
| JC948 | Isuzu 4ZE1 | Mani gsk Inlet | | 1 | |
| JC967 | Subaru EF12 | Mani gsk Inlet | IN.MAN.SUBARU EF12 | 4 | |
| JC998 | Niss KA24DA 2389cc | Mani gsk exh set | | 3 | |
| JC999 | Nissan GA16DE -plenum gsk | Mani gsk Inlet | | 7 | |
| JCB00 | | | Rear Intake gsk. D 14035-01M02 | 54 | |
| JCMD008899 | Mits | Oil screen gsk | OIL SCREEN GSK MITSUBISHI | 14 | |
| JCMD010549 | | | | 1 | |
| JCMD014194 | | | FRONT CASE GSK MITSUBISHI | 2 | |
| JCMD020353 | Mits | | Chain cover gsk. | 192 | |
| JCMD041017 | Mits | Front cover gsk | ENGINE FRONT COVER GSK MITSUBI | 5 | |
| JCMD088445 | Mits | | Mani front inlet gsk. Mits | 46 | |
| JCMD101160 | Mitsubishi 6G72 | Front cover gsk | | 1 | |
| JCMD101970 | Mitsubishi 6G72 | Front cover gsk | | 1 | |
| JCMD183243 | Mits | Rear seal hsg gsk | OIL SEAL CASE GSK.MITSUBISHI | 34 | |
| JCMD603015 | Mits | Rocker bolt washer | | 14 | |
| JCMD703734 | | | On Deletion 2237 | 57 | |
| JD001 | Nissan GA16DE | Mani gsk Inlet | IN.MAN.NISSAN GA16DE | 2 | |
| JD007 | | Mani gsk Exh | | 1 | |
| JD023 | | Mani gsk | | 1 | |
| JD030 | Nissan CA | Mani gsk Inlet | | 1 | \$ 5.00 |
| JD091 | Nissan GA | Mani gsk exh set | | 1 | \$ 10.00 |
| JD093 | Nissan GA | Mani gsk Inlet | | 1 | \$ 6.00 |
| JD130 | | Mani gsk Exh | | 1 | |
| JD166 | Honda | Mani gsk Exh | | 1 | |
| JD176 | Toyo 5AFE, 7AFE | Mani gsk Exh | | 1 | \$ 30.00 |
| JD302-5 | BMW M20B20K, M20B25 | Mani gsk Inl set | | 1 | |
| JD365 | Toyota 2L 1988 on | Mani gsk Exh | | 1 | \$ 13.00 |
| JD5032 | Mitsubishi 4G64 16v S | Mani gsk Inlet | | 1 | |
| JD5094 | Nissan LD20 81- | Mani gsk Inlet | | 3 | |
| JD5128 | Nissan SR20DE | Mani gsk Inlet | | 1 | \$ 18.00 |
| JD5169 | Isuzu 6VD1 DOHC 1998 on | Mani gsk Exh | | 1 | |
| JD5198 | Nissan RB25DE, RB25DET | Mani gsk Inlet | Pressed steel | 2 | \$ 30.00 |
| JD520-4 | Peugeot 306 XU7JP 1992 on | Mani gsk exh set | | 1 | |
| JD5258 | Toyota 2LT 1988 on, 3L, 3LT | Mani gsk Exh | | 1 | \$ 30.00 |
| JD5262 | Mitsubishi 4D55T/56T | Mani gsk | | 1 | \$ 36.00 |
| JD595 | Toyota 2LT 1988 on, 3L, 3LT | Mani gsk Inlet | | | \$ 9.00 |
| JD633 | Toyota B, 3B, 11B 1988 on | Mani gsk Exh | Lam steel | 1 | |
| JD637 | Nissan TB42 petrol | Mani gsk | | 1 | |
| JD638 | Nissan TB42S | Mani gsk Inlet | | 2 | |
| JE002 | Nissan | Ex fla | F/G NISSAN 20711-21001 | 18 | |
| JE011 | Mitsubishi 4G32 74-77 | Ex fla | | 4 | |
| JE012 | Honda EB1, 2, 3, Toyo 4K | Ex fla | | 8 | \$ 4.00 |
| JE013 | Honda EB1, 2, 3, Toyo 4K | Ex fla | | 2 | \$ 3.00 |
| JE015 | Honda | Ex fla | | 2 | \$ 4.00 |
| JE016 | Toyo 4/6 | Ex fla | | 16 | |
| JE017 | Toyota | Ex fla | | 3 | \$ 5.00 |
| JE019 | Isuzu G150, G161 | Ex fla | | 4 | \$ 8.00 |
| JE021 | Mazda | Ex fla | 0107-13-483NZ FLANGE GSK MAZDA | 2 | |
| JE027 | Nissan 240/260C&Z | Exh fla gsk | | 4 | |
| JE034 | Mazda 12A | Exh fla gsk | | 2 | \$ 3.00 |
| JE036 | Honda EB1 | Exh fla ring | | 1 | |
| JE043 | Subaru | Ex fla | EXHAUST GSK.SUBARU 6440-03042 | 35 | \$ 2.00 |
| JE050 | Toyota 3K etc | Ex fla -twin | | 3 | \$ 3.00 |
| JE057 | Mazda MA VC etc | Mani gsk Inlet | In HA271 (also JA021) | | |
| JE092 | BMC/GM | Exh fla ring | GM/BLMC 3738405/AMK1572 | 1+252 | |
| JE106 | Toyota | Ex ring | | 22 | \$ 5.00 |
| JE146 | Daihatsu Charade G11 | Ex fla | EX PIPE FLANGE 17451-87705 | 155+20 | |
| JE183 | | Ex graphite cone 42mm ID | | 17 | |
| JE184 | | Ex graphite cone 51mm ID | | 6 | |
| JE185 | | Ex graphite cone 54mm ID | | 1 | |
| JE201 | Bedford 214 | Exh fla ring | | | \$ 10.00 |
| JE209 | Standard Vanguard | Ex fla | F/G STANDARD 57924 | 6 | \$ 12.00 |
| JE209Blank | | Ex flange blank | 51mm hole | 5 | |
| JE212 | Bedford 300, 330 | Ex fla | | 6 | \$ 10.00 |
| JE213 | Morris MO Oxford (52-54 only) | Ex ring | | 10 | |
| JE216 | Vaux Viva | Exh fla ring | (38mm ID) | 10 | \$ 5.00 |
| JE227 | Humber Super Snipe | Ex fla flat 2 bolt | manifold to Y piece. 2 reqd. | 10 | \$ 10.00 |
| JE231 | Jaguar 6 cyl | Exh fla ring (2 reqd) | | 2 | \$ 9.00 |
| JE241 | BMC/Vaux | Exh fla ring | | 1 | \$ 5.00 |
| JE244 | Hillman Hunter | Exh fla gsk | | 8 | |
| JE248 | Volvo B230F eng -93 | Exh fla gsk | | 3 | |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|-------|----------------------------------|-----------------------------------|--------------------------------|-------|----------|
| JE251 | Vaux Viva HA, HB | Exh fla ring | (35mm ID) | 1 | |
| JE259 | VW | Ex fla | | 8 | |
| JE267 | Fergusson petrol 85 & 87mm bores | Ex fla | | 1 | |
| JE268 | BMC | Ex fla | NT3576 EXHAUST FLANGE B.M.C. | 3 | |
| JE277 | Perkins | Mani gsk exh single | Mani gsk Perkins 0490228 | 22 | |
| JE279 | Chrysler SV | Exh fla | small one | 1 | |
| JE284 | Ford | Ex fla 2 bolt | Ford Code-9453-A | 41 | |
| JE284 | | Exh fla flat 3 bolt | | 50 | |
| JE285 | Humber Super Snipe | Ex fla | P114340 MISC GSK PAYNE TODD | 6 | \$ 15.00 |
| JE286 | Chev V8 | Ex fla | | 5 | |
| JE289 | Leyland | Ex fla | | 20 | |
| JE298 | Rover | Ex fla | | 126 | \$ 5.00 |
| JE302 | Rover | Ex fla flat 4 bolt | | 35+15 | |
| JE314 | Standard 8, 10 Atlas | Ex fla | | 1 | |
| JE320 | Triumph | Ex fla | STANDARD GEG702 | 11 | |
| JE329 | Austin A110 | Ex fla | | 2 | \$ 5.00 |
| JE331 | Triumph | Ex fla | | 3 | \$ 5.00 |
| JE335 | Austin A70 BMC | Ex fla | | 2 | |
| JE337 | Triumph | Exh fla gsk | | 9 | \$ 8.00 |
| JE340 | BMC 5.1,5.7 | Ex fla | Ex. Flange Leyland AMK9313 P&T | 12 | \$ 12.00 |
| JE341 | Ford Trader | Exh fla gsk | | 2 | |
| JE342 | Ford Trader | Exh fla gsk | EIADKN-9450B Ex pipe gsk | 19 | \$ 2.00 |
| JE363 | Perkins V8-510, Bed 200/220 | Exh fla ring | On Deletion 1862 | 17 | \$ 10.00 |
| JE375 | Holden 186, 202 | Exh fla ring | | 1 | \$ 3.00 |
| JE383 | Vaux 3.3, Bedford CF | Exh fla gsk | | | \$ 20.00 |
| JE398 | Vaux OHC engs | Exh fla gsk | | | |
| JE420 | Holden Commodore 4 | Exh fla gsk | | 2 | |
| JE565 | | Ring gask 1.650" ID | On Deletion 2434 | 30+29 | |
| JE591 | Holden Opel | Ex fla -twin | | 14+23 | |
| JE619 | Toyo B, 11B | Exh fla ring | | 2 | \$ 10.00 |
| JE627 | Nissan TD42, L28 etc | Ex fla -twin | | 1 | \$ 9.00 |
| JE646 | Peugeot | Exh fla ring | | 2 | |
| JE647 | | | On Deletion 2058 | 416 | |
| JE648 | Renault | Exh fla? Twin | 77-00-502-706 MISC GSK RENAULT | 11 | |
| JE650 | | MGE or exh fla twin | Manifold gask. T F16175200 | 6 | |
| JE665 | Honda | Exh fla ring | | 7 | |
| JE666 | Honda | Exh fla ring 41mm ID, 49.5 O | F/G HONDA 18303-659-S00 | 82 | \$ 8.00 |
| JE667 | Honda Civic | Exh fla twin flat 3 bolt | | 90 | \$ 3.00 |
| JE673 | | Exh fla gsk -flat 3 bolt | | 40 | |
| JE678 | | Exh fla gsk -flat 3 bolt | | 2 | |
| JE679 | Honda Civic 81-RR | Ex gsk ring | | 2+39 | |
| JE683 | | Ex fla - flat 2 bolt 1.6"ID | | 25 | |
| JE693 | Mazda G6 +Subaru | Exh fla gsk | | 5 | \$ 4.00 |
| JE699 | Hillman Avenger | Ex fla -twin | | 2 | \$ 3.00 |
| JE704 | Honda | Ex ring | HONDA 18212-689-003/000 | 46 | |
| JE709 | Mazda 626 79-83 | Ex fla -twin | | 8 | |
| JE719 | Ford Sierra | Exh fla gsk -twin flat 3 bolt | | 2 | \$ 4.00 |
| JE735 | Suzuki? | Copper ring -dished | On Deletion 2058 | 406 | |
| JE735 | | | Standard 56214 | 5 | |
| JE751 | Isuzu C223T | Exh fla ring | | 1 | \$ 6.00 |
| JE762 | Holden 161, 202 | Manifold Inlet | | 3 | |
| JE915 | | Exh fla gsk -twin flat 4 bolt (NO | Todd P103646 | 50 | |
| JE915 | | | G.M. 1047193 | 194 | |
| JE932 | Niss/Hol 6 | Exh fla twin | | 1 | |
| JE933 | Nissan Patrol "P" | Exh fla gsk | | 4 | \$ 8.00 |
| JF007 | Honda | Exh fla ring | F/G Honda 18216-634-000 | 366 | |
| JF015 | Mazda FE etc (EL320) | Exh fla (turbo?) | EXHAUST PIPE E508-13-480NZ | 61 | \$ 15.00 |
| JF037 | | Ex graphite cone 45mm ID | GRAPHITE CONE 45mm ID | 114 | |
| JF040 | Ford Falcon EA26 93- | Ex fla collar | | 6 | |
| JF047 | Nissan | Exh fla gsk | | 1 | \$ 3.00 |
| JF051 | | Ex fla collar | | 1 | |
| JF058 | Toyota 4SFE | Exh fla gsk | | 1 | \$ 10.00 |
| JF066 | Mitsubishi 4G32T | Ex fla to turbo | MIT.S.TREDIA JCMD000477 | 618 | |
| JF068 | Nissan TD23-27 | Ex fla | 3 bolt | | \$ 10.00 |
| JF087 | | Ex fla ring | EX.FLANGE GSK O 90917-06039-NZ | 23 | |
| JF105 | Nissan TD42, 6G72 54mm ID | Ex fla | 2 bolt | 1 | \$ 6.00 |
| JF117 | Mits | Ex fla | Ex. Flange Mits. JCMB687012/ | 201 | |
| JF119 | | Converter gsk | CONVERTER GASKET | 14 | |
| JF124 | Daihatsu | | OIL STRAINER GSK.DAIHATSU | 1 | |
| JF146 | | Exh fla -3 bolt | | lots | |
| JF214 | Toyo 3RZ-FE 16v DOHC | Ex fla collar | | 3 | |
| JH005 | Nissan L16, L18, L20B | Sump gsk | | 1 | |
| JH007 | Nissan J13, J15 | Sump gsk | Also in GT110 | 1 | |
| JH014 | Mazda 4 | Sump gsk | | 3 | |
| JH015 | Mazda VC, MA, NA | Sump gsk | | 2 | |
| JH016 | Isuzu C190, C223, C240 | Sump gsk | 2WD (JJ192 for 4WD) | 1 | |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|-----------|--------------------------------------|------------------|-----------------------------------|-------|----------|
| JH018 | Toyota 3K -point arch ends, 18 holes | Sump gsk | | 5 | \$ 10.00 |
| JH021 | Toyota 2R, 12R | Sump gsk | | 4 | \$ 30.00 |
| JH022 | Toyota 18R etc | Sump gsk | | 3 | \$ 30.00 |
| JH023 | Toyota 5R early | Sump gsk | | 4 | \$ 30.00 |
| JH024 | Toyota M, 2M, 4M, 5MGE | Sump gsk | | 1 | \$ 35.00 |
| JH028 | Mazda 4 | Sump gsk | | 2 | |
| JH031 | Nissan LD28 etc | Sump gsk | | 1 | \$ 25.00 |
| JH034 | | Sump gsk | | 2 | |
| JH040 | Mazda 808 TC | Sump gsk | | 5 | |
| JH041 | Toyota 2T, 3T | Sump gsk | Cork | 1 | \$ 15.00 |
| JH048 | Nissan | Sump gsk | JC31313-10202 | 9 | \$ 15.00 |
| JH050 | Subaru 4 | Sump gsk | | 3 | |
| JH064 | Mitsubishi 4G41/42, KE46 | Sump gsk | MIT. JCMD010264 (KE43/44 = HC204) | 5 | \$ 25.00 |
| JH067 | Toyo 5R 72-78 | Sump gsk | | 15 | \$ 25.00 |
| JH068 | Toyo | Sump gsk | SUMP GSK 12151-56020 TOYOTA | 5 | |
| JH069 | Honda EB1, 2 | Sump gsk | 18 holes | 20+ | \$ 25.00 |
| JH071 | Mitsubishi 4G51, 4G52 to 1975 | Sump gsk | 545mm long (JJ072 is 520mm long) | 0 | \$ - |
| JH170 | Toyota 3K -round arch ends, 18 holes | Sump gsk | | 2 | \$ 20.00 |
| JH171 | Honda EB2 late, EB3, EN | Sump gsk | 50 holes | 1 | \$ 20.00 |
| JH181/2 | Chrysler Hemi 6 | Sump rails | SUMP SIDES | 19 | \$ 20.00 |
| JH238 | | Sump gsk | | 3 | |
| JH251 | Morris 8 | Sump rail pair | | 0 | |
| JH258 | IHC BD264 (conv. Set item) | Sump gsk | | 1? | |
| JH261 | Fergusson petrol 85 & 87mm bores | Sump gsk | | 27 | \$ 15.00 |
| JH277/8 | Ford Trader 4 cyl to 1965 | Sump rail pair | EIADDN-6710/11C Sump gsk Ford | 58 | \$ 15.00 |
| JH287 | Ford 100E | Sump rails | 100E-6710/11 MISC GSK FORD | 2 | |
| JH289 | | Sump gsk | | 1 | |
| JH291 | BMC "B" early | Sump gsk | GEG503 SUMP GSK B.M.C. | 18 | \$ 10.00 |
| JH298 | Austin A70, A90 atlantic, Gipsy | Sump gsk | | 1 | \$ 30.00 |
| JH310 | | Oilpan gsk? | | 2 | |
| JH311 | IHC? | Sump gsk | 703840 R1 | 1 | |
| JH319/20 | Ford 105E | Sump rail pair | 105E-6710/11-B SUMP SIDES FORD | 28 | |
| JH323 | Perkins | Rectangular seal | Perkins 0490720 | 1 | |
| JH326 | Ford | Sump rails | CODE 6710/11B SUMP L&R FORD | 6 | |
| JH327 | Austin 4 litre petrol | Sump gsk | | 2 | \$ 30.00 |
| JH330 | Vaux 3.3, 2.6 | Sump gsk | | 0 | \$ 30.00 |
| JH337 | Chrysler Valiant slant 6 | Sump rails | 1947677/8 L&R SUMP TODD CHRYS | 4 | |
| JH339 | Chrysler Valiant slant 6 | Sump rear | TODD REAR SUMP | 55 | |
| JH340 | Chrysler Valiant slant 6 | Sump front | | 1 | |
| JH357 | | Sump gsk | | 2 | |
| JH363 | Hillman Imp | Sump gsk | | 1 | \$ 30.00 |
| JH370 | Triumph 2000, 2500 | Sump gsk | | 0 | |
| JH372 | | Sump sides | 0999694 SUMP SIDES PERKINS | 3 | |
| JH376/7 | Hillman Hunter -steel sump | Sump sides | 1235112/3 SUMP SIDES TODD | 3 | |
| JH378/9 | BMC "A" | Sump sides | SUMP SIDES GSKS. N 12G377/378 | 6 | |
| JH396 | BMC "B" late | Sump gsk | | 5 | \$ 15.00 |
| JH405 | Ford Trader 4D | Sump rail pair | MISC GSK F 2701E-6710/11-B | 3 | |
| JH406/417 | Ford Trader 6D | Sump rail pair | Part of HC057 | 10+ | |
| JH415/6 | Ford | Sump rails | 2730E-6710B/11A SUMP L&R FORD | 8 | |
| JH420 | Ford Tractor 4 cyl 5000, 6600 | Sump gsk | | 36 | \$ 15.00 |
| JH425 | Rover 2.6 & 3 litre | Sump gsk | Massey Ferg. 825299M1 | | \$ 30.00 |
| JH445 | Triumph 4, Std 8 & 10 | Sump gsk | | 1 | \$ 16.00 |
| JH449 | Hillman Avenger | Sump gsk | | | \$ 15.00 |
| JH467 | Ford Trader 4D | Mani gsk pr | | 1 | |
| JH475 | Chev V8 SB | Sump sides | 3795420/3 SUMP L&R GSK G.M. | 5 | |
| JH481 | Ford Trader 6 cyl 1957-61 | Sump rails | (sump set = HC009) | 1 | \$ 30.00 |
| JH488/9 | Ford (Cortina?) | Sump rails | 681F-6710/11AA SUMP SIDE FORD | 4 | |
| JH530 | Toyo 3A | Sump gsk | | 5 | \$ 14.00 |
| JH846 | Nissan | Sump gsk | | 4 | |
| JH856 | Ford Falcon 250 | Sump set | | 3 | |
| JH881 | Lada Niva 1.6 83-88 | Sump gsk | | 4 | \$ 25.00 |
| JH896 | Chrysler Hemi 6 | Sump end | SUMP GASKET (other end LS390) | | |
| JH917 | Leyland P76 V8 | Sump gsk | | 1 | |
| JJ023 | Toyota F etc | Sump gsk | | 1 | \$ 50.00 |
| JJ072 | Mitsubishi 4G51, 4G52 1975 on | Sump gsk | 520mm long (JH071 is 545mm long) | 7 | \$ 10.00 |
| JJ075 | Mitsubishi 4G32,33,36,37 | Sump gsk | | 8 | \$ 15.00 |
| JJ093 | Toyota 3K -flat arch ends, 18 holes | Sump gsk -rubber | | 15 | \$ 20.00 |
| JJ094 | Toyota 4K -22 holes | Sump gsk -rubber | | 5 | \$ 25.00 |
| JJ098 | | Sump gsk | | 4 | |
| JJ106 | BMC 3.4 3.8 diesel | Sump gsk | | 12 | \$ 25.00 |
| JJ114 | Bedford CF | Sump rails | | 6pr | |
| JJ115/6 | Bedford 214 | Sump rails | 2681510/11 SUMP GSK GEN.MOTORS | 6 | |
| JJ117 | | Sump gsk | | 1 | |
| JJ118 | Bedford 300, 330 | Sump gsk | | | \$ 25.00 |
| JJ119 | Bedford 466, 500 | Sump gsk | | 1 | \$ 40.00 |
| JJ126 | Daihatsu | Sump gsk | | 1 | |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|---------|---------------------------------------|-----------------------------|------------------------------------------|---------|----------|
| JJ133 | Toyo Corsa, corolla | Sump gsk | | 2 | |
| JJ149 | Mazda E3, E5 | Sump gsk | | 1 | \$ 12.00 |
| JJ150 | Toyota L diesel | Sump gsk -rubber | | 1 | \$ 30.00 |
| JJ151 | Nissan 6 | Sump gsk | | 4 | |
| JJ163 | Suzuki F8A | Sump gsk | | 1 | |
| JJ164 | Nissan SD22 1979-82 | Sump gsk | | 4 | \$ 15.00 |
| JJ177 | Isuzu 4BA1 to 4BD1 | Sump gsk | | | \$ 20.00 |
| JJ192 | Isuzu C190, C223, C240 | Sump gsk | 4WD (JH016 for 2WD) | 3 | \$ 15.00 |
| JJ208 | | Sump gsk | | 1 | |
| JJ261 | Toyo B, 2B, 3B, 11B, 13B | Sump gsk | | 2 | \$ 20.00 |
| JJ268 | Ford/Mazda | Sump gsk | | 1 | |
| JJ274 | Mitsubishi 4G62, 4G63 | Sump gsk | | 1 | \$ 18.00 |
| JJ278 | | Sump gsk | | 1 | |
| JJ289 | Daihatsu DL | Sump gsk | | 2 | |
| JJ329 | Nissan A10, A12, A14, A15 | Sump rail pair | 11132/3-H5000 SUMP SIDES NISSA | 6 | |
| JJ341 | Suzuki | Sump gsk | | 4 | \$ 15.00 |
| JJ343 | Toyota 4 | Sump gsk | | 3 | |
| JJ345 | Holden 4 | Sump gsk | | 2 | |
| JJ350 | Mitsubishi 4 | Sump gsk | | 3 | |
| JJ354 | Mazda B3, B5, B6 | Sump gsk | | 2 | \$ 25.00 |
| JJ357 | Nissan RB20, RB30 | Sump gsk | | 1 | \$ 20.00 |
| JJ358 | Isuzu 4ZA1 - 4ZD1 | Sump gsk | | 6 | \$ 23.00 |
| JJ360 | Subaru EA82 | Sump gsk | | 1 | |
| JJ361 | Isuzu 4ZE1 1988 on | Oil pan set | | 1 | \$ 20.00 |
| JJ376 | Isuzu 4BC2 | Sump gsk | | | |
| JJ378/9 | Ford Falcon EA | Sump rail pair | EA FALCON SUMP GASKET | 16 | |
| JJ380 | Holden VN, VR 3.8L V6 | Sump gsk cork | | 6 | \$ 23.00 |
| JJ383 | Toyota 4 | Sump gsk | | 5 | |
| JJ385 | Holden 4 | Sump gsk | | 6 | |
| JJ387 | Toyota 4 | Sump gsk | | 3 | |
| JJ392 | Holden VN V8 | Sump gsk | | 1 | \$ 30.00 |
| JJ623 | Nissan TD42 | Sump gsk | | 1 | \$ 20.00 |
| JM004 | Nissan J15, J16 | Rocker cover gsk | | 6 | \$ 15.00 |
| JM008 | Nissan A12 etc | Rocker cover gsk | | 2 | \$ 15.00 |
| JM010 | Nissan H20, H25 | Rocker cover gsk | | 1 | \$ 20.00 |
| JM014 | Isuzu G150, G161 | Rocker cover gsk | | 0 | \$ 30.00 |
| JM020 | | Rocker cover gsk | | 1 | |
| JM021 | Vaux? | Rocker cover gsk | | 3 | |
| JM023 | Mitsubishi 4G32 | Rocker cover gsk | | 6 | \$ 8.00 |
| JM025 | Toyota 3K, 4K | Rocker cover gsk -rubber | 11213-22010 | 10 | |
| JM028 | Toyota 2R, 21R | Rocker cover gsk | | 4 | \$ 10.00 |
| JM029 | Toyota 18R | Rocker cover gsk | | 1 | |
| JM030 | Toyota 5R | Rocker cover gsk | rubber | | \$ 10.00 |
| JM042 | Isuzu C190 | Rocker cover gsk | | 1 | |
| JM044 | Nissan L20, L24, L26, L28 | Rocker cover gsk | | 1 | \$ 18.00 |
| JM054 | Toyota 2T, 3T | Rocker cover gsk -flat cork | (moulded rubber gsk is JN410) | 1 | \$ 15.00 |
| JM055 | Nissan | Rocker cover gsk | NISSAN 13270-76200 | 16 | |
| JM064 | Toyota 5R | | Sump gsk -rubber??? | 10? | \$ 12.00 |
| JM065 | Subaru | Rocker cover gsk | | 2 | |
| JM068 | Toyota B, 11B, 13B | Rocker cover gsk -rubber | | 1 | \$ 25.00 |
| JM069 | Honda EB | Rocker cover gsk -rubber | For Alloy Rocker Cover | 1 | \$ 20.00 |
| JM071 | Mitsubishi 4G51, 4G52 1973-75 | Rocker cover gsk | | 0 | \$ 42.00 |
| JM221 | Bedford 214 1938-57 | Rocker cover gsk | (no holes) | 2 | \$ 35.00 |
| JM235 | Austin 4 litre petrol | Rocker cover gsk | | 3 | \$ 30.00 |
| JM242 | Bedford 300 | Rocker cover gsk | (no holes) | 4 | \$ 20.00 |
| JM252 | Austin A110 | Rocker cover gsk | | 1 | \$ 15.00 |
| JM253 | Humber Hawk | Rocker cover gsk | | 1 | |
| JM255 | Ford Zephyr mk2,3 | Rocker cover gsk | | 0 | |
| JM258 | Bedford 300, 330 diesel | Rocker cover gsk | (6 holes) | 6 | \$ 22.00 |
| JM260 | Humber Super Snipe | Rocker cover gsk | ROCKER COVER GSK T P111395 | 0 | \$ - |
| JM261 | Triumph 1200, 1300 | Rocker cover gsk | | 1 | \$ 15.00 |
| JM264 | Austin A70 | Rocker cover gsk | ROCKER COVER GSK N 1B1247 | 2 | \$ 20.00 |
| JM267 | Ford 100E, E93A | Valve cover gsk | VALVE COVER GSK F 100E-6521 | 1 | \$ 10.00 |
| JM268 | Leyland 600/680 | Rocker cover gsk | | | |
| JM271 | Rover | Valve side cover | Rover 75, 90, 105 1950-59 | 20 plus | \$ 10.00 |
| JM274 | Austin A40 Devon, Somerset 1948-54 | Rocker cover gsk | | 1 | |
| JM277 | Fergusson, Vanguard | Rocker cover gsk | | | |
| JM287 | Rover 3 litre Mk 1, 1A, 75,90,100,105 | Valve top cover | | lots | \$ 20.00 |
| JM290 | Ford Consul mk1 | Rocker cover gsk | | | |
| JM294 | Vaux EIP | Rocker cover gsk | ROCKER COVER GSK G 7079699 | 0 | |
| JM295 | Ford Trader 1952-57 | Rocker cover gsk | | 10 | \$ 20.00 |
| JM302 | BMC "A" | Rocker cover gsk | | 5 | |
| JM314 | BMC 3.4, 3.8 early diesels | Rocker cover gsk | No holes (Later 3.8 with holes is JM474) | 8 | \$ 25.00 |
| JM315 | BMC "B" | Rocker cover gsk | | 4 | \$ 12.00 |
| JM319 | Hillman 1600 | Rocker cover gsk | | 1 | \$ 15.00 |
| JM330 | IHC BD264 1 reqd | Rocker cover gsk | | 0 | \$ 20.00 |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|--------|-------------------------------------------|-----------------------------|-------------------------------------------------|-------|----------|
| JM333 | Fiat 850, 127 | Rocker cover gsk | | 2 | \$ 15.00 |
| JM337 | Ford Consul, Zephyr 4 | Rocker cover gsk | | 1 | \$ 18.00 |
| JM346 | Bedford 214 | Rocker cover gsk | (4 holes) | 3 | \$ 30.00 |
| JM347 | Vaux PA | Rocker cover gsk | On Deletion 2003 | 5 | \$ 15.00 |
| JM348 | Perkins 3 cyl | Rocker cover gsk | CYL. HEAD COVER P 0490491 | 22 | |
| JM350 | Rover 2 litre, 2 1/4 litre diesel | Rocker cover gsk | ROCKER COVER GSK N GEG452 | 2 | |
| JM363 | Rover 3 litre | Valve side cover | Rover 3 litre Mk 1, 1A, 100 1959-62, 95 1962-67 | 10 | \$ 11.00 |
| JM373 | Falcon | Rocker cover gsk -cork | Also JN054 | 1 | |
| JM388 | Chrysler Valiant slant 6 | Rocker cover gsk -cork | | 2 | |
| JM389 | Leyland 400 V | Rocker cover gsk -cork | R/COVER GSK N 600906 G 6374879 | 10 | \$ 25.00 |
| JM393 | Perkins 6.354 | Rocker cover gsk | | | |
| JM394 | Chev V8 | Rocker cover gsk -cork | | 4 | \$ 8.00 |
| JM397 | Vaux Victor FB, FC | Rocker cover gsk -cork | rocker cover gasket | 1 | \$ 25.00 |
| JM409 | Vaux 3.3, 2.6 | Rocker cover gsk | | 4 | \$ 25.00 |
| JM413 | Vaux Viva | Rocker cover gsk | | 9 | \$ 15.00 |
| JM422 | | Rocker cover gsk | On Deletion 2405 | 10 | |
| JM423 | Ford Trader 4 cyl 1957 on | Rocker cover gsk | 528E-6584-B R/C gsk Ford | 4 | \$ 15.00 |
| JM424 | Ford Trader 6 cyl diesel 1957-66 | Rocker cover gsk | 10 holes | 5 | \$ 25.00 |
| JM434 | | Rocker cover gsk | | 2 | |
| JM439 | Skoda | Rocker cover gsk | 110-092924 VALVE COVER SKODA | 6 | |
| JM444 | Perkins 3 cyl late | Rocker cover gsk | 36811115 MISC GSK PERKINS | 7 | |
| JM449 | Ford Trader 4D | Rocker cover gsk | | 3 | |
| JM450 | Ford Trader 380 Dover etc | Rocker cover gsk | 8 holes | 2 | \$ 40.00 |
| JM453 | Ford V4 | Rocker cover gsk | | 30+15 | \$ 6.00 |
| JM456 | BMC 5.1,5.7 1966 on | Rocker cover gsk | with holes | | \$ 35.00 |
| JM460 | Ford Lotus DOHC | Rocker cover gsk | | | \$ 35.00 |
| JM464 | Ford V6 | Rocker cover gsk | | 10 | \$ 10.00 |
| JM467 | Hillman Hunter | Rocker cover gsk | | 10 | \$ 10.00 |
| JM474 | BMC 3.4 3.8 diesel | Rocker cover gsk -10 holes | CMK1343 R/C gsk NZMC | 19 | \$ 15.00 |
| JM475 | Bedford 466, 500 | Rocker cover gsk | | 3 | \$ 25.00 |
| JM477 | Triumph 2.0, 2.5 | Rocker cover gsk | | | \$ 25.00 |
| JM480 | Cummins | Rocker cover gsk | | 1 | |
| JM481 | Rover 2000, 2200 | Rocker cover gsk | | 0 | \$ 20.00 |
| JM482 | Rover 3 litre Mk 2, 3 1962-67 | Valve top cover | | 10 | \$ 20.00 |
| JM5020 | Subaru EJ20G -hydr tappets 1989-95 | Rocker cover gsk L/H | | 1 | |
| JM5021 | Subaru EJ20G -hydr tappets 1989-95 | Rocker cover gsk R/H | | 1 | |
| JM506 | Ford V8 302, 351 Cleveland | Rocker cover gsk | | 4 | \$ 9.00 |
| JM5069 | Isuzu 6VD1 SOHC 92-97 | Rocker cover gsk | | 2 | \$ 30.00 |
| JM507 | Fiat 125 | Rocker cover gsk | On Deletion 2405 | 5 | \$ 30.00 |
| JM5070 | Isuzu 6VD1 DOHC 94-97 | Rocker cover gsk +S/P seals | | 4 | \$ 40.00 |
| JM5077 | Nissan GA15DE | Rocker cover gsk | | 1 | \$ 20.00 |
| JM510 | Ford Cortina OHC | Rocker cover gsk | | 2 | \$ 12.00 |
| JM520 | Hillman | Rocker cover gsk | | 1 | |
| JM5206 | Mitsubishi 6G72 GDI 1997- | Rocker cover gsk | | 2 | \$ 40.00 |
| JM521 | Daimler V8 | Rocker cover gsk | 307827 TOP COVER GSK DAIMLER | 50 | \$ 10.00 |
| JM522 | Leyland 400 | Valve hsg gsk | 604964 MISC GSK LEYLAND | 23 | \$ 15.00 |
| JM534 | Chrysler V8 318, 360 | Rocker cover gasket | | 3 | \$ 12.00 |
| JM536 | Jaguar | Rocker cover gasket | | 1+ | |
| JM538 | Jaguar XJS | (block to top cover gsk?) | part of CH830 | 1 | |
| JM539 | VW | Rocker cover gsk | | 2 | |
| JM540 | Ford Tractor 3 cyl 2000, 3000, 4000, 4800 | Rocker cover gsk | | 1 | \$ 25.00 |
| JM547 | Fiat | Rocker cover gsk | | 2 | |
| JM548 | Fiat | Rocker cover gsk | | 1 | |
| JM550 | Bedford CF | Tappet cover gsk | | 9 | \$ 15.00 |
| JM553 | Morris 8, ser E | Valve cover gsk | MISC GSK N AAA5381 | 0 | |
| JM566 | Hillman Avenger | Valve cover gsk | | 1 | \$ 15.00 |
| JM620 | Try JM260 | | | | |
| JN014 | Austin Kimberley 70-72, Ley P76 6 | Valve cover gsk | | 6 | \$ 28.00 |
| JN015 | Chrysler Hemi 6 | Valve cover gsk | | 1 | \$ 15.00 |
| JN052 | Holden 186,202 | Rocker cover gsk | | 0 | \$ 10.00 |
| JN054 | Ford Falcon NCF | Rocker cover gsk | Also JM373 | 1 | \$ 25.00 |
| JN055 | Leyland P76 V8 | Rocker cover gsk | | | \$ 10.00 |
| JN057 | Holden V8 | Rocker cover gsk | | 4 | \$ 8.00 |
| JN075 | Chrysler Hemi 6 | Side plate gsk | | 1 | \$ 20.00 |
| JN078 | Isuzu 6BG1 86- | Rocker cover gsk | | 3 | \$ 25.00 |
| JN088 | BMC Marina 1500, 1750 | Rocker cover gsk | | 2 | \$ 25.00 |
| JN185 | Toyota 20R, 21R, 22R | Rocker cover gsk -rubber | | | yes |
| JN191 | Isuzu 161Z, 180Z | Rocker cover gsk | | 1 | |
| JN248 | Renault | Rocker cover gsk | On Deletion 2405 | 18 | \$ 15.00 |
| JN255 | Ford Falcon | Rocker cover gsk | | 1 | \$ - |
| JN275 | Mitsubishi 4G51, 4G52 1975 on | Rocker cover gsk | | 1 | \$ 15.00 |
| JN276 | Mitsubishi 4G32 | Rocker cover gsk | MITSUBISHI JCMD08785 | 112 | |
| JN318 | Honda EL | Rocker cover gsk | HONDA 12341-689000/12341PB2000 | 45 | \$ 15.00 |
| JN328 | Holden Commodore 4 | Rocker cover gsk | | 1 | \$ 25.00 |
| JN365 | Mitsubishi 4G32 etc | Rocker cover gsk | | 1 | \$ 15.00 |
| JN368 | Subaru Leone 1800 | Rocker cover gsk | | | |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|-------|------------------------------------|---------------------------|----------------------------------------|-------|----------|
| JN398 | Toyota 2L, 2LT 1982-88 | Rocker cover gsk -rubber | | 1 | \$ 20.00 |
| JN403 | Mitsubishi 4D55/56 | Rocker cover gsk -rubber | | 0 | \$ 20.00 |
| JN405 | Daihatsu DG3 | Rocker cover gsk -rubber | | 3 | |
| JN410 | Toyota 2T, 3T | Rocker cover gsk -rubber | (flat cork gsk is JM054) | 3 | \$ 20.00 |
| JN414 | Suzuki F8A, F10A | Rocker cover gsk -rubber | | 1 | |
| JN427 | Mitsubishi 4G52, 4G54 narrow block | Rocker cover gsk -rubber | See VCK427 | | |
| JN433 | Nissan CA -side distributor eng | Rocker cover gsk | R/C gsk D 13270-D0101 | 10 | \$ 15.00 |
| JN434 | Honda EL | Rocker cover gsk -rubber | | 1 | |
| JN453 | GM | Rocker cover gsk | GM 90106506 | 5 | |
| JN456 | Isuzu 4FB1,FC1,FD1 | Rocker cover gsk -rubber | | 1 | \$ 18.00 |
| JN471 | Toyota 18RGEU | Rocker cover gsk | TOYOTA 178RGEU (R/C GSK.) | 2 | \$ 30.00 |
| JN473 | Toyota 18RGEU | Rocker cover s/plug gsk | 2 reqd? | 0 | \$ 15.00 |
| JN475 | Nissan CA16, CA18, CA20 | Rocker cover gsk -rubber | | lots | \$ 10.00 |
| JN493 | Nissan LD20 1980-83 | Rocker cover gsk -rubber | | 1 | \$ 35.00 |
| JN496 | Mitsubishi 4G63 | Rocker cover gsk -rubber | | 2 | |
| JN504 | Isuzu 4BA1 to 4BD1 | Rocker cover gsk -rubber | | 2 | \$ 30.00 |
| JN533 | Mazda F6, F8, FE, F2 8V | Rocker cover gsk -rubber | | 8 | \$ 20.00 |
| JN534 | Ford | Rocker cover gsk -rubber? | Ford EIADKN-6571 | 693 | |
| JN534 | Honda EJ | Rocker cover gsk -rubber | | 5 | \$ 15.00 |
| JN537 | Daihatsu CL 82- | Rocker cover gsk -rubber | | 11 | \$ 20.00 |
| JN573 | Isuzu 4BA1, 4BB1 | Rocker cover gsk -rubber | | | \$ - |
| JN583 | Honda EB, EN | Rocker cover gsk -rubber | Steel Rocker cover | 1 | \$ 25.00 |
| JN606 | Suzuki G13A, B, G16A | Rocker cover gsk | | 1 | \$ 12.00 |
| JN609 | Mitsubishi 4D30 | Rocker cover gsk -rubber | | 1 | \$ 15.00 |
| JN616 | Ford V6 2QRD 85- | Rocker cover gsk | | 1 | \$ 10.00 |
| JN620 | Ford Sierra OHC | Rocker cover gsk | | 6 | \$ 15.00 |
| JN624 | Nissan CA18 | Rocker cover gsk -rubber | | 1 | |
| JN632 | Honda ZC DOHC 1986-90 | Rocker cover gsk -rubber | | 1 | \$ 20.00 |
| JN639 | Ford Falcon AH C/F | Rocker cover gsk | | 1 | \$ 20.00 |
| JN640 | Nissan RB30E with steel R/Cover | Rocker cover gsk -rubber | | 1? | |
| JN642 | Honda | Rocker cover gsk -rubber | Honda R/C gsk12332-PH7-003 | 84 | |
| JN661 | Isuzu 4BC2,4BD1T,4BE1 | Rocker cover gsk -rubber | | 1 | \$ 45.00 |
| JN664 | Toyota B diesel | Rocker cover gsk -rubber | | 1 | |
| JN682 | twin cam | Rocker cover gsk -rubber | | 2 | |
| JN700 | Daihatsu HD | Rocker cover gsk -rubber | | 1 | \$ 15.00 |
| JN701 | Holden V6 VN, VR | Rocker cover gsk | | | \$ 26.00 |
| JN706 | Toyo 4AF, 4AFE | Rocker cover gsk | | 1 | |
| JN708 | | Rocker cover gsk | | 4 | |
| JN709 | Mazda JE-ZE | Rocker cover gsk -rubber | | 1 | \$ 22.00 |
| JN713 | Mitsubishi 6G71, 6G72 SOHC | Rocker cover gsk -rubber | | 1 | \$ 18.00 |
| JN714 | Mazda JF/JE | Rocker cover gsk -rubber | | 1 | \$ 15.00 |
| JN722 | Nissan LD20 1985-86 | Rocker cover gsk -rubber | | 4 | \$ 30.00 |
| JN723 | Nissan LD20 1987 on | Rocker cover gsk -rubber | | | \$ 30.00 |
| JN817 | Ford Sierra DL20EFI 89- | Rocker cover gsk -rubber | | 1 | \$ 25.00 |
| JN897 | Mitsubishi 4G15 12V 89- | Rocker cover gsk -rubber | | 1 | |
| JN929 | Holden Astra, Barina C14SE | Rocker cover gsk -rubber | | 1 | |
| JN954 | Toyo 3RZ-FE | Rocker cover gsk | | 7 | \$ 20.00 |
| JN965 | Toyota 2L, 3L | Rocker cover gsk | | 2 | |
| JP087 | Subaru EJ20G -shim tappets | Rocker cover gsk R/H | 96- uses S/P sealsKK5061, 93-96 KK5083 | 2 | |
| JP088 | Subaru EJ20G -shim tappets | Rocker cover gsk L/H | 96- uses S/P sealsKK5061, 93-96 KK5083 | 1 | |
| JR007 | Toyo | Mani gsk Inlet | IN/MANIFOLD TOYOTA 17171-22010 | 30 | |
| JR033 | Ford Zephyr mk1 to 3 | Front cover gsk | CYL. FRONT COVER F EOTA-6020-B | 3 | |
| JR043 | Bedford 300 | Front cover gsk | TIMING COVER GSK G 7075059 | 4 | |
| JR064 | Jaguar | Front cover gsk | TIMING COVER GSK N C8615 | 6 | |
| JR071 | | Front plate gsk | | 11 | |
| JR074 | Jaguar | Front cover gsk | TIMING COVER GSK N C8656 | 6 | |
| JR089 | Bedford 330 | Front cover gsk | TIMING COVER GSK G 91024581 | 1 | |
| JR110 | Bedford 330 | Front cover gsk | | 10 | |
| JR112 | Vaux 2.6, 3.3 | Front cover gsk | | 1 | \$ 7.00 |
| JR119 | Leyland 400 | Front cover gsk | FRONT COVER GSK G 6374933 | 28 | |
| JR147 | Triumph 4, Std 8 & 10 | Front cover gsk | | | |
| JR148 | Vaux Viva | Front cover gsk | | 20 | \$ 6.00 |
| JR149 | BMC "A", "B" | Front cover gsk | | 0 | \$ 10.00 |
| JR152 | Ford Trader | Front cover gsk | TIMING COVER F EIADDN-6020 | 8 | \$ 10.00 |
| JR176 | Leyland 400 | | MISC GSK N 611098 | 33 | |
| JR178 | Bedford 466, 500 | Front cover gsk | | 5 | \$ 15.00 |
| JR189 | | | On Deletion 2237 | 6 | |
| JR206 | Ford | Front cover gsk (inj?) | TIMING COVER F C5NE-9F598-A | 2 | |
| JR214 | Hillman Avenger | Front cover gsk | MISC GSK T 71241046 | 2 | \$ 9.00 |
| JR224 | BMC "B" | Front cover gsk | | 10 | \$ 4.00 |
| JR239 | BMC | Misc. gsk | 32H 171misc gsk BMC | 7 | |
| JR260 | Ford V6/4 | Front cover gsk | | | |
| JR263 | Rover | Front cover gsk | 538039 ENGINE FRONT COVER GSK | 3 | |
| JR264 | BMC 1300 | Front cover gsk | | 5 | \$ 7.00 |
| JR265 | Ford Cortina, Escort | Front cover gsk | | 9 | |
| JR403 | Chrysler 318 V8 | Front cover gsk | | 8 | |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|-----------|-------------------------------------|----------------------------|-------------------------------------------|--------|----------|
| JR434 | Toyo | Front cover gsk | 11328-31010 MISC GSK TOYOTA | 3 | |
| JR448/9 | | Front cover gsk | | 10 | |
| JR450 | Toyota 3K | Front cover gsk | | 6 | |
| JR466 | Chrysler Hemi 6 | Front cover gsk | 2899069 TIMING COVER GSK T | 3 | |
| JR472 | Mazda VC,MA 75-80 | Front cover gsk | with JR473 for timing cover pair | 7 | |
| JR473 | Mazda VC,MA 75-80 | Front cover gsk | 0290-10-512NZ TIMING COVER MAZ | 9 | |
| JR519 | Nissan | | MISC GSK. NISSAN 13044-18001 | 9 | |
| JR520/1 | Nissan L20B, Z20, Z22 | Front cover gsk | About 29cm long (not for L13 to L16 engs) | 2 | \$ 10.00 |
| JR552 | Ford Falcon 6 | Front cover gsk -long ends | Also NZ330 | 30 | |
| JR557 | Ford Trader 4D, 6D | Front cover gsk | See TC110 | | |
| JR585/6 | Nissan L | Front cover gsk | About 27mm long | 1 | |
| JR607/8 | | Front cover gsk | E301-10511A/512 TIMING COVERS | 129 | |
| JR611 | Mits? | O ring | JCMD020256 'O' ring (rubber) | 26 | |
| JR612 | Toyota 4K | Front cover gsk | MISC GSK. O 11328-13011 | 111 | |
| JR622 | Toyota 6R, 18R | Front cover or plate | | 3 | |
| JR624 | Holden V8 | Front cover gsk | | 1 | \$ 7.00 |
| JR626/649 | Mits | Front cover gsk | JCMD002252/3 CHAIN CASE MITS | 4 | |
| JR659 | | Belt cover gsk -rubber | T/BELT COVER | 141 | |
| JR672 | Suzuki | Front cover foam | T/C FOAM SUZUKI 11396-82000 | 9 | |
| JR678 | Toyota | Front plate gsk | FRONT PLATE TO BLOCK GSK TOYOT | 75 | |
| JR689 | Mitsubishi 4G61, 4G62, 4G63, 4G64 | Belt cover gsk -rubber | For top cover (short) | 2 | \$ 6.00 |
| JR691 | Mitsubishi 4G61, 4G62, 4G63, 4G64 | Belt cover gsk -rubber | mitsubishi JCMD041002 | 64 | \$ 8.00 |
| JR693 | Toyota | Front cover gsk | MISC GSK.TOYOTA 11328-35010 | 13 | |
| JR696-7 | Nissan Z24 | Front cover gsk pair | about 31cm long | 1 | \$ 15.00 |
| JR701 | Toyota | Front plate gsk | C/CASE FRONT END PLATE GSK.TOY | 11 | |
| JR704 | Honda | Belt cover gsk -rubber | RUB.T/BELT CVR.GSK 11831PB2000 | 9 | |
| JR707 | | Belt cover gsk -rubber | T/BELT COVER GSK 11328-63010 | 6 | |
| JR708 | | Belt cover gsk -rubber | T/BELT COVER GSK 11329-63010 | 6 | |
| JR725 | Nissan E13, E15 early | Top dust cover -rubber | RUB DUST COVER(TOP)13521-01M00 | 133 | |
| JR743 | | Front cover gsk -rubber | TIMING CASE GSK 13521-D0113 | 15 | |
| JR745 | Nissan | Front cover gsk | NISSAN 13522-01E01 | 173 | |
| JR747 | Honda | Rubber | HONDA 11840-657-010 | 7 | |
| JR748 | BMC | Rubber block | BLMC AMK80 | 405 | |
| JR760 | | Belt cover gsk -rubber | T/BELT COVER GSK 11328-11020 | 16 | |
| JR805 | | Front cover gsk -rubber | D 13522-D0112 COVER GSK | 77 | |
| JR806 | Nissan | Rubber seal | MISC.GSK.NISSAN 13523-01E00 | 202 | |
| JR821 | Honda | Rubber seal | RUBBER SEAL HONDA11821-634-000 | 44 | |
| JR822 | Honda | Rubber seal | RUBBER SEAL HONDA11831-634-000 | 44 | |
| JR823 | Honda | T/chain guide? | RUBBER SEAL 11841-634-000 HOND | 15 | |
| JR826 | | W/pump gsk -rubber | W.P SEAL GSK F FE1H-10-543C | 15 | |
| JR827 | Mazda FE | W/pump gsk -rubber | W.P SEAL GASKET | 210 | |
| JR828 | Mazda FE | W/pump gsk -rubber | W.P.SEAL GSK FE1H-10-545A | 214 | |
| JR921 | | Belt cover gsk -rubber | T/BELT COVER GSK.O 11328-15030 | 8 | |
| JR932 | Honda | Front cover gsk -rubber | HONDA TIMING COVER GASKET | 19 | |
| JR933 | Honda | Front cover gsk -rubber | HONDA TIMING COVER GASKET | 9 | |
| JR973 | BMC | Front cover gsk -rubber | GM/BLMC 3738405/AMK1572 | 252 | |
| JR974 | | Belt cover gsk -rubber | T/BELT COVER GSK HH11840673000 | 5 | |
| JR993 | Mitsubishi 4G51 | Front cover gsk -rubber | TIMING CASE GSK MITS. | 1 | |
| JR994 | Mitsubishi 4G51 | Front cover gsk -rubber | TIMING CASE GSK.MITSUBISHI | 0 | |
| JR996 | Toyota 2T, 3T | Front cover gsk | | 1 | \$ 8.00 |
| JS027 | Toyo 3K | Head rear plate gsk | HEAD REAR PLATE GSK.TOYOTA | 365 | |
| KA016 | Bedford 214 | Water pump gsk | 7053203 WATER PUMP GSK GM | | \$ 7.00 |
| KA033 | | gsk 3 bolt | On Deletion 2405 (150) | 5 | |
| KA051 | BMC A30? | Water pump gsk | 2A31 MISC GSK B.M.C. | 5 | |
| KA053 | Bedford 330 | Water pump gsk | WATER PUMP GSK 7075083 G.M. | 8 | |
| KA072 | Ferguson | Water pump gsk | MISC GSK 825386M1 MASSEY FERG. | | \$ 10.00 |
| KA079 | BMC "B" early | Water pump gsk | | 10 | \$ 4.00 |
| KA081 | Humber Super Snipe?, Hillman Hunter | Water pump gsk | Todd 9107026 Z-112 | 1636+8 | \$ 3.00 |
| KA093 | BMC "A" | Water pump gsk | | 3 | |
| KA107 | Humber Super Snipe, Hillman Hunter | W/pump to cover gsk | WATER PUMP/TIMING COVR P111371 | 7 | |
| KA114 | Ford Escort | Water pump gsk | | 1 | |
| KA127 | Ford Falcon early | Water pump gsk | FORD CODE-8507A | 10 | |
| KA140 | Chrysler Valiant slant 6 | Water pump gsk | WATER PUMP GSK C 1947523 MITSU | 8 | |
| KA141 | Chrysler Valiant slant 6 | Water pump gsk | WATER PUMP GSK C 1947521 MITSU | 5 | |
| KA147 | Leyland 400 | Pump to head gsk | Pump to head 601219 Leyland | | \$ 2.00 |
| KA170 | Vaux Viva | Water housing gasket | Also GT194 | 10 | \$ 3.00 |
| KA177 | Standard | Water pump gsk | WATER PUMP GSK 138701 STANDARD | | |
| KA184 | BMC "B" late | Water pump gsk | | 10 | \$ 4.00 |
| KA199 | Standard | Water pump gsk | WATER PUMP GSK 138702 STANDARD | 14 | |
| KA201 | Ford V4, V6 | Water pump gsk | MISC GSK 2724E-8513A FORD | 18 | |
| KA202 | Ford Trader | Water pump gsk | | 1 | \$ 10.00 |
| KA205 | Hillman Hunter | Therm hsg to head gsk | TODD R71266220 | 7 | |
| KA211 | Leyland 400 | | MISC GSK 611122 LEYLAND | 0 | |
| KA217 | Bedford CF | Water pump gsk | WATER PUMP GSK 7201112 G.M. | 6 | |
| KA226 | BMC | Water pump gsk | WATER PUMP GSK 32H83 BMC | 4 | |
| KA229 | Bedford 330 | Water pump gsk | WATER PUMP GSK 7204348 G.M. | 8 | |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|--------|------------------------------------|--------------------|-------------------------------------|-------|----------|
| KA261 | Hillman Avenger | Water pump gsk | WATER PUMP GSK R71266362 MITSU | 5 | |
| KA274 | Triumph 2000, 2500 | Misc. gsk | MISC GSK 138792 STANDARD | 8 | |
| KA284 | Holden | Water pump gsk | | 7 | \$ 8.00 |
| KA289 | Ford Cortina OHC | Water pump gsk | | | \$ 6.00 |
| KA290 | Rover | Water pump gsk | WATER PUMP GSK 610756 ROVER | 3 | |
| KA440 | Nissan | | See GT116 | | |
| KA443 | Toyota 3K | | seeGT188 | | |
| KA446 | Mazda VC,MA small type | Water pump gsk | | 6 | |
| KA458 | Mazda VC,MA large type | Water pump gsk | | 2 | \$ 5.00 |
| KA479 | Leyland P76 V8 | Water pump gsk | MISC GSK AYD57 BMC | 1 | |
| KA483 | BMC | Water pump gsk | WATER PUMP GSK 62H350 BMC | 4 | |
| KA484 | Bedford 500 | Water pump gsk | Use A327 | 1 | |
| KA552 | Nissan | Therm gsk | MISC GSK 11062-M3001 NISSAN | 75 | |
| KA553 | Nissan | Therm gsk | MISC GSK.11062-Y7000 NISSAN | 96 | |
| KA554 | Subaru | Therm gsk | T/STAT GSK 81755-4100 SUBARU | 4 | |
| KA555 | Toyota 2T, 3T | Therm gsk | WATER OUTLET GSK O 16341-38011 | 126 | |
| KA593 | Nissan | Misc. gsk | MISC GSK NISSAN 21074-13200 | 9 | |
| KA599 | Toyota 2T, 3T | Water pump gsk | | 1 | \$ 6.00 |
| KA635 | Honda | Water pump gsk | EW HONDA WATER PUMP GSK. | 16 | |
| KA664 | Nissan CA | Water pump gsk | | 1 | \$ 3.00 |
| KA806 | Mitsubishi 4G51 | Water pump gsk | WATER PUMP GASKET MITSUBISHI | 5 | \$ 10.00 |
| KA813 | Suzuki | Plate gsk | PLATE GSK.SUZUKI | 7 | |
| KD007 | BMC | | | 2 | |
| KD013 | Austin A70 | Carb gsk | Use KD120 | | |
| KD018 | Standard Vanguard | Carb gsk | STANDARD 60574 | 5 | |
| KD025 | Ford Consul mk1 | Carb gsk | | 1 | |
| KD029 | Austin A40 Devon, Somerset 1948-54 | Carb gsk | B.L.M.C. 11G258 when gone use KD104 | 7 | |
| KD073 | Standard | Carb gsk | CARB GSK 126902 STANDARD | 4 | |
| KD081 | BMC | Carb gsk | CARB.GSK.12B814 NZMC | 16 | |
| KD082 | Vaux Viva, Standard | Carb gsk | MISC GSK. G 6366862 | 10 | \$ 5.00 |
| KD097 | Standard | Carb gsk | MISC GSK 147659 STANDARD | 40 | |
| KD098 | Ford | Carb gsk | FORD FACINGS ONLY 2724E-9447B | 13 | |
| KD104 | BMC/GM | Carb gsk | NZMC GTG109/527235 Z-225 | lots | |
| KD111 | GM | Carb gsk | GM 1017700 | 18 | |
| KD120 | Bedford 214 | Carb gsk | G.M. 1047192 | 2 | |
| KD124 | Mits | Carb gsk | CARB.GSK 110417 MISUBISHI | 36 | |
| KD136 | Jag, Rover, Kimberley | Carb gsk | CARB.GSK.JAG.C2368.STD.112867 | 34 | \$ 3.00 |
| KD147 | BMC | Carb gsk | | | |
| KD153 | BMC | | | 2 | |
| KD157 | BMC | | | 4 | |
| KD163 | Ford | Carb gsk | FORD 204E-9447B | 27- | |
| KD170 | Rover | Carb gsk | CARBURETTOR GSK 278163 ROVER | 4 | |
| KD171 | BMC | Carb gsk | CARB.GSK.NZMC SCM5075 | 18 | |
| KD172 | Bed | Carb gsk | CARB GSK. G.M.7144235 | 23 | |
| KD177 | Austin A50 | Carb gsk | | 0 | |
| KD185 | Ford Falcon | Carb gsk | MISC GSK.CODE-9455-A FORD | 4 | \$ 4.00 |
| KD197 | | Alu washer | | | |
| KD205 | BMC Healey 3000 | Carb gsk | N AEC2083 | 34 | \$ 4.00 |
| KD215 | Standard, Mits | Carb gsk | STANDARD 137881 | 60 | |
| KD225 | Fiat | Carb gsk | MISC GSK 4121933 FIAT | 6 | |
| KD226 | Fiat | Carb gsk | CARB. ADAPTOR GSK 4100576 FIAT | 3 | |
| KD227 | Humber Super Snipe | Carb gsk | CARB.GASKET 1228132 MITS. | 0 | |
| KD237 | Ford | Carb gsk | CARB.GSK 2725E-9L553-A FORD | 2 | |
| KD240 | Hillman Hunter A/H | Carb gsk | TODD 1238506 GSK | 84 | |
| KD241 | Hillman Hunter A/H | Carb gsk | | 4 | |
| KD242 | Vaux Viva | Carb gsk | G M 7130614 | 21 | |
| KD243 | Vaux Viva | Carb gsk | On Deletion 2405 (8) | lots | |
| KD254 | Bedford CF | Carb gsk | CARB.GSK 6360874 GENERAL MOTOR | 7 | |
| KD256 | Fiat | Carb gsk | MISC GSK 4123923 FIAT | 14 | |
| KD258 | Hillman Hunter A/H | | TODD R01240873 GSK | 6 | |
| KD260 | Vaux Viva | Carb gsk | On Deletion 2405 | lots | |
| KD274 | Standard | Carb gsk | CARB.GSK | 39 | |
| KD275 | Rover | Carb block -4 bolt | ROVER 610849 | 21 | \$ 10.00 |
| KD293 | Rover | Carb gsk | ROVER 568365 | 33 | \$ 3.00 |
| KD294 | Triumph | Carb gsk | | 2 | |
| KD296 | Ford | Carb gsk | FORD 213E-9447 | 10- | |
| KD313 | Standard | Carb gsk | CARB. GSK.157068 STANDARD | 2 | |
| KD329 | Ford | Carb gsk | CARB. GSK.109E-9447 FORD | 8 | |
| KD497 | Chrysler Hemi 6 | Misc. gsk | MISC GSK C 2468818 MITSUBISHI | 4 | |
| KD641 | Ford Cortina OHC 1600 | Carb gsk | | 1 | |
| KD668F | Hillman Avenger | Carb gsk | CARB FACINGS 71272810 MITS. | 12 | |
| KD674 | Ford | Misc. gsk | MISC GSK 957E-9448 FORD | 11 | |
| KD680 | Mits | Carb gsk | MITSUBISHI JCMD021255 | 0 | |
| KD681 | Mits | Carb gsk | | 2 | |
| KD701 | Triumph | Carb block -2 bolt | CARB. INSULATOR | 124 | |
| KD903 | Honda | Rubber seal | HONDA | 33 | |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|--------------|--------------------------------------|-----------------------------|--------------------------------------------|-------|----------|
| KD905 | Honda | O ring | HONDA | 45 | |
| KE009/L | Nissan J | Carb gsk | NISSAN BLOCK FACING | 14 | |
| KE009/R | Nissan J | Carb gsk | NISSAN FACING | 13 | |
| KG000 | Rover | O ring | 1 1/8"x.140" from CC941 number unknown | yes | |
| KG006 | BMC | Fibre washer 13 x 20 x 2 | B.L.M.C.FIBRE WASHER 13.7X20mm | 110 | |
| KG030 | GM | O ring | GM 838210/3835246 | 18 | |
| KG033 | Bedford early | Valve seal -felt | G.M. 1044226 | 35 | \$ 4.00 |
| KG041 | Rover | Fibre washer 6 x 11 x 1 | Rover 531742/016828 Zenith | 528 | |
| KG061 | BMC "B & C" | Valve seal | | 50 | \$ 2.00 |
| KG065 | BMC "A", "B" | Seal front felt | 1.1/2" x 2.1/16" x 7/32" (neoprene = NA473 | 5 | \$ 12.00 |
| KG067 | Hillman Hunter | O ring distributor | TODD 212173 2-215 | 39 | |
| KG069 | Rover | O ring | | yes | \$ 3.00 |
| KG073 | BMC A70-A90, early 4 Litre | Valve seal -flat | B L M C 1B1479 | 111 | \$ 2.00 |
| KG088 | BMC "C", A70 | Seal front felt | TIMING COVER SEAL 2K7139 NZMC | 25 | \$ 11.00 |
| KG092 | Ford V6 | Fuel pump seal | AC FUEL PUMP SEAL | 14 | |
| KG112 | Rover | O ring | ROVER 233419 | 4 | \$ 4.00 |
| KG114 | Fergusson | Fibre washer 7.5 x 16 x 1.5 | Mass/Ferg 825296M1 | 44 | |
| KG115 | | Fibre washer 12.5 x 22 x 1 | B L M C ZZA1566 (26) | 6 | |
| KG117orKG118 | Rover | Dist cork ring | DISTRIBUTOR GSK 52278 ROVER | 8 | |
| KG121 | Chrysler Valiant | Fibre washer 18.5 x 27 x 1 | G.M. 6348488 | 139 | |
| KG125 | Ford Trader/GM | Block to head oil passage | GM 8839241 | 100 | |
| KG126 | | | Niven C3505/44 | 107 | |
| KG128 | Nissan J15, J16, Vaux Victor, Holden | Valve seal | Round | 16 | \$ 2.00 |
| KG134 | Austin A40 - A110 | Therm gsk | B.L.M.C. 1G1365 | 44 | \$ 3.00 |
| KG140 | Fiat, Bedford | Fibre washer 14 x 21 x 1.5 | FIAT 10279985 | 20 | |
| KG148 | Bedford 466, 214 | Cork ring | G.M. 7075286 | 171 | |
| KG174 | Bedford & Vauxhall | Oil seal front felt | 1.3/4" ID | 1 | |
| KG179 | Ford | Fibre washer | FORD 118324ES | 0 | |
| KG186 | BMC 3.4 3.8 diesel | Valve seal -flat | | 395 | \$ 2.00 |
| KG205 | Bedford 330 sump plug | Fibre washer 25 x 33.5 x 2 | WASHER DRAIN PLUG GSK.G7138296 | 16 | |
| KG209 | Rover/Todd | O ring -distributor | TODD 2095740/532322 ROV. 2-216 | 21 | |
| KG215 | Ford Zephyr mk1,2,3 | O ring, by-pass | | 0 | |
| KG218 | Ford Zephyr mk1,2,3 | Valve seal -umbrella | Also use NZ359 | 12 | \$ 3.00 |
| KG239 | Rover | O ring | ROVER 246169 | 5 | |
| KG240 | Rover | O ring | ROVER 268887 2-129 | 7 | |
| KG249 | Bedford CF, Rover | O ring | ROVER 247186 2-011 | 81 | |
| KG255 | Jag | O ring | JAGUAR C2312 2-320 | 9 | |
| KG256 | Ford V4, V6 | Rubber seal | EIADKN-6761 | 17 | |
| KG274 | BMC A | Valve seal O | | 8 | |
| KG275 | BMC 3.4 3.8/Ford | Valve seal -square section | B L M C AMK125 | 100 | \$ 3.00 |
| KG275? | | | R/C Gsk EIADKN-6521 Ford | 5 | |
| KG303 | Chrysler Valiant 6, 8cyl 1961-79 | Valve seal | | 4 | |
| KG316 | Umbrella 1 1/32", 3/4" OD | Valve seal -umbrella | | 140 | \$ 4.00 |
| KG316 | | Valve seal | On Deletion 1076 | 101 | \$ 4.00 |
| KG317 | Ford Falcon | Valve seal | | | |
| KG323 | Holden Red | Dist gsk ring | G 6256636 | 65 | |
| KG329 | BMC | O ring -crankcase | | 1 | |
| KG352 | Chrysler Valiant & Hemi 6 | Air filter cork ring | AIR CLEANER GSK C1947797 MITSU | 39 | |
| KG356 | Leyland 400 | O ring | T/G.M. 600174/6374857 2-218 | 98- | |
| KG357 | Leyland 400 | O ring | T/G.M. 600876/6374871 2-119 | 94- | |
| KG358 | Leyland 400 | Valve seal | O RING G.M 6374634 2-110 | 600+- | \$ 2.50 |
| KG359 | Leyland 400 | O ring -rocker bracket | G.M. 6382022 2-113 | 58 | \$ 2.50 |
| KG360 | Jag | O ring | JAGUAR C20249 2-330 | 5 | |
| KG364 | Ford/Toyo | O ring | TOYOTA 90301-06031 2-010 | 3 | |
| KG378 | Ford V6, Albion | O ring | ALBION 231K17 2-210 | 3 | |
| KG380 | Humber Super Snipe, Hillman | Valve seal O | | | |
| KG407 | Jag | O ring | JAGUAR C19044 2-213 | 66 | |
| KG409 | Leyland 400 | O ring | O ring about 12.5x17.5x2.5 | 1636- | \$ 1.50 |
| KG409 | | | Rocker cover gasket U300/JN534 | 5 | |
| KG423 | Rover | Rubber seal | ROVER 506069 | 15 | |
| KG430 | Rover | O ring | RUB. SEAL N267828,C14990 2-212 | 14 | |
| KG431 | Bedford 466, 381, 300 | Seal head to block 1 3/16" | RUBBER RING G.M. 6399008 2-31 | | \$ 6.00 |
| KG453 | Hillman Imp | Valve seal | TODD 7100318 | 2 | \$ 5.00 |
| KG466 | | Valve seal | | 19 | |
| KG467 | Ford V4, V6 | Valve seal -umbrella | | 265 | \$ 1.50 |
| KG469 | Leyland 400, 680 | O ring | LEYLAND 606597 2-204 | 111- | \$ 3.00 |
| KG477 | BMC "A" & "B" | Side plate bolt rubber | RUBBER RING GSK.N 12A1176 | 64 | |
| KG486 | Ford Trader | O ring -flat | FORD 116572ES | 4 | |
| KG495 | | Fibre washer 13 x 19 x 2 | | 8 | |
| KG511 | Rover | | ROVER 532387 | 19 | |
| KG526 | Jag | | JAGUAR 19869 | 13 | \$ 5.00 |
| KG535 | | O ring | Massey Ferg. 184182M (98) | 3 | |
| KG536 | | O ring | Misc. Gsk. CAM5114 NZMC (9) | 8 | |
| KG547 | BMC | O ring | 11K 7521 | 9 | |
| KG549 | BMC | O ring | NZMC 602634 2-230 | 202 | |
| KG564 | BMC | O ring | B.L.M.C. 22A1563 2-012 | 40 | |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|--------|------------------------------|------------------------------|--------------------------------|--------|----------|
| KG569 | BMC "O", Ford | O ring | FORD 204E-12143 2-021 | 36 | |
| KG574 | Rover 2 1/4 litre | Valve seal | | 2 | |
| KG577 | | Valve seal | | 5 | |
| KG583 | Bedford CF, Vaux Victor FD | Valve seal -inl | | 52 | \$ 5.00 |
| KG593 | BMC | Copper washer | N Z M C 232037/MYH204 | 11 | |
| KG594 | BMC/Rover | Washer | ROVER/BLMC 272474/12H220 | 17 | |
| KG595 | Ford | Copper washer | FORD E3CH9/T.156768 NZMC232038 | 37 | |
| KG601 | Rover | Washer | ROVER 273069 | 71 | |
| KG611 | Leyland 400 to 680 | Injector washer | COPPER WASHER G 7146267 | 600- | \$ 4.00 |
| KG619 | Ford Trader 330-380 | Copper washer | OIL PRIME PLUG WASH F118194ES | 18 | |
| KG621 | Ford Trader 330-380, Bedford | Inj atomiser | MISC.GSK FORD E16CL9,N AJR2148 | 4 | |
| KG623 | IHC | Copper washer | I H C 62866D 231575 | 9 | |
| KG631 | Ford | Washer injector | FORD 681F-6L076-AA,116087ES | 43 | |
| KG632 | | Alloy washer | | 67 | |
| KG640 | Rover | Copper washer | ROVER 243967 | 25 | |
| KG650 | Ford | Copper washer | FORD 112304ES | 103 | |
| KG651 | Lister | Copper washer | LISTER 013-22-350 | 16 | |
| KG652 | BMC | Copper washer | COPPER WASHER N 243958/6K638 | 56 | |
| KG664 | Austin/Rover | Copper washer | ROVER 247179.247479.11B276 | 47+600 | \$ 3.00 |
| KG669 | | Copper washer | | 30 | |
| KG671 | BMC | Copper washer | | 243959 | 11 |
| KG673 | Rover | Copper washer | ROVER 243968/230507 | 5 | \$ 4.00 |
| KG677 | Bedford 330 | Steel shim | CYL.HEAD STUD. 6377073 | 17 | |
| KG682 | Ford Trader 330-380 | Sump plug washer | FORD 105E-6734,NZMC 232044 | 200+ | \$ 4.00 |
| KG683 | BMC | Copper washer | B L M C AEC699 | 9+150 | |
| KG685 | Rover | Copper washer | ROVER 213961 NZMC 6K431 | 3 | |
| KG686 | Bedford 466, 500 | Sump plug washer | SUMP DRAIN PLUG GSK.GM 7144743 | 29 | |
| KG690 | | Copper ring | | 100 | |
| KG697 | | Copper ring | On Deletion 2237 (4) | 9 | |
| KG706 | IHC? | Copper ring | Misc gsk I 710382R1 | 23 | |
| KG724 | IHC BD264 -8 reqd | Washer 48.3x43.3x1.2 | IHC 43002DA | 100+ | \$ 8.00 |
| KG742 | Holden | Nylon washer | NYLON WASHER G 7417490 | 725 | |
| KG757 | Bedford 330 | Fibre washer 14 x 22.5 x 1.5 | G M 1028313 | 54 | |
| KG758 | GM | O ring | GM 6358834 | 73 | |
| KG760 | Bedford 330 | Foam washer | G M 7187745 | 11 | |
| KG765 | Vaux Viva | Valve seal | VALVE STEM SEAL G 8835236 | 349 | \$ 3.00 |
| KG767 | Jag | Cork ring | JAGUAR C2430 | 8 | \$ 4.00 |
| KG768 | BMC | O ring | B.L.M.C. 13H6766 2-017 | 11 | |
| KG770 | Ford Cortina OHC | Rubber seal | FORD E832109582 | 300 | |
| KG775 | | O ring | O ring about 10x15x2.5 | 14 | |
| KG780 | Bedford CF | Copper Washer | G M 115308 | 112 | |
| KG788 | Rover | Copper Washer | COP.WASH 19.5X27.5 ROV.603521 | 6 | |
| KG794 | IHC | Copper Washer | Copper washer I 710383R1 | 13 | |
| KG819 | Vaux 3.3, 2.6, Holden | Valve seal | Square (round is KG128) | 40 | \$ 1.00 |
| KG824 | Leyland 400 | Nylon washer | G M 6374976 | 45 | |
| KG831 | Ford Trader 330-380 | O ring | FORD 116567ES 2-168 | 4? | \$ 12.00 |
| KG835 | Vaux Viva | Felt pad | G 7154179 | 35 | |
| KG848? | | valve seal | | some | |
| KG850 | | valve seal | | some | |
| KG863 | Ford V4, V6 | Rubber ring -flat | FORD 692F9364AA | 5 | |
| KG864 | Ford V4, V6 | Rubber ring -flat | FORD 692F9K354AA | 8 | |
| KG881 | Ford Trader 330-380 | Rubber ring -flat | FORD 116670ES | 50 | |
| KG883 | Ford | Nylon washer | FORD 70TM6734AA | 26 | |
| KG895 | Isuzu 4BA1 to 4BD1 | Rocker bolt seal | | 2 | |
| KG897 | Isuzu C223, G150 | Valve seal O | | 16 | \$ 4.00 |
| KG964 | Nissan A12 etc | Therm hsg gsk | WATER OUTLET GSK D 11062-18000 | 175 | |
| KH060 | | Valve stem seal (O ring) | | 21 | |
| KH061 | Toyo | O ring | TOYOTA 90301-44049 | 19 | |
| KH062 | Nissan H20 | O ring | NISSAN 22180-71200 | 58 | \$ 4.00 |
| KH066 | Toyota 5R, 12R, K | Valve seal O | | 16 | |
| KH071 | Nissan | Valve seal | | yes | \$ 2.00 |
| KH086 | Mazda | O ring | MAZDA 0107-18-201 | 46 | |
| KH199 | Toyota 3K etc | Rocker bolt seal | MISC GSK O 90210-08017 | 577 | |
| KH252 | Ford Cortina | Valve seal -umbrella | VALVE STEM SEALS F 731M6571A1A | 1362 | \$ 2.00 |
| KH267 | BMC | O ring | B M C 318B447 | 7 | |
| KH465 | | Copper washer | | 60 | |
| KH755 | Jag | Copper washer | JAGUAR C21171 | 6 | |
| KH889 | Broomwade | Copper washer | BROOMWADE C3615/10 | 47 | |
| KJ024 | Suzuki | Rubber seal | Suzuki (35) | 20 | |
| KJ105 | Nissan | Seal head to block -oil feed | NISSAN 11045-H1000 | 196 | |
| KJ127 | Toyota 6R-12R | Valve seal | | yes | |
| KJ191 | Bedford 500 | Seal head to block 1 5/16"OD | Camira | 37 | \$ 6.00 |
| KJ192 | Bedford 466, 500 | Oil seal head to block | | 2 | \$ 7.00 |
| KJ196 | GM | Copper washer | G.M. | 54 | |
| KJ197 | | | Campair NZ C3615/9 | 82 | |
| KJ206 | Nissan | Rubber washer | NISSAN 15270-78500 | 34 | |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|--------|--------------------------------------|--------------------------------|------------------------------------|-------|----------|
| KJ211 | Mitsubishi 4G32 etc | Valve seal | | 8 | |
| KJ212 | Mitsubishi 4G32 etc | Rocker bolt seal | | 1 | \$ 2.00 |
| KJ339 | GM | Rubber ring (rect) | GM 638182 | 34 | |
| KJ434 | Mitsubishi | Bal thrust pl O ring gsk | Mits JCMD021045 | 18 | \$ 4.00 |
| KJ451 | Nissan H20 | V/seal special | NISSAN 13207-66711 | 329 | |
| KJ452 | Nissan SD33, SD22 early | Valve seal (which is wrong?) | 8mm x 15mm(guide) (Late see PA378) | 12 | |
| KJ452 | Nissan SD33, SD22 early | Valve seal (which is wrong?) | 8mm x 14mm(guide) (Late see PA378) | 50 | \$ 4.00 |
| KJ453 | Nissan | Valve seal | | 8 | \$ 6.00 |
| KJ454 | Nissan A14, A15 | Valve seal | | 1 | |
| KJ456 | Honda EB1, EB3 | Valve seal | | 20 | \$ 4.00 |
| KJ458 | Mazda | Valve seal | MAZDA 0221-12-190A | 255 | |
| KJ460 | Mazda | Valve seal 8? X 12.5 | MAZDA | 347 | |
| KJ461 | Mazda | O ring | MAZDA 0324-10-155NZ | 1415 | |
| KJ462 | Subaru | Valve seal | | yes | \$ 3.00 |
| KJ465 | Honda Civic 1973-80 | Valve seal | | yes | |
| KJ466 | Toyota 20R, 21R, 22R | Valve seal | Also use ZD139 | yes | |
| KJ468 | Mazda TC | Valve seal | | yes | \$ 2.00 |
| KJ481 | Bedford CF | O ring | G M 7217033 | 1 | \$ 5.00 |
| KJ495 | BMC | Fibre washer | BLMC 2K4954 | 8 | |
| KJ499 | Hillman Avenger | Valve seal | | 8 | \$ 2.00 |
| KJ570 | Mitsubishi 79- | Valve seal | 4G15, | 19 | \$ 3.00 |
| KJ574 | Toyo | Rocker bolt seal | TOYOTA 90210-13028 | 27 | |
| KJ577 | Mitsubishi 4G15 | Valve seal | small umbrella | yes | \$ 3.00 |
| KJ578 | Mits | O ring | | 8 | |
| KJ579 | | Valve seal | | 5+35 | |
| KJ580 | Honda | Valve seal | HONDA 12211-657-003 | 27+3 | |
| KJ581 | Honda EB etc | Rocker bolt seal | | 3 | |
| KJ582 | Subaru | Rocker bolt seal | | 5 | |
| KJ641 | Chrysler Valiant 225 | Valve seal | USE KG303 WSN 2736 | 20 | |
| KJ683 | BMC "O" | O ring | NZMC AAU1108 | 4 | |
| KJ722 | Toyota 1G etc | Valve seal | | 7 | |
| KJ804 | GM/Isuzu | Copper Washer | G M ISUZU 90957-14140 | 23 | |
| KJ848 | BMC 1300 | Valve seals | | 32 | \$ 4.00 |
| KJ874 | Toyo | Rubber strip | TOYOTA 11367-31020 | 15 | |
| KJ887 | Mazda | O ring | MAZDA 0118-10-432NZ | 3 | |
| KJ950 | Mazda | O ring | MAZDA 9954-20-3001-NZ | 18 | |
| KJ951 | Mazda | O ring | MAZDA 9954-10-1801NZ | 15 | |
| KJ952 | Mazda | O ring | MAZDA 9954-10-0901NZ | 205 | |
| KJ962 | Mits | Copper Washer | MITSUBISHI JCMF660061 | 12 | |
| KJ990 | Mitsubishi 4G15 | O ring | MITSUBISHI MD030763 | 229 | |
| KK006 | Perkins (Honda?) | Ex fla gsk | Honda | 7 | |
| KK009 | Holden V8, Falcon C/F, Isuzu G161 | Exh fla ring | Exh fla ring (steel = KK243) | 1 | \$ 10.00 |
| KK022 | Austin A40 Devon, Somerset 1948-54 | Hot box gsk | HOT SPOT GSK 1A2099 NZMC | 5 | \$ 4.00 |
| KK037 | BMC | Hot box gsk | B L M C 2A106 | 15 | |
| KK059 | Daimler | Mani gsk | | 1 | |
| KK070 | Ford Trader 330-380 | Steel shim gsk | FORD 2700E-2946-B | 17 | |
| KK072 | Bedford 214 (early?) | Hot box gsk 84mm x 90mm OD | | yes | \$ 10.00 |
| KK073 | Bedford 214 | Hot box gsk 90mm x 116mm OD | G M 7075246 | 19 | \$ 10.00 |
| KK077 | Bedford 300 | Hot box gsk | | | \$ 15.00 |
| KK078 | Bedford CF | MGE/spark plug shroud | | 20 | \$ 35.00 |
| KK090 | Leyland 400 | Oil feed to rocker tube sleeve | LEYLAND 606598 | 299- | \$ 6.00 |
| KK091 | Ford V4 | Cam end seal | | 2 | |
| KK095 | Leyland 680 | Ferrule brass | For head of modified engines | 2 | \$ 12.00 |
| KK111 | Rover | Alloy gsk | ROVER 541817 | | |
| KK113 | Universal | Exh fla 23mm CA | | 3 | \$ 5.00 |
| KK114 | Universal | Exh fla 27mm CA | | 4 | \$ 5.00 |
| KK115 | Universal | Exh fla 31mm CA | | 3 | \$ 5.00 |
| KK116 | Universal | Exh fla 32.5mm CA | | 3 | \$ 5.00 |
| KK117 | Universal | Exh fla 35mm CA | | 1 | \$ 5.00 |
| KK120 | Universal | Exh fla 45mm CA | | 11 | \$ 5.00 |
| KK121 | Universal | Exh fla 48mm DSF | | 17 | \$ 5.00 |
| KK122 | Universal | Exh fla 51mm DSF | | 1 | \$ 5.00 |
| KK123 | Universal | Exh fla 54mm CA | | 1 | \$ 5.00 |
| KK243 | Ford Falcon C/F | Exh fla | (composite = KK009) | | \$ 15.00 |
| KK276 | | Carb gsk | CARB GSK 0268-13-317NZ MAZDA | 4 | |
| KK5019 | Mitsubishi 6G72/74, 4/6A11/12 | Spark plug seal | | 3 | \$ 6.00 |
| KK5061 | Subaru EJ20G -shim tappets, EJ25 98o | Spark plug seal | | 4 | |
| KK5062 | Subaru EJ20G -hydr tappets 1989-95 | Spark plug seal | 1 in each JM5021 and JM5020 | | |
| KK5083 | Subaru EJ20G -shim tappets 1993-96 | Spark plug seal | | 1 | |
| KK956 | Bedford 300, 500 | Dowel | G M 453675 | 62 | |
| KL196 | | Mani gsk (Inlet?) | PERKINS 36241505 | 25 | |
| KL342 | Mitsubishi 4G32 etc | Water pump gsk | T JCMD001309 | 4 | |
| Koma95 | Komatsu 95 series | Oil seal | 95x120x13 | 1 | |
| KR006 | Ford Cortina | Fuel pump block | Use B546 | | |
| KR047 | Bedford & Vauxhall | Oil seal front felt | 1.1/2" ID | 1 | \$ 20.00 |
| KR094 | Hillman | Therm gsk? | Todd RP116888 B/S | 9 | |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|----------|--------------------------------|-------------------------|---------------------------------|-------|----------|
| KR116 | | Rocker cover gsk | TAPPET COVER GSK C55 NZMC | 11 | |
| KR121 | | Sump end cork | 152 x 6 x 11 gsk 19-6701 Ford | 13 | |
| KR151 | Bedford 214 | Water gsk front | GM 1033350 | 24 | |
| KR161 | Morris 8, ser E | Rear seal - rope | | 0 | |
| KR223 | Bedford 300, 330 diesel | Mani gsk -Inlet | MANIFOLD GSK 7135808 G.M. | 5 | |
| KR224 | Bedford 300, 330 diesel | Side plate gasket | 11 holes along top | 4 | \$ 25.00 |
| KR225 | Bedford 300 petrol | Push rod cover gsk | 10 holes along top | 10 | \$ 15.00 |
| KR287 | Austin A70, 4 litre truck | Water outlet gsk | | 6 | |
| KR291 | IHC BD264 | Water outlet gsk | Water outlet gsk 65986D IHC | 5 | \$ 6.00 |
| KR291 | IHC BD264 -1 reqd | Water outlet gsk | | 0 | \$ 5.00 |
| KR309 | Std/Ferg | Liner gsk | MISC GSK 56286 STD/NORWOOD | 5 | |
| KR328 | | Distributor gsk | Distrib gsk 825662M1 | 6 | |
| KR335 | Standard? | Oil pump gsk? | Oil pump gsk 825652M1 N56282 | 7 | |
| KR351 | BMC "C", Vanguard | Therm hsg gsk | B L M C GTG103 | 23 | \$ 4.00 |
| KR352 | Standard | Main bg cap cork | Bearing seal gsk 59381 Std NZMC | 40 | |
| KR392 | IHC BD264 (conv. Set item) | Therm gsk | Thermostat gsk 45984D IHC | 6 | \$ 6.00 |
| KR395 | IHC BD264 -1 reqd | Injection gsk | | 0 | \$ 8.00 |
| KR418 | Rover | Insp cover gsk | INSPECTION COVER GSK 50216 ROV | 6 | |
| KR470 | Leyland 400 | | C/case gsk 7146172 GM 234378 | 3 | |
| KR499 | Jaguar | Water outlet gsk | WATER OUTLET GSK.C2380 JAG. | 2 | |
| KR501 | Jaguar | Oil pipe gsk | OIL DELIVERY PIPE GASKET | 6 | |
| KR502 | Jaguar | | Rev counter adaptor gsk C2289 | 16 | |
| KR505 | Jaguar | Front cover gsk | FRONT COVER GSK C2227 JAGUAR | 3 | |
| KR521 | Leyland 400 | Oilpump end plate gsk | | 11 | |
| KR521 | | Suction branch gsk | Suction branch gsk 232336 Leyl | 5 | |
| KR524 | Leyland 400 | C/case gsk | CRANKCASE GSK 7148285 GM 237960 | 8 | |
| KR554 | Ford Trader | Water pump gsk | FORD EIADKN8507A | | \$ 5.00 |
| KR555 | Ford | Fuel pump gsk | Ford EOTA9417A | 12 | |
| KR556 | Ford Consul, Zephyr 4 | Side plate gsk | MISC GSK EOTA-6521 FORD | 1 | \$ 15.00 |
| KR559 | Jaguar | Therm gsk | Thermostat gsk C2475 Jaguar | 5 | |
| KR571 | Ford Zephyr 6 | Side plate gsk | | 0 | |
| KR595 | Leyland 400 | | Starter motor gsk 273006 Leyla | 3 | |
| KR605 | BMC | Sump end cork | BLMC 2A280 | 9 | |
| KR611 | BMC | Water pipe gsk | BLMC 88G221 | 111 | |
| KR613 | Bedford 214, Vaux EIP | Sump end cork | G M 364396/7080530 | 5 | |
| KR615 | Bedford 466, 500, 300 | Water outlet gsk | MISC GSK. GM 7075138 | 1 | |
| KR616 | | Felt packing -cap sides | | 1 | |
| KR616-24 | Vaux 3.3, Bedford | Felt packing -cap sides | | 4 | \$ 11.00 |
| KR619 | Bedford 330 | Bell hsg gsk | CLUTCH/TRANS.GSK 7083018 GM | 5 | |
| KR654 | Ford Trader | Push rod cover gsk | Peugeot | 5 | \$ 8.00 |
| KR665 | Perkins | Therm hsg gsk | WATER OUTLET GSK 0490184 PERKI | 10 | |
| KR667 | Ford Trader 380 Dover etc | Therm hsg gsk -use WG1 | FORD EIADKN8587 | 0 | \$ 5.00 |
| KR717 | Triumph 4, Std 8 & 10 | Rear seal hsg gsk | | 1 | |
| KR724 | Standard 8 | Front backing plate | | 1 | |
| KR725 | Standard | Therm hsg gsk? | STANDARD 104939 | 24 | |
| KR732 | Ford 100E | Front cover gsk | Ford 100E6020 | 10 | |
| KR753 | BMC 3.4, 3.8, 5.1, 5.7 diesels | Mani gsk inl -single | 2 for 4 cyl, 3 for 6 cyl | 20 | |
| KR763 | Leyland 400 | | MISC GSK 7146164 GM 289021 LEY | 8 | |
| KR770 | BMC A,C | Oil filter hsg gsk | Oil pump gsk 62B5 NZMC | 20 | |
| KR815 | BMC B | Oilpump gsk | BLMC 88G420 | 14 | |
| KR816 | BMC | Oil pickup gsk? | BLMC 88G423 | 18 | |
| KR831 | Hillman? | | see GT186 | | |
| KR848 | Hillman OHV | Side cover gsk | | 2 | |
| KR850 | BMC | Side cover gsk | Side cover gsk AEC310 NZMC | 8 | |
| KR856 | BMC | T/C tens gsk | BLMC AEC339 | 4 | |
| KR859 | Hillman? | | see GT186 | | |
| KR910 | BMC | Fuel pump gsk | BLMC 1G2615 | 7 | |
| KR914 | Austin A110 | Front cover gsk | TIMING COVER GSK AEC202 NZMC | 6 | |
| KR951 | IHC BD264 -1 reqd | Pump gear gsk | | 0 | \$ 8.00 |
| KR954 | IHC BD264 -1 reqd | Push rod cover gsk | | 2 | \$ 16.00 |
| KR992 | Humber Super Snipe | Fuel pump gsk | FUEL PUMP GSK TP44994/N BMK652 | 6 | |
| KR993 | GM | Distributor gsk | Distributor gsk 3836247 GM | 6 | |
| KS021 | Jaguar | Water pipe gsk | Waterpipe gsk C11577 Jaguar | 0 | |
| KS024 | Jaguar | Sump end cork | Sump seal rear C2302/S Jag | 20 | |
| KS109 | | Cyl head cover gsk | | 15 | |
| KS127 | Rover | Oil filter hsg gsk | Oil filter Rover 298354/598354 | 5 | |
| KS129 | Jaguar | Water pipe gsk | Water pipe gsk C12309 Jaguar | 11 | |
| KS148 | Perkins | Cyl head front gsk | CYL.HEAD FRNT.GSK 0490482 NORW | 8 | |
| KS154 | Rover | Misc gsk | ROVER 247555 | 6 | |
| KS156 | Rover | Distr pump gsk | Distr pump gsk 247212 Rover | 12 | |
| KS157 | Rover | Misc gsk | ROVER 247554 | 32 | |
| KS159 | Ford Trader 6 | Pushrod cover gsk | ROCKER COVER GSK 508E-6521-1/2 | 2 | \$ 12.00 |
| KS160 | | Therm gsk thin | | 1 | |
| KS161 | Rover | Air filter gsk | | yes | |
| KS170 | Vaux 2.6, 3.3 | Water pump gsk | | 1? | |
| KS195 | Vaux 2.6, 3.3 | G/box gsk | G/BOX/CLUTCH HOUSING 7140240 | 0 | |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|--------|--------------------------------|-----------------------------------|-----------------------------------------|-------|----------|
| KS227 | Humber Super Snipe | Therm gsk | Therm housing gsk P111446 Mits | 11 | |
| KS235 | BMC "B" -late | Oil pickup gsk | | 1 | |
| KS266 | Standard | Front plate gsk (1 of 3 possible) | FRONT ENGINE PLATE 205457 STD | 1 | |
| KS274 | BMC 1100, 1300 transverse | Rear of eng. -g/box housing | | 5 | |
| KS290 | Toyota 3K, 4K etc (also LT220) | Therm hsg gsk | | 1 | |
| KS307 | Ford Cortina | Oilpump gsk | | lots | \$ 5.00 |
| KS308 | Ford | Sump end cork | Ford E21-CE-1 | 12 | |
| KS367 | Perkins 6.354 | | CYL.REAR CVR.PLATE GSK 0490485 | 4 | |
| KS374 | Ford | Therm hsg gsk | Ford CODE8255A | 25 | \$ 5.00 |
| KS376 | Ford Falcon | Oilpump gsk | OIL PUMP GSK CODE-6626-A FORD | 2 | |
| KS376 | | | Oil pump gsk CODE-6626-A Ford | 13? | |
| KS410 | Vaux 3.3 | Push rod cover gsk | | 1 | \$ 25.00 |
| KS422 | Jaguar | Sump end cork | Sump rear oil seal C16315 | 23 | |
| KS489 | IHC | Oil pipe gsk | Oil pipe gsk 840674R2 IHC | 9 | \$ 2.00 |
| KS499 | Chrysler Valiant slant 6 | Oil pump gsk | | 10 | |
| KS500 | Chrysler Valiant slant 6 | Front cover gsk | MISC GASKET C1947554 MITSUBISHI | 4 | \$ 9.00 |
| KS519 | Jaguar | Rubber semi circle | JAGUAR C14991 | 10 | |
| KS519B | Jaguar | Rubber semi circle | JAGUAR C14991 | 10 | |
| KS520 | Leyland 400 | Water pipe gsk? | Misc gsk 602024 Leyland | 4 | \$ 1.00 |
| KS521 | Leyland 400 | Rear cover gsk | Rear cover gsk 6374922 GM | 17 | \$ 2.00 |
| KS522 | Leyland 400 | Water outlet gsk | WATER O/LET GSK 600968 LEYLAND | 9 | \$ 4.00 |
| KS523 | Leyland 400 | Water pump gsk | WATER PUMP 6374905 GM.601218 | 5 | |
| KS535 | Rover | Water pipe gsk | WATER PIPE GSK 90511958 ROVER | 9 | |
| KS536 | Rover | Therm hsg gsk | Rover 511957/GTG117 | 5 | |
| KS546 | Vaux Victor FB, FC | Side cover gsk | PUSH ROD COVER GSK | 6 | \$ 18.00 |
| KS566 | Leyland 400 | Rear cover gsk | REAR COVER GSK 6374988 G.M. | 12 | |
| KS592 | Standard | Air body gsk | Air body gsk 130415 Standard | 7 | |
| KS596 | Ford | Misc gsk | MISC GSK. C20Z-6870-A FORD | 4 | |
| KS617 | Fiat | W/outlet elbow | WATER O/LET ELBOW 4065247 FIAT | 9 | |
| KS633 | Chrysler Valiant slant 6 | Rear cap seal | Included in HN016 | | 2 x |
| KS634 | Chrysler Valiant slant 6 | Rear seal | Use HN065 or HN016 | | 2 x |
| KS683 | Hillman | Therm hsg? | TODD 1214649 | 7 | |
| KS684 | Hillman? | | see GT186 | | |
| KS687 | Jaguar | Air pipe gsk | AIR PIPE GSK. C15553 JAGUAR | 3 | |
| KS690L | Holden 149-186 | rear seal lower | | 10 | \$ 10.00 |
| KS690U | Holden 149-186 | rear seal upper | | 100 | \$ 10.00 |
| KS705 | Ford Trader to 61 | Front plate gsk | | 0 | |
| KS706 | Ford Trader 61-65 | Front plate gsk | | 3 | \$ 5.00 |
| KS707 | BMC | Oil filter hsg gsk | FUEL PUMP GSK..NZMC 88G402 | 11 | |
| KS723 | Chev 216, 235 | Rear seal wick | Rope type. (2 piece neoprene is PR6288) | 1pr | |
| KS735 | Vaux Viva | Oil pump gsk | G 6366775 | 19 | \$ 5.00 |
| KS754 | Ford Trader 4 & 6 cyl 1961-65 | Sump front cork | SUMP SEAL FORD EIADDN6707 | 3 | \$ 20.00 |
| KS755 | Ford Trader | Fuel pump gsk | | 0 | \$ 5.00 |
| KS777 | BMC 1622, 1800 | Oilpump gsk | | 1 | |
| KS779 | | | MISC GSK. 22H694 NZMC | 8 | |
| KS795 | Humber Super Snipe | Misc gsk | MISC GASKET P111446 MITS. | 10 | |
| KS796 | Humber Super Snipe | Therm? | MISC GSK.P111447 MITS. | 2 | |
| KS799 | | Bell hsg gsk | | | |
| KS802 | BMC "B" | Bearing cap cork (pair) | Shorten KS308? | 4 | \$ 5.00 |
| KS803 | Hillman Hunter | Sump end cork | SUMP SEAL HILLMAN | 1 | |
| KS806 | BMC | C/case gsk | C/CASE - TRANS.R.H.22A883 NZMC | 27 | |
| KS808 | BMC "B" | Front plate gsk | ENG. FRONT PLATE 12H1576 NZMC | 14 | |
| KS808E | BMC "B" | Front plate gsk -early | | 1 | |
| KS809 | BMC "A", "B", "C" (cork, 3mm) | Side plate gsk 76mm wide (thi | B L M C 12A1139 | 11 | \$ 4.00 |
| KS813 | Ford Trader | Oil filter hsg gsk | FORD 2701E6838 | 0 | |
| KS816 | BMC "A" | Front plate gsk | | 19 | |
| KS879 | BMC "A", "B" | Therm gsk | BLMC GTG101 | 467 | \$ 3.00 |
| KS902 | | Misc gsk | PN 36862511 MISC GSK | 198 | |
| KS957 | Jaguar | Oil cleaner gsk | OIL CLEANER GSK C19659 JAGUAR | 97 | |
| KS958 | Jaguar | Oil pipe gsk | OIL DEL.PIPE GSK.C22598 JAGUAR | 54 | |
| KS969 | Ford V4, V6 | Fuel pump block | | 1 | \$ 8.00 |
| KS981 | Triumph 2000, 2500 | Main bg cap cork | TRIUMPH 3.6X14.7X25.4 36234 | 5 | \$ 4.00 |
| KS982 | Standard | Front plate gsk (1 of 3 possible) | FRONT ENG.PLATE GSK 215350 STD | 0 | \$ 25.00 |
| KS983 | Standard | Fuel pump gsk | FUEL PUMP GSK 138591 STANDARD | 5 | |
| KT005 | BMC "A", "B", "C" (cork, 5mm) | Side plate gsk pair -72mm wid | (76mm wide = KS809) | 8 | \$ 8.00 |
| KT015 | Leyland 400 | Misc gsk | MISC GSK. 602814 LEYLAND | 24 | \$ 3.00 |
| KT018 | BMC | Oil pump gsk | OIL PUMP GSK 12G730 NZMC | 5 | |
| KT034 | Bedford 330 | Front backing plate | C/CASE FRONT PLATE 7150666 GM | 4 | |
| KT035 | Bedford 330 | Front backing plate | TIMING COVER GSK 6397043 G.M. | 6 | |
| KT036 | Ford V8C | Therm gsk | F C30E-8255-A | 8 | |
| KT037 | Ford | Mani gsk Inlet | IN MAN GSK 692F-9K438 FORD | 3 | |
| KT048 | Ford Trader | Sump end rubber | FORD 693F-6723AAA | 20 | |
| KT049 | Ford Trader | Sump end rubber | FORD 2701E6722B | 0 | |
| KT051 | Ford Trader | P/steer pump gsk | P/STEER PUMP GSK.2700E-3A760A | 22 | \$ 5.00 |
| KT052 | Ford Trader | P/steer pump gsk | | 0 | |
| KT054 | Ford Trader | Fuel injector pump gsk | | 0 | |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|--------|------------------------------------|-----------------------------|--------------------------------|-------|----------|
| KT055 | Ford Trader | Front backing plate | See TC110 | | \$ 25.00 |
| KT066 | Ford Trader 380 Dover etc | | | | |
| KT092 | Vaux Viva | Carb/air filter gsk | ON DELETION 2058 | 258 | |
| KT093 | Bedford 330 | Exhauster gsk | EXHAUSTER GSK.7166079 G.M. | 8 | |
| KT123 | Leyland 400 | Misc gsk | MISC GSK. 604849 LEYLAND | 3 | |
| KT124 | Leyland 400 | Misc gsk | MISC GSK. 604850 LEYLAND | 3 | |
| KT125 | Leyland 400 | Misc gsk | MISC GSK. 321062 LEYLAND | 1 | |
| KT126 | Leyland 400 | Misc gsk | MISC GSK. 611000 LEYLAND | 1 | |
| KT127 | Leyland 400 | Misc gsk | MISC GSK. 612603 LEYLAND | 2 | |
| KT145 | Bedford 466, 500 | Front plate gsk | FRONT PLATE GSK. | 6 | |
| KT146 | Bedford 466, 500 | Pushrod cover gsk | | | \$ 20.00 |
| KT148 | Jaguar | Rear seal pr -rope type | | | |
| KT149 | Jaguar | Oil cleaner gsk | OIL CLEANER GSK.C20532 JAGUAR | 7 | |
| KT151 | | Misc gsk | ON DELETION 2237 | 83 | |
| KT166 | Rover | Main cap gsk | REAR MAIN BRG.CAP GSK.537279 | 8 | |
| KT169 | Rover | Therm switch gsk | T/STAT SWITCH GSK 535703 ROVER | 11 | |
| KT171 | Rover | W/inlet gsk | WATER INLET GSK.538038 ROVER | 11 | |
| KT190 | Bedford CF | Cam cover gsk | | 5 | \$ 15.00 |
| KT194 | | | CONVERT HOUSING 22A1689 NZMC | 10 | |
| KT220 | Bedford CF | Oil pump/Distr gsk -2 reqd. | OIL PUMP GSK. 7206309 G.M. | 6 | |
| KT221 | Bedford CF | Oil filter hsg gsk | OIL FILTER GSK.7213450 G.M. | 5 | \$ 4.00 |
| KT222 | Bedford CF | Thermostat gasket | Use WG3 | | |
| KT223 | Bed 214 | Side plate gsk | | 3 | \$ 30.00 |
| KT233 | Rover | Misc gsk | MISC GSK. 602633 ROVER | 11 | |
| KT235 | Rover V8 | Rear seal -rope | B L M C 602178 | 1 | |
| KT236 | Rover V8 | Main cap seal | B L M C 603726 | 21 | |
| KT237 | Rover | Fuel pump gsk | MISC GSK.602180 ROVER | 5 | |
| KT238 | Rover | Oil screen gsk | OIL SCREEN GSK 602068 ROVER | 5 | |
| KT245 | BMC | Fuel pump gsk | FUEL PUMP GSK. 37D2891 NZMC | 9 | |
| KT259 | | | see GT128 | | |
| KT260 | Bed 214 | Front plate gsk | MISC GSK. 7150668 G.M. | 4 | |
| KT261 | Bedford CF | Fuel pump gsk | FUEL PUMP GSK. 7950173 G.M. | 2 | |
| KT289 | Vaux 2.6, 3.3 | Front backing plate | | | |
| KT290 | Ford | Sump end seal -cork | FORD 2733E6722A | 40 | |
| KT293 | BMC 1800 | Air cleaner gsk | In GT192 | | |
| KT300 | Austin Kimberley | Therm gsk | THERM/HOUSING GSK. 32H85 NZMC | 34 | \$ 3.00 |
| KT301 | BMC Transv. | Sump side | TRANS/CRANKCASE GSK.42H147NZMC | 4 | |
| KT302 | BMC Transv. | Sump side | TRANS/CRANKCASE GSK.42H336NZMC | 6 | |
| KT304 | | Bell hsg gsk | FLYWHEEL HOUSING 42H246 NZMC | 3 | |
| KT312 | BMC 1800 | Air cleaner gsk | CARB/AIR CLEANER 12G2125 NZMC | 28 | |
| KT314 | | Misc gsk | ON DELETION 2237 | 87 | |
| KT325 | Triumph 2000, 2500 | Misc gsk | MISC GSK. 150022 STANDARD | 1 | |
| KT327 | Hillman Avenger | Water pipe gsk | WATER PIPE GSK. R71241082 MITS | 12 | |
| KT329 | BMC 1800 | | see GT191 | | |
| KT331 | BMC | Sump strip seal | SUMP STRIP SEAL GSK.N 12G3017 | 1 | |
| KT346 | | Sump filter gsk | SUMP FILTER GSK.C 1881933 | 4 | |
| KT370 | Bedford 300 | Misc gsk | G M 7075136 | 4 | |
| KT398 | | Misc gsk | ON DELETION 2232 | 6 | |
| KT436 | Ford | Fuel pump gsk | FUEL - BLOCK GSK.11405218 FORD | 295 | |
| KT449 | Ford | Fuel pump gsk | FUEL PUMP GSK F C5NE-9F585-A | 10 | |
| KT474 | Ford 240.300 petrol | Sump end | FORD C5AE-6722-A | 5 | |
| KT477 | Bedford 466, 500 | Fuel pump gsk | ON DELETION 2237 | 4 | |
| KT478 | Vaux 3.3, Holden | Therm gsk | MISC GSK. GM 7401111 | 7 | \$ 3.00 |
| KT491 | Bedford 466, 500 | Inj pump gsk? | | 5 | |
| KT492 | Bedford 466, 500 | Gsk | | 5 | |
| KT494 | Bedford 466, 500 | Gsk | | 5 | |
| KT495 | Bedford 330 | Fuel pump gsk | FUEL PUMP GSK.2681874 GM | 91 | |
| KT497 | Ford | Oil pump cover gsk | OIL PUMP GSK.682F-6626-AA FORD | 22 | |
| KT499 | | Valve seal | | some | |
| KT500 | | | see GT128 | | |
| KT501 | | | see GT128 | | |
| KT503 | Rover | Misc gsk | MISC GSK.610387 ROVER | 13 | |
| KT506 | | Oil filter hsg gsk | OIL FILTER GSK.C14817 | 4 | |
| KT507 | | Oil filter hsg gsk | OIL FILTER GSK.C15962 | 4 | |
| KT508 | BMC 1300 | Front plate gsk | MOUNTING PLATE 12G 2981 NZMC | 4 | |
| KT509 | Rover | A/filter gsk | CARB/ADAPTOR GSK 610327 ROVER | 33 | |
| KT511 | Rover V8 | Main cap seal -cork | B L M C 611089 | 6 | \$20/pr |
| KT515 | GM | Fibre washer | G M 7209225 | 7 | |
| KT519 | Bedford 214 | Oil filter hsg gsk | MISC GSK.6376139 G.M. | 20 | |
| KT529 | Ford | Oil pump cover gsk | OIL PUMP GSK.71HM-6659-AA FORD | 216 | |
| KT540 | Humber Super Snipe | Fuel pump gsk | FUEL PUMP GSK.R71244744 MITS. | 5 | |
| KT544F | Humber Super Snipe, Hillman Hunter | Fuel pump gsk | R25361300 | 22 | |
| KT545 | Bedford CF | Fuel pump gsk | also KT261 | | \$ 3.00 |
| KT562 | Jaguar | Therm gsk | T/STAT BY-PASS GSK.C2381 JAG | 2 | |
| KT569 | Leyland 400 | Sump side cover | MISC GSK.7148310 G.M. | 8 | \$ 10.00 |
| KT570 | BMC | Rear main oil plate gsk | MISC GSK. N 2A127 | 4 | |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|----------|-----------------------------------|------------------------------------|--------------------------------|-------|----------|
| KT585 | BMC | Rear plate gsk | REAR ENG.PLATE GSK.1G2425 NZMC | 2 | |
| KT591 | BMC MGA | Axle seal plate gsk | MISC GSK.GFG111 (ATB7355) NZMC | 7 | \$ 5.00 |
| KT614 | Ford Anglia | Rear oil hsg gsk | F 105E-6369 | 166 | |
| KT620 | Ford Falcon 200 | Sump end rubber | OIL PAN FRONT 14cm long | 82 | |
| KT621 | Ford Falcon 200 | Sump end rubber | FORD CODE6723A 18cm long | 71 | |
| KT622 | Ford | Rear seal - rope | | 1 | |
| KT624B | Ford Cortina NCF | Rear seal - rope 130 long black | | 3 | \$ 20.00 |
| KT624W | Ford Cortina NCF | Rear seal - rope 160 long white | | 15 | \$ 15.00 |
| KT630 | Vaux PA, FB etc | Rear seal - rope | USE KT631 | | |
| KT631 | Vaux 3.3, 2.6, Bed CF | Rear seal - rope | ROPE SEAL GSK 6390312 | | |
| KT632 | Holden 202, 253, 308, Bedford | Rear seal - rope | new # HN022 | | |
| KT633 | Perkins 3.152 | Rear seal - rope | | 1 | \$12/pr |
| KT638 | Ford Trader 380 Dover etc | Rear seal - rope | (Is neoprene 30136?) | | \$45/pr |
| KT647 | BMC | Rear main oil plate gsk | MISC GSK.AEG240 NZMC | 8 | |
| KT648 | BMC "A" | Rear plate gsk | G/BOX MOUNTING PLATE AEG554 | 0 | |
| KT649 | Bedford CF | Rear cam cvr gsk | REAR CAMSHAFT COVER G 7204357 | 45 | |
| KT651 | Bedford 500 | Rear seal - rope | GM 7159753 | 6 | \$35/pr |
| KT655 | Rover V8 | Rear seal - rope | B L M C 602058 | 5 | \$25/pr |
| KT658 | BMC, Rover 3500 | Rubber seal | B L M C 42B104 | 67 | |
| KT695 | Holden 149 - 202 | Side plate gsk | | 5 | |
| KT696 | Holden 149 - 202 | Oil pump | | 3 | |
| KT697 | Holden 149 - 202 | Oil pump face plate | | 10 | |
| KT698 | GM | Therm gsk | THERM.HOUSING GSK.7420090 GM | 186 | |
| KT699 | Holden 4 & 6 | Front cover gsk | also in TG002 | 9 | \$ 4.00 |
| KT700 | Ford V6 | Nylon washer | NYLON WASHER 711M-6734-AA | 26 | |
| KT701 | Holden 4 & 6, V8, chev 6 | Sump end seal | | | |
| KT702 | Holden 4 & 6 | Sump end seal front | Included in TG002 | | |
| KT727 | Simca | Misc gsk | MISC GSK.F55123200 SIMCA | 46 | |
| KT728 | Bedford CF | Sump ends | | | |
| KT737 | BMC | Sump end rubber strip | B L M C 12G3016 | 5 | |
| KT738 | Ford Cortina OHC | Therm gsk -rubber | FORD E853-1005 | 28+4 | |
| KT739 | Ford Cortina OHC | Therm gsk | F 70HM-8255-AB | 243 | \$ 2.00 |
| KT740 | Ford | Sump end rubber | FORD 681F6722A | 140 | |
| KT741 | Ford | Sump end rubber | FORD 681F-6723-AA | 176 | |
| KT839 | Ford Cortina OHC | Front cover gsk | (TCG850) | 10 | |
| KV171 | Holden 138 | Side plate gsk | | 2 | \$ 15.00 |
| KV384 | Ford | Misc gsk | FORD 2725E-9673C | 3 | |
| KV389 | Toyo | Rubber ring -flat | TOYOTA 90430-07121 | 33 | |
| KV402 | Toyo 3K | Front backing plate | (GT185 includes) | 1 | |
| KV412 | Toyota 2R | Oil seal rear pair | | | |
| KV414 | Toyo 3K, Chrysler 225 | Spark plug tube seals? | | 4 | |
| KV441 | Nissan | Main cap side seal | NISSAN 12289-B3000 | 29 | |
| KV464 | Toyo | Misc gsk | MISC GASKET TOYOTA | 20 | |
| KV466 | Toyota 6R, 2T/3T | Fuel pump gsk | (block# is LT176) | 2 | |
| KV467 | Toyota 12R | | SIDE PLATE GSK.TOY.11253-31011 | | |
| KV468 | Ford C4, C5 | | TPG Ford C4, C5 | 1 | \$ 6.00 |
| KV494 | Leyland P76 V8 | Valley cover gsk | | 0 | \$ 70.00 |
| KV495 | Hillman | Pushrod cover gsk | | 5 | |
| KV512/3 | Holden V8 | Mani gsk Inlet ends | | 0 | |
| KV512/3B | Holden V8 | Mani gsk Inlet ends plus cork ring | | 1 | |
| KV515 | Holden V8 red | Therm gsk | T STAT GASKET HOLDEN V8 RED | 11 | |
| KV517 | Holden 202, 253, 308 | Rear seal - rubber | (Other #'s 97199, PR6416) | 6 | \$ 20.00 |
| KV518 | Holden 202 | Fuel pump gsk | | 4 | |
| KV575 | Mazda | Oil filter hsg gsk | OIL FILTER GSK 022114342NZ MAZ | 18 | |
| KV646 | Nissan H20 | Therm? | D 11062-S3001,G 8942098720 | 5 | |
| KV647 | Nissan | Therm gsk | THERM. HOUS. GSK.D 11072-S3001 | 61 | |
| KV648 | Nissan | Misc gsk | MISC GSK.13050-21000 NISSAN | 33 | |
| KV651 | Nissan | | see GT116 | | |
| KV692 | Mazda various 1970-79 | Therm gsk | WATER OUTLET GSK.0221-10-161NZ | 25 | |
| KV693 | Mazda | Head end gsk | HEAD END GSK.0221-10-181NZ MAZ | 106 | |
| KV695 | Mazda | Side plate gsk | SIDE COVER GSK.M.0221-10523ANZ | 58 | |
| KV703 | Mazda FE, E3, E5 | Therm gsk | | lots | |
| KV718 | Standard | A/filter gsk | AIR CLEANER GSK.158712 STANDAR | 23 | |
| KV730 | Todd | Main cap side seal | TODD 71268778 | 4 | |
| KV780c | Ford EA26 | Timing/head gsk -cork | | 3 | |
| KV780r | Ford EA26 | Timing/head gsk -rubber | | 3 | |
| KV782E | Ford Falcon early | Front cover gsk -short ends | Can use NZ330 and JR552 | 1 | |
| KV789 | Austin Kimberley 70-72, Ley P76 6 | Water gsk front | | 0 | |
| KV804 | BMC | | MISC GSK.AYH681 NZMC | 5 | |
| KV834 | Nissan | see GT116 | | | |
| KV879 | Chrysler Valiant & Hemi 6 | Fuel pump gsk | MISC GSK C 2843770 MITSUBISHI | 4 | |
| KV880 | Chrysler Hemi 6 | Misc gsk | MISC GSK.A2899202 MITSUBISHI | 217 | |
| KV882 | Chrysler Hemi 6 | Rear seal pair | | | |
| KV954 | BMC | Oil/crankcase gsk | OIL/CRANKCASE GSK.AYD103 NZMC | 2 | |
| KV955F | BMC | Fuel pump gsk | FACINGS ONLY AYD200 LEYL. NZMC | 15 | |
| KV966 | Mazda | Baffle gsk | BAFFLE GSK.0305-10-229NZ MAZDA | 21 | |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|---------|---------------------|-------------------------|--------------------------------|-------|---------|
| KV968 | Holden | Therm housing to head | | 10 | |
| KV970 | Toyota 2T, 3T etc | Spark plug seals | 4 required | | \$ 8.00 |
| KZ816 | Bedford 500 | Water outlet gsk | WATER O/LET GSK.2693730 G.M. | 7 | |
| L590M81 | Grease Nipple | Grease Nipple | M8 x 1 90Degree | 40 | |
| LA049 | Mitsubishi 4G32 etc | Rubber seal | mitsubishi JCMD009039 | 65 | |
| LA053 | GM | Front cover gsk | FRONT COVER TO BLOCK R.H. GM | 4 | |
| LA054 | GM | Front cover gsk | FRONT COVER TO BLOCK L.H. GM | 3 | |
| LA059 | Toyota 2F | Rubber ring flat | MISC GSK O 90430-40058 | 51 | |
| LA090 | Toyo | Water outlet gsk | WATER OUTLET 16341-63010 TOY. | 18 | |
| LA096 | Toyo | Misc gsk | MISC GSK.16129-33030 TOY. | 5 | |
| LA104 | Toyo | Water outlet gsk | H2O OUTLET TOYOTA 16235-70021 | 12 | |
| LA110F | Honda EB | Fuel pump gsk | FUEL PUMP BLOCK FACING | 183 | |
| LA111 | Toyo | Water outlet gsk | TOYOTA WATER OUTLET | 31 | |
| LA117 | Mazda R2, RF | Oil seal retainer gsk | OIL SEAL RETAINER F801-11-318 | 21 | |
| LA125 | Suzuki | Therm gsk | T/STAT GSK.17569-82001 SUZUKI | 21 | |
| LA133 | Mitsubishi 4G32T | Exh fla turbo to pipe | mitsubishi JCMD075943 | 55 | |
| LA134 | | Therm gsk -3 bolt | H2O GASKET M S211-15-173 | 6 | |
| LA174 | | Copper washer | 1.5MM COP WASH ID12.14,OD17.46 | 312 | |
| LA177 | Nissan | Fuel pump gsk | FUEL PUMP GSK 16420-D0103 NISS | 10 | |
| LA179 | Toyota 6R | Rear seal plate gsk | OIL SEAL RETAINER GSK TOYOTA | 5 | |
| LA180 | Mits? | Bolt rubber seal | JCMD010563 RUBBER SEAL | 42 | |
| LA187 | Toyo | Exh fla -big | EX.FLANGE GSK.25576-13010 TOY. | 11 | |
| LA198 | Isuzu 161Z, 180Z | Therm gsk | T/STAT. GSK. | 11 | |
| LA199 | Suzuki | Therm? Gsk | CAP GASKET SUZUKI 17569-80000 | 25 | |
| LA219 | | Front cover gsk | FRONT COVER GSK | 203 | |
| LA251 | Mits | Rear cover gsk | REAR COVER GSK JCMD030156 | 9 | |
| LA383 | Suzuki | Fuel pump gsk | FUEL PUMP GSK SUZUKI | 28 | |
| LA400 | | Water outlet gsk | WATER OUTLET GASKET | 41 | |
| LA452 | Subaru | Filler cap rubber | FILLER CAP S 80393-5010 | 7 | |
| LA466 | Nissan E13, E15 | Therm gsk | THERM.HOUSING GSK. 11072-01M00 | 15 | |
| LA468 | Nissan E13/15 | Oil seal retainer gsk | OIL SEAL RETAINER NISS. E13/15 | 7 | |
| LA473 | Nissan | Front plate gsk | FRONT COVER GSK NISSAN | 12 | |
| LA475 | Nissan E13/15 | Front cover gsk | FRONT COVER GSK NISSAN E13/E15 | 22 | |
| LA481 | Nissan | Carb gsk | INSULATOR GSK NISSAN | 8 | |
| LA488 | Nissan E13/15 | Oil strainer gsk | OIL STRAINER GSK NISSAN E13/15 | 18 | |
| LA489 | Nissan | Oil filter hsg gsk | OIL FILTER GSK.NISSAN | 29 | |
| LA490 | Nissan | Oil strainer gsk | OIL STRAINER GSK.NISSAN | 14 | |
| LA491 | Nissan | Oil strainer gsk | OIL STRAINER GSK.NISSAN | 21 | |
| LA492 | Nissan E13/15 | Oil pump cover gsk | OIL PUMP GSK NISSAN E13/E15 | 8 | |
| LA494 | Nissan H20 | Oil pump to cyl gsk | OIL PUMP TO CYL. GSK.NISSAN | 18 | |
| LA499 | Nissan H20 | Oil filter hsg gsk | OIL FILTER GSK.NISSAN | 18 | |
| LA516 | | Insp. Cover gsk | FR.COVER GSK D 11049-D0101 | 15 | |
| LA635 | Toyo | Water outlet gsk | H2O OUTLET TOYOTA 16341-70010 | 4 | |
| LA661 | | Cam end bung 1/2 round | | 1 | |
| LA702 | | Oil strainer gsk | OIL STRAINER GASKET | 16 | |
| LA703 | Toyo | Oil pickup gsk | OIL PUMP GSK.15197-15012 TOY. | 27 | |
| LB063 | Toyo 2RZE | Thermostat seal | | 1 | |
| LB065 | Toyo | Fuel pump gsk | FUEL PUMP GSK TOYOTA | 10 | |
| LB086 | Nissan | Oil pump cover gsk | OIL PUMP GSK.NISSAN | 6 | |
| LB160 | Honda | Carb gsk | CARB GSK 19313-PC6-000 HONDA | 54 | |
| LB316 | Honda | Spark plug rubber seal | | 8 | |
| LB318 | | Oil filler -rubber | OIL FILLER HH 15613-PC6-000 | 98 | |
| LB351 | Toyo 4AF, 4AFE | Spark plug seal | | 4 | |
| LB363 | Nissan H20, L | Gasket | PACKING SUPPORT DIS.GSK NISSAN | 20 | |
| LB369 | | O ring | O RING | 85 | |
| LB475 | Toyo (3K?) | Head front gsk | HEAD FRONT COVER GSK.TOYOTA | 38 | |
| LB498 | Daihatsu delta | Therm gsk | T/STAT GASKET DELTA DAIHATSU | 6 | |
| LB519 | Mits | Inj seal rubber | INJECTOR SEAL MITSUBISHI | 194 | |
| LB520 | Honda | Misc gsk | MISC.GSK HONDA 18765-PA6-010 | 30 | |
| LB522 | Toyota 3K etc | Hot box? | | 1 | |
| LB537 | GM | Carb gsk | CARB.INSULATOR GSK GM | 7 | |
| LB553 | Honda F2 | Spark plug seal | | 19 | |
| LB664 | | Fuel pump block | FUEL PUMP BLOCK | 12+4 | |
| LB792 | | Baffle gsk | BAFFLE GSK B630-10-229 | 23 | |
| LR062 | Ford Trader 330-380 | Rubber seal | FORD 2701E-9K540A1/2 | 200+ | \$ 5.00 |
| LR104 | Nissan A12 etc | Water pump gsk | Included in GT98 | | |
| LR329 | Rover | Cork ring large | Rover | 7+68 | |
| LR646 | Honda | Misc gsk | Honda | 31+4 | |
| LR911 | Nissan | Fuel pump gsk | FUEL PUMP GSK.17099-E3012 NISS | 5 | |
| LS358 | | Therm gsk | THERM.COVER GSK.19312-657-S00 | 9 | |
| LS373 | Mitsubishi 4G51 | Rubber ring -large flat | MITSUBISHI JCMD001210 | 4 | \$ 7.00 |
| LS374/5 | Mitsubishi 4G54 etc | Front cover gsks | CHAIN GASE GSKS JCMD020324/5 | 8 | \$ 9.00 |
| LS376 | Mitsubishi 4G54 etc | Rear seal cover gsk | T JCMD020292 | 8 | |
| LS377 | Mitsubishi 4G15 | Therm gsk | Use WG6 | | |
| LS379 | Mitsubishi 4G54 etc | Misc gsk | T JCMD021539 | 33 | |
| LS381 | Mitsubishi 4G54 etc | Misc gsk | T JCMD003358 | 218 | |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|--------------|----------------------------------------|-------------------------|--------------------------------|-------|----------|
| LS390 | Chrysler Hemi 6 | Sump end | SUMP GASKET (other end JH896) | 7 | \$ 10.00 |
| LS401 | Holden V8 | Water pump gsk | Also in TC20 | 1 | \$ 6.00 |
| LS562 | Mitsubishi 4G54 etc, Chrysler Hemi | Bolt seal? | Todd 2899089 | 14 | |
| LS623 | Ford Trader 330-380 | Ex | EXH.OUTLET 2704E-6K688-A FORD | 0 | |
| LS661 | BMC "O" | Front cover gsk | ? | 66 | |
| LS667 | Ford C3 | | TPG Ford C3 | 1 | \$ 8.00 |
| LS823 | BMC Transv. | Sump side | C/CASE TO TRANS.L.H.N 22G1003 | 42 | |
| LS844 | BMC | cap arch seal | | | |
| LS874 | Jag | Sump end rubber? | JAGUAR C36499 | 10+6 | |
| LS928 | BMC "O" | Cam end cover gsk | CAMSHAFT COVER CAM1879 NZMC | 3 | |
| LT098 | Toyo | Cam end bung | | 1 | |
| LT176 | Toyo | Fuel pump block | TOYOTA 90923-06001 | 29 | |
| LT202 | Mazda | Cap side seals | 2 reqd | 4 | \$ 8.00 |
| LT220 | Toyota 3K, 4K etc (also KS290) | Therm gsk | WATER OUTLET GSK.O 16341-13011 | 27 | |
| LT226 | Mazda | Therm gsk | THERM.GSK.0221-15-173NZ MAZDA | 38 | |
| LT244 | GM | Sump end rubber | SUMP GSK GM 7020650 | 8 | |
| LT245 | GM | Rubber strip | G M 7020653 | 8 | |
| LT246 | Ford Y8C | Inlet Mani -valley ends | Should this be V8 Cleveland? | 16 | |
| LT273 | Mitsubishi 4G32 etc (also in GT205) | Rear oil hsg gsk | REAR OIL CASE GSK.JCMD008886 | 8 | |
| LT274 | Mitsubishi 4G32 etc (also in GT205) | | 4 bolt gsk? | | |
| LT275 | Mitsubishi 4G32 etc (also in GT205) | Oil screen gsk | OIL SCREEN GSK.JCMD008907 MITS | 9 | |
| LT276 | Mitsubishi 4G32 etc (also in GT205) | Fuel pump gsk | JCMD008933 FUEL PUMP GASKET | 379 | |
| LT430 | Mits | Fuel pump gsk | FUEL PUMP GSK..T JCMD030836 | 22 | |
| LT442 | GM | Front cover gsk | CRANKCASE GSK.90106432 G.M. | 5 | |
| LT443 | GM | Misc gsk | FLANGE GSK.90122258 G.M | 12 | |
| LT456 | Holden V8 253, 308 | Oilpump inner | | 2 | |
| LT457 | Holden V8 253, 308 | Oilpump outer | | 2 | |
| LT577 | Nissan | Insp. Cover gsk | FRONT COVER GSK. NISSAN | 61 | |
| LT581 | Toyo | Sump plate gsk | Sump gsk Toyota | 20 | |
| LT582 | Toyo | Oil filter hsg gsk | OIL FILTER GSK.TOYOTA | 26 | |
| LT787 | Toyota 6R | Cork gsk | | 1 | |
| LT810 | Honda | Therm gsk | THERM.COVER GSK H19313-634-S00 | 1 | |
| LT910 | Honda | Rubber gsk | 19305-PAO-000 | 47 | |
| LT918 | | Therm hsg gsk | WATER OUTLET 11062-01M00 | 13 | |
| LT983 | Nissan, Honda | Erg valve gsk | ERG VALVE GSK 14719-N3301 NISS | 23 | |
| LV032 | Ford Cortina | | Use NA576 | | |
| LV433 | Holden 4 | Side plate | | 2 | |
| LV434/5 | Holden 4 | Sump sides | SUMP GSKS.9945632/3 G.M. | 30 | |
| LV501 | Nissan SD22 early | Oil seal rear | 2 piece neoprene seal | 1? | |
| LV507 | Mazda XA, XB | Oil seal rear wick | 1978-82 (Later use NJ330) | | |
| LV563 | | Inj adapt. Plate gsk | INJECT ADAPTER PLATE GASKET | 23 | |
| LV575 | Mitsubishi 4G32 etc -Use LV647 | Cam end plug | | | \$ 5.00 |
| LV581 | Nissan H20, Ford | Fuel pump gsk | FUEL PUMP GSK 0107-13449 FORD | 61 | |
| LV599 | Isuzu 161Z, 180Z | Fuel pump gsk | FUEL PUMP GASKET | 197 | |
| LV619 | Isuzu | Cam end plug | CAM PLUG ISUZU | 151 | |
| LV647 | Mitsubishi 4D55/56 etc (can use LV575) | Cam end plug | | 2 | \$ 5.00 |
| LV922 | | Water bypass gsk | WATER BY PASS GSK.16258-15011 | 18 | |
| LV926 | Honda | Breather cover gsk | BREATH.COVER GSK.12412-634-000 | 136 | |
| LX020 | Toyo | Rocker retainer clip | ROCKER RETAINER CLIP TOYOTA | 1389 | |
| M053-27-622A | Ford/Mazda | Seal | | 1 | |
| M4146 | | Oil seal -special | about 57x75x11mm | 1 | |
| MD311638 | Mitsubishi 4D55/56 | Oil filler seal | | 1 | |
| MD603015 | Mits | Rocker bolt seal | | 10 | |
| ME060124 | Mitsubishi 4D22T | Oil seal front crank | 95x125x12/19.5 | 1 | |
| MG0013 | Toyota B, 3B, 11B 1988 on | Mani gsk exhaust | A868 | 5 | |
| MG2096 | Bedford 214 | Mani gsk -one piece | | 0 | \$ 12.00 |
| MG3000 | Isuzu G200 DOHC | Mani gsk Inlet pr | | 1 | \$ 10.00 |
| MG3024 | Toyota 4AGE | Mani gsk Inlet | | 1 | |
| MG3037 | Nissan CA18DE | MGC | | 1 | \$ 6.00 |
| MG3059 | Mazda B6-D | MGC | | 1 | \$ 6.00 |
| MG3073 | Ford Trader 380 Dover | Mani set | | | |
| MG3084 | Suzuki G16B | MGC | | 1 | \$ 7.00 |
| MG3090 | Mitsubishi 4G63T 95 Evo 3-5 | Mani gsk Inlet | | 1 | |
| MG3100 | Nissan GA15DE, GA16DE (injected) | Mani gsk Inlet | | 2 | \$ 15.00 |
| MG3134 | Mitsubishi 4G63T 01/97 on | Mani gsk Inlet | | 1 | |
| MG3244 | Mazda F2 Turbo | Mani gsk exh set | (JC778 x 2 plus JC780) | 2 | \$ 45.00 |
| MG3348 | Bedford 330 | Mani gsk exh set | | 2 | |
| MR025X3 | Bedford 466, 500 | O ring -oil pickup | | 5 | |
| MS040 | Mitsubishi G32B | Mani gsk set | | 5 | |
| MS060 | Mitsubishi G11B/13B | Mani gsk set | | 9 | |
| MSPD3 | Hon? | Mani gsk set | | 2 | |
| MSPE3 | Honda EW Shuttle | Mani gsk set | | 2 | |
| N1052 | | Mani gsk Inlet | | 1 | |
| N467 | Mitsubishi (4G63?) | Front cover gsk plus | | 2 | |
| N607 | Austin Maxi, Allegro | G/box hsg | | | |
| N667 | Ford Trader 380 Dover etc | Therm hsg gsk | | | \$ 9.00 |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|----------------|---------------------------------------|----------------------------|--------------------------------------------|-------|----------|
| NA956 | Ford V4, V6 ? | Oil pump gsk | | 3 | \$ 7.00 |
| NA068 | | Oil seal | ON DELETION 2405 | 36 | |
| NA174 | Vaux Viva | Oil seal front | 1.375"x1.875"x.312" | 44 | \$ 13.00 |
| NA200 | Bedford 330 | Oil seal | BEDFORD 6358833 (TC12043)(PR2402) | 13 | |
| NA201 | Ford Trader | Oil seal -auxillary | Ford EIADDN-66610A Aux drive shaft seal | 3 | |
| NA298 | Stand. Vanguard | Oil seal front | | 1 | \$ 25.00 |
| NA308 | Rover 2, 2.25 litre etc | Use NB849 | | | |
| NA329 | Holden, Triumph | Oil seal front | 1.625"x2.375"x.500" | | \$ - |
| NA341 | Ford Zephyr | Oil seal front | | 3 | \$ 10.00 |
| NA416 | BMC "C" | Oil seal front | (PR3858) | 15 | \$ 12.00 |
| NA417 | Holden 6, V8, chev 6 | Oil seal | GM3980267 (& PR6232) also in TG002 | 14 | \$ 7.00 |
| NA455 | Ford 240,300 petrol | Oil seal front | | | |
| NA473 | BMC | Oil seal | P2141, NZMC 88G561 (felt = KG065) | 6 | |
| NA5014 | Toyo, Mazda? | Oil seal | 32x46x6 | 3 | |
| NA5033 | Mazda FS | Oil seal -front crank | 42.5x54.5x6 -also in TSK18 | 1 | \$ 14.00 |
| NA512 | Vaux 3.3, 2.6, PA2.2, Bedford | Oil seal front cover | 1.937"x2.562"x.375" G M 7195654 | | \$ 25.00 |
| NA5172 | Isuzu 4JG2 | Oil seal front cover | 50x68x10 -in TSK20K | | \$ 35.00 |
| NA523 | Massey Ferguson | Oil seal | Massey Ferguson 897363M1 | 1 | |
| NA524 | Hillman Imp | Oil seal front cover | OIL SEAL T 9102085 (& Mits?) | 20 | \$ 15.00 |
| NA543 | Ford V6 1966-71 | Oil seal | 47x66x11 | 1 | \$ 15.00 |
| NA563 | Bedford 466 | Oil seal front cover | BEDFORD 6384745 PR6181 | 18 | \$ 20.00 |
| NA567 | Bedford CF | Oil seal -cam/aux | 44x63.5x9 GM 7199290 ABS1958N | 6 | \$ 20.00 |
| NA571 | Bedford CF | Oil seal -front crank | 51.6 x 67.85 x 9.5 | | |
| NA576 | Ford Cortina | Oil seal | 1.375x2.062x5/32" | | |
| NA576Turquoise | | Oil seal | 1.218x2.062x1/2"? | 1 | |
| NA577 | Hillman Avenger | Oil seal -front crank | ABS2139N | 3 | \$ 25.00 |
| NA582 | Ford Cortina OHC | Oil seal front | & auxillary | | |
| NA584 | BMC 1100, 1300 transverse | Oil seal rear | 55x70x10 | 2 | \$ 20.00 |
| NA625 | Volvo 1946-70 1225,PV444,PV445,PV | Oil seal -pinion | 1.562"x3.16"x0.6" 480030A | 30+ | |
| NA736 | Perkins 3.152 | Oil seal front | | | \$ 20.00 |
| NA741 | Perkins | Oil seal front | | 1 | \$ 12.00 |
| NA748 | Ford Trader | Oil seal front | FORD 510E-6362 | 20 | \$ 25.00 |
| NA749 | | Oil seal | | 20? | |
| NA759 | Triumph/Standard (for 3/8" deep use N | Oil seal front | 2"x3"x0.5" TRIUMPH 125631 (TC12154) | | \$ 20.00 |
| NA764 | | Oil seal | ON DELETION 2058 | 185 | |
| NA774 | Triumph 2000, 2500 | Oil seal rear | 3.375" x 2.875" x .375" | 1 | \$ 25.00 |
| NA785 | BMC "E" series | Oil seal front | 38 x 73 x 12.5 HTCR | | |
| NA785* | | Oil seal | 2.5" x 3.5" x 3/4" | 1 | |
| NA788 | Leyland 600, 680 690 | Oil seal front | 2.750x3.875x.750" | 1 | \$ 35.00 |
| NA792A | 76.2 x 98.65 x 10.7 | Oil seal | 76.2 x 98.65 x 10.7 ACL too wide for Viva? | 2 | \$ 20.00 |
| NA792N | Vaux Viva | Oil seal | 76 x 98 x 9 | | \$ 30.00 |
| NA793 | Ford Cortina, V4/V6 | Oil seal rear | | 5 | \$ 20.00 |
| NA965 | | Oil seal | 121x141x12 | 1 | |
| NA987 | Rover 2.25, 2.6 & 3 litre 1958-67 | Oil seal rear | 63.5x83.2x8 (2.5"x3.276"x.315") | 2 | \$ 30.00 |
| NA993 | Ford Falcon, BMC Marina | Oil seal front | | 1 | |
| NB051 | Rover 2.25, 2.6 & 3 litre 1958-67 | O ring | ROVER 244488 | 7 | |
| NB062 | Ford Trader to 1957 | Inj adaptor seal 14mm long | 14mm long (later=19mm) | 12 | \$ 11.00 |
| NB064 | Ford Trader 1957 on | Inj adaptor seal 19mm long | FORD EIADDN993156C | 13 | \$ 11.00 |
| NB076 | BMC Maxi, Tasman | Valve seal inlet | AYH553 | ? | |
| NB077 | Ford Trader 380 Dover etc | Inj seal | | 2 | \$ 14.00 |
| NB093B | Hillman Avenger, Triumph Stag | Oil seal rear | 3"x3.750"x.375" | 12 | \$ 35.00 |
| NB123 | BMC 1800, Leyland P76 V8 | Oil seal | 3.5x4.125x.375 (=PR4978?) | 2 | \$ 30.00 |
| NB132 | Triumph/Standard (for 1/2" deep use N | Oil seal front | 2"x3"x0.375" STANDARD 155695 | 34 | \$ 20.00 |
| NB272 | Toyo use NB578 | Oil seal | 38.5x58x11 | 1 | |
| NB289 | Austin Maxi, Allegro | Oil seal rear | 2.853x3.625x0.5" B L M C 42H118 | 45 | \$ 20.00 |
| NB384 | Mazda | Oil seal | 40x55x8 | 3 | \$ 8.00 |
| NB469 | GM | Oil seal | GM 614809 | 2 | |
| NB470 | Bedford 500 | Oil seal front cover | GM 91000883 | 21 | \$ 20.00 |
| NB570 | Ford | Oil seal | CODR-7052R | 1 | |
| NB571 | BMC | Oil seal | NZMC AYH3202 | 1 | |
| NB578 | Toyo replaces NB272 | Oil seal | 38.5x58x11 | 1 | |
| NB584 | | Oil seal | C30002 | 2 | |
| NB586 | BMC "O" | Oil seal front cover | 29x40x6 CAM1403 | 2 | |
| NB604 | | Oil seal | 35x57x14.5? | 2 | |
| NB610 | 47x67x9 | Oil seal | 47x67x9 B02049 | | \$ 12.00 |
| NB611 | BMC "O" | Oil seal camshaft | 36.58x70x14 NZMC 12H5079 | 10 | \$ 20.00 |
| NB613 | Chrysler Valiant, V8 360 etc | Oil seal front | TODD 2899531 (PR6363) | 12 | \$ 30.00 |
| NB614 | Chrysler Hemi 6 | Oil seal | Timing cover set = TCS21 | 1 | |
| NB615 | Ford | Oil seal | Ford DOA6700A | 1 | |
| NB628 | GM | Oil seal | 45x60x8.5 GM638185 | 6 | |
| NB688 | Ford Trader 380 Dover etc | Oil seal front | 66.67mm x 89.28mm x 9.52mm | | |
| NB699 | | Oil seal | (PR1479, KNB699) | 4 | |
| NB701 | | | G.M. 901063501 | 15 | |
| NB848 | Rover | Oil seal + sleeve | 99x120x11 | 1? | |
| NB849 | Rover 2.25, 2.6 & 3 litre 1958-67 | Oil seal front | 48.6x63.5x9.5 (1.915x2.5x.375") | 4 | \$ 20.00 |
| NJ001 | Toyota 3K, 4K, 5K | Oil seal -rear crank | 70x92x8.5 | 1 | \$ 16.00 |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|--------|---------------------------------------|----------------------------|--------------------------------|-------|----------|
| NJ004 | Nissan A15 etc | Oil seal -rear crank | 60x82x12 | 1 | \$ 12.00 |
| NJ005 | Mitsubishi | Oil seal -front crank | 44x60x7 | 2 | |
| NJ005P | Mitsubishi 4D55/56 etc | Oil seal -front crank | 44x60x7 -also in TSK005 | 2 | \$ 8.00 |
| NJ006 | Mitsubishi 4G32, | Oil seal | 72x96x9 | 2 | \$ 15.00 |
| NJ007 | Mitsubishi 4G32 to 1977 | Oil seal (PR0479) | 44x65x11 | 7 | \$ 8.00 |
| NJ008 | Mits | Oil seal | MITSUBISHI JCMD000248 | 16 | \$ 6.00 |
| NJ011 | | Oil seal | 40x52x7 (also NJ765?) | 2 | |
| NJ014 | Isuzu C190, G161 etc | Oil seal front | 50x68x9 -also in TSK19 | 2 | \$ 10.00 |
| NJ020 | Mits special | Oil seal | 70x96x103x8x11 MD010324/53 | 1 | |
| NJ021 | Nissan A12 etc | Oil seal rear | 60x82x12 | 1 | \$ 6.00 |
| NJ022 | Nissan A12 etc | Oil seal front | 38x55x9 | 1 | \$ 8.00 |
| NJ028 | | Oil seal | | 2 | |
| NJ030 | Toyota 5R | Oil seal | 80x100x12 | 2 | |
| NJ044 | Toyota 2T, | Oil seal | 75x100x13 | 2 | |
| NJ045 | Nissan | Oil seal | 48x70x9 NJ045, 48x70x8 TC12875 | 2 | |
| NJ049 | Nissan | Oil seal | 48x65x7 Nissan | 19 | |
| NJ050 | Nissan J series front | Oil seal | 39.7x62x11 NISSAN 13042-B3000 | 11 | \$ 5.00 |
| NJ052 | 42x55x7 | Oil seal | 42x55x7 | 1 | \$ 12.00 |
| NJ055 | Toyota F, 2F, 3F early | Oil seal rear PR0099 | 100x120x11 | 1 | |
| NJ056 | Nissan | Oil seal | | 1 | |
| NJ057 | Mitsubishi 4G51 etc | Oil seal front | 48x68x11 | 2 | \$ 6.00 |
| NJ058 | Mitsubishi 4G51 | Oil seal rear | 80x96x9 | 9 | \$ 16.00 |
| NJ060 | Isuzu C190, G161 etc | Oil seal rear | 82x105x13 | 2 | |
| NJ068 | Mit/Toy | Oil seal | 52x65x9 | 2 | |
| NJ073 | Honda | Oil seal | 74x98x12 | 3 | |
| NJ074 | Honda | Oil seal | 45x93x5.8x7.8 | 31 | |
| NJ075 | Honda | Oil seal | 45x64x9x14 | 31+14 | |
| NJ098 | Ford Falcon, Daihatsu | Oil seal | 95x110x11 | 7 | |
| NJ102 | Toyota 2R | Oil seal front | | | |
| NJ099 | Mazda | Oil seal | 70x88x12 | 13 | |
| NJ161 | | Oil seal | 35x56x8x11.5 | 50 | |
| NJ206 | 36x49x7 | Oil seal | 36x49x7 | 1 | |
| NJ207 | Nissan GA | Oil seal | 27x49x10 13276-53Y00 | 5 | \$ 10.00 |
| NJ231 | Isuzu 4B/6B | Oil seal front | 60x82x12 | 1 | \$ 12.00 |
| NJ232 | Isuzu 4B/6B | Oil seal rear | | 1 | \$ 22.00 |
| NJ236 | Toyota 2K, 3K | Oil seal rear | 70x92x12 | yes | \$ 12.00 |
| NJ239 | Toyota B, 2B, 3B, 11B, 13B, H, 2H, 12 | Oil seal front | 50x72x12 | | |
| NJ240 | Toyota B, 2B, 3B, 11B, 13B, H, 2H, 12 | Oil seal rear | 95x115x12 | 2 | |
| NJ242 | Mitsubishi 4D55/56 etc | Oil seal -cam | 35x50x8 -also in TSK05 | 4 | \$ 6.00 |
| NJ243 | Toyota 4M etc | Oil seal front | 45x68x12 | 1 | |
| NJ251P | Mitsubishi 4D55/56 etc | Oil seal rear | 80x96x9 | 1 | \$ 15.00 |
| NJ252 | Mitsubishi | Oil seal | 30x46x7 | 1 | \$ 5.00 |
| NJ254 | Honda | Oil seal | 27x43x9 | 4 | \$ 5.00 |
| NJ255P | Mitsubishi 4D55/56 etc | Oil seal -oil pump | 17x28x7 -also in TSK05 | 5 | \$ 6.00 |
| NJ258 | Mit/Toy | Oil seal | 55x78x12 | 1 | |
| NJ265 | Isuzu C190 | Oil seal rear | | 1 | |
| NJ267N | Isuzu | Oil seal | 42x55x9 | 1 | |
| NJ276 | | Oil seal | | 1 | |
| NJ280 | Nissan CD17 | Oil seal -front crank | | 1 | |
| NJ284 | Nissan | Oil seal | 84x104x11 | 2 | |
| NJ285 | Use NJ324 | Oil seal | | | |
| NJ286 | Nissan E13, E15, E16 | Oil seal | 36x49x7 -also in TSK45K | 1+2 | \$ 6.00 |
| NJ287 | Nissan | Oil seal | 80x100x10 | 2 | |
| NJ287N | Nissan | Oil seal | 80x100x10 | 2 | |
| NJ288 | Nissan E13, E15, E16 | Oil seal | 40x55x9 -in TSK45K | | \$ 6.00 |
| NJ291 | Nis/Maz | Oil seal | 50x72x12 | 2 | \$ 30.00 |
| NJ309 | Honda | Oil seal | 76x98x12 HTCR | 1 | \$ 12.00 |
| NJ312 | Honda | Oil seal | 80x100x10 | 3 | \$ 20.00 |
| NJ313 | Honda | Oil seal | 29x45x8 | 1 | |
| NJ321 | Isuzu | Oil seal | 28x47x8 | 1 | |
| NJ322 | Isuzu 4JB1, 4JB1T | Oil seal -rear crank | 95x118x10 | 1 | |
| NJ323 | Isuzu | Oil seal | 40x56x7 -also in TSK19, TSK20K | 3 | \$ 6.00 |
| NJ324 | Dai/Maz | Oil seal | 34x48x7 -also in TSK17 | 2 | \$ 5.00 |
| NJ325 | Mazda | Oil seal | 90x110x9 | 1 | \$ 15.00 |
| NJ330 | Mazda SL | Oil seal -rear crank | 101.6x125x13 | 0 | |
| NJ334 | Mits oilpump | Oil seal | 23x34x8 | 4 | |
| NJ336 | Suzuki G13A, various | Oil seal -front & camshaft | 32x47x8 -also in TSK30K | 3 | \$ 8.00 |
| NJ337 | Suzuki F5, F8, F10 | Oil seal rear | 60x80x8 | | \$ 11.00 |
| NJ344 | Toyota L, 2L | Oil seal | 42x60x7 -in TSK37 | | \$ 10.00 |
| NJ344V | Toyota 1C, 2C | Oil seal | 42x60x7 -in TSK22 | | \$ 27.00 |
| NJ346 | Mazda FE 1983-87, Toyo 1C, 2C | Oil seal rear | 90x110x8.5 | 2 | |
| NJ353 | Toyo 3AF, 3AFE | Oil seal -cam | 35x49x6 | 4 | |
| NJ354V | Toyota | Oil seal | 85x105x10 | 1 | |
| NJ360 | Nissan | Oil seal -use NJ287N | 80x100x8.5 | | |
| NJ367 | Mazda XA, XB | Oil seal | Front Cover seal | 3 | \$ 11.00 |
| NJ369 | Nissan SD22 | Oil seal | 58x80x12 | 1 | \$ 20.00 |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|--------|------------------------|-------------------------|-------------------------------------|-------|----------|
| NJ373 | Mitsubishi balance | Oil seal | 28x40x8 | 5 | \$ 6.00 |
| NJ377 | Suzuki G13A | Oil seal | 32x47x6 -also in TSK30K | 1 | \$ 8.00 |
| NJ378 | Suzuki | Oil seal | 68x86x8 | 4 | \$ 20.00 |
| NJ381 | Honda | Oil seal | 31x46x8 Honda | 1 | |
| NJ383 | Isuzu | Oil seal | 49x100x8 Isuzu | 7 | |
| NJ385 | | Oil seal | 70x112x14x20 90043-11053-999 DAIHA | 305 | |
| NJ390 | | Oil seal | 68x88x10 90043-11102-999 DAIHA | 227 | |
| NJ444 | Toyota 19x32x8 | Oil seal | 19x32x8 | 3 | |
| NJ448 | Mazda B6 etc | Oil seal | 30x44x7 -also in TSK13 | 4 | \$ 6.00 |
| NJ454 | Isuzu | Oil seal | 30x45x8 | 1 | |
| NJ464 | Honda | Oil seal | 45x72.2x7.5x8.5 91251-692-013 | 161 | \$ 7.00 |
| NJ465 | Isuzu | Oil seal | 75x112x10x17.5 G 1096250060 | 195 | |
| NJ477 | 60x77x12 | Oil seal | 60x77x12 | 1 | \$ 15.00 |
| NJ523 | Toyota | Oil seal | 48x82x12 | 9 | |
| NJ528 | Honda | Oil seal | 45x64x6.5x13.5 91250-SA2-023 | 159 | |
| NJ556N | 104x120x11 | Oil seal | 104x120x11 | 2 | \$ 45.00 |
| NJ609 | Toyota 90311-38043 | Oil seal | 30x58x11 | 17 | \$ 10.00 |
| NJ610 | Mitsubishi 4D55/56 etc | Oil seal -balance shaft | 25x35x6 | 2 | \$ 6.00 |
| NJ646 | Isuzu | Oil seal -rear crank | 100x135x10 | 2 | |
| NJ647 | Daihatsu/Hino | Oil seal | 50x82x12 90043-11077-999 DAIHA | 53 | |
| NJ654P | Toyota 1C, 2C -oilpump | Oil seal | 20x32x5 -in TSK22K | | \$ 6.00 |
| NJ655 | Mitsubishi 4G63 etc | Oil seal | | 4 | \$ 5.00 |
| NJ667 | Daihatsu | Oil seal | 35x68x9x15.5 90043-11153-999 DAIHA | 3 | |
| NJ675 | V6 crank | Oil seal | 80x98x10 HONDA 91214-PL2-003 | 1 | \$ 20.00 |
| NJ692 | | Oil seal | 56x72x10 | 5 | |
| NJ699 | Subaru | Oil seal | Subaru | 9 | |
| NJ706 | Toyota 1C, 2C -cam | Oil seal | 37.5x50x6 -also in TSK22K | 6 | \$ 7.00 |
| NJ707 | Toyota, Hino | Oil seal | 38x55x9 Hin/Toy | 6 | |
| NJ719 | Toyota 3K, 4K, 5K, 12R | Oil seal -front crank | 38.5 x 58 x 8.5 | yes | |
| NJ731 | Honda | Oil seal | 35x62x8x11.5 91205-689-005 HONDA | 4 | |
| NJ732 | Honda | Oil seal | 38x54x8x11.5 HONDA 91205-PC8-935 | 40 | |
| NJ733 | Honda | Oil seal | 35x68x9x12 HONDA 91205-PE6-004 | 29 | |
| NJ734 | Honda | Oil seal | 47x64x68x6x14 HONDA 91250-SB0-624 | 25 | |
| NJ751 | Daihatsu | Oil seal | 24x35x6 90043-10036-999 DAIHA | 34 | |
| NJ765 | Nissan GA15, RB20+ | Oil seal | 40x52x7 Also NJ011? | 1 | |
| NJ766 | Daihatsu | Oil seal | 40x64x16 90043-11106-999 DAIHA | 27 | |
| NJ766 | Daihatsu | Oil seal | 40x64x16 90043-11106-000 | 1 | |
| NJ768 | Daihatsu | Oil seal | 45x80x10x16.5 90043-11148-000 | 2 | |
| NJ777 | Honda | Oil seal trans. | 35x76x9x12 | 21 | \$ 25.00 |
| NJ778 | Honda | Oil seal | 22x35x7 91216-PA0-003 HONDA | 4 | |
| NJ778 | Honda | Oil seal | 22x35x7 91216-PA0-003 | 1 | |
| NJ779 | Honda | Oil seal | 27x42x7 91216-PC8-003 | 4 | |
| NJ780 | Honda | Oil seal NLR inner | | 18 | \$ 14.00 |
| NJ781 | Honda | Oil seal | 47x72.2x6x8 Honda 91251-SA5-005 | 6 | |
| NJ782 | Honda | Oil seal | 49x72.2x6x8 HONDA 91251-SB0-015 | 53 | |
| NJ809 | Mazda | Oil seal | 48x65x8 Mazda | 15 | |
| NJ819 | Mazda ZB | Oil seal -rear crank | 60x78.9x11 | 15 | \$ 10.00 |
| NJ830 | Nissan | Oil seal | 25x35x7 | 1 | |
| NJ831 | Nissan | Oil seal | 58x80x10 | 1 | |
| NJ850 | | Oil seal | 30x53?x9 | 1 | |
| NJ873 | Mitsubishi | Oil seal | 91x111x9 | 1 | |
| NJ889 | Honda | Oil seal | 40x76x8x11 HONDA 91206-PC8-005 | 51 | |
| NJ915 | Honda | Oil seal | 35x56x8 91205-611-005 | 1 | |
| NJ918 | Honda | Oil seal | 45x58x6.5x14.5 HONDA 91250-SA7-013 | 105 | |
| NJ934 | Honda | Oil seal | 25x40x7 91216-689-003 HONDA | 61 | |
| NJ937V | | Oil seal | | 1 | |
| NJ951 | Nissan | Oil seal | 32x50x8 13168-01M00 | 1 | |
| NJ951P | Nissan E13, E15, E16 | Oil seal | 32x50x8 -in TSK45K | | \$ 6.00 |
| NJ978 | Mazda G6 | Oil seal | 46x60x7 | 1 | |
| NJ983 | Honda | Oil seal | 42x56.2x7.5x9.5 HONDA 91252-692-931 | 54 | |
| NJ990 | | Oil seal | | 1 | |
| NJ992 | Suzuki | Oil seal | Suzuki | 1 | |
| NJ993 | 45x68x8.5 | Oil seal | 45x68x8.5 | 1 | \$ 15.00 |
| NK005 | Honda | Oil seal | OS HONDA ZC | 3 | \$ 25.00 |
| NK022 | Honda | Oil seal | 35x68x9x12.5 HONDA 91206-611-005 | 46 | |
| NK023 | Honda | Oil seal | 41x56x8 | 7 | |
| NK065 | Honda | Oil seal | OIL SEAL HONDA 91205-PC9-711 | 4 | |
| NK066 | Honda | Oil seal | 40x76x9x12.5 HONDA 91206-PC9-711 | 18 | |
| NK067 | Honda | Oil seal | 40x56x9x12.5 HONDA 91206-PG2-005 | 11 | |
| NK100 | Honda | Oil seal | 44x68x8 91207-639-015 | 20 | |
| NK117 | Subaru EJ20T | Oil seal | | 3 | |
| NK117P | Subaru EJ20, EJ25 etc | Oil seal | 32x45x8 -in TSK26 | | \$ 6.00 |
| NK153P | Subaru EJ20, EJ25 etc | Oil seal | 33x49x8 -in TSK26 | | \$ 7.00 |
| NK157 | Mazda B3 etc | Oil seal | 83x100x9 | 1 | \$ 15.00 |
| NK158 | Mazda B6 etc | Oil seal | 36x50.5x7 -in TSK13 | | \$ 8.00 |
| NK203 | Honda | Oil seal | 44x68x8 HONDA | 70 | |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|--------|---------------------|------------------------|--------------------------------|-------|----------|
| NK205P | Mazda FS | Oil seal -rear crank | 90x109x9/10.3 | 1 | |
| NU101 | | Oil seal | 45x67x12 | 1 | |
| NX202 | GM G/box? | Oil seal | GM2707882 | 1 | |
| NZ001 | Mitsubishi 4G54 etc | O ring | O ring | 16 | |
| NZ002 | Honda | O ring | O RING HONDA | 10 | |
| NZ003 | Honda | O ring | O ring Honda | 16 | |
| NZ005 | Rover SD1 | O ring | O ring Rover SD1 | 6 | |
| NZ006 | Mitsubishi 4G54 etc | O ring | O ring Mitsubishi | 7 | |
| NZ007 | Mazda | Baffle gsk | BAFFLE GSK. MAZ.0324-10-229ANZ | 3 | \$ 10.00 |
| NZ008 | Mazda TC, UD | Mani gsk -exh single | Ex mani gsk Mazda TC UD | 96 | |
| NZ009 | Mazda TC, UD | Mani gsk -exh twin | Ex mani gsk Mazda TC UD | 7 | |
| NZ011 | Mazda | Misc gsk | MISC GSK.MAZDA 0370-10-523ANZ | 28 | |
| NZ012 | Rover SD1 | O ring | O RING ROVER SDI | 7 | |
| NZ020 | GM | Therm gsk | MISC GASKET GM 08930323 | 9 | |
| NZ021 | | Nylon screw plug | NYLON PLUG GSK. 08966222 | 22 | |
| NZ023 | GM | Grommet | MISC.GSK. HOLDEN/BEDFORD | 21 | |
| NZ024 | Skoda | Rubber washer | Rubber washer 4 x 18mm Skoda | 12 | |
| NZ031 | Suzuki | Misc gsk | MISC GSK. SUZUKI 11159-73001 | 5 | |
| NZ033 | Suzuki | Breather plate gsk | BREATHER PLATE GASKET SUZUKI | 10 | |
| NZ036 | Toyo | Head rear plate gsk | HEAD REAR PLATE GSK.TOYOTA | 17 | |
| NZ037 | Toyo | Head front gsk | HEAD FRONT COVER GSK.TOYOTA | 15 | |
| NZ038 | Toyo | Head front gsk | HEAD FRONT COVER GSK.TOYOTA | 179 | |
| NZ039 | Toyo | Head rear plate gsk | HEAD REAR PLATE GSK.TOYOTA | 225 | |
| NZ040 | Toyo | C/S housing gsk | C/S HOUSING GSK.TOYOTA | 7 | |
| NZ042 | Toyo | R/cover breather gsk | R/C BREATHER GSK.TOYOTA 2C | 27 | |
| NZ047 | Suzuki | Misc gsk | MISC GSK.SUZUKI 11241-38300 | 16 | |
| NZ063 | Toyo | T/C foam | T/C FOAM WITH ADHESIVE TOYOTA | 15 | |
| NZ065 | Toyo | Rear seal retainer gsk | O/S RETAINER GSK.TOYOTA | 5 | |
| NZ066 | Toyota 2T, 3T | Rear seal retainer gsk | | 1 | \$ 8.00 |
| NZ070 | Toyo | Rear seal retainer gsk | O/S RETAINER TOY.11384-70010 | 11 | |
| NZ073 | BMC | Hypoid hsg gsk | HYPOID HOUSING NZMC 114749 | 9 | |
| NZ082 | Toyo | Vent fla gsk | Ventilation flange gsk Toyota | 4 | |
| NZ083 | BMC "O" | Fuel pump gsk | MISC GASKET NZMC 12G4137 | 25 | |
| NZ084 | BMC "O" | Air filter gsk | MISC GASKET NZMC 12H4271 | 3 | |
| NZ085 | | O ring | O RING 13017-42L00 | 12 | |
| NZ088 | Suzuki | Carb gsk | CARB.GSK.SUZUKI 13125-73000 | 6 | |
| NZ089 | Suzuki | Misc gsk | MISC.GSK.SUZUKI 13125-76000 | 9 | |
| NZ090 | Suzuki | Carb gsk | CARB.GSK SUZUKI 13125-78100 | 81 | |
| NZ091 | | O ring | O RING | 28 | |
| NZ092 | Holden | Therm hsg gsk | T/STAT HOUSING GSK.HOLDEN | 7 | |
| NZ094 | | | MISC GSK.POWER FARMING | 37 | |
| NZ095 | Suzuki | Air filter gsk | AIR CLEANER GSK.SUZUKI | 40 | |
| NZ096 | Nissan | Balance tube gsk | BALANCE TUBE GSK NISSAN | 464 | |
| NZ097 | Nissan | Mani gsk Inlet | In mani gsk Nissan/Holden | 3 | |
| NZ100 | Nissan | Mani gsk Inlet | IN.MAN.GSK.NISSAN 14035-11M02 | 6 | |
| NZ101 | Nissan | Mani gsk Inlet | IN.MAN.GSK.NISSAN/HOLDEN | 2 | |
| NZ105 | | Misc gsk | MISC GASKET HG143243302800 | 4 | |
| NZ108 | Holden Comm VL | EGR valve | EGR VALVE VL COMMODORE | 15 | |
| NZ109 | Nissan | EGR valve | EGR VALVE NISSAN.E13/0.09 | 10 | |
| NZ110 | Holden | Therm hsg gsk | THERMOSTAT GSK. 7401194 GM | 5 | |
| NZ111 | Nissan | Oil pump cover gsk | OIL PUMP COVER GSK.NISSAN | 6 | |
| NZ118 | Honda | Oil pump gsk | HONDA OIL PUMP BODY GSK. | 13 | |
| NZ119 | | Misc gsk | ON DELETION 2237 | 27 | |
| NZ121 | IHC | Misc gsk | MISC GSK. INTL TRUCKS 151193R3 | 9 | |
| NZ122 | | O ring | O RING 15142-PE0-000 | 8 | |
| NZ125 | Nissan H20 | Misc gsk | MISC GSK.NISSAN 15239-78200 | 33 | |
| NZ128 | Nissan H20 | Oil filter cork ring | OIL FILTER GSK.15270-11200 | 20 | |
| NZ134 | Suzuki | Oil pump cover gsk | OIL PUMP CASE GSK SUZUKI | 7 | |
| NZ137 | Subaru | Carb gsk | CARBURETTOR GSK SUBARU | 4 | |
| NZ138 | Subaru | Carb gsk | CARBURETTOR GSK SUBARU | 6 | |
| NZ139 | | | MISC GSK NISSAN 16177-23000 | 93 | |
| NZ140 | Honda | Carb gsk | MISC GSK HONDA 16213-663-000 | 21 | |
| NZ141 | | Carb gsk | MISC.GASKET 16215-689-000 | 22 | |
| NZ142 | | Mani insulator gsk | INSULATOR GSK.16215-PC3-600 | 33 | |
| NZ143 | | Carb gsk | CARB. GSK.16215-PH1-000 | 6 | |
| NZ144 | Toyo | Water pump gsk | WATER PUMP HOUSING GSK TOYOTA | 14 | |
| NZ146 | Dai | Misc gsk | MISC GSK.DAIHATSU 16322-87701 | 4 | |
| NZ150 | Dai | Therm gsk | WATER OUTLET GSK DIAHATSU | 25 | |
| NZ152 | Toyo | Water outlet gsk | WATER OUTLET GSK TOYOTA | 23 | |
| NZ153 | Suzuki | Adapter case gsk | ADAPTER CASE GSK SUZUKI | 21 | |
| NZ164 | Toyo | Mani gsk | MANIFOLD GSK TOY. 17178-41010 | 4 | |
| NZ165 | Suzuki | Pump gsk | PUMP ASSEM. SUZUKI | 9 | |
| NZ166 | Suzuki | Water pump gsk | WATER PUMP GSK SUZUKI | 4 | |
| NZ169 | Fergusson | Misc gsk | MISC GSK MASS.FERG.180434M1 | 22 | |
| NZ170 | Norwood | Case cover gsk | CASE COVER GSK NORWOOD 180511M | 17 | |
| NZ172 | Norwood | Sump gsk | SUMP GSK NORWOOD 1861986M2 | 22 | |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|-------|------------------------------|---------------------------|----------------------------------|-------|----------|
| NZ173 | Norwood | Misc gsk | MISC GSK NORWOOD 188807M2 | 1 | |
| NZ174 | Ford | Rear axle gsk | REAR AXLE SHAFT GSK.FORD | 10 | |
| NZ175 | Nissan CA20 | Exh fla gsk | EXH FLANGE GSK NISSAN CA20 | 29 | |
| NZ176 | Toyo | Fuel pump gsk | FUEL PUMP GSK TOYOTA 20846 | 4 | |
| NZ177 | Ford Falcon 200 | Sump sides pair | SUMP SIDES FORD ARC8DE-6710-A | 8 | |
| NZ178 | Lada | Misc gsk | MISC GSK LADA 21010101423 | 6 | |
| NZ179 | Lada | Carb gsk | MISC GSK AVTO IMP.210101107015 | 6 | |
| NZ180 | Lada | Water outlet gsk | OUTLET FLANGE GSK AVTO IMP. | 4 | |
| NZ181 | Lada | Misc gsk | MISC GSK AVTO IMP.210101307048 | 5 | |
| NZ189 | Holden 6 | Cork ring (s/plugs) | Misc gask Holden 6 7401140 | 2 | \$ 1.50 |
| NZ192 | Toyo | Carb gsk | CARB GSK TOYOTA 21911-63010 | 72 | |
| NZ193 | | A/filter gsk | | 7 | |
| NZ195 | | Copper washer | WASHER 22636-W4200 | 11 | |
| NZ198 | Niss | Misc gsk | MISC GSK NISSAN/HOLDEN | 16 | |
| NZ199 | Dai | Fuel pump gsk | Fuel pump gsk Daihatsu | 25 | |
| NZ200 | Dai | Fuel pump gsk | Fuel pump gsk Daihatsu | 3 | |
| NZ204 | Ford V4/6 | MGI end cork | PART OF JA747/8 (2724E-9A424) | 177 | \$ 3.00 |
| NZ205 | Ford V4/6 | MGI end cork | PART OF JA747/8 (2724E-9A425) | 190 | \$ 3.00 |
| NZ207 | Holden | Mani water outlet gsk | Mani water outlet gsk GM | 6 | |
| NZ213 | IHC | Ex fla gsk large | MISC GSK INT.TRUCKS 304063R1 | 7 | |
| NZ214 | IHC | Ex fla gsk | MISC GSK INT.TRUCKS 304064R1 | 7 | |
| NZ215 | IHC | W/collection pipe gsk | WATER COLLECTION PIPE GSK INT. | 4 | |
| NZ218 | Nissan | Misc gsk | MISC GSK NISSAN 32112-E9001 | 4 | |
| NZ220 | Toyo | Misc gsk | Misc gask Toyota 33132-30030 | 6 | |
| NZ221 | Toyo | Misc gsk | MISC GSK TOYOTA 33142-26010 | 8 | |
| NZ229 | Simca | Carb gsk | CARBURETTOR GSK SIMCA 38450F | 6 | |
| NZ232 | Toyo | Misc gsk | MISC GSK TOYOTA 42181-12010 | 8 | |
| NZ233 | Toyo | Misc gsk | MISC GSK TOYOTA 42181-30010 | 13 | |
| NZ234 | Toyo | Misc gsk | MISC GSK TOYOTA 42181-35010 | 68 | |
| NZ235 | Toyo | Diff carrier gsk | DIFF.CARRIER GSK TOYOTA | 7 | |
| NZ236 | | | | | |
| NZ238 | Toyo | Misc gsk | MISC GSK TOYOTA 42443-55020 | 7 | |
| NZ240 | Toyo | Misc gsk | MISC GSK TOYOTA 43422-60010 | 6 | |
| NZ241 | Dai | Misc gsk | MISC GASKET DAI.45435-26010 | 14 | |
| NZ243 | Norwood | Misc gsk | MISC GSK NORWOOD 512787M2 | 1 | |
| NZ244 | Norwood | Misc gsk | MISC GSK NORWOOD 521181M1 | 6 | |
| NZ246 | | O ring | O RING | 62 | |
| NZ248 | | O ring | O RING | 47 | |
| NZ249 | GM | Side cover gsk | SIDE COVER GSK GM 607500 | 5 | |
| NZ250 | GM | Cam cover gsk | CAMSHAFT COVER GSK GM 638602 | 4 | |
| NZ251 | Bedford 500 | Dowel pin | G M 6397142 | 71 | |
| NZ254 | GM | Emulsion block gsk | EMULSION BLOCK GSK GM 7086882 | 23 | |
| NZ255 | BMC "O", GM | Carb gsk | CARBURETTOR GSK GM 7195926 | 18 | |
| NZ259 | Holden V8 | Sump front rubber | FRONT SUMP SEAL HOLDEN V8 square | 73 | |
| NZ260 | Holden V8 | Sump rear rubber | rounded corners | nil | |
| NZ261 | Holden V8 | Gsk -water outlet? | | 1 | |
| NZ268 | Ford Falcon CIH X/F (HA303?) | Mani gsk Inlet | IN.MAN.GSK FORD 76DA-9461-AB | 91 | \$ 7.00 |
| NZ269 | Ford Falcon CIH X/F | Foam | FORD 76DA-9A641-A | 1 | |
| NZ270 | | Misc gsk | ON DELETION 2237 | 6 | |
| NZ271 | | Mani gsk -exh? | ON DELETION 2237 | 7 | |
| NZ272 | | Misc gsk | ON DELETION 2237 | 8 | |
| NZ277 | Subaru | Therm gsk | THERM.GSK SUBARU 81755-4120 | 17 | |
| NZ279 | Norwood | Felt strip | MISC GSK NORWOOD 825220M1 | 14 | |
| NZ281 | Norwood | Misc gsk | MISC GSK NORWOOD 825931M1 | 16 | |
| NZ283 | Norwood | Ex fla | EX.FLANGE GSK NORWOOD 827877M | 7 | |
| NZ284 | GM | Carb gsk | MISC GSK GM 832528 | 8 | |
| NZ285 | GM | Hot box gsk 80mm x 87mm O | INLET TO EXH MANIFOLD GSK GM | 7 | \$ 10.00 |
| NZ286 | GM | Ex gsk | MISC GSK GM 854835 | 6 | |
| NZ287 | Ford Falcon EB- | Therm rubber ring | EB-FALCON T/STAT O RING | 75 | |
| NZ288 | Isuzu 161Z, 180Z | Mani gsk 1&2 cyl | 1 & 2 CYL.INL MANIFOLD GSK GM | 4 | |
| NZ290 | Isuzu 161Z, 180Z | Mani gsk Inlet #4 cyl | NO.4 CYL.INLET MANIFOLD GSK GM | 5 | |
| NZ295 | | Carb gsk | HEAT INSULATOR GASKET | 12 | |
| NZ299 | GM | Carb gsk | CARB FACING G.M.90080100F | 277 | |
| NZ300 | Toyo | Steel washer | TOY. 5/16X5/8" ZINC PL ST WASH | 6 | |
| NZ302 | Toyo | Rubber ring flat | 35MM X 51MM TOYOTA 90341-25054 | 10 | |
| NZ307 | Daihatsu Delta | Exh fla gsk | EX.FLANGE GSK.DELTA DAIHATSU | 4 | |
| NZ310 | Honda | Oil seal | HONDA OIL SEAL"91203-PR4-004" | 380 | |
| NZ311 | GM | Rear seal retainer gsk | RETAINER TO BLOCK GSK GM | 7 | |
| NZ312 | | O ring | O RING 91324-PC6-000 | 31 | |
| NZ313 | | Therm gsk | THERMOSTAT GSK GM 92013634 | 12 | |
| NZ314 | GM | Adapter to head gsk | ADAPTOR TO CYL.HEAD V.H. GM | 62 | |
| NZ316 | Holden? | O ring | 'O' RING 2.5mmX65mmX70mm | 41 | |
| NZ317 | Holden V8 308, 253 | Oil pickup gsk | OIL FEED TO PICK UP GSK. | 13 | |
| NZ318 | | Therm gsk | WATER OUTLET GSK.94209872 | 10 | |
| NZ319 | GM | Erg valve gsk | ERG.VALVE GSK GM 9933112 | 20 | |
| NZ320 | Holden V8 (2 required) | Mani gsk Exh | | 9 | \$ 4.00 |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|-------|-----------------------------------------|------------------------------|------------------------------------|-------|----------|
| NZ322 | GM | Misc gsk | MISC GSK GM 9947224 | 11 | |
| NZ323 | GM | Exh gsk | MISC GSK GM 9947754 | 9 | |
| NZ325 | Chrysler Hemi 6 | Rubber ring flat | MISC GSK MITS. A2536626 | 9 | |
| NZ326 | Chrysler Hemi 6 | | Flange gasket Mits. A3543247 | 3 | |
| NZ327 | Ford | Misc gsk | MISC GSK. ARC6DR-7051A | 6 | |
| NZ329 | Ford | Misc gsk | MISC GSK. ARC6DR-7A036A | 4 | |
| NZ330 | Ford Falcon | Front cover gsk -long ends | MISC GSK FORD ARC8DE-6020-A | 11 | \$ 12.00 |
| NZ331 | Ford | Misc gsk | FORD MISC.GSK.ARC8DE-9455-A | 11 | |
| NZ332 | Ford | Fuel pump gsk | MISC GSK FORD ARC9DE-9417-A | 14 | |
| NZ334 | Leyland P76 V8 | Carb gsk | CARBURETTOR GSK NZMC AYD102 | 14 | \$ 4.00 |
| NZ335 | Leyland P76 V8 | Therm gsk | WATER OUTLET GSK NZMC AYD104 | 1 | \$ 5.00 |
| NZ336 | BMC | Sump sides | SUMP SIDES NZMC AYH3106/7 | 3 | |
| NZ337 | BMC | Misc gsk | MISC GSK NZMC AYH403 | 3 | |
| NZ338 | Austin Kimberley, Aus Marina | Therm gsk | WATER OUTLET GSK NZMC AYH451 | 1 | |
| NZ340 | | Rear seal retainer gsk | O SEAL RETAINER B630-11-318 | 6 | |
| NZ342 | Ford | Therm gsk | WATER OUTLET CONNECTION FORD | 6 | |
| NZ343 | Chrysler V8 318, 360 | Mani gsk Inlet | INTAKE GASKET CHRYSLER V8 | 13 | \$ 10.00 |
| NZ344 | Chrysler Valiant slant 6 | Misc gsk | MISC GSK MITS. C2596174 | 17 | |
| NZ346 | Chrysler Hemi 6 | Misc gsk | MISC GSK MITS.C2899082 | 3 | |
| NZ348 | Ford | Misc gsk | MISC GSK FORD C30E-9447 | 9 | |
| NZ349 | Mits | Rocker cover gsk | MITS.ROCKER COVER GSK C3427541 | 1 | |
| NZ353 | Ford Falcon | Fuel pump gsk | F/P GASKET C3DE-9417-A | 21 | |
| NZ354 | Ford | Fuel pump gsk | MISC GSK FORD C3TE-9417-A | 22 | |
| NZ355 | Ford Truck 240, 300 petrol | Side cover gsk | SIDE PLATE GASKET FORD "D" PET | 20 | \$ 15.00 |
| NZ356 | Ford Truck 240, 300 petrol | Rubber ring flat 51 x 33 x 3 | MISC GSK FORD C5AE-6789-A | 12 | \$ 10.00 |
| NZ359 | Ford Truck 240, 300 petrol 5/16", .9" C | Valve seal -umbrella | VALVE STEM SEALC5AZ-6571-D | 384 | \$ 2.00 |
| NZ361 | Ford Truck 240, 300 petrol | Oil seal rear | MISC GSK.FORD C5AZ-6701-B | 88 | \$ 25.00 |
| NZ365 | Ford | Sump? | MISC GSK FORD C5NN-4N507-A | 13 | |
| NZ366 | Ford | Misc gsk | MISC GSK.C5NN-7N057-A | 11 | |
| NZ368 | Ford Truck 240, 300 petrol | Valve seal? | FORD C5TZ-6571-A | 4 | |
| NZ369 | Ford Truck 240, 300 petrol | Carb or air cleaner gsk? | MISC GASKET FORD C5TZ-9447-C | 7 | |
| NZ370 | Ford Truck 240, 300 petrol | Valve cover gsk | | 1 | \$ 20.00 |
| NZ372 | Ford | Oil pickup gsk | OIL PUMP TO BODY GSK FORD | 10 | |
| NZ374 | Ford | Misc gsk | MISC GSK FORD C9DE-6625-A2 | 35 | |
| NZ376 | Ford | Misc gsk | MISC GSK FORD D6NN-867-A | 18 | |
| NZ377 | | | FRONT COVER GASKET FORD | 21 | |
| NZ378 | Ford V8 Cleveland | Mani gsk Inlet pair | MANIFOLD GSK FORD DOAZ-9433 | 1 | |
| NZ379 | Ford | Distr gsk | DISTRIBUTOR GSK FORD LASER | 240 | |
| NZ381 | Ford Tractor 4 cyl 5000 etc -extra hole | Sump gsk | SUMP GSK.E9NN-6710-AB | 6 | \$ 20.00 |
| NZ383 | Ford | Misc gsk | MISC GSK FORD | 6 | |
| NZ386 | Simca | Mani gsk Inlet | INTAKE MANIFOLD GSK SIMCA | 3 | |
| NZ387 | Mazda | Rear cover gsk | REAR COVER GSK MAZDA | 181 | |
| NZ388 | Mazda | Hsg rear cover gsk | HOUSING REAR COVER GSK MAZDA | 292 | |
| NZ389 | Mazda | Hsg front cover gsk | HOUSING FRONT COVER GSK MAZDA | 465 | |
| NZ390 | Mazda | Misc gsk | MISC GSK MAZDA F801-10-229NZ | 532 | |
| NZ392 | Mazda | Oil pickup gsk | OIL STRAINER GSK MAZDA | 8 | |
| NZ393 | Mazda | Water pump gsk | WATER PUMP GSK MAZ.F80115165NZ | 47 | |
| NZ398 | Mazda | Carb gsk | CARB.GSK MAZDA FE05-13-316ANZ | 16 | |
| NZ400 | Austin Maxi??? | Rocker cover gsk | ROCKER COVER GSK NZMC GEG463 | 9 | |
| NZ401 | | Stub axle gsk | STUB AXLE GASKET (277289) | 21 | |
| NZ403 | BMC | Misc gsk | MISC GSK NZMC GFG117 | 8 | |
| NZ404 | BMC | Therm? Gsk | MISC GASKET NZMC GTG120 | 16 | |
| NZ411 | Mits | Carb gsk | CARB.GSK.MITS.JCMD003164 | 7 | |
| NZ415 | Mits | Oil pump cover gsk | OIL PUMP COVER GSK MITSUBISHI | 5 | |
| NZ416 | Mits | Ring gsk | | | |
| NZ426 | Mits | Oil pump gsk | MISC GSK MITS.JCMD021557 | 1 | |
| NZ427 | Mits | Oil pump gsk | OIL PUMP GSK MITS.JCMD021559 | | |
| NZ431 | Mits | Oil filter hsg gsk | OIL FILTER BRACKET GSK MITSUBI | 115 | |
| NZ437 | Mits | Oil pump cover gsk | OIL PUMP CASE GSK MITSUBISHI | 2 | |
| NZ439 | Mits | | OIL FUEL BRACKET GSK MITSUBISHI | 2 | |
| NZ443 | | | ON DELETION 2232 | 237 | |
| NZ444 | | Sump gsk | OIL PAN GSK.JCMD739236/R | 11 | |
| NZ448 | | Water pump gsk | WATER PUMP GSK PIONEER | 9 | |
| NZ560 | GM | Therm gsk | GM 6308878 (X4063) | 115 | |
| NZ561 | Ford Falcon 250 | Water pump gsk | WATER PUMP GSK.FORD XB-8507-A | 10 | |
| NZ626 | Isuzu G161Z, G180Z, G200Z | Mani gsk Inlet | INLET MANIFOLD GSK (pair is HA345) | 142 | |
| NZ628 | diesel? | Front plate gsk | FRONT PLATE GSK.11328-56041000 | 34 | |
| NZ629 | | O ring | O RING | 132 | |
| NZ630 | Leyland 400 | Inj washer | WASHER,INJECTOR NJJ1014 | 200- | |
| NZ816 | Bedford 500 | Intake gsk? | | 1 | |
| NZ997 | BMC | Oil seal | 65x83x8 542492 | 1 | |
| NZ997 | Rover 2.25, 2.6 & 3 litre 1958-67 | Rear seal kit | 63.5x83.2x8 (2.5"x3.276"x.315") | 1 | \$ 40.00 |
| P1305 | | Oil seal -Repco | Payen# C332 | 3 | |
| P1577 | | Oil seal -Repco | Payen# | 1 | |
| P2056 | | Oil seal -Repco | Payen# D578 | | |
| P2057 | | Oil seal -Repco | Payen# C911 | 1 | |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|--------|--------------------------|---------------------------------|----------------------------------------|-------|-------|
| P2213 | Vauxhall 1948-57 | Oil seal -Repco Transm. Rear | Payen# C505 | | |
| P2404 | | Oil seal -Repco | Payen# C574? | | |
| P2491 | | Oil seal -Repco | Payen# C889 | 1 | |
| P2492 | | Oil seal -Repco | Payen# C896 | 2 | |
| P2493 | | Oil seal -Repco | Payen# C897 | 1 | |
| P2493 | | Oil seal -Repco | Payen# C988 | 1 | |
| P2494 | | Oil seal -Repco | Payen# B532 | 3 | |
| P2625 | | Oil seal -Repco | Payen# C617 | 2 | |
| P2641 | | Oil seal -Repco | Payen# C720, Flaseal# 11948 | 2 | |
| P3002? | | Oil seal -Repco | Payen# C120? | 1? | |
| P3002? | | Oil seal -Repco | Payen# X157? | 1? | |
| P3003 | | Oil seal -Repco | Payen# | 1 | |
| P3011 | Vauxhall 1948-51 | Oil seal -Repco Front hub (M/L) | Payen# C245 | 1 | |
| P3011 | | Oil seal -Repco Front hub (M/R) | Payen# C385 -alternate to C245 | | |
| P3025 | | Oil seal -Repco | Payen# | 1 | |
| P3029 | | Oil seal -Repco | Payen# | 9? | |
| P3037 | | Oil seal -Repco | Payen# B114 | 2 | |
| P3039 | | Oil seal -Repco | Payen# C155 | 2 | |
| P3087 | | Oil seal -Repco | Payen# C291 | 2 | |
| P3089 | | Oil seal -Repco | Payen# C735 | | |
| P3089 | | Oil seal -Repco | Payen# C736 | | |
| P3117 | | Oil seal -Repco | Payen# C941 | 2 | |
| P3131 | Fiat 128 | Oil seal -Repco Rear crank | Payen# | 1 | |
| P3134 | Vauxhall 1948-57 | Oil seal -Repco Transm. Rear | Payen# C505 | | |
| P3156 | | Oil seal -Repco | Payen# C500 | 1 | |
| P3189 | Rover 211392 | Oil seal -Repco | Payen# B398 | 2 | |
| P3195 | | Oil seal -Repco | Payen# | 1 | |
| P3196 | | Oil seal -Repco | Payen# | 1 | |
| P3260 | | Oil seal -Repco | Payen# C459 | 1 | |
| P3274 | | Oil seal -Repco | Payen# | 2 | |
| P3275 | | Oil seal -Repco | Payen# X124 | 2 | |
| P3284 | Wolseley 6/80 | Oil seal -Repco Pinion | Payen# C520 | | |
| P3316 | | Oil seal -Repco | Payen# C600? | 1 | |
| P3420 | | Oil seal -Repco | Payen# B269 | 1 | |
| P3450 | | Oil seal -Repco | Payen# B273? | 1 | |
| P3477 | | Oil seal -Repco | Payen# C674 | 4 | |
| P3481 | | Oil seal -Repco | Payen# C680 | 2 | |
| P3491 | | Oil seal -Repco | Payen# B309 | 2 | |
| P3511 | | Oil seal -Repco | Payen# | 2 | |
| P3540 | Holden SP | Oil seal -front crank | Payen# | 1 | |
| P3570 | | Oil seal -Repco | Payen# | 3 | |
| P3575 | | Oil seal -Repco | Payen# | 1 | |
| P3583 | | Oil seal -Repco | Payen# C797 | 1 | |
| P3636 | | Oil seal -Repco | Payen# C352 | 1+ | |
| P3637 | | Oil seal -Repco | Payen# E210 | 1 | |
| P3811 | | Oil seal -Repco | Payen# C780 | 2 | |
| P3830 | | Oil seal -Repco | Payen# B401 | 1 | |
| P3860 | | Oil seal -Repco | Payen# D430 | 1 | |
| P4070 | | Oil seal -Repco | Payen# 11471 | 2 | |
| P4152 | | Oil seal -Repco | Payen# 14198 | 1 | |
| P4351 | | Oil seal -Repco | Payen# | 1 | |
| P4501 | | Oil seal -Repco | Payen# B or D521 | 1 | |
| P4557 | | Oil seal -Repco | Payen# D576 | 2 | |
| P4561 | | Oil seal -Repco | Payen# | 1 | |
| P4595 | BMC "C" | Oil seal -Repco Front hub | Payen# C941 | 1 | |
| P4658 | Vauxhall Viva HA, HB, HC | Rear gearbox seal | 1.125"x1.756/1.679"x2.25"long GM#27078 | 1 | |
| P4659 | | Oil seal -Repco | Payen# L115 | 1? | |
| P4666 | | Oil seal -Repco | Payen# C947 | 1 | |
| P4668 | | Oil seal -Repco | Payen# B538 | 1 | |
| P4781 | | Oil seal -Repco | Payen# | 1 | |
| P4788 | | Oil seal -Repco | Payen# | 1 | |
| P5005 | | Oil seal -Repco | Payen# X126 | 3 | |
| P5067? | | Oil seal -Repco | Payen# S291 | 1 | |
| P6177 | | Oil seal -Repco | Payen# C1014 | 1 | |
| P6203 | | Oil seal -Repco | Payen# | 1 | |
| P6394 | | Oil seal -Repco | Payen# D660 | 3 | |
| PA021 | Toyota 5R, 12R, 2F | Valve seal -cup | | 11 | |
| PA079 | Nissan SR20DET, CD20 | Valve seal | | 26 | |
| PA086 | VW | O ring | V.W. 052-905-261 | 21 | |
| PA138 | Toyo L, 2L | Valve seal | | 8 | |
| PA153 | Holden 4 | O ring | RUBBER 'O' RING | 40 | |
| PA154 | | valve seal | | some | |
| PA155 | GM | O ring | G.M. 90106456 | 11 | |
| PA185 | GM | O ring | G.M. 90128513 | 49 | |
| PA203 | Nissan E15 | Valve seal | | 8 | |
| PA208 | Isuzu 4B/6B | Valve seal | | 12 | |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|--------|---------------------------|-------------------------|------------------------------------|---------|---------|
| PA273 | Holden | Side cover bolt seal | HOLDEN.SIDE PLATE BOLT WASHER | 1 | \$ 0.80 |
| PA286 | Honda EJ inl (brown) | Valve seal | | 4 | \$ 4.00 |
| PA288 | Honda 80-84 | Valve seal | Exh, green | 4 | |
| PA305 | Suzuki | Valve seal | | 26 | |
| PA313 | | Valve seal | | 4 | |
| PA314 | Honda | O ring | HONDA 91302-657-000 | 1 | |
| PA342 | Honda & Suzuki | O ring | HONDA 91302-317-700 | 21 | |
| PA344 | Toyo 4K (some) | V/cover bolt seal | larger than KH199 | 2 | |
| PA373 | Honda aux. | Valve seal | | 24 | \$ 4.00 |
| PA375 | Honda | Valve seal | V SEAL O RING HH 91301-657-000 | 25 | |
| PA378 | Nissan TD engs & late SD | Valve seal | 8mm x 12mm(guide) (early is KJ452) | 8 | |
| PA387 | Daihatsu CB | Valve seal | | 8 | \$ 4.00 |
| PA391 | BMC "O" series | Valve seal | | 30 | \$ 5.00 |
| PA392 | Honda | O ring | HONDA 91303-634-010 | 33 | |
| PA425 | Toyota 4SFE, Mazda B3, Z5 | Valve seal | | 24 | |
| PA426 | Mazda | Valve seal | | 8 | \$ 4.00 |
| PA441 | Honda | O ring | O RING.HONDA 91306-634-000 | 168 | |
| PA468 | Mitsubishi 4DR5 late | Valve seal | | ? | |
| PA5004 | Mitsubishi 6A11, 6A12 | Valve seal -inl | | 6 | |
| PA525 | Mitsubishi 4D30 | Valve seal | | 5 | |
| PA529 | Honda B20A Exh | Valve seal | | yes | \$ 3.00 |
| PA551 | Nissan Patrol "P" | Valve seal | | 12 | \$ 3.00 |
| PA552 | | O ring | O' ring 90043-01043 | 67 | |
| PA554 | | Fuel pump gasket washer | FUEL PUMP GASKET | 346 | |
| PA555 | Dai | Distr O ring | DISTRIBUTOR O RING 90043-01037 | 20 | |
| PA564 | Honda | O ring | HONDA 91307-611-000 | 57 | |
| PA567 | | Valve seal | | 2 | |
| PA581 | Mazda KL, FE | V/cover bolt seal | | 7 | |
| PA622 | Nissan Patrol P40 | Valve seal | (Or PA860?) | 12 | |
| PA632 | Bedford CF | Valve seal -inl | GM RUBBER VALVE STEM SEAL | 216 | \$ 5.00 |
| PA655 | Subaru EA81 | Valve seal | | 7 | |
| PA657 | Toyo | Washer gsk | TOYOTA WASHER 90430-25013 | 15 | |
| PA709 | | Valve seal | | 4 | |
| PA722 | Mits | Alloy washer | | 16 | |
| PA746 | Mits | O ring | RUBBER OIL SEAL JCMD050461 | 36 | |
| PA751 | Mits | Rubber ring | RUBBER GASKET JCMD050128 | 37 | |
| PA757 | | O ring -water pipe | WATER PIPE 'O' RING | 134 | |
| PA761 | Subaru EJ20, EJ25 etc | Rocker cover bolt seals | | 25 | |
| PA775 | Mits? | Diff Case gsk | JCMB092375 | 9 | |
| PA788 | Honda | O ring | HONDA O RING 56.1 X 2.0 | 11 | |
| PA790 | Toyo 4AF, 4AFE | Rocker bolt seal | | 4 | |
| PA796 | Nissan | O ring | NISSAN O RING 22180-01E00 | 16 | |
| PA803 | Nissan | Oil filter rubber ring | OIL FILTER GSK 15270-D0103 NIS | 153 | |
| PA808 | Toyo 2L | Inj washer? | FUELWASHERS TOYOTA 2L | 115 | |
| PA842 | | Alloy washer | HEAD PLUG S 80391-2030 | 17 | |
| PA844 | Daihatsu CB | Rocker bolt seal | ROCKER BOLT SEAL DAIHATSU CB | 47 | |
| PA846 | Mazda | Alloy washer | MAZDA 9956-41-400NZ | 70 | |
| PA853 | | Drain plug washer | DRAIN PLUG GSK.S 31168-0100 | 10 | |
| PA856 | Isuzu C190, C223, C240 | Rocker bolt rubber | | 6 | \$ 3.00 |
| PA858 | | Rocker bolt rubber | | 1 | |
| PA860 | See PA622 | | | | |
| PA873 | Honda ZC | Spark plug seal | | 4 | \$ 5.50 |
| PA874 | Nissan SR20DET | Valve seal | | 8 | |
| PA881 | Toyo | O ring | O RING TOYOTA 96732-31060 | 16 | |
| PA882 | | Valve seal | | 7 | |
| PA883 | Mazda | Valve seal 7? X 12 | | 8, Lots | |
| PA908 | | W/bypass gsk | WATER BYPASS GSK.F E301-15-287 | 273 | |
| PA913 | Ford EA | Valve seal | | yes | \$ 5.00 |
| PA930 | Niss | O ring | OIL RING | 6 | |
| PA946 | | O ring | SUCTION PIPE GSK 96721-19020 | 69 | |
| PA956 | Mazda FE | Valve seal | | 16 | |
| PA966 | | Seal | OIL SEAL S 80693-8020 | 5 | |
| PA968 | Mitsubishi 6G71 | Valve seal | | 24 | |
| PA970 | Honda | Valve seal | | 8 | |
| PA979 | Honda | O ring | O RING.HONDA 91315-634-000 | 25 | \$ 4.00 |
| PA984 | Honda EG/EK/EN | W/pump O ring | | 23 | |
| PA986 | Mitsubishi 4G54 etc | O ring | O RING D 22131-78501 | 28 | |
| PB002 | | O ring | O RING D 22180-D0100 | 5 | |
| PB020 | | O ring | ON DELETION 1862 | 19 | |
| PB022 | | O ring | ON DELETION 1862 | 20 | |
| PB053 | Dai | Alloy washer | WASHER DAIHATSU 90044-30042 | 25 | |
| PB054 | | O ring | O RING | 12 | |
| PB055 | | O ring | O RING | 12 | |
| PB106 | | O ring | O RING | 15 | |
| PB121 | Honda | O ring | O RING HONDA 91301-PB9-000 | 3 | |
| PB146 | Toyota 6R | Rubber | TOYOTA 90480-18180 | 113 | |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|---------|----------------------------------------|--------------------------|---------------------------------|-------|----------|
| PB147 | Nissan | Copper washer | WASHER NISSAN 11026-01M02 | 9 | |
| PB150 | | Alloy washer -drain plug | DRAIN PLUG WASH.HH 94109-20000 | 44 | |
| PB157 | | | O RING | 165 | |
| PB159 | | Rocker bolt washer? | WASHER | 12 | |
| PB183 | Toyo | Fuel pipe gsk | FUEL PIPE GSK. TOY.90430-12011 | 1159 | |
| PB270 | Dai | Sump plug gsk | SUMP PLUG GASKET DAIHATSU | 218 | |
| PB285 | Toyota 4SFE | Spark plug seal | | 4 | |
| PB288 | Honda ZC | Rocker bolt seal | | 4 | \$ 4.00 |
| PB300 | Honda | Copper washer | VALVE HOLDER 14777-PC6-000 HON | 341 | |
| PB301 | Honda | O ring | O RING 91303-PC6-000 HONDA | 20 | |
| PB302 | | V/seal O | VALVE GUIDE O RING 91301PC6004 | 460 | |
| PB345 | Toyo 4AGE | Rocker bolt seal | | 2 | |
| PB347 | Toyo 2C | Rocker bolt seal | R.C. SEAL TOTOTA 2C | 310 | |
| PB355 | Honda F22B SOHC | Valve seal | | 4 | |
| PB356 | Honda F22B SOHC | Valve seal | | 4 | |
| PB382 | Mazda | Water pump gsk | WATER PUMP GSK MAZDA | 171 | |
| PB449 | Suzuki | Sump washer gsk | SUMP WASHER SUZUKI 09168-12007 | 19 | |
| PM1922E | | Collet cover 22 mm pipe | | 17 | |
| PNZ061 | Mits | | | 1 | |
| PNZ072 | GM | Sump sides LH&RH | L.H & R.H. SUMP SIDES GSKS G.M | 11 | |
| PNZ186 | Bedford | Inj pump gsk?) | Components of set 91093363 | 1 | |
| PNZ187 | Bedford | Inj pump gsk?) | Components of set 91093363 | 2 | |
| PNZ195 | Ford V4/6 | MGI copper disc | SQUARE CENTRE DISC FOR JA747/8 | 204 | \$ 3.00 |
| PNZ196 | Ford V4/6 | MGI copper disc | COPPER WASHER FOR JA747/8 | 700 | \$ 3.00 |
| PNZ239 | Ford Falcon CIH X/F | Mani gsk Exh | See HA048 | 1 | |
| PNZ263 | | Exhaust gsk | | 1 | |
| PNZ264 | Mits | Ex fla gsk | MIT.S.EXH.FLANGE/G JCMB687013/R | 12+2 | |
| PNZ266 | Chrysler V8 318, 360 | Mani gsk Exh | EX.MANIFOLD GASKET V8. | 5 | \$ 15.00 |
| PNZ267 | Ford V8 Cleveland | Mani gsk Exh Extractor | DFS27 or HSM27 | 11 | \$ 10.00 |
| PNZ268 | Mazda 626 | Baffle gsk | BAFFLE 626/TELSTR F80110229ANZ | 268 | |
| PNZ269 | Toyo | Fuel pump gsk | FUEL PUMP GSK.TOYOTA | 5 | |
| PNZ271 | | Misc gsk | ON DELETION 2237 | 91 | |
| PNZ272 | | Therm gsk | THERMOSTAT GSK SAMPLE H.PAYEN | 110 | |
| PNZ326 | Mazda F8, FE | Front cover gsk | | 20 | |
| PNZ330 | Mazda FE | Ex fla? | | 1 | |
| PNZ331 | Ford Falcon EA, EB | Ex header tail gsk | EA/EB HEADER TAIL GASKET | 64 | |
| PNZ334 | Toyota 1Y, 2Y, 3Y | Water outlet gsk | Water outlet housing gsk | 182 | |
| PNZ337 | 55mm | Therm gsk | T/STAT GSK BLANK 55mm 1D | 10 | |
| PNZ338 | 53mm | Therm gsk | T/STAT GSK BLANK 53mm 1D | 23 | |
| PNZ339 | 49mm | Therm gsk | T/STAT GSK BLANK 49mm 1D | 102 | |
| PNZ340 | 44mm | Therm gsk | T/STAT GSK BLANK 44mm 1D | 53 | |
| PNZ359 | Nissan L16, L18 | Oil pump cover gsk | OIL PUMP GSK | 58 | |
| PNZ360 | Toyo | Oil pump cover gsk | OIL PUMP GSK TOYOTA | 676 | |
| PNZ367 | BMC | Oil filter hsg gsk | | | |
| PNZ370 | Toyota | Mani gsk | | 2 | |
| PNZ371 | Honda | Misc gsk | MISC.GSK | 14 | |
| PNZ372 | Honda | Misc gsk | MISC. GSK. HH16215-PE8-600 | 36 | |
| PNZ378 | Ford V6 | MGI part ("D" port) | F 722M-3441-AA (PART OF JA748) | 19 | \$ 10.00 |
| PNZ379 | Ford V4 | MGI part | F 702M-9A454-BA (PART OF JA747) | 35 | \$ 10.00 |
| PNZ389 | | 3 gsks | | 4 | |
| PNZ390 | | W/pump gsk? | | 1 | |
| PNZ391 | | W/pump gsk? | | 1 | |
| PNZ392 | Honda | Transm gsk | TRANSMISSION GASKET HONDA | 2 | |
| PNZ393 | Honda | Transm gsk | TRANSMISSION GASKET HONDA | 15 | |
| PNZ408 | | Mani gsk Inlet | plus JC401 = GT252 | | |
| PNZ437 | | Baffle gsk | BAFFLE PLATE GASKET | 22 | |
| PNZ439 | | Carb gsk | CARB GASKET | 10 | |
| PNZ445 | Mazda 626 | Water pump gsk | WATER PUMP GSK MAZDA 626 12V | 6 | |
| PNZ454 | | Therm gsk large | WATER OUTLET GASKET | 79 | |
| PNZ455 | Mazda TC | Misc gsk | MISC GSK. MAZDA TC | 7 | |
| PNZ458 | Mazda B6 | Fuel pump gsk | FUEL PUMP GSK. MAZDA B6 | 7 | |
| PNZ459 | Mazda B6 | Misc gsk | MISC GSK. MAZDA B6 | 4 | |
| PNZ464 | Nissan | Carb gsk | CARB GSK.NISSAN | 110 | |
| PNZ465 | Nissan | Carb gsk | CARB GSK.NISSAN | 195 | |
| PNZ487 | | | MISC.GSK. | 21 | |
| PR0177 | | Oil seal (also 97239) | 48x62x8 | 2 | |
| PR0736 | | Oil seal (also 97226) | 40x75x12 | 2 | |
| PR0767 | | Oil seal (PR6205?) | 1.937"x2.686"x.500" | 1 | |
| PR2157 | Transfer case, wheel seal | Oil seal | 1.375x2.250x.375 | 50 | \$ 10.00 |
| PR2436 | | Oil seal -Repco | Payen# | 2 | |
| PR2505 | | Oil seal | 1.120x1.870x.375 | 1 | |
| PR4069 | Austin 8, Austin 10 (smaller is KG065) | Oil seal -felt | 1.7/8" x 2.9/16" x 11/32" | | \$ 12.00 |
| PR4765 | | Oil seal (TC12191) | 2.375x2.875x.312 | 7 | |
| PR4978 | | Oil seal (=NB123?) | 88?x105x10 | 1 | |
| PR5138 | | Oil seal | 2.000x3.125x.375 | 7 | |
| PR6061 | BMC Marina 6? | Oil seal | 40x59/67x10 | 1 | |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|-----------|---------------------------------------|----------------------------|-------------------------------------------|-------|----------|
| PR6120 | BMC | Oil seal | 55x70x10 | 1 | |
| PR6140 | Tractor | Oil seal | 2.250x3.000x.375 | 2 | |
| PR6181 | | Oil seal | 2.062x2.750x.375 | 1 | |
| PR6202 | | Oil seal | 47?x70x9 | 2 | |
| PR6205 | | Oil seal | 48x70x9 | 1 | |
| PR6234 | | Oil seal | 1.37x2x.437 | 7 | |
| PR6288 | Chev 235 | Oil seal | 2 piece neoprene seal (Rope is KS723) | | |
| PR6293 | | Oil seal | 1.260x1.812x.315 | 2 | |
| PR6295 | | Oil seal | 1.750x2.375x.375 | 2 | |
| PR6312 | Austin Maxi, Allegro | Oil sear rear | 2.853x3.625x0.5" -Use NB289 | | |
| PR6350 | | Oil seal | 1.875x2.570x.500 | 1 | |
| PR6350 | | Oil seal (also 97071) | 1.875x3.141x2.570x.625 | 1 | |
| PR6365 | | Rear seal -rope | | 1 | |
| PR6407 | | Oil seal | 1.75x2.35x.25 | 1 | |
| PR6487 | Vauxhall Viva | Oil seal 3.000x3.875x.465 | 3"x3.875"x.465" | | |
| PR6502 | Mazda 323/Laser 81- Rear | Oil seal 40x54x5.5 | 40x54x5.5 | 1 | |
| PR6695 | | Oil seal | | 1 | |
| PR7001 | Volvo? | Oil seal | 52x68x10? | 2 | |
| PR7002 | | Oil seal | 4"x5"x3/8" | 0 | |
| PR7020 | | Oil seal | 80x96x9? | 1 | |
| PR7081 | | Oil seal | 39x51x7.5 | 10 | |
| PR7107K | | Oil seal | 52x68x13 | 1 | |
| PR7215 | Ford Falcon | Oil seal | 108mm OD (NZ552) | | |
| PR8277 | Mits L300 front wheel | Oil seal 45x62x6 | 45x62x6 | 1 | |
| PS-11 | 3/8" valve seals (.562" guide OD) | Valve seal -umbrella kit | Hastings 16 x 3/8" seals with installer | 23 | \$ 40.00 |
| PS-2 | 5/16" valve seals (.502" guide OD) | Valve seal -umbrella kit | Hastings 12 x 5/16" seals with installer | 36 | \$ 30.00 |
| R71267895 | | Mani gsk | INDUCTION & EX.MAN.GSK MI 1830 | 5 | |
| RC0001 | Mazda ZB (with alloy rocker cover) | Rocker cover gsk -rubber | Earlier engines with tin R/C use cork gsk | 2 | \$ 25.00 |
| RC0023 | Ford V8 EFI | Rocker cover gsk | | 2 | |
| RC3000 | Isuzu G200 DOHC | Rocker cover gsk | | 1 | \$ 25.00 |
| RC3008 | Nissan TD42 | Rocker cover gsk -rubber | | 1 | |
| RC3011 | Toyo 2C, 3C | Rocker cover gsk -rubber | | 1 | |
| RC3017 | Toyota 1G-EU | Rocker cover gsk -rubber | | 1 | \$ 22.00 |
| RHA60 | Grease Nipple | Grease Nipple | 1/4 GAS 90 Degree | 27 | |
| RMF1230B | Mazda XA (FJ630) | Rear seal -rope | pairs | 6 | |
| S32684R | Mitsubishi 4DR5 | Sump gsk | | 2 | \$ 20.00 |
| S50451 | Ford Trader 380 Dover etc | Fuel pump gsk also KS755 | | | \$ 4.00 |
| S62632N | 50x68x9 | Oil seal | 50x68x9 | 2 | |
| SK18R | Toyota 18R etc | Oil seal kit | NJ030, NJ243, KH061, PB146, KJ127-8 | 1 | |
| SS318 | BMW 318 | Valve seal | | 8 | |
| ST2002BC | Universal -for 3/8" stem, 9/16" guide | Valve seal -umbrella | -grip on guide | 920 | |
| TC110 | Ford Trader 4D, 6D | Front cover/backing plate | JR557 + KT055 | 0 | |
| TC12048 | 1.125x2.062x.375 | Oil seal | 1.125x2.062x.375 | 1 | |
| TC12058 | 1.250x1.875x.375 | Oil seal | 1.250x1.875x.375 | 2 | |
| TC12508 | 32x50x10 | Oil seal | 32x50x10 | 1 | |
| TC12577 | 45x62x8 | Seal | | 1 | |
| TC12631 | 60x90x8 | Oil seal | 60x90x8 | 4 | |
| TC12896 | Nissan Patrol 82 | Seal for hub | | 1 | |
| TC1812 | 1.182x3.000x0.375 | Oil seal 1.182x3.000x0.375 | 1.182x3.000x0.375 | 1 | |
| TC20 | Holden V8 253, 308 | Timing cover set | NA417, NZ258, LS401, NZ261 | 3 | \$ 12.00 |
| TC23 | Holden Camira JE 1987 on | Timing cover set | | 1 | \$ 20.00 |
| TC3 | Nissan Z16, Z20, Z22, Z24 | Timing cover set | NJ045 plus t/cover gsk pair | 1 | |
| TC32 | Mazda B6 SOHC 1985 on | Timing cover set | | 1 | \$ 25.00 |
| TC4 | Holden 4 | Front cover set | | 1 | |
| TC42538 | 42x56x7 | Oil seal | NA582? | 1 | |
| TC450 | Mits | front cover gsk pr | JCM020311/JCM020312 | 1 | |
| TCS21 | Chrysler Hemi 6 | Front seal set | | 1 | \$ 30.00 |
| TCS22 | Nissan J | Timing cover set | | 1 | |
| TCS2309 | Toyota -3C/T | Oil seal -pump | 22x34x6.5 | | |
| TCS32 | Nissan 4 | Timing cover set | | 1 | |
| TCS34 | BMC | Timing cover set | | 1 | |
| TCS576 | 1.375x2.000x.375 | Oil seal 1.375x2.000x.375 | 1.375x2.000x.375 | 1 | |
| TG001 | Ford Falcon | Timing cover set | | 1 | |
| TG002 | Holden 4 & 6 | Front cover set | NA417, KT699, KT702 | 1 | \$ 40.00 |
| TG005 | Mazda | Front cover set | | 1 | |
| TG006 | Nissan A12 etc | Front cover set | | 4 | \$ 5.00 |
| TG007 | Toyota 3K, 4K | Front cover set | NJ719, JR612 | 1 | \$ 25.00 |
| TG008 | Nissan L16, L18 | Front cover set | | 3 | \$ 20.00 |
| TG010 | Mitsubishi 4G32 to 1977 | Front cover set | NJ007, JR649, LA051 | 12 | \$ 20.00 |
| TG011 | Ford Cortina 2.0 | Front cover set | | 1 | |
| TK013 | Mitsubishi 4G63 etc | Front seal set | NJ005,NJ242,NJ255,NJ610,NJ655,JR689, | 11 | \$ 30.00 |
| TSK05 | Mitsubishi 4G32B, 4g37 | Timing seal kit | NJ005P, NJ242P, NJ373, NJ255P | 1 | \$ 20.00 |
| TSK13 | Mazda B series SOHC 16V | Timing seal kit | NK158, NJ448 | 1 | \$ 10.00 |
| TSK17 | Mazda F2, F6, F8, FE | Timing seal kit | NJ324 x 2 | 1 | |
| TSK18 | Mazda K8, KF, KJ, KL | Timing seal kit | NA5033, NJ448 x 2 | 4 | \$ 20.00 |
| TSK19 | Isuzu 4JB1, 4JB1T, 4JG1, 4JG2 | Timing seal kit | NJ014, NJ323 | 4 | \$ 13.00 |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026

LOOSE GASKETS AND SEALS

FEB 2026

| Part# | Vehicle | What | Part Description | Stock | Price |
|-----------------|-------------------------------------|-------------------------|--------------------------------|--------------|-----------------|
| TSK20K | Isuzu 4JG2 1992 on | Timing seal kit | NA5172, NJ323 | 3 | \$ 40.00 |
| TSK22K | Toyota 1C, 2C 1985-90 | Timing seal kit | NJ344V, NJ706, NJ654P | 4 | \$ 35.00 |
| TSK26 | Subaru EJ20, EJ25 etc | Timing seal kit | NK153P, NK117P X 4 | 2 | \$ 30.00 |
| TSK30K | Suzuki G13A, G13B | Timing seal kit | NJ336, NJ377P | 3 | \$ 15.00 |
| TSK37 | Toyota L, 2L, 2LT 1981-88 | Timing seal kit | NJ344 x 2 | 6 | \$ 15.00 |
| TSK45K | Nissan E13, E15, E15-T, E16 | Timing seal kit | NJ288, NJ286, NJ951P | 2 | \$ 18.00 |
| V200 | | Therm gsk | MISC GSK.N.Z.M.C. | 9 | |
| VCK427 | Mitsubishi 4G52, 4G54 narrow block | Rocker cover set | | 1 | \$ 15.00 |
| VPC5113 | Ford Trader? | Oil seal | 2.125"x2.875"x.500" | 1 | |
| VSS128 | round | Valve seal | | 36 | |
| VSS218 | .280"? , 7/8" OD | Valve seal -umbrella | | yes | |
| VSS318 | Ford 5/16" or 11/32"? (.502" guide) | Valve seal -umbrella | -grip on guide | yes | |
| W08 | Toyota 21R | Therm hsg gsk | | yes | |
| WG1 | Universal | Therm hsg gsk | | 228 | \$ 2.00 |
| WG2 | Universal | Therm hsg gsk | | 235 | \$ 2.00 |
| WG3 | Universal | Therm hsg gsk | | 23 | \$ 4.00 |
| WG6 | Universal | Therm hsg gsk | | 358 | \$ 2.00 |
| WP733 | Ford Telstar | Water pump gsk | rubber | 3 | |
| ZD139 | Toyota 2T, 3T, etc (also use KJ466) | Valve seal | VALVE STEM SEAL O.90913-02057 | 563 | |
| ZD167 | | O ring | OIL SEAL O RING GSK.9030165002 | 40 | |
| ZD170 | | O ring | OIL PUMP O RING 96721-24056 | 17 | |
| ZD171 | | Rubber | T/BELT COVER GSK 11328-11040 | 13 | |
| ZD173 | | Copper washer | SUMP PLUG 90430-13002 | 29 | |
| ZD174 | | Alloy washer | SUCTION PIPE GSK O 90430-24246 | 10 | |
| ZG174 | | T/belt cvr rubber strip | T/BELT COVER GSK F8B2-10-512 | 11 | |
| ZG175 | | Front plate gsk | Front plate gsk F210-10-185 | 22 | |
| ZL150 | Honda | Copper washer | MISC GSK HONDA 14777-657-000 | 181 | |
| ZL156 | Honda | Rocker bolt seal | ROCKER BOLT SEAL HONDA | 23 | |
| ZL157 | Honda | Rubber | RUB/TIM.B/COVER.11109-689-000 | 9 | \$ 15.00 |
| ZL159 | | Oil pump gsk | OIL PUMP GSK HH15105-689-010 | 9 | |
| ZL163 | Honda?? | T/belt cvr rubber | T/BELT COVER GSK HH11831PC0000 | 12 | |
| ZL165 | | Oil pump cover gsk | OIL PUMP GSK.HH 15105-PA5-000 | 13 | |
| ZL166 | | Drain plug alloywasher | DRAIN PLUG GSK.HH90443-PA6-003 | 13 | |
| ZL167 | | Inj seal | INJECTOR SEAL | 218 | |
| ZL168 | | Inj seal | INJECTOR SEAL | 230 | |
| ZL169 | | Carb gsk | CARB.GSK.HH16105-PG6-000 | 30 | |
| ZL170 | | O ring -injector | INJECTOR O RING | 82 | |
| ZL171 | | O ring | O RING | 27 | |
| ZQ109 | Subaru | Rubber gsk | INSULATOR BLOCK S 16175-AA020 | 34 | |
| ZQ114 | | Alloy washer | PLUG 80321-6010 | 10 | |
| ZQ115 | | Copper washer | PLUG S 80350-6020 | 9 | |
| ZQ116 | | Alloy washer | PLUG S 80392-6020 | 8 | |
| ZS109 | Suzuki | O ring | O RING SUZUKI 09280-16005 | 20 | |
| | | | | | |
| Part No. | Vehicle | What | Part Description | Stock | Price ea |

Bowden Engine Parts, 40 Bowden Road, Taupo Bay, R.D.1, Mangonui 0494, New Zealand

Phone: (mobile) +64 27 2920461

Email: sales@bowdenengineparts.co.nz

Prepared by Chris Bowden 17/02/2026