

BOWDEN ENGINE PARTS

DEC 2010

OIL PUMPS AND KITS

Fits	Part#	Other	Stock	Price
PUMPS (KITS Listed Below Pumps. DRIVES At Bottom)				
Austin Maxi 1750 OHC	DAS013		✓	\$ 180
Austin Princess 2.0, Marina 1.7 ("O" series)	DAS156	WDC2	✓	\$ 160
Austin Princess 2200	DAS153	VOP199	✓	\$ 160
Bedford 381, 466 (60/70 series)	POL716		✓	
BMC "A" series -slot drive (Pin in camshaft)	POL600		✓	\$ 95
BMC 1300 -star drive	POL621		✓	\$ 95
BMC 1800, Princess 1800 (transverse)	OP46		✓	\$ 140
Daihatsu (housing only, no rotors)	15110-87703		✓?	
Daihatsu Charade G10, G11 to 1987	OPD-G11		✓	
Fiat 128A 1970-77	DAS154		✓	\$ 140
Ford Dover 130 380cu in	DAS124		✓	\$ 250
Ford V6 early (21mm long nose)	DAS132	(VOP103)	✓	\$ 130
Ford V8 289, 302W	M68		✓	\$ 80
Ford V8 351C, 351W	EM84A		✓	\$ 90
GMC V6-305, V6-401, 351,379,432 6cyl (3/8" mounting ho	224-41154		✓	\$ 200
Hillman Side Valve engines	P87428		✓	\$ 180
Holden Rodeo, Jackaroo 2.0, Isuzu Piazza 1951cc	8942156370	(=POL792)	✓	\$ 150
Honda Civic EJ 1335cc	DAS160		✓	\$ 130
Isuzu	8942024631	EM506	✓	\$ 150
Isuzu C190 1983 on	OPI-C190		✓	
Isuzu C240	OPI-C240		✓	
Isuzu Gemini G161, G180, G200	POL792	DAS142	✓	\$ 150
Mazda 1800 1978-82	8173-14-100	(=POL858)	✓	\$ 190
Mazda FE 8 valve 1983-87	FE65-14-100F		✓	\$ 150
Mitsubishi 4G32 1970-83 (belt drive engine?)	POL783	(MD001400)	✓	\$ 90
Mitsubishi 4G51, 52 1976 on, 4G54 non B/S	POL861	MDO21550	✓	\$ 220
Nissan -early (Patrol?)	15000-10600		✓	\$ 210
Nissan (SD33?)	15010-C6801		✓	\$ 200
Nissan A15	15010-M3001		✓?	\$ 120
Nissan E10, E13, E15, E16	OPN-E15 815		✓	
Nissan J13, J15, J16	POL786		✓	\$ 180
Nissan LD20 mk2 (front cover assy)	OPN-LD20		✓	
Nissan SD22 1966-70 (different pumps for later engines)	POL823		✓	\$ 210
Nissan SD22, SD25 2 wheel drive	OPN-SD22	POL787	✓	
Nissan VG30 1985-88	OPN-VG30		✓	
Nissan VG 30 Pathfinder & 4WD truck	OPN-VG30-1		✓	
Perkins	41314034	Perkins#	✓	\$ 150
Perkins	41314154	Perkins#	✓	\$ 160
Perkins (751188/191)	57191	Perkins#	✓	\$ 210
Perkins 6.354 (turbo & non turbo)	DAS155	VOP124	✓	\$ 200
Pontiac 350-455	P-236		✓	\$ 90
Subaru Leone 1600, 1800 (EA71,82) 1984 on (belt driven)	F4-1400-N		✓	\$ 170
Toyota 18R 1973-78 (pickup below pump)	15100-36010	(=POL835)	✓	\$ 180
Toyota 18R to 1978 (pickup offset)	M94		✓	\$ 180
Toyota 2T, 2TB, 2TC 1974-79, 3T,13T 1977 on	POL830		✓	\$ 170
Toyota 3K 1975-77 (25mm shank)	15100-24011	POL829	✓	\$ 75
Toyota 3K, 4K 1977 on (offset pickup, split pin relief)	POL827		✓	\$ 90
Toyota 3K, K 1968-75 (23mm shank)	15100-22011	(OP830??)	✓	\$ 65

Bowden Engine Parts, 1014 Taupo Bay Road, R.D.1, Mangonui 0494, New Zealand

Phone/Fax: 64 9 4061388

Email: conrodchris@quicksilver.net.nz

BOWDEN ENGINE PARTS

DEC 2010

OIL PUMPS AND KITS

Fits	Part#	Other	Stock	Price
Toyota 3KJ, 4KJ) (25mm shank, split pin relief)	15100-24013	15100-24013	✓	\$ 80
Toyota 3Y, 4Y	M159		✓	\$ 190
Toyota 4A	15100-15020		✓	\$ 110
Toyota 5R Dyna (reconditioned?)	POL837(R?)		✓	\$ 150
Triumph 1500 FWD 1970-73 (angled pickup hole)	POL740		✓	\$ 140
Triumph 1300, 1500 RWD (vertical pickup)	OP59		✓	\$ 180
VW - Audi	049 115 105 A		✓	\$ 200
OIL PUMP KITS				
Rotor 1.597"x1.502", .498" shaft with tang, length 6.04"	?	Rotor set only	✓	
Chrysler Valiant Hemi 245, 265	OP422C	Kit	✓	\$ 80
Ford 289 - 302 Windsor	B8A-6608-AMR	Rotor set only	✓	\$ 50
Ford crossflow 1100, 1300, 1600	OPK8	Kit	✓	\$ 50
Ford Falcon 200, 250 (short shaft)	OP325C	944K	✓	\$ 80
GMC Trucks 1967-72 637,D637,DH637 engs	224-51155	Kit	✓	\$ 80
Holden 149, 161, 179, 186	OP222C	Kit	✓	\$ 50
Holden 202, 3.3	OP223C	Kit	✓	\$ 70
Izuzu (rotor 54x20mm, 13mm shaft, total length 220mm)	9131200360	Rotor set only	✓	\$ 80
Mazda E3 (rotor set)	E301 14 130	Rotor set only	✓	\$ 60
Mazda NA	0222-14-130	Rotor set only	✓	\$ 70
Mazda TC, D4, D5	0324-14-130B	Rotor set only	✓	\$ 70
Mazda/Ford Telstar (gear set)	F80114132/41	Gear set only	✓	\$ 50
Mitsubishi 4G63 (gear set)	MD009033	Gear set only	✓	\$ 70
Nissan A10, A12, A13, A14, A15	OP521C	Kit	✓	\$ 80
Nissan E, F, J	15020-08700	Rotor set only	✓	\$ 70
Nissan L	15020-21005	Rotor set only	✓	\$ 70
Toyota 12R	15101-31011	Rotor set only	✓	\$ 70
Toyota 16R, 18R	OP623C	Kit	✓	\$ 90
Toyota 2C diesel	04151-64020	Rotor set only	✓	
OIL PUMP DRIVES				
Ford 2.0 OHC (6mm x 58mm)		58mm x 6mm		\$ 20
Ford V4/V6 early (8mm x 216mm)	DSS02	216mm x 8mm	✓	\$ 15
Ford V4/V6 late (8mm x 160mm) OPDV62	DSS03	160mm x 8mm	✓	\$ 15
Ford V8 289 - 302 Windsor	IS-68	105mm x 8mm	✓	\$ 15
(8mm x 237mm)		237mm x 8mm	✓	\$ 20
(8mm x 103mm)		103mm x 8mm	✓	\$ 15
(6mm x 184mm)		184mm x 8mm	✓	\$ 20

Bowden Engine Parts, 1014 Taupo Bay Road, R.D.1, Mangonui 0494, New Zealand

Phone/Fax: 64 9 4061388

Email: conrodchris@quicksilver.net.nz