

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009



Part No.	Vehicle	What	Part Description	Stock	Price ea
229		O ring	O RING	17	
23128	Filter seal?	Rubber ring		43	
30136	Ford (6D?)	Oil seal -rear crank	Neoprene	1pr	\$ 50.00
97051	2x2.623x.280	Oil seal		1	
97071	1.875x3.141x2.562x.6	Oil seal	(PR6350)	1	
97076	35x64x9	Oil seal		1	
97096	42x65x13.9x16.4	Oil seal		22	
97099	45x75x8	Oil seal		4	
97133	55/6x82x10	Oil seal	(PR0767)	1	
97151	15x32x7	Oil seal		1	-97364
97164	71x96x9	Oil seal		3	
97194	48x70x9	Oil seal	(PR0178)	5	
97195	Holden?	Oil seal	2 piece (Holden?)	1	
97199	Holden 202?	Oil seal	2 piece (Holden?) 2.430x3.020x.320	4	
97208	85x105x13	Oil seal		1	
97219	45x72.2x7.5x8.5	Oil seal		1	
97226	40x75x9	Oil seal	(PR0736)	1	
97239	48x62x8	Oil seal	(PR0177)	3	
97248	3.687x5.125x.5	Oil seal		1	
97277	65x88x11.5	Oil seal		1	
97288	32x44x9	Oil seal	(PR0098)	1	
97304	28x36x8	Oil seal	mower?	1	
97305	52x68x13	Oil seal		1	
97323	35x54x9x15	Oil seal		3	
97358	32x48x8	Oil seal		2	
97361	38x65x9	Oil seal		1	
97362	35x55x11	Oil seal		1	
97376	65x88x12	Oil seal	(PR0141)	2	
97382	48x74x10	Oil seal		1	
97515	35x56x15	Oil seal		2	
233473		Oil seal retainer gsk	Oil seal retainer gsk	16	
305356		Copper washer		200	
393225	1.5"x2.375"x0.5" GM	Seal		1	
2707882	GM	Oil seal (G/box rear?)	(small - Viva?)	2	
3832961	Chev	Mani inl end seal	CHEV IN MAN END SEAL	29	
3927109	Chev	Mani inl end seal	CHEV IN MAN END SEAL	102	
4068617	Chrysler V8	Mani gsk Inlet set		1	
7206309	Bedford CF	Distr. Gsk		20	
7405144		Copper ring		79	
7405147		Fibre washer		202	
14146069	Isuzu G150	Mani gsk round/square ports		2	\$ 20.00
2004650030	For oil seal?	Spring		4	
0.8x4x8		Fibre washer		11	
06-08-201-900		Misc gsk	On Deletion 2237	13	
08930041		Front cover gsk	On Deletion 2237	4	
08930042		Front cover gsk	On Deletion 2237	12	
09729		Alloy washer		300	
11493-45010	Toyo	Misc gsk	Misc gsk Toyota	7	
13119-84360	Suzuki	Mani gsk Inlet	INLET MANIFOLD GSK SUZUKI	2	
17105-PE3-000				1	
304012R1	IHC?	Copper washer, large IHC?		20	

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

3138042R1	IHC	T/C or side gsk		5
31397-X0101	Nissan	Sump gsk	OIL PAN GSK NISSAN	3
369984R1	IHC	Sump gsk	Misc gsk Int. truck	3
38320-18010	Nissan	Diff gsk	Diff gsk Nissan	7
48x4B		O ring 48x56x4		39
5x10x1.5		Fibre washer		8
76HF9447AA	Ford	Carb insulator		5
897148M3	Norwood	Water gsk?	Misc gsk Norwood	45
90215-18011		Copper washer with locate tab		19
90313-48001	Toyota	Seal special		1
90430-72114	Toyo	Cork ring	MISC GSK TOYOTA	4
90923-05004	Toyo	Fuel pump gsk	Fuel pump gsk Toyota	16
90923-06007	Toyo	Fuel pump insul block	TOYOTA	6
ATJ5628		Front cover gsk		10
ATJ5630		Sump gsk		1
AUC4900		Fibre washer		15
B23285	2.375 x 1.625 x .500	Oil Seal		1
BIG1	4.750x5.562x.460	Oil seal		1
BRF1		Brass Ferrule	BRASS FERRULE FOR KV384	145
BW679A		Valve seal		13
C2806789	Mitsu		MISC GSK. MITSUBISHI	9
C3681438	Mitsu	Sump gsk	Sump gsk Mits	11
C6490	1.562x2.625x.625	Oil seal		1
C7AZ-6571-B	Ford 11/32", 7/8"OD	Valve seal -umbrella	FORD	302
DMG762/2S	Rover 216, 416 1995 on	Mani gsk Inlet		9 \$ 8.00
DMS4301	Ford V8 351C 70-74	MGI valley cover		1
DR720VCBS	Holden V6 VN	Valve cover bolt seal set		1 \$ 20.00
DSF27	See PNZ267			
GJ106-3	Ford Falcon	Shim 1/8"		12
GT108			15691/15193/16271-33010,11312-	16
GT110			JH007 & 13044	16
GT116			KA440,KV651/834	43
GT133	Mits		JB904, JB905, JCMD020622	nil
GT145				3
GT177			E301-15-116/162NZ,E301-12502NZ	9
GT185			KV402,11383-22010,16124-22011	3
GT186	Hillman		KR831,KR859,KS684, MITSUBISHI	9
GT187	BMC "A"	Oil pump & fuel pump gsks.	FUEL PUMP GSK	19
GT188	Toyota 3K		KA443,JR450,20846,16343-22011	7
GT190	Bedford 300		KR615,KT478,KT370 GM	8
GT191	BMC		KD136,KT329,KD205 NZMC	25
GT192	BMC		KT312,KT293 NZMC	12
GT193	Vaux Viva	Carb gsks	2 x KD243, 1 x KT092, 2 x KD082 GM	3
GT194	Vaux Viva	Water hsg gsks	KT478, KA170 GM	5
GT195			KG134,KD153,KD157,KD007,KD111	7
GT196	Mits		KT327,KD258,PNZ061 MITSUBISHI	26
GT197	Mits		KD668,KD215 MITSUBISHI	4
GT200	Ford		JH488/9,JH415/6 FORD	20
GT201			KA081,KR859,KT191,KT192 MITSU	5
GT203	Hillman Hunter		KT071,KR831,KA205 MITSUBISHI	30
GT204	Mits		1X JCMD009043,1X JCMD009006	50
GT205	Mits?		1X LT273,LT274,LT275,2X LT276	6
GT214			KS014/15/16/17/KA087/KR993/379	19
GT215	Jaguar		LS550,LS551,LS549,LS548 JAGUAR	8
GT219	Nissan RB30		15066-42L01,16175-V5200,13017-	6
GT220	Niss?	Mani gsk exh set	Cont:17170/3-87302	2
GT230		Mani gsk exh set	CONT:JA768/770 EX.MAN.GSK.SET	23
GT231		Mani gsk exh set	JA963 = 1 + 2 PIECES	6
GT232	JC653 x 6	Mani gsk exh group	CONT:JC653 X 6 EX.MAN.GROUP	12
GT233	KD153 x 6	Carb gsks? (6)	CONT:KD153 X 6 OFF	16
GT234	KD177 x 6	Carb gsks	CONT:KD177 X 6	9
GT235	Bedford 466, 500	Cork ring	CONT:KG756 X 10	4
GT237	KG033 x 6	V/seals felt	CONTAINS KG033 X 6	3

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

GT241		Mani gsk exh set		1	
GT242				2	
GT244	Holden		BARINA/SWIFT	4	
GT245		Carb gsks?	KD241A X 4	1	
GT249			KD260,KD082,KD242,KD243X2,KT09	2	
GT251		Mani gsk exh set	EX.MANIFOLD GSK.	7	
GT252	Mazda F8 carb	Mani gsk set	JC401+PNZ408	194	\$ 5.00
GT258	Toyota 3K, 4K	W/p, therm gsks.	MISC GSKS (KA443,LA131,LT220)	181	
GT259			CAM.COVER GSKS.	6	
GT260	Bedford 214	Mani gsk set (2 ends only)	JA219/20 (G 1033949/51) (part HA003)	10	
GT39	BMC "B"?	W/p, O/pickup	KS235,KA079 NZMC	2	
GT58	Leyland 400			10	
GT58	Leyland 400		JR097,KR591/296,KS340,KS065,KS	10	
GT59	Leyland 400			3	
GT59	Leyland 400		BMC "C"? comb.		
GT74	Ford V4	Sump set	HC067	1	
GT78	Ford V6	Sump set	JH401,JH439,JH440,JH441 FORD HC066	7	
GT97	Nissan H20		1X21074-69200,22179/1307932200	12	
GT98			21014/15053-18000,13044-18001,	15	
HA002	Bedford 214 early	Mani gsk set	1 x JA223, 2 x JA224 (or Chev?)		\$ 25.00
HA003	Bedford 214	Mani gsk set	exh ends GT260, centre JA218/9	6	\$ 25.00
HA004	Chev 6 216, 235 1937-52	Mani gsk set	JA223 + 2 x JA224	1	\$ 25.00
HA010	Ford Trader 4 cyl diesel 1952-57	Mani gsk set		2	\$ 25.00
HA016	BMC "C"	Mani gsk set			\$ 30.00
HA017	Bedford 300	Mani gsk set		1	\$ 25.00
HA024	Rover	Mani gsk set -exh	4 cyl "F" head to 1958	lots	\$ 20.00
HA025	Rover	Mani gsk set -exh	6 cyl "F" (JA424/5/6?)	lots	\$ 25.00
HA033	Hillman	Mani gsk		2	
HA039	Mits 4	Mani gsk Exh		1	
HA043	Mits 4	Mani gsk Exh		1	
HA044	Mits 4	Mani gsk Inlet		3	
HA045	Mits 4	Mani gsk Inlet		2	
HA048	Ford Falcon CIH X/F	Mani gsk Exh	(PNZ239)	3	\$ 7.00
HA054	Toyo 4	Mani gsk		1	
HA154	Chev V8 S/B	Mani gsk Inlet set		1	\$ 20.00
HA172	Vaux Viva	Mani gsk set		yes	
HA180	Toyo 4	Mani gsk set		1	
HA190	Chrys Val 225	Mani gsk		1	\$ 15.00
HA191	Holden 186, 202	Mani gsk set		5	
HA208	Mazda 4	Mani gsk set		3	
HA264	Bedford CF	Mani gsk exh set		yes	\$ 16.00
HA265	Holden V8 308 red	Mani gsk Inlet set		3	\$ 14.00
HA271	Mazda NA, UB, VB, VC	Mani gsk set		12	\$ 8.00
HA278	Bedford CF	Mani gsk Inlet pair	(JA608 + JA609)	4	
HA285	Ford V8 289,302W	Mani gsk Inlet set		7	
HA294		Mani gsk pr		1	
HA295	Ford V8 302C, 351C 2V	Mani gsk Inlet set		1	
HA295EX	Ford V8 302C, 351C 2V	Mani gsk exh set		1	
HA295LP	Ford V8 -large port	Mani gsk Inlet set		1	
HA297	Ford Cortina 2.0	Mani gsk Inlet		2	
HA303	Ford Falcon CIH X/F	Mani gsk Inlet	(see NZ268)		
HA305	Holden 1900	Mani gsk exh		3	
HA309	Holden V8	Mani gsk exh set		1	
HA331	Ford V8	Mani gsk Inlet set		4	
HA336	Mazda 4	Mani gsk set		3	
HA345	Isuzu 4	Mani gsk Inlet pair		1	
HA346	Isuzu 4	Mani gsk exh set		2	
HA347	Nissan 4	Mani gsk		1	
HA349	Holden V8	Mani gsk Inlet set		2	
HA350	Mazda 4	Mani gsk set		1	
HA353	Ford 6	Mani gsk Exh	(2 x JC158?)	1?	
HA366	Nissan E13	Mani gsk Inlet -small port		2	
HA368	Holden	Mani gsk set		2	

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

HA372	Nissan E16	Mani gsk exh -big port		1
HA373	Falcon EFI 85-88	Mani gsk Inlet		1+5
HA383	Honda	Mani gsk exh set		1
HA391	Mits 4	Mani gsk Exh		0 \$ 10.00
HA393	Falcon 4.1	Mani gsk Inlet		1
HA399	Ford 4	Mani gsk set		1
HA405	Nissan RB30E	Mani gsk Inlet set		2 \$ 16.00
HA413	Honda 4	Mani gsk set		1
HA416	Holden V6 VN	Mani gsk Inlet set		1
HA420	Toyo 4	Mani gsk		1
HA424	Holden V8 304, 348	Mani gsk Inlet		2
HC001	Chrysler SV 6 (short engine)	Sump set		1 \$ 30.00
HC002	Chrysler SV 6 (long engine)	Sump set		3 \$ 30.00
HC015	Morris Series E, MM Minor	Sump set		1 \$ 30.00
HC016		Sump set		2
HC020	Ford Consul	Sump set		2 \$ 25.00
HC021	Ford Zephyr 6 mk1,2,3	Sump set		2 \$ 15.00
HC023	Vaux Wyvern 1952-56	Sump set		1
HC025	Ford 100E	Sump set		1 \$ 25.00
HC027	Fiat 850 1964-72	Sump set		1 \$ 15.00
HC028	Chev 285-350 V8 small block to 1980	Sump set		1 \$ 20.00
HC028L	Chev 350, 400 V8 small block 1980 on	Sump set	dipstick hole on RH sump rail	1 \$ 15.00
HC031	BMC "A" transverse	Sump set		2 \$ 11.00
HC035	Chrysler Valiant slant 6	Sump set		2
HC039	Ford Trader 1961-65 4 cyl	Sump set	JH277/8, KS754, KT638	\$ 35.00
HC043	Holden 149-202	Sump set		1 \$ 15.00
HC048	BMC "A" in line	Sump set	sides = JH378/9, ends KT331	1 \$ 20.00
HC056	Ford Trader 4D	Sump set	KT048, KT049, JH405pr	4
HC057	Ford Trader 6D	Sump set	KT048, KT049, JH406/417	10 \$ 25.00
HC059	Vaux Viva	Sump set		1
HC065	Bed 2.3, Victor FC	Sump set		5 \$ 35.00
HC066	Ford V6	Sump set	Also GT78	1
HC067	Ford V4	Sump set	Also GT74	1
HC068	Ford Cortina NCF	Sump set		1
HC069	BMC Allegro, Marina	Sump set		4 \$ 15.00
HC070	Ford Cortina C/F	Sump set		1
HC072	Hillman Hunter -steel sump	Sump set		2 \$ 20.00
HC074	Hillman Hunter -alloy sump	Sump set		1 \$ 30.00
HC210	Nissan A10, A12, A14, A15	Sump set	JJ329+KV420+KV421 (NZG SS130)	1
HC242?	Chry V8	Sump end pr -rubber		1
HC253	BMC Maxi, Marina	Sump set		3 \$ 15.00
HC257	Ford Falcon	Sump set		2
HC285	Ford Cort 2.0	Sump set		1 \$ 17.00
HC311	Holden 253, 308 V8	Sump set		2 \$ 18.00
HC403	Toyo 5K	Sump gsk		1 \$ 20.00
HC424	Jaguar 2.8 68-79, 3.4 75-86, 4.2 68-86	Sump set		1 \$ 20.00
HC435	Mazda R2, S2	Sump gsk		4 \$ 11.00
HC442	Nissan E13, E15, E16	Sump gsk		2 \$ 20.00
HC453	Mazda	Sump gsk		1
HC460	Falcon?)	Sump end pr -rubber		4
HC473	Mazda SL diesl	Sump set		1
HM5200	Subaru EJ20T 6/96- LH (shim tappet)	Rocker cover gsk set	(VC088 or JP088 plus 2 x KK5061)	1
HM5210	Subaru EJ20T 6/96- RH (shim tappet)	Rocker cover gsk set		1
HNO17	Holden 149-186	Seal - rear.	KS690L + KS690U	yes
HNO39			Misc gsk Toyota 11553-31010	16
HN056	Ford V8 Windsor	Seal - rear.		10pr
HR103	Rover	Valve seal		lots
HR501	Nissan inlet	Valve seal		6
HR569			FIAT 4174355(1 BAG = 8 PIECES)	2
HR625	BMC "O"	Valve seal	NZMC PRINCESS AHU1626	74
HSC	BMC Princess	Oil seal g/box	0.875x1.125x0.375	1
HSM27	See PNZ267			
HYP64				

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

JA007	Nissan L16, L18, L20B	Mani gsk		1	\$ 10.00
JA010	Nissan 4	Mani gsk		1	
JA011		Mani gsk		7	\$ 10.00
JA013	Nissan 4	Mani gsk		2	
JA016	Isuzu G150	Mani gsk round ports			
JA021	Mazda 4	Mani gsk Inlet		1	
JA024	Mits 4G41 etc	Mani gsk		2	
JA025	Mits 4G32	Mani gsk Exh	EXH.MANIFOLD GSK JCMD002565	4	\$ 2.00
JA030	Toyota 2R	Mani gsk	MANIFOLD GSK 17172-31012	9+1	\$ 15.00
JA031	Toyo 12R?	Mani gsk		5	
JA032	Toyo 4	Mani gsk		2	
JA033	Toyota Crown 4M	Mani gsk set		6	
JA039	Mazda	Mani gsk		2	
JA052	Mazda S2, ZB	Mani gsk Exh	S2 requires 4, ZB 6.	8	
JA053	Toyo 4	Mani gsk Exh		1	
JA063	Toyota 12R	Mani gsk		1	
JA064		Mani gsk (hotbox?)	MANIFOLD GSK 17171-44010	3	
JA074	Toyo 4	Mani gsk		1	
JA075	Toyota B/2B 72-80	Mani gsk Exh		4	
JA077	Honda EB1, EB2, EB3, EN	Mani gsk exh set		44	\$ 8.00
JA078	Mitsubishi 4G51, 4G52	Mani gsk Exh square port		3	\$ 10.00
JA086	Mazda 4	Mani gsk Inlet		1	
JA093	Isuzu	Mani gsk		2	
JA094	Lada	Mani gsk	part of CX660	1	
JA208	Hillman SV	Mani gsk		1	
JA218	Bedford 214	Mani gsk centre	G 1033950 (part of HA003)	0	
JA219/20	Bedford 214	Mani gsk ends -see GT260	(part of HA003)	0	
JA223	Chev 216	Mani gsk -centre	MANIFOLD CENTRE 838287 GM (HA002?)	16	
JA224	Chev 216	Mani gsk -ends	MANIFOLD ENDS 838288 GM (HA002?)	25	
JA249	Austin A70	Mani gsk			
JA256	Austin A40 Devon, Somerset 1948-54	Mani gsk		0	\$ 18.00
JA258	Fergusson	Mani gsk each		2	\$ 8.00
JA259	Standard Vanguard -2 required	Mani gsk each		4	\$ 10.00
JA260	Jowett	Mani?		1	
JA264	BMC 4 litre	Mani gsk -44mm inlet holes		1	\$ 30.00
JA266	Nuffield tractor	Mani gsk set	B L M C AAA4460	3	
JA272	Jaguar			1	
JA275	IHC trucks BD,SD 220/240/264 vertical	Mani gsk	69752R1		\$ 20.00
JA279			Manifold gsk F 100E-9448	7	
JA281	BMC 3.4 3.8 diesel		sample	1	
JA282	BMC "B"	Mani gsk		1	\$ 8.00
JA285	Triumph 1200	Mani gsk		2	
JA286	Hillman	Mani gsk		1	
JA290	Jaguar	Mani gsk	MANIFOLD GSK. JAGUAR C7619	5	\$ 15.00
JA295	BMC 2.2 diesel	Mani gsk		1	\$ 15.00
JA296	IHC BD264	Mani gsk	IHC 700830R2	6	\$ 12.00
JA296	IHC BD264 -2 reqd	Mani gsk		8	\$ 12.00
JA299	V8	Mani gsk Inlet	G 373196	6	
JA306	Triumph TR4	Mani gsk pr		1	\$ 30.00
JA307	BMC 4 litre	Mani gsk -37mm inlet holes		1	
JA308	Triumph TR2	Mani gsk pr		1	\$ 30.00
JA315	Ford (Trader?)	Mani gsk		3	
JA316	Ford Trader 6 cyl diesel 1957-66	Mani gsk	2 reqd	4	
JA317	Ford Trader 4 cyl diesel 1957-65	Mani gsk	2 reqd	6	\$20/pair
JA318	BMC?	Mani gsk	MANIFOLD GSK N GEG685	3	
JA322	Austin Healey 3000	Mani gsk	MANIFOLD GSK N GEG624		\$ 20.00
JA323	Rover	Mani gsk		2	
JA324	Rover	hot box	HOT BOX GASKET L/ROVER 57-PET	6	
JA328	IHC	Mani gsk exh single	Manifold gsk I. 704165R2	6	
JA329	Humber Super Snipe	Mani gsk	MANIFOLD GSK T R5220308	10	\$ 14.00
JA345	GM?	Mani gsk exh ends	MANIFOLD ENDS G 3835503	15	
JA367	Bedford	Mani gsk -centre	not 214	1	
JA371		Mani gsk exh -centre	EXH.MANIFOLD CENTRE G 3704836	4	

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

JA372		Mani gsk Exh	EXH.MANIFOLD G 3704835	13	
JA380		Mani gsk Inlet	INLET MANIFOLD J C14127/1	10	
JA381	Skoda	Mani gsk		1	
JA391	Chry Val?		TODD 1947762	4	
JA394	Leyland 400 -6 reqd	Mani gsk exh single		12	\$ 5.00
JA395	Leyland 400 -1 reqd	Mani gsk Inlet	INLET MANIFOLD GSK N 601286	2	\$ 16.00
JA397	Ford Zephyr 6 & 4 mk3	Mani gsk Inlet -big port	FORD 211E-9441	124	\$ 5.00
JA408	Ford Cortina	Mani gsk small port		1	
JA419	Hillman Imp	Mani gsk	MANIFOLD TO CYL.HD T R7100313	2	
JA424	Rover part of HA024/5 sets	Mani gsk exh part	Rover 3 litre	10	\$ 3.00
JA425	Rover part of HA024/5 sets	Mani gsk exh part	(sets HA024/5)	13	
JA426	Rover part of HA024/5 sets	Mani gsk exh part		12	
JA426			Mani gsk N 534102	12	
JA432	Ford Cortina	Mani gsk big port		3	
JA444	Perkins	Mani gsk exh single		21	
JA457		Mani gsk	S 110-095840	1	
JA464		Mani gsk exh single	EXH.MANIFOLD GSK PN 36862143	11	
JA467	Ford Trader 240-255	Mani gsk -exh	2 reqd	2	\$ 10.00
JA468	Ford Trader 330-380 (2 reqd)	Mani gsk -exh	2 reqd	6	\$ 10.00
JA476	Ford	Inl mani gsk steel (101?)	Ford EIADKN-6053	186	
JA478	Leyland 600/680	Mani gsk -exh	(4 reqd)	2	\$ 8.00
JA480	Chev/Bed 6	Mani gsk		1	
JA482	Ford	MGI -steel 4 port (JA482K9 24	Mani gsk Ford C5NE-9448-B	15+16	
JA484	Vaux Viva	Mani gsk Inlet	MANIFOLD GSK. G 9966621	12	\$ 5.00
JA486	Ford	Mani gsk Inlet	Mani gsk Ford C5NE-9448-A	8	
JA488	Hillman Hunter A/H	Mani gsk -exh	TODD 1238426	36	
JA493	Leyland 400 -2 reqd	Mani gsk exh single	EX MAN GSK LEYLAND 602827	53	\$ 5.00
JA494	Leyland 400 -2 reqd	Mani gsk exh single	EX MAN GSK LEYLAND 602828	32	\$ 5.00
JA495	Leyland 400 -2 reqd	Mani gsk exh single		36	\$ 5.00
JA496	Leyland 400 -1 reqd	Mani gsk inl twin		20	
JA497	Leyland 400 -4 reqd	Mani gsk inl single	MISC GSK LEYLAND 602832	44	
JA500	Rover 2 1/4 litre	Mani gsk Inlet		2	
JA502	Triumph 1300,1500	Mani gsk		1	\$ 8.00
JA5047	Mits	Mani gsk Inlet		1	
JA5059	Toyo	Mani gsk Exh		1	
JA508	Rover 3500	MGI valley cover		2	
JA510	Triumph?	Mani gsk		2	
JA512	Fiat	Mani gsk	MANIFOLD GSK FIAT 4127971	5	
JA516	BMC Marina 1500, 1750	Mani gsk	MANIFOLD GSK N GEG621/32H93	1	\$ 12.00
JA545	Perkins	Mani gsk Inlet	MANIFOLD GSK PERKINS 0490738	5	
JA550	BMC	hot box	HOT SPOT GSK NZMC AEC950	53	
JA567	Leyland 400		Misc gsk Leyland 601304	5	
JA585	Humber Super Snipe	Mani gsk Inlet	INDUC.MANIFOLD GSK T 1228053	12	\$ 7.00
JA599	Ford	Mani gsk Inlet		1	
JA608	Bedford CF	Mani gsk Inlet -rear	Set = HA278	9+12	\$ 4.00
JA609	Bedford CF	Mani gsk Inlet -rear	Set = HA278	2	\$ 8.00
JA628		Exh fla - flat 2 bolt 1.27"ID		2	
JA635	IHC	Mani gsk exh single	Mani gsk Int. Trucks 704162R1	4	
JA694	Hillman Hunter A/H	Mani gsk -steel	MANIFOLD GSK.TODD 1238427	39	
JA704	Bedford 466	Mani gsk Inlet	INDUC.MANIFOLD GSK G 8825524	146	
JA719	BMC	Mani gsk?	B L M C NT5072	3	
JA721	Leyland 600/680	Mani gsk Inlet	(2 reqd)	3?	\$ 3.00
JA722	Leyland 600/680	Mani gsk Inlet	(2 reqd)	2?	\$ 3.00
JA730	Vaux Viva	Mani gsk Exh		1	\$ 10.00
JA737	IHC BD264 -4 reqd	Exh fla gsk	Mani gsk I. 700832R2	14 + 17	\$ 10.00
JA742	Rootes?	Mani gsk Inlet	Inl mani gsk P 36867153	15	
JA745					
JA747	Ford V4	Mani inlet gsk	(PNZ379+NZ204+NZ205+PNZ195+PNZ19	4	\$ 15.00
JA748	Ford V6	Mani inlet gsk "D" ports	(PNZ378+NZ204+NZ205+PNZ195+PNZ19	1	\$ 15.00
JA754	Fiat	Mani gsk Exh	EXH.MANIFOLD GSK FIAT 4048457	5	
JA765	Austin Kimberley?	Mani gsk		1	
JA769	Ford Cortina OHC	Mani gsk Inlet		2	
JA782	Holden 179	Mani gsk		12	

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

JA791			IN & EX MAN GSK N GEG664	9	
JA793	Jag?	Mani gsk		3	
JA796	Vaux 1600 OHC	Inl mani rear			\$ 8.00
JA935	IHC 6 ABD, AGD240/264/282	Mani gsk		1	\$ 30.00
JA961	Chrysler 245, 265 Hemi	Mani gsk		1	
JAGBS1			On Deletion 2237	7	
JB310	Holden 4	Mani gsk		2+3	
JB408		Mani gsk	Mani gsk N. AYB2172	83	
JB502	Vaux 3.3, 2.6	Mani gsk Inlet (1 reqd)		75	\$ 4.00
JB503	Vaux 3.3, 2.6	Mani gsk Inlet (2 reqd)		29	\$ 7.00
JB553	IHC	Mani gsk joints		lots	
JB568		Mani gsk	MANIFOLD GSK D 14035-H7200	2	
JB581	Renault	Mani gsk		2	
JB683		Exh fla -twin pipe		2	
JB766	Honda 4	Mani gsk		1	
JB802	Mazda MA, NA (square port)	Mani gsk Exh		1	
JB857	Renault	Mani gsk		2	
JB903	Ford 6	Mani gsk Inlet		3	
JB906			T. JCMD020624	77	
JB907	Chrysler V8	Mani gsk Inlet set		1	
JB908	Mits?	Mani gsk Inlet	IN MAN GSK T JCMD000561	7	
JB909	Mits?	Mani gsk Inlet	IN MAN GSK T JCMD000560	4	
JB910/1	Toyo 3K, 4K, 5K	Mani gsk set		2	\$ 9.00
JB912	Mitsubishi 4G51, 4G52	Mani gsk Exh round port		4	\$ 15.00
JB913	Mits 4G32,36	Mani gsk Exh		73+1	
JB949	Toyo 4	Mani gsk Inlet		1	
JB971	Mits 4G51/2/3/4 -84	Mani gsk Inlet		1+1	
JB977	Ford Trader 330-380	Mani gsk -steel	MAN GSK FORD 2704E-6K698A	30, 43	
JB980	Toyo 4	Mani gsk Exh		1	
JB983	6 cyl	Mani gsk Exh		1	
JB984	Toyo 6	Mani gsk Inlet		1	
JB989	Bedford 500	Side plate gsk	SIDE PLATE GSK G 91010432	5	
JB998	Mits	Mani gsk Exh		1	
JB999	Mits 4G52	Mani gsk Exh		50	
JC004	Mits 4G52	Mani gsk Exh		9	
JC024		Mani gsk		1	
JC025	Honda EK/ED 6 hole in/ex	Mani gsk	EX.MAN.HONDA EK,EF	11	\$ 15.00
JC038	Mazda 626	Ex fla?		4	
JC040	GM	Mani gsk	MANIFOLD GSK.G 9940097	11	
JC046	Mazda MA, NA (round port)	Mani gsk Exh	Ford 0459-20-745ANZ	3	
JC048		Mani gsk		4	
JC057	Nissan A14 (round inl)	Mani gsk		1	\$ 5.00
JC060	Isuzu Gemini	Mani gsk	2 = GT239	2	
JC088	Daihatsu G11	Mani gsk		1	
JC092			MANIFOLD GSK. M 3607-13-462NZ	14	
JC107	Bed		GM 91056334	1	
JC108	Bed 8.2 litre diesel	Adaptor to induction mani		1	
JC118	Honda EC, EG, EL	Mani gsk		3	\$ 5.00
JC119	Honda EL, EJ, EK, EM, EP	Mani gsk		7	\$ 20.00
JC121	BMC "O"	Mani gsk		2	\$ 8.00
JC123		Mani gsk Inlet -twin	ON DELETION 2238	47	
JC124	Mitsu 4G32	Mani gsk Inlet		11	
JC125	Mitsu 4G54	Mani gsk Exh		0	\$ 12.00
JC126	Nissan	Mani gsk Inlet		4	
JC156	Ford 6	Mani gsk Inlet		1	
JC157	Ford Falcon AH C/F	Mani gsk Inlet		1	
JC158		Mani gsk Exh	(2 = HA353?)	1	
JC159 (B)	GM	Mani gsk		1ea	
JC163	Ford Laser 1980-87	Mani gsk Exh		6	
JC183		Mani gsk Inlet		1	
JC214	Nissan A15	Mani gsk			\$ 10.00
JC215	Toyota 2R	Mani gsk Inlet		2	
JC224	Mitsubishi 4D56T	Mani gsk		1	

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

JC225	Mitsubishi 4G32	Mani gsk Inlet			
JC242		Mani gsk Exh		lots	
JC253	Honda EK	Mani gsk		2	\$ 12.00
JC272	Mitsubishi 4G32	Mani gsk Exh		2	\$ 14.00
JC283	Holden 1600, 1800	Mani gsk Inlet		2	\$ 6.00
JC284	Isuzu 4FB1,FC1,FD1	Mani gsk Exh		2	\$ 6.00
JC285	Holden V8 308 beaded	Mani gsk Inlet set		1	\$ 20.00
JC317	Nissan CA16, CA18, CA20	Mani gsk Inlet		2	\$ 4.00
JC319		Mani gsk exh?	On Deletion 2232	210	
JC324	Mitsubishi 6DS7 1973 on	Mani gsk -exh		9	\$ 15.00
JC336	Isuzu 4B/6B diesels	Mani gsk Exh -2 port	4B requires 2, 6B 3.	3	
JC344	Toyota "H" 1972 on	Mani gsk exh set		3	\$ 24.00
JC356	Ford Falcon AH C/F	Mani gsk Inlet		1	
JC400	Ford Telstar 12v 1987	Mani gsk exh set	Is this same as JC777?	4	
JC401		Mani gsk Inlet	plus PNZ408 = GT252		
JC403	Toyo 2SEL 81-88	Mani gsk Exh		2	
JC404		Mani gsk		1	
JC405		Mani gsk		1	
JC408	Mitsubishi 4G62/3	Mani gsk		2	
JC410	Toyo	Mani gsk		1	
JC414	Honda	Mani gsk Inlet		1	
JC427	Mazda Rotary	Mani gsk		2?	
JC429	Isuzu 4FG1	Mani gsk Inlet		1	\$ 6.00
JC438	Replaced by JC615	Mani gsk		1	
JC443-4	Mazda HA	Mani gsk -exh			
JC444	Toyo 1C diesel 85 on (,2CT,3CT)	Mani gsk -exh	laminated steel	2	\$ 30.00
JC445	Toyota 2LT 1982-88	Mani gsk -exh		3	
JC446	Rover	Mani gsk	MANIFOLD GASKET ROVER	5	
JC449	Holden Camira	Mani gsk Inlet		5	
JC471	Nissan VG30E	Mani gsk singles	3 = JC472	3	
JC472	Nissan VG30E	Mani gsk		1	
JC473	Nissan SD23,25	Mani gsk		1	
JC475	Nissan B/bird	Mani gsk -exh		2	
JC493	Mitsubishi 4G62, 4G63	Mani gsk Inlet		1	\$ 8.00
JC511	Mitsu 4G52, 4G54	Mani gsk Inlet	large retangle hole between ports 3 & 4	2	
JC512	Mits	Mani gsk Inlet	JCMD026528	9	
JC514	Suzuki G10	Mani gsk Exh	EX.MAN.SUZUKI G10	2	\$ 13.00
JC516	Honda ES, ET	Mani gsk Inlet		3	\$ 5.00
JC526		Mani gsk Inlet	IN.MANIFOLD HH17116-PE2-000	3	
JC530	Falcon?	Mani gsk Inlet		3	
JC532	Suzuki G10	Mani gsk Inlet	IN.MAN.SUZUKI G10	5	\$ 8.00
JC534	Honda EV, EW	Mani gsk -exh set		1	
JC536	HA393 use	Mani gsk Inlet	WSN USE HA393	4	
JC537	HA393 use		WSN USE HA393	16	
JC557	Honda ER	Mani gsk		2	\$ 15.00
JC579	Toyota 4A	Mani gsk -exh		1	
JC588	Suzuki G13A, B	Mani gsk Inlet		1	
JC589	Suzuki G13A, B	Mani gsk -exh		1	
JC595	Subaru	Mani gsk Inlet	only 1 in set?	1	
JC611	Mitsu 4G63	Mani gsk -exh		2	\$ 10.00
JC614	Mitsu	Mani gsk Inlet single	INLET MANIFOLD REAR MITSUBISHI	12	
JC615		Mani gsk	also JC438	1	
JC623	Toyota 3F	Mani gsk		1	\$ 13.00
JC627	Mitsu 4G32	Mani gsk Exh		19	\$ 15.00
JC628	Mitsu 4G12T	Mani gsk Exh	EX MAN GSK MITSU JCMD013795	52	\$ 20.00
JC629	Mitsu 4G12	Mani gsk Inlet		3	\$ 5.00
JC632	Mitsu 4D68T 92-	Mani gsk Exh		7	\$ 30.00
JC637					
JC640	Toyota 2L up to 1988 (mk 1)	Mani gsk Inlet		1	
JC641		Mani gsk Exh	EX.MANIFOLD	3	
JC644	Mitsu 4G52, 4G54	Mani gsk Inlet	slotted hole between ports 3 & 4	1	
JC645	Mits Magna	Mani gsk Exh		3	
JC646	Mits?)	Mani gsk Exh		5	

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

JC652	Honda A20, B20	Mani gsk Inlet		1	
JC653	Nissan RB20E, RB30E	Mani gsk Exh		2	\$ 10.00
JC657	Toyota 4M	Mani gsk Inlet		1	
JC664		Mani gsk		3?	
JC665	Mazda	Mani gsk Inlet		10	
JC668	Nissan SD23,25	Mani gsk		3	
JC670	Isuzu 4ZB1	Mani gsk Inlet		5	
JC674	Honda	Mani gsk Exh		1	
JC675	Nissan	Mani gsk	Niss 14005-J2001	1	
JC683	Isuzu	Mani gsk Exh		4	
JC686	Honda	Mani gsk Inlet		2	
JC700	Subaru EF12	Mani gsk Exh	EX.MAN.SUBARU EF12	6	
JC719	Mits	Mani gsk		2	
JC727	Ford 6	Mani gsk Inlet		2	\$ 5.00
JC728	Ford 6	Mani gsk Inlet		3	\$ 18.00
JC730	Falcon EA multi-point	Mani gsk			\$ 12.00
JC740	Toyota 7MGTEU	Mani gsk Exh		1	
JC744	Nissan	Mani gsk exh part		1	
JC745	Nissan E13, E15	Mani gsk exh part	WSN USE HA372	8	
JC749	Nissan E13, E15	Mani gsk Exh	EX.MAN.GSK.NISSAN 14036-01M02	2	
JC751	Mits	Mani gsk		1	
JC752	Mits	Mani gsk		1	
JC757	Holden Astra 1.6 87-90	Mani gsk Inlet		2	
JC776	Daihatsu	Mani gsk Exh		2	
JC777	Ford Telstar 12v 1987	Mani gsk exh set	Is this same as JC400?	2+	
JC777A	Ford Telstar 12v	Mani gsk exh set	Is this same as JC400?	1	
JC779	Mazda FE 12v	Mani gsk Inlet		1	
JC781/2	Mazda B6 16v DOHC Tur	Mani gsk exh pr		1	
JC797		Mani gsk Exh -singles		3	
JC798	Nissan E13, E15		FRONT INTAKE GSK.D 14035-01M00	1	
JC799	Nissan E13, E15	Mani gsk Inlet -centre	CENTRE INTAKE GSK D14035-01M01	383	
JC841	Toyota 3SGE, 3SGELU	Mani gsk Inlet		1	
JC870		Mani gsk Exh		1(+1?)	
JC875	Niss Micra CG13DE 95-97	Mani gsk Inlet		1	
JC882	Rover Landrover diesel 2.3 61-71	Mani gsk		2	\$ 25.00
JC920	Honda B18A	Mani gsk Inlet		3	
JC931	Mazda	Mani gsk Exh		1	
JC967	Subaru EF12	Mani gsk Inlet	IN.MAN.SUBARU EF12	4	
JC998	Niss KA24DA 2389cc	Mani gsk exh set		3	
JC999	Nissan GA16DE -plenum gsk	Mani gsk Inlet		7	
JCB00			Rear Intake gsk. D 14035-01M02	54	
JCMD008899	Mits	Oil screen gsk	OIL SCREEN GSK MITSUBISHI	14	
JCMD010549				1	
JCMD014194			FRONT CASE GSK MITSUBISHI	2	
JCMD020353	Mits		Chain cover gsk.	192	
JCMD041017	Mits	Front cover gsk	ENGINE FRONT COVER GSK MITSUBI	5	
JCMD088445	Mits		Mani front inlet gsk. Mits	46	
JCMD101160				1	
JCMD101970				1	
JCMD183243	Mits	Rear seal hsg gsk	OIL SEAL CASE GSK.MITSUBISHI	34	
JCMD603015	Mits	Rocker bolt washer		14	
JCMD703734			On Deletion 2237	57	
JD001	Nissan GA16DE	Mani gsk Inlet	IN.MAN.NISSAN GA16DE	2	
JD007		Mani gsk Exh		1	
JD023		Mani gsk		1	
JD030	Nissan CA	Mani gsk Inlet		1	\$ 5.00
JD093	Nissan GA	Mani gsk Inlet		1	\$ 6.00
JD130		Mani gsk Exh		1	
JD166	Honda	Mani gsk Exh		1	
JD365	Toyota 2L 1988 on	Mani gsk Exh		1	\$ 13.00
JD5032	Mits 4G64 16v S	Mani gsk Inlet		1	
JD5094	Nissan LD20 81-	Mani gsk Inlet		3	
JD5169	Isuzu 6VD1 DOHC 1998 on	Mani gsk Exh		1	

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

JD520-4	Peugeot 306 XU7JP 1992 on	Mani gsk exh set		1	
JD5258	Toyota 2LT 1988 on, 3L, 3LT	Mani gsk Exh		1	\$ 30.00
JD5262	Mits 4D55T/56T	Mani gsk		1	\$ 36.00
JD595	Toyota 2LT 1988 on, 3L, 3LT	Mani gsk Inlet			\$ 9.00
JD633	Toyota B, 3B, 11B 1988 on	Mani gsk Exh	USE MG0013		
JD637	Nissan TB42 petrol	Mani gsk		1	
JD638	Nissan TB42S	Mani gsk Inlet		2	
JE002	Nissan	Ex fla	F/G NISSAN 20711-21001	18	
JE011	Mitsu 4G32 74-77	Ex fla		5	
JE012	Honda EB1, 2, 3, Toyo 4K	Ex fla		1	\$ 3.00
JE013	Honda EB1, 2, 3, Toyo 4K	Ex fla			\$ 3.00
JE015	Honda	Ex fla		3	\$ 4.00
JE016	Toyo 4/6	Ex fla		16	
JE017	Toyota	Ex fla		1	
JE021	Mazda	Ex fla	0107-13-483NZ FLANGE GSK MAZDA	2	
JE027	Nissan 240/260C&Z	Exh fla gsk		4	
JE034	Mazda 12A	Exh fla gsk		2	\$ 3.00
JE036		Exh fla ring		1	
JE043	Subaru	Ex fla	EXHAUST GSK.SUBARU 6440-03042	35	\$ 2.00
JE050	Toyo	Ex fla -twin		4	\$ 3.00
JE092	BMC/GM	Exh fla ring	GM/BLMC 3738405/AMK1572	1+252	
JE106	Toyota	Ex ring		22	\$ 5.00
JE146	Daihatsu Charade G11	Ex fla	EX PIPE FLANGE 17451-87705	155+20	
JE183		Ex graphite cone 42mm ID		17	
JE184		Ex graphite cone 51mm ID		6	
JE185		Ex graphite cone 54mm ID		1	
JE201	Bedford 214	Exh fla ring		1	\$ 5.00
JE209	Standard Vanguard	Ex fla	F/G STANDARD 57924	2	
JE212	Bedford 300, 330	Ex fla		5	
JE213		Ex ring		10	
JE216	Vaux	Exh fla ring		4	\$ 4.00
JE227	Humber Super Snipe	Ex fla flat 2 bolt		20	\$ 2.00
JE231	Jag	Exh fla ring		2	\$ 8.00
JE241	BMC/Vaux	Exh fla ring		1	\$ 5.00
JE244	Hillman Hunter	Exh fla gsk		8	
JE248	Volvo B230F eng -93	Exh fla gsk		3	
JE251	Vaux Viva HA, HB	Exh fla ring		4	
JE259	VW	Ex fla		8	
JE268	BMC	Ex fla	NT3576 EXHAUST FLANGE B.M.C.	3	
JE277	Perkins	Mani gsk exh single	Mani gsk Perkins 0490228	22	
JE284	Ford	Ex fla 2 bolt	Ford Code-9453-A	41	
JE284		Exh fla flat 3 bolt		50	
JE285	Humber Super Snipe	Ex fla	P114340 MISC GSK PAYNE TODD	13	\$ 11.00
JE286	Chev V8	Ex fla		5	
JE289	Leyland	Ex fla		15	
JE298	Rover	Ex fla		lots	\$ 3.00
JE302	Rover	Ex fla flat 4 bolt		35+15	
JE320	Triumph	Ex fla	STANDARD GEG702	11	
JE329	Austin A110	Ex fla		12	\$ 5.00
JE331	Triumph			1	\$ 5.00
JE335	Austin A70 BMC	Ex fla		7	\$ 7.00
JE337	Triumph	Exh fla gsk			\$ 8.00
JE340	BMC 5.1,5.7	Ex fla	Ex. Flange Leyland AMK9313 P&T	11	\$ 12.00
JE342	Ford Trader	Exh fla gsk	EIADKN-9450B Ex pipe gsk	19	\$ 2.00
JE363		Exh fla ring	On Deletion 1862	17	
JE375	Holden	Exh fla ring		1	\$ 3.00
JE383	Vaux 3.3, Bedford CF	Exh fla gsk		8	\$ 8.00
JE398	Vaux OHC engs	Exh fla gsk			
JE565		Ring gask 1.650" ID	On Deletion 2434	30+29	
JE591	Holden Opel	Ex fla -twin		14+23	
JE627	Nissan TD42, L28 etc	Ex fla -twin		1	\$ 9.00
JE646	Peugeot	Exh fla ring		2	
JE647			On Deletion 2058	416	

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

JE648	Renault	Exh fla? Twin	77-00-502-706 MISC GSK RENAULT	11	
JE650		MGE or exh fla twin	Manifold gask. T F16175200	6	
JE665	Honda	Exh fla ring		7	
JE666	Honda	Ex fla	F/G HONDA 18303-659-S00	82	
JE667		Exh fla twin flat 3 bolt		90	
JE673		Exh fla gsk -flat 3 bolt		40	
JE678		Exh fla gsk -flat 3 bolt		2	
JE679	Honda Civic 81-RR	Ex gsk ring		2+39	
JE683		Ex fla - flat 2 bolt 1.6"ID		25	
JE693	Mazda G6 +Subaru	Exh fla gsk		5	\$ 4.00
JE699	Chrysler	Ex fla -twin		3	\$ 3.00
JE704	Honda	Ex ring	HONDA 18212-689-003/000	46	
JE709	Mazda 626 79-83	Ex fla -twin		8	
JE719	Ford Sierra	Exh fla gsk -twin flat 3 bolt		2	\$ 4.00
JE735	Suzuki?	Copper ring -dished	On Deletion 2058	406	
JE735			Standard 56214	5	
JE751	Isuzu C223T	Exh fla ring		1	\$ 6.00
JE915		Exh fla gsk -twin flat 4 bolt (NO	Todd P103646	50	
JE915			G.M. 1047193	194	
JE932	Niss/Hol 6	Exh fla twin		1	
JF007	Honda	Exh fla ring	F/G Honda 18216-634-000	366	
JF015		Exh fla (turbo?)	EXHAUST PIPE E508-13-480NZ	61	
JF037		Ex graphite cone 45mm ID	GRAPHITE CONE 45mm ID	114	
JF040	Ford Falcon EA26 93-	Ex fla collar		6	
JF047	Nissan	Exh fla gsk		1	\$ 3.00
JF051		Ex fla collar		1	
JF066	Mits 4G32T	Ex fla to turbo	MIT.S.TREDIA JCMD000477	618	
JF068	Nissan TD23-27	Ex fla	3 bolt	1	\$ 10.00
JF087		Ex fla ring	EX.FLANGE GSK O 90917-06039-NZ	23	
JF105	Nissan TD42, 6G72 54mm ID	Ex fla	2 bolt	1	\$ 6.00
JF117	Mits	Ex fla	Ex. Flange Mits. JCMB687012/	201	
JF119		Converter gsk	CONVERTER GASKET	14	
JF124			OIL STRAINER GSK.DAIHATSU	1	
JF146		Exh fla -3 bolt		lots	
JF214	Toyo 3RZ-FE 16v DOHC	Ex fla collar		3	
JH007	Nissan J13, J15	Sump gsk		1	\$ 12.00
JH015	Mazda VC, MA, NA	Sump gsk		2	\$ 9.00
JH018	Toyota 3K -point arch ends, 18 holes	Sump gsk		yes	\$ 10.00
JH023	Toyota 5R early	Sump gsk		2	
JH024	Toyota M, 2M, 4M, 5MGE	Sump gsk		2	
JH034		Sump gsk		2	
JH040	Mazda 808	Sump gsk		1	
JH048	Nissan	Sump gsk	JC31313-10202	8	\$ 15.00
JH064	Mitsubishi 4G41/42, KE43/44/46	Sump gsk	SUMP GSK.MITS. JCMD010264	12	\$ 20.00
JH067	Toyo 5R 72-78	Sump gsk		1	\$ 10.00
JH068	Toyo	Sump gsk	SUMP GSK 12151-56020 TOYOTA	5	
JH069	Honda EB1, 2	Sump gsk		20+	\$ 15.00
JH071	Mitsubishi 4G51, 4G52	Sump gsk		3	\$ 20.00
JH170	Toyota 3K -round arch ends, 18 holes	Sump gsk		3	\$ 10.00
JH181/2		Sump rails	SUMP SIDES	20	
JH238		Sump gsk		3	
JH251	Morris 8	Sump rail pair		0	
JH258	IHC BD264 (conv. Set item)	Sump gsk		1	
JH261	Fergusson petrol 85 & 87mm bores	Sump gsk		27	\$ 15.00
JH277/8	Ford Trader 4 cyl to 1965	Sump rail pair	EIADDN-6710/11C Sump gsk Ford	58	\$ 15.00
JH287	Ford 100E	Sump rails	100E-6710/11 MISC GSK FORD	2	
JH291	BMC "B" early	Sump gsk	GEG503 SUMP GSK B.M.C.	20	\$ 10.00
JH298	Austin A70, A90 atlantic, Gipsy	Sump gsk		8	\$ 15.00
JH311	IHC?	Sump gsk	703840 R1	1	
JH319/20	Ford 105E	Sump rail pair	105E-6710/11-B SUMP SIDES FORD	28	
JH323	Perkins	Rectangular seal	Perkins 0490720	1	
JH326	Ford	Sump rails	CODE 6710/11B SUMP L&R FORD	6	
JH327	BMC 4 litre	Sump gsk			\$ 30.00

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

JH330	Vaux 3.3, 2.6	Sump gsk		5	\$ 25.00
JH337	Chrysler	Sump rails	1947677/8 L&R SUMP TODD CHRYS	4	
JH339	Chrysler Valiant slant 6	Sump rear	TODD REAR SUMP	55	
JH340	Chrysler Valiant slant 6	Sump front		1	
JH357		Sump gsk		3	
JH363		Sump gsk		2	
JH372		Sump sides	0999694 SUMP SIDES PERKINS	3	
JH376/7	Hillman Hunter -steel sump	Sump sides	1235112/3 SUMP SIDES TODD	3	
JH378/9	BMC "A"	Sump sides	SUMP SIDES GSKS. N 12G377/378	9	
JH396	BMC "B" late	Sump gsk		4	\$ 15.00
JH405	Ford Trader 4D	Sump rail pair	MISC GSK F 2701E-6710/11-B	9	
JH406/417	Ford Trader 6D	Sump rail pair	Part of HC057	10	
JH415/6	Ford	Sump rails	2730E-6710B/11A SUMP L&R FORD	8	
JH420	Ford Tractor 4 cyl 5000, 6600	Sump gsk		36	\$ 15.00
JH425	Rover 2.6 & 3 litre	Sump gsk	Massey Ferg. 825299M1	7	
JH445	Triumph 4	Sump gsk		1	
JH467	Ford Trader 4D	Mani gsk pr		1	
JH475			3795420/3 SUMP L&R GSK G.M.	5	
JH488/9	Ford	Sump rails	681F-6710/11AA SUMP SIDE FORD	4	
JH530	Toyo 3A	Sump gsk		5	\$ 14.00
JH846	Nissan	Sump gsk		3	
JH856	Ford Falcon 250	Sump set		4	
JH881	Lada Niva 1.6 83-88	Sump gsk		3	\$ 25.00
JJ072					
JJ075	Mitsu 4G32,33,36,37	Sump gsk		5	\$ 15.00
JJ093	Toyota 3K -flat arch ends, 18 holes	Sump gsk -rubber		15	\$ 13.00
JJ094	Toyota 4K -22 holes	Sump gsk -rubber		1	\$ 25.00
JJ106	BMC 3.4 3.8 diesel	Sump gsk		12	\$ 25.00
JJ115/6	Bedford 214	Sump rails	2681510/11 SUMP GSK GEN.MOTORS	9	
JJ119	Bed 466,500	Sump gsk		1	\$ 30.00
JJ133	Toyo Corsa, corrolla	Sump gsk		3	
JJ149	Mazda E3, E5	Sump gsk		1	\$ 12.00
JJ150	Toyota L diesel	Sump gsk -rubber		1	
JJ164	Nissan SD22 1979-82	Sump gsk		1	\$ 15.00
JJ261	Toyo B, 2B, 3B, 11B, 13B	Sump gsk		1	
JJ274	Mitsubishi 4G62, 4G63	Sump gsk		2	\$ 13.00
JJ278		Sump gsk		1	
JJ329	Nissan A10, A12, A14, A15	Sump rail pair	11132/3-H5000 SUMP SIDES NISSA	6	
JJ354	Mazda B3, B5, B6	Sump gsk -rubber		1	\$ 25.00
JJ358	Isuzu 4ZA1 - 4ZD1	Sump gsk		3	\$ 23.00
JJ376	Isuzu 4BC2	Sump gsk			
JJ378/9	Ford Falcon EA	Sump rail pair	EA FALCON SUMP GASKET	16	
JJ380	Holden VN, VR 3.8L V6	Sump gsk cork		1	\$ 23.00
JJ623	Nissan TD42	Sump gsk		1	\$ 20.00
JM020		Rocker cover gsk		1	
JM021	Vaux?	Rocker cover gsk		1	
JM023	Mitsu 4G32	Rocker cover gsk		6	\$ 8.00
JM028	Toyota 2R, 21R	Rocker cover gsk		5	\$ 10.00
JM029	Toyota 18R	Rocker cover gsk		1	
JM030	Toyota 5R	Rocker cover gsk	rubber		\$ 10.00
JM044	Nissan L20, L24, L26, L28	Rocker cover gsk		1	\$ 18.00
JM055	Nissan	Rocker cover gsk	NISSAN 13270-76200	16	
JM064	Toyota 5R		Sump gsk -rubber???	10?	\$ 12.00
JM069	Honda EB	Rocker cover gsk -rubber		1	\$ 14.00
JM071	Mits 4G51, 4G52 1973-75	Rocker cover gsk		2	\$ 42.00
JM221	Bedford 214 1938-57	Rocker cover gsk		2	\$ 20.00
JM252	Austin A110	Rocker cover gsk		2	\$ 15.00
JM255	Ford Zephyr mk2,3	Rocker cover gsk			\$ 18.00
JM260	Humber Super Snipe	Rocker cover gsk	ROCKER COVER GSK T P111395	6	\$ 25.00
JM261	Triumph 1200, 1300	Rocker cover gsk			\$ 12.00
JM264	Austin A70	Rocker cover gsk	ROCKER COVER GSK N 1B1247	1	\$ 15.00
JM267	Ford 100E	Valve cover gsk	VALVE COVER GSK F 100E-6521	1	
JM268	Leyland 600/680	Rocker cover gsk		2	\$ 25.00

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

JM271	Rover	Valve side cover	Rover 75, 90, 105 1950-59	20 plus	\$ 10.00
JM274	Austin A40 Devon, Somerset 1948-54	Rocker cover gsk		1	\$ 15.00
JM277	Fergusson, Vanguard	Rocker cover gsk			\$ 15.00
JM287	Rover 3 litre Mk 1, 1A, 75,90,100,105	Valve top cover		lots	\$ 16.00
JM290	Ford Consul mk1	Rocker cover gsk		1	
JM294	Vaux EIP	Rocker cover gsk	ROCKER COVER GSK G 7079699	0	
JM295	Ford Trader 1952-57	Rocker cover gsk		0	\$ 25.00
JM315	BMC "B"	Rocker cover gsk		1	\$ 9.00
JM330	IHC BD264 1 reqd	Rocker cover gsk		9	\$ 20.00
JM337	Ford Consul, Zephyr 4	Rocker cover gsk		1	\$ 18.00
JM346	Bedford 214	Rocker cover gsk		1	\$ 15.00
JM347	Vaux PA	Rocker cover gsk	On Deletion 2003	13	\$ 15.00
JM348		Rocker cover gsk	CYL. HEAD COVER P 0490491	22	
JM350	BMC	Rocker cover gsk	ROCKER COVER GSK N GEG452	2	
JM363	Rover 3 litre	Valve side cover	Rover 3 litre Mk 1, 1A, 100 1959-62, 95 19	10	\$ 11.00
JM373	Falcon	Rocker cover gsk -cork		1	
JM389	Leyland 400 V	Rocker cover gsk -cork	R/COVER GSK N 600906 G 6374879	12	\$ 15.00
JM394	Chev V8	Rocker cover gsk -cork		4	\$ 10.00
JM397	Vaux Victor	Rocker cover gsk -cork	rocker cover gasket	1	\$ 10.00
JM409	Vaux 3.3, 2.6	Rocker cover gsk		7	\$ 15.00
JM422		Rocker cover gsk	On Deletion 2405	10	
JM423	Ford Trader 4 cyll	Rocker cover gsk	528E-6584-B R/C gsk Ford	4	\$ 15.00
JM424	Ford Trader 6 cyl diesel 1957-66	Rocker cover gsk		2	\$ 25.00
JM434		Rocker cover gsk		2	
JM439	Skoda	Rocker cover gsk	110-092924 VALVE COVER SKODA	6	
JM444	Perkins	Rocker cover gsk	36811115 MISC GSK PERKINS	7	
JM449	Ford Trader 4D	Rocker cover gsk		4	\$ 25.00
JM450	Ford Trader 380 Dover etc	Rocker cover gsk		1	\$ 25.00
JM453	Ford V4	Rocker cover gsk		30+15	\$ 6.00
JM467	Hillman Hunter	Rocker cover gsk		10	\$ 10.00
JM474	BMC 3.4 3.8 diesel	Rocker cover gsk -10 holes	CMK1343 R/C gsk NZMC	20	\$ 15.00
JM477	Triumph 2.0, 2.5	Rocker cover gsk			\$ 10.00
JM482	Rover 3 litre Mk 2, 3 1962-67	Valve top cover		5	\$ 16.00
JM507	Rover	Rocker cover gsk	On Deletion 2405	17	
JM510	Ford Cort. OHV	Rocker cover gsk		1	
JM521	Daimler V8	Rocker cover gsk	307827 TOP COVER GSK DAIMLER	50	\$ 10.00
JM522	Leyland 400	Valve hsg gsk	604964 MISC GSK LEYLAND	23	\$ 11.00
JM534	Chrysler V8 318, 360	Rocker cover gasket		1	\$ 12.00
JM550	Bedford CF	Tappet cover gsk			\$ 15.00
JM553	Morris 8, ser E	Valve cover gsk	MISC GSK N AAA5381	0	
JM566	Chrysler	Valve cover gsk		2	
JM620	Try JM260				
JN014	BMC Kimberley 70-72, Ley P76 6	Valve cover gsk		2	\$ 20.00
JN015	Chrysler Hemi 6	Valve cover gsk		1	\$ 10.00
JN052	Holden 186,202	Rocker cover gsk		5	\$ 6.00
JN054	Ford Falcon NCF	Rocker cover gsk		1	
JN078	Isuzu 6BG1 86-	Rocker cover gsk		3	\$ 25.00
JN088	BMC Marina 1500, 1750	Rocker cover gsk		1	\$ 8.00
JN191		Rocker cover gsk		1	
JN248	Renault	Rocker cover gsk	On Deletion 2405	18	\$ 15.00
JN255	Ford Falcon	Rocker cover gsk		2	\$ 10.00
JN276	Mits 4G32	Rocker cover gsk	mitsubishi JCMD08785	112	
JN318	Honda EL	Rocker cover gsk	HONDA 12341-689000/12341PB2000	45	\$ 15.00
JN365	Mits 4G32 etc	Rocker cover gsk		1	\$ 9.00
JN368	Subaru Leone 1800	Rocker cover gsk			\$ 7.00
JN398		Rocker cover gsk -rubber		1	
JN405	Daihatsu DG3	Rocker cover gsk -rubber		1	
JN414	Suzuki F8A, F10A	Rocker cover gsk -rubber		1	
JN427	Mits 4G52, 4G54 narrow block	Rocker cover gsk -rubber	See VCK427		
JN433	Nissan CA -side distributor eng	Rocker cover gsk	R/C gsk D 13270-D0101	10	\$ 15.00
JN456	Isuzu 4FB1,FC1,FD1	Rocker cover gsk -rubber		1	\$ 18.00
JN471	Toyota 18RGEU	Rocker cover gsk	TOYOTA 178RGEU (R/C GSK.)	6	
JN473	Toyota 18RGEU	Rocker cover gsk		3	

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

JN475		Rocker cover gsk -rubber		lots	
JN493	Nissan LD20 1980-83	Rocker cover gsk -rubber		1	\$ 25.00
JN496	Mits 4G63	Rocker cover gsk -rubber		1	
JN504	Isuzu 4BD1	Rocker cover gsk -rubber		2	\$ 30.00
JN534	Ford	Rocker cover gsk -rubber?	Ford EIADKN-6571	693	
JN534	Honda EJ	Rocker cover gsk -rubber		5	\$ 15.00
JN537	Daihatsu CL 82-	Rocker cover gsk -rubber		11	\$ 20.00
JN573	Isuzu 4BA1, 4BB1, 4BC1	Rocker cover gsk -rubber		1	\$ 30.00
JN583	Honda EB, EN	Rocker cover gsk -rubber		1	\$ 18.00
JN609	Mitsubishi 4D30	Rocker cover gsk -rubber		1	\$ 15.00
JN616	Ford V6 2QRD 85-	Rocker cover gsk		1	\$ 10.00
JN639	Ford Falcon AH C/F	Rocker cover gsk		1	
JN642	Honda	Rocker cover gsk -rubber	Honda R/C gsk12332-PH7-003	84	
JN661	Isuzu 4BC2,4BD1T,4BE1	Rocker cover gsk -rubber		3	
JN682	twin cam	Rocker cover gsk -rubber		2	
JN700		Rocker cover gsk -rubber		1	
JN709	Mazda JE-ZE	Rocker cover gsk -rubber		1	\$ 22.00
JN713	Mitsubishi 6G71, 6G72 SOHC	Rocker cover gsk -rubber		1	\$ 18.00
JN714	Mazda JF/JE	Rocker cover gsk -rubber		1	\$ 15.00
JN722	Nissan LD20 1985-86	Rocker cover gsk -rubber		4	\$ 30.00
JN723	Nissan LD20 1987 on	Rocker cover gsk -rubber			\$ 30.00
JN897	Mitsubishi 4G15 12V 89-	Rocker cover gsk -rubber		1	
JN929	Holden Astra, Barina C14SE	Rocker cover gsk -rubber		1	
JN954	Toyo 3RZ-FE	Rocker cover gsk		7	\$ 35.00
JN965	Toyota 2L, 3L	Rocker cover gsk		1	
JP088	Subaru EJ20T 6/96- LH	Rocker cover gsk -rubber		1	
JR007	Toyo	Mani gsk Inlet	IN/MANIFOLD TOYOTA 17171-22010	30	
JR033	Ford Zephyr mk1 to 3	Front cover gsk	CYL. FRONT COVER F EOTA-6020-B	10	
JR043	Bedford 300	Front cover gsk	TIMING COVER GSK G 7075059	4	
JR064		Front cover gsk	TIMING COVER GSK N C8615	6	
JR071		Front plate gsk		11	
JR074		Front cover gsk	TIMING COVER GSK N C8656	6	
JR089			TIMING COVER GSK G 91024581	2	
JR112	Vaux 2.6, 3.3	Front cover gsk		1	
JR119	Leyland 400	Front cover gsk	FRONT COVER GSK G 6374933	32	
JR149	BMC	Front cover gsk		1	
JR152	Ford Trader	Front cover gsk	TIMING COVER F EIADDN-6020	13	\$ 10.00
JR176	Leyland 400		MISC GSK N 611098	33	
JR189			On Deletion 2237	6	
JR206	Ford	Front cover gsk (inj?)	TIMING COVER F C5NE-9F598-A	2	
JR214	Todd?	Front cover gsk	MISC GSK T 71241046	3	
JR224	BMC "B"	Front cover gsk		10	\$ 4.00
JR239	BMC	Misc. gsk	32H 171misc gsk BMC	7	
JR260	Ford V6/4	Front cover gsk		1	
JR263		Front cover gsk	538039 ENGINE FRONT COVER GSK	3	
JR264	BMC	Front cover gsk		2	
JR434	Toyo	Front cover gsk	11328-31010 MISC GSK TOYOTA	3	
JR448/9		Front cover gsk		10	
JR450	Toyota 3K	Front cover gsk		6	
JR466		Front cover gsk	2899069 TIMING COVER GSK T	3	
JR472	Mazda VC,MA 75-80	Front cover gsk		8	
JR473	Mazda	Front cover gsk	0290-10-512NZ TIMING COVER MAZ	10	
JR519	Nissan		MISC GSK. NISSAN 13044-18001	9	
JR552	Ford Falcon 6	Front cover gsk		30	
JR607/8		Front cover gsk	E301-10511A/512 TIMING COVERS	129	
JR611	Mits?	O ring	JCMD020256 'O' ring (rubber)	26	
JR612	Toyota 4K	Front cover gsk	MISC GSK. O 11328-13011	112	
JR624	Holden V8	Front cover gsk		1	
JR626/649	Mits	Front cover gsk	JCMD002252/3 CHAIN CASE MITS	4	
JR659		Belt cover gsk -rubber	T/BELT COVER	141	
JR672	Suzuki	Front cover foam	T/C FOAM SUZUKI 11396-82000	9	
JR678	Toyota	Front plate gsk	FRONT PLATE TO BLOCK GSK TOYOT	75	
JR689	Mitsubishi 4G61, 4G62, 4G63, 4G64	Belt cover gsk -rubber	For top cover (short)	2	\$ 6.00

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

JR691	Mitsubishi 4G61, 4G62, 4G63, 4G64	Belt cover gsk -rubber	MITSUBISHI JCMD041002	64	\$ 8.00
JR693	Toyota	Front cover gsk	MISC GSK.TOYOTA 11328-35010	13	
JR701	Toyota	Front plate gsk	C/CASE FRONT END PLATE GSK.TOY	11	
JR704	Honda	Belt cover gsk -rubber	RUB.T/BELT CVR.GSK 11831PB2000	9	
JR707		Belt cover gsk -rubber	T/BELT COVER GSK 11328-63010	6	
JR708		Belt cover gsk -rubber	T/BELT COVER GSK 11329-63010	6	
JR725	Nissan E13, E15	Top dust cover -rubber	RUB DUST COVER(TOP)13521-01M00	133	
JR743		Front cover gsk -rubber	TIMING CASE GSK 13521-D0113	15	
JR745	Nissan	Front cover gsk	NISSAN 13522-01E01	173	
JR747	Honda	Rubber	HONDA 11840-657-010	7	
JR748	BMC	Rubber block	BLMC AMK80	405	
JR760		Belt cover gsk -rubber	T/BELT COVER GSK 11328-11020	16	
JR805		Front cover gsk -rubber	D 13522-D0112 COVER GSK	77	
JR806	Nissan	Rubber seal	MISC.GSK.NISSAN 13523-01E00	202	
JR821	Honda	Rubber seal	RUBBER SEAL HONDA11821-634-000	44	
JR822	Honda	Rubber seal	RUBBER SEAL HONDA11831-634-000	44	
JR823	Honda	T/chain guide?	RUBBER SEAL 11841-634-000 HOND	15	
JR826		W/pump gsk -rubber	W.P SEAL GSK F FE1H-10-543C	15	
JR827	Mazda FE	W/pump gsk -rubber	W.P SEAL GASKET	210	
JR828	Mazda FE	W/pump gsk -rubber	W.P.SEAL GSK FE1H-10-545A	214	
JR921		Belt cover gsk -rubber	T/BELT COVER GSK.O 11328-15030	8	
JR932	Honda	Front cover gsk -rubber	HONDA TIMING COVER GASKET	19	
JR933	Honda	Front cover gsk -rubber	HONDA TIMING COVER GASKET	9	
JR973	BMC	Front cover gsk -rubber	GM/BLMC 3738405/AMK1572	252	
JR974		Belt cover gsk -rubber	T/BELT COVER GSK HH11840673000	5	
JR993	Mits	Front cover gsk -rubber	TIMING CASE GSK MITS.	4	
JR994	Mits	Front cover gsk -rubber	TIMING CASE GSK.MITSUBISHI	2	
JS027	Toyo 3K	Head rear plate gsk	HEAD REAR PLATE GSK.TOYOTA	365	
KA016	GM	Water pump gsk	7053203 WATER PUMP GSK GM	6	
KA033		gsk 3 bolt	On Deletion 2405 (150)	5	
KA051	BMC A30?	Water pump gsk	2A31 MISC GSK B.M.C.	5	
KA053	GM	Water pump gsk	WATER PUMP GSK 7075083 G.M.	8	
KA072	Fergusson	Water pump gsk	MISC GSK 825386M1 MASSEY FERG.	3	
KA079	BMC "B" early	Water pump gsk		10	\$ 4.00
KA081	Hill Hunter	Water pump gsk	Todd 9107026 Z-112	1636+8	
KA093	BMC "A"	Water pump gsk		6	
KA107	Hill Hunter	W/pump to cover gsk	WATER PUMP/TIMING COVR P111371	11	
KA114	Ford Escort	Water pump gsk		1	
KA127	Ford Falcon?	Water pump gsk	FORD CODE-8507A	11	
KA140	Mits	Water pump gsk	WATER PUMP GSK C 1947523 MITSU	8	
KA141	Mits	Water pump gsk	WATER PUMP GSK C 1947521 MITSU	5	
KA147	Leyland 400	Pump to head gsk	Pump to head 601219 Leyland	11	\$ 2.00
KA177	Standard	Water pump gsk	WATER PUMP GSK 138701 STANDARD	2	
KA184	BMC "B" late	Water pump gsk		10	\$ 4.00
KA199	Standard	Water pump gsk	WATER PUMP GSK 138702 STANDARD	14	
KA201	Ford V4, V6	Water pump gsk	MISC GSK 2724E-8513A FORD	19	
KA205	Hillman Hunter	Therm hsg to head gsk	TODD R71266220	7	
KA211	Leyland 400		MISC GSK 611122 LEYLAND	4	
KA217	Bedford CF	Water pump gsk	WATER PUMP GSK 7201112 G.M.	8	
KA226	BMC	Water pump gsk	WATER PUMP GSK 32H83 BMC	4	
KA229	GM	Water pump gsk	WATER PUMP GSK 7204348 G.M.	9	
KA261	Mits	Water pump gsk	WATER PUMP GSK R71266362 MITSU	5	
KA274	Standard	Misc. gsk	MISC GSK 138792 STANDARD	8	
KA289		Water pump gsk		1	
KA290	Rover	Water pump gsk	WATER PUMP GSK 610756 ROVER	3	
KA446	Mazda VC,MA small type	Water pump gsk		6	
KA458	Mazda VC,MA large type	Water pump gsk		2	\$ 5.00
KA479	BMC		MISC GSK AYD57 BMC	1	
KA483	BMC	Water pump gsk	WATER PUMP GSK 62H350 BMC	4	
KA552	Nissan	Therm gsk	MISC GSK 11062-M3001 NISSAN	75	
KA553	Nissan	Therm gsk	MISC GSK.11062-Y7000 NISSAN	97	
KA554	Subaru	Therm gsk	T/STAT GSK 81755-4100 SUBARU	4	
KA555		Therm gsk	WATER OUTLET GSK O 16341-38011	126	

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

KA593	Nissan	Misc. gsk	MISC GSK NISSAN 21074-13200	9	
KA635	Honda	Water pump gsk	EW HONDA WATER PUMP GSK.	16	
KA664	Nissan CA	Water pump gsk		1	\$ 3.00
KA806	Mits	Water pump gsk	WATER PUMP GASKET MITSUBISHI	9	
KA813	Suzuki	Plate gsk	PLATE GSK.SUZUKI	7	
KD013	Austin A70	Carb gsk	Use KD120		
KD018	Standard Vanguard	Carb gsk	STANDARD 60574	9	
KD025	Ford Consul mk1	Carb gsk		1	
KD029	Austin A40 Devon, Somerset 1948-54	Carb gsk	B.L.M.C. 11G258 when gone use KD104	17	
KD073	Standard	Carb gsk	CARB GSK 126902 STANDARD	4	
KD081	BMC	Carb gsk	CARB.GSK.12B814 NZMC	16	
KD082	Standard	Carb gsk	MISC GSK. G 6366862	9	
KD097	Standard	Carb gsk	MISC GSK 147659 STANDARD	40	
KD098	Ford	Carb gsk	FORD FACINGS ONLY 2724E-9447B	13	
KD104	BMC/GM	Carb gsk	NZMC GTG109/527235 Z-225	lots	
KD111	GM	Carb gsk	GM 1017700	18	
KD120	Bed	Carb gsk	G.M. 1047192	46	
KD124	Mits	Carb gsk	CARB.GSK 110417 MISUBISHI	36	
KD136	Jag, Rover	Carb gsk	CARB.GSK.JAG.C2368.STD.112867	76	\$ 3.00
KD147	BMC	Carb gsk			
KD163	Ford	Carb gsk	FORD 204E-9447B	27	
KD170	Rover	Carb gsk	CARBURETTOR GSK 278163 ROVER	4	
KD171	BMC	Carb gsk	CARB.GSK.NZMC SCM5075	18	
KD172	Bed	Carb gsk	CARB GSK. G.M.7144235	23	
KD185	Ford Falcon	Carb gsk	MISC GSK.CODE-9455-A FORD	6	\$ 4.00
KD197		Alu washer			
KD205	BMC Healey 3000	Carb gsk	N AEC2083	85	\$ 4.00
KD215	Standard	Carb gsk	STANDARD 137881	60	
KD225	Fiat	Carb gsk	MISC GSK 4121933 FIAT	6	
KD226	Fiat	Carb gsk	CARB. ADAPTOR GSK 4100576 FIAT	3	
KD227	Humber Super Snipe	Carb gsk	CARB.GASKET 1228132 MITS.	8	
KD237	Ford	Carb gsk	CARB.GSK 2725E-9L553-A FORD	5	
KD240	Hillman Hunter A/H	Carb gsk	TODD 1238506 GSK	84	
KD242	GM Vaux/Bed	Carb gsk	G M 7130614	35	
KD243		Carb gsk	On Deletion 2405 (8)	lots	
KD254	Bedford CF	Carb gsk	CARB.GSK 6360874 GENERAL MOTOR	7	
KD256	Fiat	Carb gsk	MISC GSK 4123923 FIAT	14	
KD258	Hillman Hunter A/H		TODD R01240873 GSK	10	
KD260		Carb gsk	On Deletion 2405	9	
KD274	Standard	Carb gsk	CARB.GSK	39	
KD275	Rover	Carb block -4 bolt	ROVER 610849	45	
KD293	Rover	Carb gsk	ROVER 568365	57	
KD296	Ford	Carb gsk	FORD 213E-9447	10	
KD313	Standard	Carb gsk	CARB. GSK.157068 STANDARD	2	
KD329	Ford	Carb gsk	CARB. GSK.109E-9447 FORD	8	
KD497	Mits	Misc. gsk	MISC GSK C 2468818 MITSUBISHI	5	
KD668F		Carb gsk	CARB FACINGS 71272810 MITS.	12	
KD674	Ford	Misc. gsk	MISC GSK 957E-9448 FORD	11	
KD680	Mits	Carb gsk	MITSUBISHI JCMD021255	9	
KD681	Mits	Carb gsk		2	
KD701	Triumph	Carb block -2 bolt	CARB. INSULATOR	124	
KD903	Honda	Rubber seal	HONDA	34	
KD905	Honda	O ring	HONDA	46	
KE009/L	Nissan	Carb gsk	NISSAN BLOCK FACING	14	
KE009/R	Nissan	Carb gsk	NISSAN FACING	13	
KG000	Rover	O ring	1 1/8"x.140" from CC941 number unknown	yes	
KG006	BMC	Fibre washer	B.L.M.C.FIBRE WASHER 13.7X20mm	112	
KG030	GM	O ring	GM 838210/3835246	18	
KG033	Bedford early	Valve seal -felt	G.M. 1044226	41	
KG041	Rover	Fibre washer	Rover 531742/016828 Zenith	528	
KG061	BMC "B & C"	Valve seal		100	\$ 0.50
KG065	BMC "B"	Seal front felt	(neoprene = NA473)		
KG067	Hillman Hunter	O ring distributor	TODD 212173 2-215	39	

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

KG069	Rover	O ring		yes	
KG073	BMC A40-A90	Valve seal -flat	B L M C 1B1479	119	\$ 2.00
KG088	BMC "C", A70	Seal front felt	TIMING COVER SEAL 2K7139 NZMC	27	\$ 11.00
KG092	Ford V6	Fuel pump seal	AC FUEL PUMP SEAL	14	
KG112	Rover	O ring	ROVER 233419	12	
KG114	Fergusson	Fibre washer	Mass/Ferg 825296M1	44	
KG115		Fibre washer	B L M C ZZA1566 (26)	7	
KG117	Rover	Dist cork ring	DISTRIBUTOR GSK 52278 ROVER	8	
KG121	GM	Fibre washer	G.M. 6348488	139	
KG125	Ford Trader/GM	Block to head oil passage	GM 8839241	25	
KG126			Niven C3505/44	107	
KG134	Austin A40 - A110	Therm gsk	B.L.M.C. 1G1365	44	\$ 3.00
KG140	Fiat	Fibre washer	FIAT 10279985	30	
KG148	Bedford 466	Cork ring	G.M. 7075286	172	
KG179	Ford	Fibre washer	FORD 118324ES	0	
KG186	BMC 3.4 3.8 diesel	Valve seal -flat		395	\$ 2.00
KG205		Sump plug washer	WASHER DRAIN PLUG GSK.G7138296	17	
KG209	Rover/Todd	O ring	TODD 2095740/532322 ROV. 2-216	21	
KG218	Ford Zephyr mk1,2,3	Valve seal -umbrella		12	\$ 2.00
KG239	Rover	O ring	ROVER 246169	6	
KG240	Rover	O ring	ROVER 268887 2-129	7	
KG249	Rover, Bed CF	O ring	ROVER 247186 2-011	81	
KG255	Jag	O ring	JAGUAR C2312 2-320	13	
KG256	Ford	Rubber seal	EIADKN-6761	18	
KG275	BMC 3.4 3.8/Ford	Valve seal -flat	B L M C AMK125	100	\$ 3.00
KG275?			R/C Gsk EIADKN-6521 Ford	5	
KG303	Chrysler Valiant 6, 8cyl 1961-79	Valve seal		4	
KG316	Umbrella 11/32", 3/4" OD	Valve seal -umbrella		150	
KG316		Valve seal	On Deletion 1076	101	
KG317	Ford Falcon	Valve seal		12	
KG323	Holden Red	Dist gsk ring	G 6256636	65	
KG352	Mits	Air filter cork ring	AIR CLEANER GSK C1947797 MITSU	40	
KG356	Leyland 400	O ring	T/G.M. 600174/6374857 2-218	98	
KG357	Leyland 400	O ring	T/G.M. 600876/6374871 2-119	94	
KG358	Leyland 400	Valve seal	O RING G.M 6374634 2-110	794	\$ 2.50
KG359	Leyland 400	O ring -rocker bracket	G.M. 6382022 2-113	85	\$ 2.50
KG360	Jag	O ring	JAGUAR C20249 2-330	5	
KG364	Ford/Toyo	O ring	TOYOTA 90301-06031 2-010	3	
KG378	Ford V6, Albion	O ring	ALBION 231K17 2-210	7	
KG380	Hillman	Valve seal O		54	\$ 1.50
KG407	Jag	O ring	JAGUAR C19044 2-213	66	
KG409	Leyland 400	O ring	O ring about 12.5x17.5x2.5	1636	\$ 1.50
KG409			Rocker cover gasket U300/JN534	5	
KG423	Rover	Rubber seal	ROVER 506069	15	
KG430	Rover	O ring	RUB. SEAL N267828,C14990 2-212	16	
KG431	Bedford 466, 381	Seal head to block 1 3/16"	RUBBER RING G.M. 6399008 2-31	5	\$ 6.00
KG453	Hillman Imp	Valve seal	TODD 7100318	18	
KG466		Valve seal		19	
KG467	Ford V4, V6	Valve seal -umbrella		265	\$ 1.50
KG469	Leyland 400	O ring	LEYLAND 606597 2-204	117	\$ 3.00
KG477	BMC "A" & "B"	Side plate bolt rubber	RUBBER RING GSK.N 12A1176	72	
KG486	Ford Trader	O ring -flat	FORD 116572ES	14	
KG495		Fibre washer		8	
KG511	Rover		ROVER 532387	20	
KG526	Jag		JAGUAR 19869	13	
KG535		O ring	Massey Ferg. 184182M (98)	3	
KG536		O ring	Misc. Gsk. CAM5114 NZMC (9)	8	
KG547			11K 7521	10	
KG549	BMC	O ring	NZMC 602634 2-230	202	
KG564	BMC	O ring	B.L.M.C. 22A1563 2-012	40	
KG569	Ford	O ring	FORD 204E-12143 2-021	40	
KG574		Valve seal		2	
KG583	Bedford CF	Valve seal -inl			\$ 5.00

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

KG593	BMC	Copper washer	N Z M C 232037/MYH204	12	
KG594	BMC/Rover	Washer	ROVER/BLMC 272474/12H220	17	
KG595	Ford	Copper washer	FORD E3CH9/T.156768 NZMC232038	37	
KG601	Rover	Washer	ROVER 273069	79	
KG611	Leyland 400	Injector washer	COPPER WASHER G 7146267	701	\$ 4.00
KG619	Ford Trader 330-380	Copper washer	OIL PRIME PLUG WASH F118194ES	142	
KG621	Ford Trader 330-380	Inj atomiser	MISC.GSK FORD E16CL9,N AJR2148	69	\$ 4.00
KG623	IHC	Copper washer	I H C 62866D 231575	10	
KG631	Ford	Washer	FORD 681F-6L076-AA,116087ES	43	
KG632		Alloy washer		67	
KG640	Rover	Copper washer	ROVER 243967	27	
KG650	Ford	Copper washer	FORD 112304ES	103	
KG651	Lister	Copper washer	LISTER 013-22-350	16	
KG652	BMC	Copper washer	COPPER WASHER N 243958/6K638	61	
KG664	Austin/Rover	Copper washer	ROVER 247179.247479.11B276	47+600	\$ 3.00
KG669		Copper washer		30	
KG671	BMC	Copper washer	243959	13	
KG673	Rover	Copper washer	ROVER 243968/230507	18	
KG677	Bedford 330	Steel shim	CYL.HEAD STUD. 6377073	17	
KG682	Ford Trader 330-380	Sump plug washer	FORD 105E-6734,NZMC 232044	325	
KG683	BMC	Copper washer	B L M C AEC699	9+150	
KG685	Rover	Copper washer	ROVER 213961 NZMC 6K431	7	
KG686	Bedford 466, 500	Sump plug washer	SUMP DRAIN PLUG GSK.GM 7144743	47	
KG690		Copper ring		100	
KG697		Copper ring	On Deletion 2237 (4)	9	
KG706	IHC?	Copper ring	Misc gsk I 710382R1	23	
KG724	IHC BD264 -8 reqd	Washer 48.3x43.3x1.2	IHC 43002DA	188	\$ 8.00
KG742	Holden?	Nylon washer	NYLON WASHER G 7417490	725	
KG757	GM	Fibre washer	G M 1028313	55	
KG758	GM	O ring	GM 6358834	74	
KG760	GM	Foam washer	G M 7187745	12	
KG765	Vaux Viva	Valve seal	VALVE STEM SEAL G 8835236	364	
KG767	Jag	Cork ring	JAGUAR C2430	8	
KG768	BMC	O ring	B.L.M.C. 13H6766 2-017	11	
KG770	Ford	Rubber seal	FORD E832109582	302	
KG775		O ring	O ring about 10x15x2.5	14	
KG780	Bedford CF	Copper Washer	G M 115308	112	
KG788	Rover	Copper Washer	COP.WASH 19.5X27.5 ROV.603521	6	
KG794	IHC	Copper Washer	Copper washer I 710383R1	13	
KG819	Vaux 3.3, 2.6, Holden	Valve seal		40	\$ 1.00
KG824	Leyland 400	Nylon washer	G M 6374976	48	
KG831	Ford Trader 330-380	O ring	FORD 116567ES 2-168	11	
KG835		Felt pad	G 7154179	35	
KG863	Ford	Rubber ring -flat	FORD 692F9364AA	8	
KG864	Ford	Rubber ring -flat	FORD 692F9K354AA	11	
KG881	Ford Trader 330-380	Rubber ring -flat	FORD 116670ES	70	
KG883	Ford	Nylon washer	FORD 70TM6734AA	26	
KG897	Isuzu C223, G150	Valve seal O	Can use KG380	16	\$ 4.00
KG964		Therm hsg gsk	WATER OUTLET GSK D 11062-18000	175	
KH060		Valve stem seal (O ring)		21	
KH061	Toyo	O ring	TOYOTA 90301-44049	19	
KH062	Nissan	O ring	NISSAN 22180-71200	59	
KH066	Toyo	Valve seal O		8	\$ 1.00
KH071	Nissan	Valve seal		yes	\$ 2.00
KH086	Mazda	O ring	MAZDA 0107-18-201	46	
KH199	1 1/8" x 5/16"	Rocker bolt seal	MISC GSK O 90210-08017	577	
KH252	Ford Cortina	Valve seal -umbrella	VALVE STEM SEALS F 731M6571A1A	1362	\$ 2.00
KH267	BMC	O ring	B M C 318B447	7	
KH465		Copper washer		60	
KH755	Jag	Copper washer	JAGUAR C21171	20	
KH889	Broomwade	Copper washer	BROOMWADE C3615/10	47	
KJ024	Suzuki	rubber seal	Suzuki (35)	20	
KJ105	Nissan	Seal head to block -oil feed	NISSAN 11045-H1000	196	

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

KJ127	Toyota 6R-12R	Valve seal		yes	
KJ191	Bedford 500	Seal head to block 1 5/16"OD	Camira	37	\$ 6.00
KJ196	GM	Copper washer	G.M.	54	
KJ197			Campair NZ C3615/9	82	
KJ206	Nissan	Rubber washer	NISSAN 15270-78500	35	
KJ211	Mits 4G32 etc	Valve seal		8	
KJ212	Mits 4G32 etc	Rocker bolt seal		1	
KJ339	GM	Rubber ring (rect)	GM 638182	34	
KJ434	Mitsubishi	Bal thrust pl O ring gsk	Mits JCMD021045	18	\$ 4.00
KJ451	Nissan H20	V/seal special	NISSAN 13207-66711	345	
KJ453	Nissan	Valve seal		8	\$ 6.00
KJ454	Nissan A14, A15	Valve seal		1	\$ 5.00
KJ456	Honda EB1, EB3	Valve seal		yes	\$ 4.00
KJ458	Mazda	Valve seal	MAZDA 0221-12-190A	255	
KJ460	Mazda	Valve seal	MAZDA	347	
KJ461	Mazda	O ring	MAZDA 0324-10-155NZ	1415	
KJ462	Subaru	Valve seal		yes	\$ 3.00
KJ465	Honda Civic 1973-80	Valve seal		yes	
KJ468	Mazda TC	Valve seal		yes	\$ 2.00
KJ481	Bedford CF	O ring	G M 7217033	12	
KJ495	BMC	Fibre washer	BLMC 2K4954	8	
KJ570	Mitsubishi 79-	Valve seal		30	
KJ574	Toyo	Rocker bolt seal	TOYOTA 90210-13028	27	
KJ577	Mits	Valve seal	small umbrella	yes	\$ 3.00
KJ578	Mits	O ring		8	
KJ579		Valve seal		5+35	
KJ580	Honda	Valve seal	HONDA 12211-657-003	27+3	
KJ582	Subaru	Rocker bolt seal		5	
KJ641		Valve seal	USE KG303 WSN 2736	20	
KJ683	BMC	O ring	NZMC AAU1108	6	
KJ804	GM/Isuzu	Copper Washer	G M ISUZU 90957-14140	23	
KJ874	Toyo	Rubber strip	TOYOTA 11367-31020	15	
KJ887	Mazda	O ring	MAZDA 0118-10-432NZ	3	
KJ950	Mazda	O ring	MAZDA 9954-20-3001-NZ	18	
KJ951	Mazda	O ring	MAZDA 9954-10-1801NZ	15	
KJ952	Mazda	O ring	MAZDA 9954-10-0901NZ	205	
KJ962	Mits	Copper Washer	MITSUBISHI JCMF660061	12	
KJ990	Mits	O ring	MITSUBISHI MD030763	229	
KK006	Perkins (Honda?)	Ex fla gsk	Honda	7	
KK009	Falcon C/F	Exh fla ring	Exh fla ring	0	\$ 2.00
KK022	Austin A40 Devon, Somerset 1948-54	Hot box gsk	HOT SPOT GSK 1A2099 NZMC	8	\$ 4.00
KK037	BMC	Hot box gsk	B L M C 2A106	15	
KK059	Daimler	Mani gsk		1	
KK070	Ford Trader 330-380	Steel shim gsk	FORD 2700E-2946-B	31	
KK072	Bedford 214 (early?)	Hot box gsk 84mm x 90mm		yes	\$ 10.00
KK073	Bedford 214	Hot box gsk 90mm x 116mm	G M 7075246	19	\$ 8.00
KK078	Bedford CF	MGE/spark plug shroud		20	\$ 25.00
KK090	Leyland 400	Oil feed to rocker tube sleeve	LEYLAND 606598	299	\$ 6.00
KK091	Ford V4	Cam end seal		1	
KK095	Leyland 680	Ferrule brass	For head of modified engines	2	\$ 12.00
KK111	Rover	Alloy gsk	ROVER 541817	1	
KK113	Universal	Exh fla 23mm CA		3	\$ 5.00
KK114	Universal	Exh fla 27mm CA		4	\$ 5.00
KK115	Universal	Exh fla 31mm CA		3	\$ 5.00
KK116	Universal	Exh fla 32.5mm CA		3	\$ 5.00
KK117	Universal	Exh fla 35mm CA		1	\$ 5.00
KK120	Universal	Exh fla 45mm CA		11	\$ 5.00
KK121	Universal	Exh fla 48mm DSF		17	\$ 5.00
KK122	Universal	Exh fla 51mm DSF		1	\$ 5.00
KK123	Universal	Exh fla 54mm CA		1	\$ 5.00
KK276		Carb gsk	CARB GSK 0268-13-317NZ MAZDA	4	
KK5019	Mitsubishi 6G72/74, 4/6A11/12	Spark plug seal		3	\$ 6.00
KK5083		rubber		1	

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

KK956	Bedford 300, 500		G M 453675	63
KL196		Mani gsk (Inlet?)	PERKINS 36241505	25
KL342	Todd	Water pump gsk	T JCMD001309	4
KR094	Todd	Therm gsk?	Todd RP116888 B/S	12
KR116		Rocker cover gsk	TAPPET COVER GSK C55 NZMC	11
KR121		Sump end cork	152 x 6 x 11 gsk 19-6701 Ford	13
KR151	GM	Water gsk front	GM 1033350	45
KR161	Morris 8, ser E	Rear seal - rope		0
KR223	Bedford 300, 330 diesel	Mani gsk -Inlet	MANIFOLD GSK 7135808 G.M.	5
KR225	Bedford 300 petrol	Push rod cover gsk		5 \$ 15.00
KR291	IHC BD264	Water outlet gsk	Water outlet gsk 65986D IHC	5 \$ 6.00
KR291	IHC BD264 -1 reqd	Water outlet gsk		9 \$ 5.00
KR309	Std/Ferg	Liner gsk	MISC GSK 56286 STD/NORWOOD	5
KR328		Distributor gsk	Distrib gsk 825662M1	6
KR335	Standard?	Oilpump gsk?	Oil pump gsk 825652M1 N56282	7
KR351	BMC "C", Vanguard	Therm hsg gsk	B L M C GTG103	25 \$ 4.00
KR352	Standard	Main bg cap cork	Bearing seal gsk 59381 Std NZMC	40
KR392	IHC BD264 (conv. Set item)	Therm gsk	Thermostat gsk 45984D IHC	6 \$ 6.00
KR395	IHC BD264 -1 reqd	Injection gsk		4 + 5 \$ 8.00
KR418	Rover	Insp cover gsk	INSPECTION COVER GSK 50216 ROV	7
KR470	Leyland 400		C/case gsk 7146172 GM 234378	3
KR499	Jaguar	Water outlet gsk	WATER OUTLET GSK.C2380 JAG.	4
KR501		Oil pipe gsk	OIL DELIVERY PIPE GASKET	6
KR502			Rev counter adaptor gsk C2289	16
KR505	Jaguar	Front cover gsk	FRONT COVER GSK C2227 JAGUAR	5
KR521	Leyland 400	Oilpump end plate gsk		16
KR521		Suction branch gsk	Suction branch gsk 232336 Leyl	5
KR524	Leyland 400	C/case gsk	CRANKCASE GSK 7148285 GM 237960	8
KR554	Ford Trader	Water pump gsk	FORD EIADKN8507A	5 \$ 5.00
KR555	Ford	Fuel pump gsk	Ford EOTA9417A	17
KR556	Ford Consul, Zephyr 4	Side plate gsk	MISC GSK EOTA-6521 FORD	1 \$ 15.00
KR559	Jaguar	Therm gsk	Thermostat gsk C2475 Jaguar	7
KR571	Ford Zephyr 6	Side plate gsk		1 \$ 10.00
KR595	Leyland 400		Starter motor gsk 273006 Leyla	3
KR605	BMC	Sump end cork	BLMC 2A280	9
KR611	BMC	Water pipe gsk	BLMC 88G221	111
KR613	Bedford 214, Vaux EIP	Sump end cork	G M 364396/7080530	10
KR615	Bedford 466, 500, 300	Water outlet gsk	MISC GSK. GM 7075138	3
KR616		Felt packing -cap sides		1
KR616-24	Bed/Vaux	Felt packing -cap sides		9 \$ 8.00
KR619	GM	Bell hsg gsk	CLUTCH/TRANS.GSK 7083018 GM	5
KR654	Ford Trader	Push rod cover gsk	Peugeot	51 \$ 8.00
KR665	Perkins	Therm hsg gsk	WATER OUTLET GSK 0490184 PERKI	10
KR667	Ford Trader 380 Dover etc	Therm hsg gsk	FORD EIADKN8587	14 \$ 5.00
KR725	Standard	Therm hsg gsk?	STANDARD 104939	27
KR732	Ford 100E	Front cover gsk	Ford 100E6020	10
KR753	BMC 3.4 3.8 diesel	Mani gsk inl	Suzuki (47)	17
KR763	Leyland 400		MISC GSK 7146164 GM 289021 LEY	11
KR770	BMC A,C	Oil filter hsg gsk	Oil pump gsk 62B5 NZMC	20
KR815	BMC B	Oilpump gsk	BLMC 88G420	19
KR816	BMC	Oil pickup gsk?	BLMC 88G423	20
KR850	BMC	Side cover gsk	Side cover gsk AEC310 NZMC	8
KR856	BMC	T/C tens gsk	BLMC AEC339	6
KR910	BMC	Fuel pump gsk	BLMC 1G2615	11
KR914	Austin A110	Front cover gsk	TIMING COVER GSK AEC202 NZMC	6
KR951	IHC BD264 -1 reqd	Pump gear gsk		4 + 5 \$ 8.00
KR954	IHC BD264 -1 reqd	Push rod cover gsk		12 \$ 16.00
KR992	Humber Super Snipe	Fuel pump gsk	FUEL PUMP GSK TP44994/N BMK652	10
KR993	GM	Distributor gsk	Distributor gsk 3836247 GM	6
KS021	Jaguar	Water pipe gsk	Waterpipe gsk C11577 Jaguar	6
KS024	Jaguar	Sump end cork	Sump seal rear C2302/S Jag	20
KS109		Cyl head cover gsk	Cyl head cover gsk	15
KS127	Rover	Oil filter hsg gsk	Oil filter Rover 298354/598354	5

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

KS129	Jaguar	Water pipe gsk	Water pipe gsk C12309 Jaguar	19	
KS148	Perkins	Cyl head front gsk	CYL.HEAD FRNT.GSK 0490482 NORW	8	
KS154	Rover	Misc gsk	ROVER 247555	8	
KS156	Rover	Distr pump gsk	Distr pump gsk 247212 Rover	12	
KS157	Rover	Misc gsk	ROVER 247554	32	
KS159	Ford Trader 6	Rocker cover gsk	ROCKER COVER GSK 508E-6521-1/2	4	\$ 10.00
KS161	Rover	Air filter gsk		yes	
KS170	Vaux 2.6, 3.3	Water pump gsk		2	
KS195	Vaux 2.6, 3.3	G/box gsk	G/BOX/CLUTCH HOUSING 7140240	0	
KS227	Humber Super Snipe	Therm gsk	Therm housing gsk P111446 Mits	15	
KS266	Standard	Front plate gsk (1 of 3 possible)	FRONT ENGINE PLATE 205457 STD	2	
KS290	Toyota 3K, 4K etc (also LT220)	Therm hsg gsk		1	
KS307	Ford Cortina	Oilpump gsk		lots	\$ 5.00
KS308	Ford	Sump end cork	Ford E21-CE-1	12	
KS367			CYL.REAR CVR.PLATE GSK 0490485	4	
KS374	Ford	Therm hsg gsk	Ford CODE8255A	32	
KS376	Ford	Oilpump gsk	OIL PUMP GSK CODE-6626-A FORD	2	
KS376			Oil pump gsk CODE-6626-A Ford	13?	
KS410	Vaux 3.3	Push rod cover gsk		5	\$ 25.00
KS422		Sump end cork	Sump rear oil seal C16315	23	
KS489	IHC	Oil pipe gsk	Oil pipe gsk 840674R2 IHC	9	\$ 2.00
KS500	Mits	Front cover gsk	MISC GASKET C1947554 MITSUBISHI	5	
KS519	Jaguar	Rubber semi circle	JAGUAR C14991	32	
KS520	Leyland 400	Water pipe gsk?	Misc gsk 602024 Leyland	19	\$ 1.00
KS521	Leyland 400	Rear cover gsk	Rear cover gsk 6374922 GM	32	\$ 2.00
KS522	Leyland 400	Water outlet gsk	WATER O/LET GSK 600968 LEYLAND	24	\$ 4.00
KS523	Leyland 400	Water pump gsk	WATER PUMP 6374905 GM.601218	10	
KS535	Rover	Water pipe gsk	WATER PIPE GSK 90511958 ROVER	9	
KS536	Rover	Therm hsg gsk	Rover 511957/GTG117	6	
KS546	Vaux Victor FB, FC	Side cover gsk	PUSH ROD COVER GSK	7	
KS566	Leyland 400	Rear cover gsk	REAR COVER GSK 6374988 G.M.	16	
KS592	Standard	Air body gsk	Air body gsk 130415 Standard	7	
KS596	Ford	Misc gsk	MISC GSK. C20Z-6870-A FORD	4	
KS617	Fiat	W/outlet elbow	WATER O/LET ELBOW 4065247 FIAT	9	
KS683	Todd	Therm hsg?	TODD 1214649	7	
KS687	Jaguar	Air pipe gsk	AIR PIPE GSK. C15553 JAGUAR	7	
KS690L	Holden 149-186	rear seal lower		10	\$ 10.00
KS690U	Holden 149-186	rear seal upper		100	\$ 10.00
KS705	Ford Trader to 61	Front plate gsk		1	
KS706	Ford Trader 61-65	Front plate gsk		8	
KS707	BMC	Oil filter hsg gsk	FUEL PUMP GSK..NZMC 88G402	13	
KS723	Chev 216	Rear seal wick		2	
KS735		Misc gsk	G 6366775	19	
KS754	Ford Trader 4 & 6 cyl 1961-65	Sump front cork	SUMP SEAL FORD EIADDN6707	24	\$ 20.00
KS779			MISC GSK. 22H694 NZMC	8	
KS795	Humber Super Snipe	Misc gsk	MISC GASKET P111416 MITS.	15	
KS796	Humber Super Snipe	Therm?	MISC GSK.P111447 MITS.	6	
KS799		Bell hsg gsk			
KS803	Hillman Hunter	Sump end cork	SUMP SEAL HILLMAN	1	
KS806	BMC	C/case gsk	C/CASE - TRANS.R.H.22A883 NZMC	28	
KS808	BMC "B"	Front plate gsk	ENG. FRONT PLATE 12H1576 NZMC	17	
KS809	BMC "A", "B", "C" (cork)	Side plate gsk thick (thin KT005)	B L M C 12A1139	17	\$ 4.00
KS813	Ford Trader	Oil filter hsg gsk	FORD 2701E6838	7	
KS816	BMC (A?)	Front plate gsk		2	
KS879	BMC "A", "B"	Therm gsk	BLMC GTG101	469	
KS902		Misc gsk	PN 36862511 MISC GSK	198	
KS957	Jaguar	Oil cleaner gsk	OIL CLEANER GSK C19659 JAGUAR	97	
KS958	Jaguar	Oil pipe gsk	OIL DEL.PIPE GSK.C22598 JAGUAR	54	
KS981	Triumph	Main bg cap cork	TRIUMPH 3.6X14.7X25.4 36234	25	
KS982	Standard	Front plate gsk (1 of 3 possible)	FRONT ENG.PLATE GSK 215350 STD	4	
KS983	Standard	Fuel pump gsk	FUEL PUMP GSK 138591 STANDARD	5	
KT005	BMC "A", "B", "C" (cork)	Side plate gsk thin (thick KS809)		2	
KT015	Leyland 400	Misc gsk	MISC GSK. 602814 LEYLAND	39	\$ 3.00

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

KT018	BMC	Oil pump gsk	OIL PUMP GSK 12G730 NZMC	5	
KT034	GM	C/case gsk	C/CASE FRONT PLATE 7150666 GM	4	
KT035	GM	Front cover gsk	TIMING COVER GSK 6397043 G.M.	6	
KT036	Ford V8C	Therm gsk	F C30E-8255-A	8	
KT037	Ford	Mani gsk Inlet	IN MAN GSK 692F-9K438 FORD	6	
KT048	Ford Trader	Sump end rubber	FORD 693F-6723AAA	40	
KT049	Ford Trader	Sump end rubber	FORD 2701E6722B	21	
KT051	Ford Trader	P/steer pump gsk	P/STEER PUMP GSK.2700E-3A760A	29	
KT092		Carb/air filter gsk	ON DELETION 2058	258	
KT093	GM	Exhauster gsk	EXHAUSTER GSK.7166079 G.M.	9	
KT123	Leyland 400	Misc gsk	MISC GSK. 604849 LEYLAND	3	
KT124	Leyland 400	Misc gsk	MISC GSK. 604850 LEYLAND	11	
KT125	Leyland 400	Misc gsk	MISC GSK. 321062 LEYLAND	5	
KT126	Leyland 400	Misc gsk	MISC GSK. 611000 LEYLAND	5	
KT127	Leyland 400	Misc gsk	MISC GSK. 612603 LEYLAND	6	
KT145		Front plate gsk	FRONT PLATE GSK.	6	
KT149	Jaguar	Oil cleaner gsk	OIL CLEANER GSK.C20532 JAGUAR	7	
KT151		Misc gsk	ON DELETION 2237	83	
KT166		Main cap gsk	REAR MAIN BRG.CAP GSK.537279	10	
KT169	Rover	Therm switch gsk	T/STAT SWITCH GSK 535703 ROVER	12	
KT171	Rover	W/inlet gsk	WATER INLET GSK.538038 ROVER	11	
KT190	Bedford CF	Cam cover gsk		4	\$ 10.00
KT194			CONVERT HOUSING 22A1689 NZMC	10	
KT220	Bedford CF	Oil pump/Distr gsk	OIL PUMP GSK. 7206309 G.M.	23, 4	
KT221	Bedford CF	Oil filter hsg gsk	OIL FILTER GSK.7213450 G.M.	6	
KT223	Bed 214	Side plate gsk		1	\$ 22.00
KT233	Rover	Misc gsk	MISC GSK. 602633 ROVER	11	
KT235	BMC	Rear seal -rope	B L M C 602178	2	
KT236	BMC	Main cap seal	B L M C 603726	23	
KT237	Rover	Fuel pump gsk	MISC GSK.602180 ROVER	6	
KT238	Rover	Oil screen gsk	OIL SCREEN GSK 602068 ROVER	6	
KT245	BMC	Fuel pump gsk	FUEL PUMP GSK. 37D2891 NZMC	9	
KT260	Bed 214	Front plate gsk	MISC GSK. 7150668 G.M.	4	
KT261	GM	Fuel pump gsk	FUEL PUMP GSK. 7950173 G.M.	4	
KT290	Ford	Sump end seal -cork	FORD 2733E6722A	40	
KT300	BMC	Therm gsk	THERM/HOUSING GSK. 32H85 NZMC	47	
KT301	BMC Transv.	Sump side	TRANS/CRANKCASE GSK.42H147NZMC	4	
KT302	BMC Transv.	Sump side	TRANS/CRANKCASE GSK.42H336NZMC	6	
KT304		Bell hsg gsk	FLYWHEEL HOUSING 42H246 NZMC	3	
KT312	BMC	Air cleaner gsk	CARB/AIR CLEANER 12G2125 NZMC	34	
KT314		Misc gsk	ON DELETION 2237	87	
KT325	Standard	Misc gsk	MISC GSK. 150022 STANDARD	5	
KT327	Mits	Water pipe gsk	WATER PIPE GSK. R71241082 MITS	12	
KT331	BMC	Sump strip seal	SUMP STRIP SEAL GSK.N 12G3017	9	
KT346		Sump filter gsk	SUMP FILTER GSK.C 1881933	4	
KT370	Bedford 300	Misc gsk	G M 7075136	4	
KT398		Misc gsk	ON DELETION 2232	6	
KT436	Ford	Fuel pump gsk	FUEL - BLOCK GSK.11405218 FORD	297	
KT449	Ford	Fuel pump gsk	FUEL PUMP GSK F C5NE-9F585-A	10	
KT474	Ford 240,300 petrol	Sump end	FORD C5AE-6722-A	5	
KT477		Fuel pump gsk	ON DELETION 2237	4	
KT478	Vaux 3.3, Holden	Therm gsk	MISC GSK. GM 7401111	85	
KT495		Fuel pump gsk	FUEL PUMP GSK.2681874 GM	92	
KT497	Ford	Oil pump cover gsk	OIL PUMP GSK.682F-6626-AA FORD	22	
KT503	Rover	Misc gsk	MISC GSK.610387 ROVER	13	
KT506		Oil filter hsg gsk	OIL FILTER GSK.C14817	4	
KT507		Oil filter hsg gsk	OIL FILTER GSK.C15962	4	
KT508	BMC (A?)	Front plate gsk	MOUNTING PLATE 12G 2981 NZMC	5	
KT509	Rover	A/filter gsk	CARB/ADAPTOR GSK 610327 ROVER	33	
KT511	BMC	Main cap seal -cork	B L M C 611089	10	
KT515	GM	Fibre washer	G M 7209225	7	
KT519	Bedford 214	Oil filter hsg gsk	MISC GSK.6376139 G.M.	3	
KT529	Ford	Oil pump cover gsk	OIL PUMP GSK.71HM-6659-AA FORD	216	

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

KT540	Humber Super Snipe	Fuel pump gsk	FUEL PUMP GSK.R71244744 MITS.	9	
KT544F	Hillman Hunter	Fuel pump gsk	R25361300	27	
KT562	Jaguar	Therm gsk	T/STAT BY-PASS GSK.C2381 JAG	4	
KT569	Leyland 400	Sump side cover	MISC GSK.7148310 G.M.	8	\$ 10.00
KT570		Rear main oil plate gsk	MISC GSK. N 2A127	4	
KT585	BMC	Rear plate gsk	REAR ENG.PLATE GSK.1G2425 NZMC	1	
KT591	BMC	Misc gsk	MISC GSK.GFG111 (ATB7355) NZMC	7	
KT614	Ford Anglia	Rear oil hsg gsk	F 105E-6369	166	
KT620	Ford Falcon 200	Sump end rubber	OIL PAN FRONT	82	
KT621	Ford Falcon 200	Sump end rubber	FORD CODE6723A	71	
KT622	Ford	Rear seal - rope		1	
KT624	Ford 1600	Rear seal - rope 130 long black		9	
KT624	Ford 1600	Rear seal - rope 160 long white		lots	
KT630	Vaux PA, FB etc	Rear seal - rope	USE KT631		
KT631	Vaux 3.3, 2.6, Bed CF	Rear seal - rope	ROPE SEAL GSK 6390312	347	\$25/pr
KT632	Holden 202, Bedford	Rear seal - rope		1	\$22/pr
KT638	Ford Trader 380 Dover etc	Rear seal - rope	(Is neoprene 30136?)	12	\$15/ea
KT647	BMC	Rear main oil plate gsk	MISC GSK.AEG240 NZMC	9	
KT648	BMC "A"	Rear plate gsk	G/BOX MOUNTING PLATE AEG554	2	
KT649	Bedford CF	Rear cam cvr gsk	REAR CAMSHAFT COVER G 7204357	45	
KT651	Bedford 500	Rear seal - rope	GM 7159753		\$35/pr
KT655	BMC	Rear seal - rope	B L M C 602058	11	\$25/pr
KT658	BMC, Rover 3500	Rubber seal	B L M C 42B104	71	
KT695	Holden 161, 173, 202	Side plate gsk		7	
KT698	GM	Therm gsk	THERM.HOUSING GSK.7420090 GM	186	
KT699	Holden 4 & 6	Front cover gsk		9	
KT700	Ford V6	Nylon washer	NYLON WASHER 711M-6734-AA	30	
KT701	Holden	Sump end sea?		2	
KT727	Simca	Misc gsk	MISC GSK.F55123200 SIMCA	46	
KT737	BMC	Sump end rubber strip	B L M C 12G3016	7	
KT738	Ford Cort OHC	Therm gsk -rubber	FORD E853-1005	28+4	
KT739	Ford	Therm gsk	F 70HM-8255-AB	243	
KT740	Ford	Sump end rubber	FORD 681F6722A	140	
KT741	Ford	Sump end rubber	FORD 681F-6723-AA	176	
KV171	Holden 138	Side plate gsk		2	\$ 15.00
KV384	Ford	Misc gsk	FORD 2725E-9673C	4	
KV389	Toyo	Rubber ring -flat	TOYOTA 90430-07121	33	
KV441	Nissan	Main cap side seal	NISSAN 12289-B3000	29	
KV464	Toyo	Misc gsk	MISC GASKET TOYOTA	20	
KV467			SIDE PLATE GSK.TOY.11253-31011	16	
KV515	Holden V8 red	Therm gsk	T STAT GASKET HOLDEN V8 RED	11	
KV517	Holden 202	Rear seal - rubber	includes 97199	8	
KV518	Holden 202	Fuel pump gsk		4	
KV575	Mazda	Oil filter hsg gsk	OIL FILTER GSK 022114342NZ MAZ	18	
KV646	Nissan H20	Therm?	D 11062-S3001,G 8942098720	7	
KV647		Therm gsk	THERM. HOUS. GSK.D 11072-S3001	62	
KV648	Nissan	Misc gsk	MISC GSK.13050-21000 NISSAN	33	
KV692	Mazda various 1970-79	Therm gsk	WATER OUTLET GSK.0221-10-161NZ	25	
KV693	Mazda	Head end gsk	HEAD END GSK.0221-10-181NZ MAZ	106	
KV695		Side plate gsk	SIDE COVER GSK.M.0221-10523ANZ	58	
KV703	Mazda FE, E3, E5	Therm gsk		lots	
KV718	Standard	A/filter gsk	AIR CLEANER GSK.158712 STANDAR	23	
KV730	Todd	Main cap side seal	TODD 71268778	8	
KV780c	Ford EA26	Timing/head gsk -cork		3	
KV780r	Ford EA26	Timing/head gsk -rubber		3	
KV804	BMC		MISC GSK.AYH681 NZMC	6	
KV879	Mits	Fuel pump gsk	MISC GSK C 2843770 MITSUBISHI	5	
KV880	Mits	Misc gsk	MISC GSK.A2899202 MITSUBISHI	218	
KV954	BMC	Oil/crankcase gsk	OIL/CRANKCASE GSK.AYD103 NZMC	2	
KV955F	BMC	Fuel pump gsk	FACINGS ONLY AYD200 LEYL. NZMC	15	
KV966	Mazda	Baffle gsk	BAFFLE GSK.0305-10-229NZ MAZDA	21	
KZ816	Bedford 500	Water outlet gsk	WATER O/LET GSK.2693730 G.M.	7	
L590M81	Grease Nipple	Grease Nipple	M8 x 1 90Degree	40	

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

LA049	Mits	Rubber seal	mitsubishi JCMD009039	65	
LA053	GM	Front cover gsk	FRONT COVER TO BLOCK R.H. GM	4	
LA054	GM	Front cover gsk	FRONT COVER TO BLOCK L.H. GM	3	
LA059		Rubber ring flat	MISC GSK O 90430-40058	51	
LA090	Toyo	Water outlet gsk	WATER OUTLET 16341-63010 TOY.	18	
LA096	Toyo	Misc gsk	MISC GSK.16129-33030 TOY.	5	
LA104	Toyo	Water outlet gsk	H2O OUTLET TOYOTA 16235-70021	12	
LA110F		Fuel pump gsk	FUEL PUMP BLOCK FACING	183	
LA111	Toyo	Water outlet gsk	TOYOTA WATER OUTLET	31	
LA117		Oil seal retainer gsk	OIL SEAL RETAINER F801-11-318	21	
LA125	Suzuki	Therm gsk	T/STAT GSK.17569-82001 SUZUKI	21	
LA133	Mits 4G32T	Exh fla turbo to pipe	mitsubishi JCMD075943	55	
LA134		Therm gsk -3 bolt	H2O GASKET M S211-15-173	6	
LA174		Copper washer	1.5MM COP WASH ID12.14,OD17.46	312	
LA177	Nissan	Fuel pump gsk	FUEL PUMP GSK 16420-D0103 NISS	10	
LA179			OIL SEAL RETAINER GSK TOYOTA	5	
LA180	Mits?	Bolt rubber seal	JCMD010563 RUBBER SEAL	42	
LA187	Toyo	Exh fla -big	EX.FLANGE GSK.25576-13010 TOY.	11	
LA198		Therm gsk	T/STAT. GSK.	11	
LA199	Suzuki	Therm? Gsk	CAP GASKET SUZUKI 17569-80000	25	
LA219		Front cover gsk	FRONT COVER GSK	203	
LA251	Mits	Rear cover gsk	REAR COVER GSK JCMD030156	9	
LA383	Suzuki	Fuel pump gsk	FUEL PUMP GSK SUZUKI	28	
LA400		Water outlet gsk	WATER OUTLET GASKET	41	
LA452		Filler cap rubber	FILLER CAP S 80393-5010	7	
LA466	Nissan E13, E15	Therm gsk	THERM.HOUSING GSK. 11072-01M00	15	
LA468	Nissan E13/15	Oil seal retainer gsk	OIL SEAL RETAINER NISS. E13/15	7	
LA473	Nissan	Front plate gsk	FRONT COVER GSK NISSAN	12	
LA475	Nissan E13/15	Front cover gsk	FRONT COVER GSK NISSAN E13/E15	22	
LA481	Nissan	Carb gsk	INSULATOR GSK NISSAN	9	
LA488	Nissan E13/15	Oil strainer gsk	OIL STRAINER GSK NISSAN E13/15	18	
LA489	Nissan	Oil filter hsg gsk	OIL FILTER GSK.NISSAN	29	
LA490	Nissan	Oil strainer gsk	OIL STRAINER GSK.NISSAN	14	
LA491	Nissan	Oil strainer gsk	OIL STRAINER GSK.NISSAN	21	
LA492	Nissan E13/15	Oil pump cover gsk	OIL PUMP GSK NISSAN E13/E15	8	
LA494	Nissan	Oil pump to cyl gsk	OIL PUMP TO CYL. GSK.NISSAN	18	
LA499	Nissan	Oil filter hsg gsk	OIL FILTER GSK.NISSAN	18	
LA516		Insp. Cover gsk	FR.COVER GSK D 11049-D0101	15	
LA635	Toyo	Water outlet gsk	H2O OUTLET TOYOTA 16341-70010	4	
LA702		Oil strainer gsk	OIL STRAINER GASKET	16	
LA703	Toyo	Oil pickup gsk	OIL PUMP GSK.15197-15012 TOY.	27	
LB065	Toyo	Fuel pump gsk	FUEL PUMP GSK TOYOTA	10	
LB086	Nissan	Oil pump cover gsk	OIL PUMP GSK.NISSAN	6	
LB160	Honda	Carb gsk	CARB GSK 19313-PC6-000 HONDA	54	
LB316	Honda	Spark plug rubber seal		8	
LB318		Oil filler -rubber	OIL FILLER HH 15613-PC6-000	98	
LB363	Nissan	O ring	PACKING SUPPORT DIS.GSK NISSAN	22	
LB369		O ring	O RING	85	
LB475	Toyo (3K?)	Head front gsk	HEAD FRONT COVER GSK.TOYOTA	38	
LB498	Daihatsu delta	Therm gsk	T/STAT GASKET DELTA DAIHATSU	6	
LB519	Mits	Inj seal rubber	INJECTOR SEAL MITSUBISHI	194	
LB520	Honda	Misc gsk	MISC.GSK HONDA 18765-PA6-010	30	
LB537	GM	Carb gsk	CARB.INSULATOR GSK GM	7	
LB553	Honda F2	Sprk plug seal		19	
LB664		Fuel pump block	FUEL PUMP BLOCK	12+4	
LB792		Baffle gsk	BAFFLE GSK B630-10-229	23	
LR062	Ford Trader 330-380	Rubber seal	FORD 2701E-9K540A1/2	298	\$ 5.00
LR329	Rover	Cork ring large	Rover	7+68	
LR646	Honda	Misc gsk	Honda	31+4	
LR911	Nissan	Fuel pump gsk	FUEL PUMP GSK.17099-E3012 NISS	5	
LS358		Therm gsk	THERM.COVER GSK.19312-657-S00	9	
LS373	Mits	Rubber ring -large flat	MITSUBISHI JCMD001210	10	
LS374/5	Mits 4G54 etc	Front cover gsk	CHAIN GASE GSks JCMD020324/5	8	\$ 9.00

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

LS376	Mits 4G54 etc	Rear seal cover gsk	T JCMD020292	10	
LS377	Mits	Therm gsk	Use WG6		
LS379	Mits 4G54 etc	Misc gsk	T JCMD021539	33	
LS381	Mits 4G54 etc	Misc gsk	T JCMD003358	218	
LS390		Sump end	SUMP GASKET	13	
LS401	Holden V8	Water pump gsk		1	
LS562	Mits 4G54 etc		Todd 2899089	20	
LS623	Ford Trader 330-380	Ex	EXH.OUTLET 2704E-6K688-A FORD	12	
LS661	BMC "O"	Front cover gsk	?	66	
LS823	BMC Transv.	Sump side	C/CASE TO TRANS.L.H.N 22G1003	43	
LS874	Jag	Sump end rubber?	JAGUAR C36499	10+6	
LS928	BMC "O"	Cam end cover gsk	CAMSHAFT COVER CAM1879 NZMC	5	
LT098	Toyo	Cam end bung		1	
LT176	Toyo	Fuel pump block	TOYOTA 90923-06001	29	
LT220	Toyota 3K, 4K etc (also KS290)	Therm gsk	WATER OUTLET GSK.O 16341-13011	27	
LT226	Mazda	Therm gsk	THERM.GSK.0221-15-173NZ MAZDA	38	
LT244	GM	Sump end rubber	SUMP GSK GM 7020650	8	
LT245	GM	Rubber strip	G M 7020653	8	
LT246	Ford Y8C	Inlet Mani -valley ends	Should this be V8 Cleveland?	16	
LT273	Mits	Rear oil hsg gsk	REAR OIL CASE GSK.JCMD008886	8	
LT275	Mits	Oil screen gsk	OIL SCREEN GSK.JCMD008907 MITS	9	
LT276	Mits	Fuel pump gsk	JCMD008933 FUEL PUMP GASKET	379	
LT430	Mits	Fuel pump gsk	FUEL PUMP GSK..T JCMD030836	22	
LT442	GM	Front cover gsk	CRANKCASE GSK.90106432 G.M.	5	
LT443	GM	Misc gsk	FLANGE GSK.90122258 G.M	12	
LT577	Nissan	Insp. Cover gsk	FRONT COVER GSK. NISSAN	61	
LT581	Toyo	Sump gsk	Sump gsk Toyota	20	
LT582	Toyo	Oil filter hsg gsk	OIL FILTER GSK.TOYOTA	26	
LT810		Therm gsk	THERM.COVER GSK H19313-634-S00	5	
LT910		Rubber gsk	19305-PAO-000	48	
LT918		Therm hsg gsk	WATER OUTLET 11062-01M00	13	
LT983	Nissan	Erg valve gsk	ERG VALVE GSK 14719-N3301 NISS	24	
LV434/5	GM	Sump sides	SUMP GSKS.9945632/3 G.M.	30	
LV563		Inj adapt. Plate gsk	INJECT ADAPTER PLATE GASKET	23	
LV575	Mits 4G32 etc	Cam end plug		2	\$ 5.00
LV581	Ford	Fuel pump gsk	FUEL PUMP GSK 0107-13449 FORD	61	
LV599		Fuel pump gsk	FUEL PUMP GASKET	197	
LV619	Isuzu	Cam end plug	CAM PLUG ISUZU	151	
LV922		Water bypass gsk	WATER BY PASS GSK.16258-15011	18	
LV926		Breather cover gsk	BREATH.COVER GSK.12412-634-000	136	
LX020	Toyo	Rocker retainer clip	ROCKER RETAINER CLIP TOYOTA	1389	
M053-27-622A	Ford/Mazda	Seal		1	
MD311638	Mits 4D55/56	Oil filler seal		1	
MD603015	Mits	Rocker bolt seal		10	
MG0013	Toyota B, 3B, 11B 1988 on	Mani gsk exhaust	A868	5	
MG2096	Bedford 214	Mani gsk -one piece		1	\$ 12.00
MG3000	Isuzu G200 DOHC	Mani gsk Inlet pr		1	\$ 5.00
MG3024	Toyota 4AGE	Mani gsk Inlet		1	
MG3037	Nissan CA18DE	MGC		1	\$ 6.00
MG3059	Mazda B6-D	MGC		1	\$ 6.00
MG3073	Ford Trader 380 Dover	Mani set		1	\$ 25.00
MG3084	Suzuki G16B	MGC		1	\$ 7.00
MG3090	Mits 4G63T 95 Evo 3-5	Mani gsk Inlet		1	
MG3348	Bedford 330	Mani gsk exh set		2	
MS040	Mits G32B	Mani gsk set		5	
MS060	Mits G11B/13B	Mani gsk set		9	
MSM4405	Chrys SV 1937-59	Mani gsk set	(ACL# JA221)	1?	
MSPD3	Hon?	Mani gsk set		2	
MSPE3	Honda EW Shuttle	Mani gsk set		2	
N1052		Mani gsk Inlet		1	
N467	Mitsu (4G63?)	Front cover gsk plus		2	
N607	Austin Maxi, Allegro	T/cover gsk?		2	
N667	Ford Trader 380 Dover etc	Therm hsg gsk			\$ 7.00

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

NA068		Oil seal	ON DELETION 2405	36	
NA174	Vaux Viva	Oil seal front	1.375 x1.875x.312	49	\$ 13.00
NA200	Bed	Oil seal	BEDFORD 6358833 (TC12043)	13	
NA201	Ford Trader	Oil seal	Ford EIADDN-66610A Aux drive shaft seal	3	
NA298	Stand. Vanguard	Oil seal front			\$ 30.00
NA308	Rover 2, 2.25 litre etc	Use NB849			
NA329	Holden, Triumph	Oil seal front		1	
NA341	Ford Zephyr	Oil seal front		3	\$ 10.00
NA416	BMC "C"	Oil seal front	(PR3858)	20	\$ 12.00
NA417	Holden V8, chev 6	Oil seal	GM3980267	2	\$ 6.00
NA473	BMC	Oil seal	NZMC 88G561 (felt = KG065)	1	\$ 15.00
NA512	Vaux 3.3, 2.6, PA2.2	Oil seal front cover	G M 7195654	33	\$ 15.00
NA523	Massey Fergusson	Oil seal	Massey Fergusson 897363M1	1	
NA524	Mits	Oil seal	OIL SEAL T 9102085	20	
NA543	Ford V6 1966-71	Oil seal	47x66x11	3	\$ 10.00
NA563	Bedford 466	Oil seal front cover	BEDFORD 6384745	26	
NA567	Bedford CF	Oil seal -cam/aux	44*63.5*9 GM 7199290	1	\$ 9.00
NA571	Bedford CF	Oil seal -front crank	51*67*9	2	\$ 14.00
NA576		Oil seal	1.375x2.062x5/32"	1	
NA576Turquoise		Oil seal	1.218x2.062x1/2"?	1	
NA577		Oil seal		1	
NA584	BMC 1100, 1300 transverse	Oil seal rear		1	\$ 16.00
NA741	Perkins	Oil seal front		1	\$ 12.00
NA748	Ford Trader	Oil seal front	FORD 510E-6362	30	\$ 20.00
NA749		Oil seal		20?	
NA759	Triumph/Standard 2" x 3" x 0.500"	Oil seal front	TRIUMPH 125631 (TC12154)	7	\$ 15.00
NA764		Oil seal	ON DELETION 2058	185	
NA774	Triumph 2000, 2500	Oil seal rear		11	\$ 22.00
NA792A	76.2 x 98.65 x 10.7	Oil seal	ACL too wide for Viva?	2	\$ 20.00
NA792N	76 x 98 x 9 -Viva	Oil seal			
NA965		Oil seal	121x141x12	1	
NA987	Rover 2.25, 2.6 & 3 litre 1958-67	Oil seal rear	(2.5" ID?)	20	\$ 19.00
NB051	Rover 2.25, 2.6 & 3 litre 1958-67	O ring	ROVER 244488	7	
NB062	Ford Trader	Inj adaptor seal to 1957	14mm long (later=19mm)		\$ 15.00
NB064	Ford Trader	Inj adaptor seal 1957 on	FORD EIADDN993156C	13	\$ 14.00
NB076	BMC Maxi, Tasman	Valve seal inlet		0	\$ 4.00
NB077	Ford Trader 380 Dover etc	Inj seal		42	\$ 16.00
NB123	BMC 1800	Oil seal	3.5x4.125x.375	1	
NB132	Triumph/Standard 2" x 3" x 0.375"	Oil seal front	STANDARD 155695	36	\$ 15.00
NB272	Toyo use NB578	Oil seal	38.5x58x11	1	
NB289	BMC	Oil seal	B L M C 42H118	60	
NB384	Mazda	Oil seal	40x55x8	1	\$ 8.00
NB469	GM	Oil seal	GM 614809	2	
NB470	Bedford 500	Oil seal front cover	GM 91000883	21	
NB570	Ford	Oil seal	CODR-7052R	1	
NB571	BMC	Oil seal	NZMC AYH3202	1	
NB578	Toyo replaces NB272	Oil seal	38.5x58x11	1	
NB584		Oil seal	C30002	2	
NB586	BMC "O"	Oil seal front cover	29x40x6 CAM1403	2	
NB604		Oil seal	35x57x14.5?	2	
NB610	47x67x9	Oil seal	B02049	3	\$ 12.00
NB611	BMC		NZMC 12H5079	12	
NB613	Chrysler V8 360 etc	Oil seal front	TODD 2899531 (PR6363)	12	\$ 20.00
NB614		Oil seal		1	
NB615	Ford	Oil seal	Ford DOA6700A	1	
NB628	GM	Oil seal	GM638185	3	
NB688	Ford Trader 380 Dover etc	Oil seal front	66.67mm x 89.28mm x 9.52mm	1	\$ 15.00
NB699		Oil seal	(PR1479, KNB699)	4	
NB701			G.M. 901063501	15	
NB848		Oil seal + sleeve	99x120x11	1	
NB849	Rover 2.25, 2.6 & 3 litre 1958-67	Oil seal front		5	\$ 20.00
NJ001	Toyota 3K, 4K, 5K	Oil seal -rear crank	70x92x8.5	2	\$ 12.00
NJ004	Nissan A15 etc	Oil seal -rear crank		1	\$ 12.00

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

NJ005	Mitsubishi 4D55/56 etc	Oil seal -front crank	44x60x7	2	\$ 6.00
NJ006	Mits	Oil seal	72x96x9	2	
NJ008	Mits	Oil seal	MITSUBISHI JCMD000248	16	\$ 6.00
NJ011		Oil seal	40x52x7	3	
NJ020	Mits special	Oil seal	MD010324/53	1	
NJ021	Nissan A12 etc	Oil seal rear		1	\$ 6.00
NJ022	Nissan A12 etc	Oil seal front			\$ 8.00
NJ028		Oil seal		2	
NJ030	80x100x12 HTCL	Oil seal		1	
NJ044		Oil seal	75x100x13	1	
NJ045	48x70x8	Oil seal	TC12875	1	
NJ049	Nissan	Oil seal	Nissan	19	
NJ050	Nissan J series front	Oil seal	NISSAN 13042-B3000	11	\$ 5.00
NJ052	42x55x7	Oil seal		1	\$ 12.00
NJ055	PR0099	Oil seal	rear crank seal?	1	
NJ057	Mitsu 4G51	Oil seal	48x68x11	2	\$ 6.00
NJ058	Mitsu 4G51	Oil seal rear	80x96x9	12	\$ 16.00
NJ068	Mit/Toy	Oil seal	52x65x9	2	
NJ074	Honda	Oil seal	OIL SEAL HONDA 91251-634-005	31	
NJ075	Honda	Oil seal	OIL SEAL HONDA 91250-634-003	31+14	
NJ099	Mazda	Oil seal	70x88x12	1	
NJ161		Oil seal	OIL SEAL HH91205-PL3-A01	50	
NJ206	36x49x7	Oil seal		1	
NJ207	Nissan GA	Oil seal	13276-53Y00 27x49x10	5	\$ 10.00
NJ240	Dai/Toyo	Oil seal	95x115x12	2	
NJ242	Mitsubishi 4D55/56 etc	Oil seal -cam	35x50x8	2	\$ 5.00
NJ251	Mitsubishi 4D55/56 etc	Oil seal rear			
NJ254	Honda	Oil seal	Honda	1	\$ 5.00
NJ255	Mitsubishi 4D55/56 etc	Oil seal -oil pump	Mitsubishi 17x28x7	2	\$ 6.00
NJ276		Oil seal		1	
NJ284	Nissan	Oil seal	84x104x11	3	
NJ285	Use NJ324	Oil seal			
NJ286	Nissan	Oil seal	36x49x7	1+2	
NJ287	Nissan	Oil seal	80x100x10	2	
NJ291	Nis/Maz	Oil seal	50x72x12	2	
NJ309	Honda	Oil seal	76x98x12 HTCR	1	\$ 12.00
NJ312	Honda	Oil seal	80x100x10	3	\$ 11.00
NJ323	40x56x7	Oil seal		1	
NJ324	Dai/Maz	Oil seal	34x48x7	2	
NJ325	Mazda	Oil seal	90x110x9	1	
NJ336	Suzuki various	Oil seal -camshaft		1	
NJ346	Mazda FE 1983-87	Oil seal rear		1	
NJ354	85x105x10	Oil seal		1	
NJ367	Mazda XA, XB	Oil seal	Front Cover seal	3	\$ 11.00
NJ373	28x40x8 HTCR	Oil seal		1	
NJ377	Suzuki	Oil seal	32x47x6	2	
NJ378	Suzuki	Oil seal	68x86x8	2	
NJ381	Honda	Oil seal	Honda	1	
NJ383	Isuzu	Oil seal	Isuzu	7	
NJ385		Oil seal	OIL SEAL 90043-11053-999 DAIHA	305	
NJ390		Oil seal	OIL SEAL 90043-11102-999 DAIHA	227	
NJ444	Toyota 19x32x8	Oil seal		3	
NJ464	Honda	Oil seal	HONDA OIL SEAL 91251-692-013	161	\$ 7.00
NJ465	Isuzu	Oil seal	OIL SEAL G 1096250060	195	
NJ477	60x77x12	Oil seal		1	
NJ523	Toyota	Oil seal	48x82x12	9	
NJ528	Honda	Oil seal	HONDA OIL SEAL 91250-SA2-023	159	
NJ556N	104x120x11	Oil seal		2	\$ 45.00
NJ609	Toyota 90311-38043	Oil seal		17	\$ 10.00
NJ610	Mitsubishi 4D55/56 etc	Oil seal -balance shaft	Mitsubishi 25x35x6	3	\$ 6.00
NJ647	Daihatsu/Hino	Oil seal	OIL SEAL 90043-11077-999 DAIHA	53	
NJ655	Mitsubishi 4G63 etc	Oil seal		2	\$ 5.00
NJ667	Daihatsu	Oil seal	OIL SEAL 90043-11153-999 DAIHA	3	

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

NJ675	V6 crank	Oil seal	OIL SEAL HONDA 91214-PL2-003	1	\$ 20.00
NJ692		Oil seal	56x72x10	5	
NJ699		Oil seal	Subaru	9	
NJ706	Toyota 1C -cam	Oil seal	37.5x50x6	5	\$ 6.00
NJ707		Oil seal	Hin/Toy	6	
NJ719	Toyota 3K, 4K, 5K	Oil seal -front crank	70x92x8.5	yes	\$ 4.00
NJ731	Honda	Oil seal	OIL SEAL 91205-689-005 HONDA	4	
NJ732	Honda	Oil seal	OIL SEAL HONDA 91205-PC8-935	40	
NJ733	Honda	Oil seal	OIL SEAL HONDA 91205-PE6-004	29	
NJ734	Honda	Oil seal	OIL SEAL HONDA 91250-SB0-624	25	
NJ751	Daihatsu	Oil seal	OIL SEAL 90043-10036-999 DAIHA	34	
NJ766	Daihatsu	Oil seal	OIL SEAL 90043-11106-999 DAIHA	27	
NJ766	Daihatsu	Oil seal	90043-11106-000	1	
NJ768	Daihatsu	Oil seal	90043-11148-000	2	
NJ777	Honda	Oil seal trans.	35x76x9x12	21	\$ 25.00
NJ778	Honda	Oil seal	OIL SEAL 91216-PA0-003 HONDA	4	
NJ778	Honda	Oil seal	91216-PAO-003	1	
NJ779	Honda	Oil seal	Oil seal 91216-PC8-003	4	
NJ780	Honda	Oil seal NLR inner		18	\$ 14.00
NJ781	Honda	Oil seal	Oil seal Honda 91251-SA5-005	6	
NJ782	Honda	Oil seal	OIL SEAL HONDA 91251-SB0-015	53	
NJ809	Mazda	Oil seal	Mazda	15	
NJ819	Mazda	Oil seal	60x78.9x11	16	\$ 10.00
NJ850		Oil seal	30x53?x9	1	
NJ889	Honda	Oil seal	OIL SEAL HONDA 91206-PC8-005	51	
NJ915	Honda	Oil seal	91205-611-005	1	
NJ918	Honda	Oil seal	OIL SEAL HONDA 91250-SA7-013	105	
NJ934	Honda	Oil seal	OIL SEAL 91216-689-003 HONDA	61	
NJ951	Nissan	Oil seal	13168-01M00	1	
NJ983	Honda	Oil seal	OIL SEAL HONDA 91252-692-931	54	
NJ990		Oil seal		1	
NJ992	Suzuki	Oil seal	Suzuki	1	
NJ993	45x68x8.5	Oil seal		1	\$ 15.00
NK005	Honda	Oil seal	OS HONDA ZC	3	\$ 11.00
NK022	Honda	Oil seal	OIL SEAL HONDA 91206-611-005	46	
NK023	Honda	Oil seal	Oil Seal	7	
NK065	Honda	Oil seal	OIL SEAL HONDA 91205-PC9-711	4	
NK066	Honda	Oil seal	OIL SEAL HONDA 91206-PC9-711	18	
NK067	Honda	Oil seal	OIL SEAL HONDA 91206-PG2-005	11	
NK100	Honda	Oil seal	OIL SEAL 91207-639-015	20	
NK203	Honda	Oil seal	OIL SEAL HONDA	70	
NX202	GM G/box?	Oil seal	GM2707882	1	
NZ001	Mits 4G54 etc	O ring	O ring	16	
NZ002	Honda	O ring	O RING HONDA	11	
NZ003	Honda	O ring	O ring Honda	16	
NZ005	Rover SD1	O ring	O ring Rover SD1	6	
NZ006	Mits 4G54 etc	O ring	O ring Mitsubishi	7	
NZ007	Mazda	Baffle gsk	BAFFLE GSK. MAZ.0324-10-229ANZ	5	
NZ008	Mazda TC, UD	Mani gsk -exh single	Ex mani gsk Mazda TC UD	96	
NZ009	Mazda TC, UD	Mani gsk -exh twin	Ex mani gsk Mazda TC UD	7	
NZ011	Mazda	Misc gsk	MISC GSK.MAZDA 0370-10-523ANZ	28	
NZ012	Rover SD1	O ring	O RING ROVER SDI	7	
NZ020	GM	Therm gsk	MISC GASKET GM 08930323	9	
NZ021		Nylon screw plug	NYLON PLUG GSK. 08966222	22	
NZ023	GM	Grommet	MISC.GSK. HOLDEN/BEDFORD	21	
NZ024	Skoda	Rubber washer	Rubber washer 4 x 18mm Skoda	12	
NZ031	Suzuki	Misc gsk	MISC GSK. SUZUKI 11159-73001	5	
NZ033	Suzuki	Breather plate gsk	BREATHER PLATE GASKET SUZUKI	10	
NZ036	Toyo	Head rear plate gsk	HEAD REAR PLATE GSK.TOYOTA	17	
NZ037	Toyo	Head front gsk	HEAD FRONT COVER GSK.TOYOTA	15	
NZ038	Toyo	Head front gsk	HEAD FRONT COVER GSK.TOYOTA	179	
NZ039	Toyo	Head rear plate gsk	HEAD REAR PLATE GSK.TOYOTA	225	
NZ040	Toyo	C/S housing gsk	C/S HOUSING GSK.TOYOTA	7	

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

NZ042	Toyo	R/cover breather gsk	R/C BREATHER GSK.TOYOTA 2C	27
NZ047	Suzuki	Misc gsk	MISC GSK.SUZUKI 11241-38300	16
NZ063	Toyo	T/C foam	T/C FOAM WITH ADHESIVE TOYOTA	15
NZ065	Toyo	Rear seal retainer gsk	O/S RETAINER GSK.TOYOTA	5
NZ070	Toyo	Rear seal retainer gsk	O/S RETAINER TOY.11384-70010	11
NZ073	BMC	Hypoid hsg gsk	HYPOID HOUSING NZMC 114749	9
NZ082	Toyo	Vent fla gsk	Ventilation flange gsk Toyota	5
NZ083	BMC	Front plate gsk	MISC GASKET NZMC 12G4137	27
NZ084	BMC	Air filter gsk	MISC GASKET NZMC 12H4271	5
NZ085		O ring	O RING 13017-42L00	12
NZ088	Suzuki	Carb gsk	CARB.GSK.SUZUKI 13125-73000	6
NZ089	Suzuki	Misc gsk	MISC.GSK.SUZUKI 13125-76000	9
NZ090	Suzuki	Carb gsk	CARB.GSK SUZUKI 13125-78100	81
NZ091		O ring	O RING	28
NZ092	Holden	Therm hsg gsk	T/STAT HOUSING GSK.HOLDEN	7
NZ094			MISC GSK.POWER FARMING	37
NZ095	Suzuki	Air filter gsk	AIR CLEANER GSK.SUZUKI	40
NZ096	Nissan	Balance tube gsk	BALANCE TUBE GSK NISSAN	464
NZ097	Nissan	Mani gsk Inlet	In mani gsk Nissan/Holden	3
NZ100	Nissan	Mani gsk Inlet	IN.MAN.GSK.NISSAN 14035-11M02	6
NZ101	Nissan	Mani gsk Inlet	IN.MAN.GSK.NISSAN/HOLDEN	2
NZ105		Misc gsk	MISC GASKET HG143243302800	4
NZ108	Holden Comm VL	EGR valve	EGR VALVE VL COMMODORE	15
NZ109	Nissan	EGR valve	EGR VALVE NISSAN.E13/0.09	10
NZ110	Holden	Therm hsg gsk	THERMOSTAT GSK. 7401194 GM	5
NZ111	Nissan	Oil pump cover gsk	OIL PUMP COVER GSK.NISSAN	6
NZ118	Honda	Oil pump gsk	HONDA OIL PUMP BODY GSK.	13
NZ119		Misc gsk	ON DELETION 2237	27
NZ121	IHC	Misc gsk	MISC GSK. INTL TRUCKS 151193R3	9
NZ122		O ring	O RING 15142-PE0-000	8
NZ125	Nissan H20	Misc gsk	MISC GSK.NISSAN 15239-78200	33
NZ128	Nissan H20	Oil filter cork ring	OIL FILTER GSK.15270-11200	20
NZ134	Suzuki	Oil pump cover gsk	OIL PUMP CASE GSK SUZUKI	7
NZ137	Subaru	Carb gsk	CARBURETTOR GSK SUBARU	6
NZ138	Subaru	Carb gsk	CARBURETTOR GSK SUBARU	6
NZ139			MISC GSK NISSAN 16177-23000	93
NZ140	Honda	Carb gsk	MISC GSK HONDA 16213-663-000	21
NZ141		Carb gsk	MISC.GASKET 16215-689-000	22
NZ142		Mani insulator gsk	INSULATOR GSK.16215-PC3-600	33
NZ143		Carb gsk	CARB. GSK.16215-PH1-000	6
NZ144	Toyo	Water pump gsk	WATER PUMP HOUSING GSK TOYOTA	14
NZ146	Dai	Misc gsk	MISC GSK.DAIHATSU 16322-87701	4
NZ150	Dai	Therm gsk	WATER OUTLET GSK DIAHATSU	25
NZ152	Toyo	Water outlet gsk	WATER OUTLET GSK TOYOTA	23
NZ153	Suzuki	Adapter case gsk	ADAPTER CASE GSK SUZUKI	21
NZ164	Toyo	Mani gsk	MANIFOLD GSK TOY. 17178-41010	4
NZ165	Suzuki	Pump gsk	PUMP ASSEM. SUZUKI	9
NZ166	Suzuki	Water pump gsk	WATER PUMP GSK SUZUKI	4
NZ169	Fergusson	Misc gsk	MISC GSK MASS.FERG.180434M1	22
NZ170	Norwood	Case cover gsk	CASE COVER GSK NORWOOD 180511M	17
NZ172	Norwood	Sump gsk	SUMP GSK NORWOOD 1861986M2	22
NZ173	Norwood	Misc gsk	MISC GSK NORWOOD 188807M2	1
NZ174	Ford	Rear axle gsk	REAR AXLE SHAFT GSK.FORD	10
NZ175	Nissan CA20	Exh fla gsk	EXH FLANGE GSK NISSAN CA20	29
NZ176	Toyo	Fuel pump gsk	FUEL PUMP GSK TOYOTA 20846	4
NZ177	Ford Falcon 200	Sump sides pair	SUMP SIDES FORD ARC8DE-6710-A	8
NZ178	Lada	Misc gsk	MISC GSK LADA 21010101423	6
NZ179		Carb gsk	MISC GSK AVTO IMP.210101107015	6
NZ180		Water outlet gsk	OUTLET FLANGE GSK AVTO IMP.	4
NZ181		Misc gsk	MISC GSK AVTO IMP.210101307048	5
NZ189	Holden 6	Cork ring (s/plugs)	Misc gask Holden 6 7401140	2 \$ 1.50
NZ192	Toyo	Carb gsk	CARB GSK TOYOTA 21911-63010	72
NZ193		A/filter gsk		7

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

NZ195		Copper washer	WASHER 22636-W4200	11	
NZ198	Niss	Misc gsk	MISC GSK NISSAN/HOLDEN	16	
NZ199	Dai	Fuel pump gsk	Fuel pump gsk Daihatsu	25	
NZ200	Dai	Fuel pump gsk	Fuel pump gsk Daihatsu	3	
NZ204	Ford V4/6	MGI end cork	PART OF JA747/8 (2724E-9A424)	177	\$ 3.00
NZ205	Ford V4/6	MGI end cork	PART OF JA747/8 (2724E-9A425)	190	\$ 3.00
NZ207	GM	Mani water outlet gsk	Mani water outlet gsk GM	6	
NZ213	IHC	Ex fla gsk large	MISC GSK INT.TRUCKS 304063R1	7	
NZ214	IHC	Ex fla gsk	MISC GSK INT.TRUCKS 304064R1	7	
NZ215	IHC	W/collection pipe gsk	WATER COLLECTION PIPE GSK INT.	4	
NZ218	Nissan	Misc gsk	MISC GSK NISSAN 32112-E9001	4	
NZ220	Toyo	Misc gsk	Misc gask Toyota 33132-30030	6	
NZ221	Toyo	Misc gsk	MISC GSK TOYOTA 33142-26010	8	
NZ229	Simca	Carb gsk	CARBURETTOR GSK SIMCA 38450F	6	
NZ232	Toyo	Misc gsk	MISC GSK TOYOTA 42181-12010	8	
NZ233	Toyo	Misc gsk	MISC GSK TOYOTA 42181-30010	13	
NZ234	Toyo	Misc gsk	MISC GSK TOYOTA 42181-35010	68	
NZ235	Toyo	Diff carrier gsk	DIFF.CARRIER GSK TOYOTA	7	
NZ236					
NZ238	Toyo	Misc gsk	MISC GSK TOYOTA 42443-55020	7	
NZ240	Toyo	Misc gsk	MISC GSK TOYOTA 43422-60010	6	
NZ241	Dai	Misc gsk	MISC GASKET DAI.45435-26010	14	
NZ243	Norwood	Misc gsk	MISC GSK NORWOOD 512787M2	1	
NZ244	Norwood	Misc gsk	MISC GSK NORWOOD 521181M1	6	
NZ246		O ring	O RING	62	
NZ248		O ring	O RING	47	
NZ249	GM	Side cover gsk	SIDE COVER GSK GM 607500	5	
NZ250	GM	Cam cover gsk	CAMSHAFT COVER GSK GM 638602	4	
NZ251	Bedford 500	Dowel pin	G M 6397142	71	
NZ254	GM	Emulsion block gsk	EMULSION BLOCK GSK GM 7086882	23	
NZ255	GM	Carb gsk	CARBURETTOR GSK GM 7195926	20	
NZ259	Holden V8	Sump front rubber	FRONT SUMP SEAL HOLDEN V8	73	
NZ268	Ford Falcon CIH X/F (HA303?)	Mani gsk Inlet	IN.MAN.GSK FORD 76DA-9461-AB	1	\$ 7.00
NZ269	Ford Falcon CIH X/F	Foam	FORD 76DA-9A641-A	1	
NZ270		Misc gsk	ON DELETION 2237	6	
NZ271		Mani gsk -exh?	ON DELETION 2237	7	
NZ272		Misc gsk	ON DELETION 2237	8	
NZ277	Subaru	Therm gsk	THERM.GSK SUBARU 81755-4120	17	
NZ279	Norwood	Felt strip	MISC GSK NORWOOD 825220M1	14	
NZ281	Norwood	Misc gsk	MISC GSK NORWOOD 825931M1	16	
NZ283	Norwood	Ex fla	EX.FLANGE GSK NORWOOD 827877M	7	
NZ284	GM	Carb gsk	MISC GSK GM 832528	8	
NZ285	GM	Hot box gsk	INLET TO EXH MANIFOLD GSK GM	7	
NZ286	GM	Ex gsk	MISC GSK GM 854835	6	
NZ287	Ford Falcon EB-	Therm rubber ring	EB-FALCON T/STAT O RING	75	
NZ288	GM	Mani gsk 1&2 cyl	1 & 2 CYL.INL MANIFOLD GSK GM	4	
NZ290	GM	Mani gsk Inlet #4 cyl	NO.4 CYL.INLET MANIFOLD GSK GM	5	
NZ295		Carb gsk	HEAT INSULATOR GASKET	12	
NZ299	GM	Carb gsk	CARB FACING G.M.90080100F	277	
NZ300	Toyo	Steel washer	TOY. 5/16X5/8" ZINC PL ST WASH	6	
NZ302	Toyo	Rubber ring flat	35MM X 51MM TOYOTA 90341-25054	10	
NZ307	Daihatsu Delta	Exh fla gsk	EX.FLANGE GSK.DELTA DAIHATSU	4	
NZ310	Honda	Oil seal	HONDA OIL SEAL"91203-PR4-004"	380	
NZ311	GM	Rear seal retainer gsk	RETAINER TO BLOCK GSK GM	7	
NZ312		O ring	O RING 91324-PC6-000	31	
NZ313		Therm gsk	THERMOSTAT GSK GM 92013634	12	
NZ314	GM	Adapter to head gsk	ADAPTOR TO CYL.HEAD V.H. GM	65	
NZ316		O ring	'O' RING 2.5mmX65mmX70mm	41	
NZ317	Holden V8 308, 253	Oil pickup gsk	OIL FEED TO PICK UP GSK.	13	
NZ318		Therm gsk	WATER OUTLET GSK.94209872	10	
NZ319	GM	Erg valve gsk	ERG.VALVE GSK GM 9933112	23	
NZ320		Mani gsk Exh		11	
NZ322	GM	Misc gsk	MISC GSK GM 9947224	11	

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

NZ323	GM	Exh gsk	MISC GSK GM 9947754	15	
NZ325	Mits	Rubber ring flat	MISC GSK MITS. A2536626	10	
NZ326			Flange gasket Mits. A3543247	3	
NZ327	Ford	Misc gsk	MISC GSK. ARC6DR-7051A	6	
NZ329	Ford	Misc gsk	MISC GSK. ARC6DR-7A036A	4	
NZ330	Ford	Front cover gsk	MISC GSK FORD ARC8DE-6020-A	13	
NZ331	Ford	Misc gsk	FORD MISC.GSK.ARC8DE-9455-A	11	
NZ332	Ford	Fuel pump gsk	MISC GSK FORD ARC9DE-9417-A	14	
NZ334	BMC	Carb gsk	CARBURETTOR GSK NZMC AYD102	16	
NZ335	BMC	Therm gsk	WATER OUTLET GSK NZMC AYD104	5	
NZ336	BMC	Sump sides	SUMP SIDES NZMC AYH3106/7	4	
NZ337	BMC	Misc gsk	MISC GSK NZMC AYH403	4	
NZ338	BMC	Therm gsk	WATER OUTLET GSK NZMC AYH451	5	
NZ340		Rear seal retainer gsk	O SEAL RETAINER B630-11-318	6	
NZ342	Ford	Therm gsk	WATER OUTLET CONNECTION FORD	6	
NZ343	Chrysler V8 318, 360	Mani gsk Inlet	INTAKE GASKET CHRYSLER V8	13	\$ 10.00
NZ344	Mits	Misc gsk	MISC GSK MITS. C2596174	17	
NZ346	Mits	Misc gsk	MISC GSK MITS.C2899082	4	
NZ348	Ford	Misc gsk	MISC GSK FORD C30E-9447	10	
NZ349	Mits	Rocker cover gsk	MTS.ROCKER COVER GSK C3427541	1	
NZ353	Ford	Fuel pump gsk	F/P GASKET C3DE-9417-A	22	
NZ354	Ford	Fuel pump gsk	MISC GSK FORD C3TE-9417-A	22	
NZ355	Ford Truck 240, 300 petrol	Side cover gsk	SIDE PLATE GASKET FORD "D" PET	20	
NZ356	Ford Truck 240, 300 petrol	Rubber ring flat	MISC GSK FORD C5AE-6789-A	12	
NZ359	Ford Truck 240, 300 petrol	Valve seal -umbrella	VALVE STEM SEALC5AZ-6571-D	940	\$ 1.00
NZ361	Ford Truck 240, 300 petrol	Oil seal rear	MISC GSK.FORD C5AZ-6701-B	88	\$ 25.00
NZ365	Ford	Sump?	MISC GSK FORD C5NN-4N507-A	13	
NZ366	Ford	Misc gsk	MISC GSK.C5NN-7N057-A	11	
NZ368	Ford Truck 240, 300 petrol	Valve seal?	FORD C5TZ-6571-A	4	
NZ369	Ford Truck 240, 300 petrol	Carb or air cleaner gsk?	MISC GASKET FORD C5TZ-9447-C	7	
NZ370	Ford Truck 240, 300 petrol	Valve cover gsk			
NZ372	Ford	Oil pickup gsk	OIL PUMP TO BODY GSK FORD	10	
NZ374	Ford	Misc gsk	MISC GSK FORD C9DE-6625-A2	35	
NZ376	Ford	Misc gsk	MISC GSK FORD D6NN-867-A	18	
NZ377			FRONT COVER GASKET FORD	21	
NZ378	Ford V8 Cleveland	Mani gsk Inlet pair	MANIFOLD GSK FORD DOAZ-9433	1	
NZ379	Ford	Distr gsk	DISTRIBUTOR GSK FORD LASER	240	
NZ381	Ford Tractor 4 cyl 5000 etc -extra hole	Sump gsk	SUMP GSK.E9NN-6710-AB	6	\$ 20.00
NZ383	Ford	Misc gsk	MISC GSK FORD	6	
NZ386	Simca	Mani gsk Inlet	INTAKE MANIFOLD GSK SIMCA	3	
NZ387	Mazda	Rear cover gsk	REAR COVER GSK MAZDA	181	
NZ388	Mazda	Hsg rear cover gsk	HOUSING REAR COVER GSK MAZDA	292	
NZ389	Mazda	Hsg front cover gsk	HOUSING FRONT COVER GSK MAZDA	465	
NZ390	Mazda	Misc gsk	MISC GSK MAZDA F801-10-229NZ	532	
NZ392	Mazda	Oil pickup gsk	OIL STRAINER GSK MAZDA	8	
NZ393	Mazda	Water pump gsk	WATER PUMP GSK MAZ.F80115165NZ	47	
NZ398	Mazda	Carb gsk	CARB.GSK MAZDA FE05-13-316ANZ	16	
NZ400	Austin Maxi???	Rocker cover gsk	ROCKER COVER GSK NZMC GEG463	9	
NZ401		Stub axle gsk	STUB AXLE GASKET (277289)	21	
NZ403	BMC	Misc gsk	MISC GSK NZMC GFG117	8	
NZ404	BMC	Therm? Gsk	MISC GASKET NZMC GTG120	16	
NZ411	Mits	Carb gsk	CARB.GSK.MITS.JCMD003164	7	
NZ415	Mits	Oil pump cover gsk	OIL PUMP COVER GSK MITSUBISHI	5	
NZ426	Mits	Oil pump gsk	MISC GSK MITS.JCMD021557	2	
NZ427	Mits	Oil pump gsk	OIL PUMP GSK MITS.JCMD021559	2	
NZ431	Mits	Oil filter hsg gsk	OIL FILTER BRACKET GSK MITSUBI	115	
NZ437	Mits	Oil pump cover gsk	OIL PUMP CASE GSK MITSUBISHI	2	
NZ439	Mits		OIL FUEL BRACKET GSK MITSUBISHI	2	
NZ443			ON DELETION 2232	237	
NZ444		Sump gsk	OIL PAN GSK.JCMD739236/R	11	
NZ448		Water pump gsk	WATER PUMP GSK PIONEER	9	
NZ560	GM	Therm gsk	GM 6308878 (X4063)	115	
NZ561	Ford Falcon 250	Water pump gsk	WATER PUMP GSK.FORD XB-8507-A	10	

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

NZ626		Mani gsk Inlet		4
NZ626		Mani gsk Inlet	INLET MANIFOLD GSK	142
NZ628	diesel?	Front plate gsk	FRONT PLATE GSK.11328-56041000	34
NZ629		O ring	O RING	132
NZ630	Leyland 400	Inj washer	WASHER,INJECTOR NJJ1014	206
NZ997	BMC	Oil seal	542492	1
NZ997	Rover 2.25, 2.6 & 3 litre 1958-67	Seal - rear.		3 \$ 30.00
P6061		Oil seal	40x59x67x10	1
P6202		Oil seal	47?x70x9	2
PA079		Valve seal		9
PA086	VW	O ring	V.W. 052-905-261	21
PA138	Toyo L, 2L	Valve seal		8
PA153		O ring	RUBBER 'O' RING	40
PA155	GM	O ring	G.M. 90106456	11
PA185	GM	O ring	G.M. 90128513	49
PA273	Holden	Side cover bolt seal	HOLDEN.SIDE PLATE BOLT WASHER	634
PA286	Honda EJ inl (brown)	Valve seal		8 \$ 4.00
PA288	Honda 80-84	Valve seal		4
PA314	Honda	O ring	HONDA 91302-657-000	1
PA342	Honda	O ring	HONDA 91302-317-700	22
PA373	Honda aux.	Valve seal		28 \$ 4.00
PA375		Valve seal	V SEAL O RING HH 91301-657-000	29
PA387	Daihatsu CB	Valve seal		8 \$ 4.00
PA392	Honda	O ring	HONDA 91303-634-010	33
PA426	Mazda	Valve seal		8 \$ 4.00
PA441	Honda	O ring	O RING.HONDA 91306-634-000	168
PA5004	Mitsu 6A11, 6A12	Valve seal -inl		6
PA529	Honda B20A Exh	Valve seal		yes \$ 3.00
PA552		O ring	O' ring 90043-01043	67
PA554		Fuel pump gasket washer	FUEL PUMP GASKET	346
PA555		Distr O ring	DISTRIBUTOR O RING 90043-01037	20
PA564	Honda	O ring	HONDA 91307-611-000	73
PA567		Valve seal		2
PA581	Mazda KL, FE	V/cover bolt seal		7
PA632	Bedford CF	Valve seal -inl	GM RUBBER VALVE STEM SEAL	216 \$ 5.00
PA655	Subaru EA81	Valve seal		7
PA657	Toyo	Washer gsk	TOYOTA WASHER 90430-25013	15
PA709		Valve seal		4
PA722	Mits	Alloy washer		16
PA746	Mits	O ring	RUBBER OIL SEAL JCMD050461	36
PA751	Mits	Rubber ring	RUBBER GASKET JCMD050128	37
PA757		O ring -water pipe	WATER PIPE 'O' RING	134
PA775	Mits?	Diff Case gsk	JCMB092375	9
PA788		O ring	HONDA O RING 56.1 X 2.0	11
PA796	Nissan	O ring	NISSAN O RING 22180-01E00	16
PA803	Nissan	Oil filter rubber ring	OIL FILTER GSK 15270-D0103 NIS	153
PA808	Toyo 2L	Inj washer?	FUELWASHERS TOYOTA 2L	115
PA842		Alloy washer	HEAD PLUG S 80391-2030	17
PA844	Daihatsu CB	Rocker bolt seal	ROCKER BOLT SEAL DAIHATSU CB	47
PA846	Mazda	Alloy washer	MAZDA 9956-41-400NZ	70
PA853		Drain plug washer	DRAIN PLUG GSK.S 31168-0100	10
PA856	Isuzu C190, C223, C240	Rocker bolt rubber		6 \$ 3.00
PA858		Rocker bolt rubber		1
PA881	Toyo	O ring	O RING TOYOTA 96732-31060	16
PA882		Valve seal		7
PA883	Mazda	Valve seal		8, Lots
PA908		W/bypass gsk	WATER BYPASS GSK.F E301-15-287	273
PA913	Ford EA	Valve seal		yes \$ 5.00
PA930	Niss	O ring	OIL RING	6
PA946		O ring	SUCTION PIPE GSK 96721-19020	69
PA966		Seal	OIL SEAL S 80693-8020	5
PA970	Honda	Valve seal		8
PA979	Honda	O ring	O RING.HONDA 91315-634-000	25 \$ 4.00

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

PA984	Honda EG/EK/EN	W/pump O ring		23	
PA986	Mits 4G54 etc	O ring	O RING D 22131-78501	28	
PB002		O ring	O RING D 22180-D0100	5	
PB020		O ring	ON DELETION 1862	19	
PB022		O ring	ON DELETION 1862	20	
PB053	Dai	Alloy washer	WASHER DAIHATSU 90044-30042	25	
PB054		O ring	O RING	12	
PB055		O ring	O RING	12	
PB106		O ring	O RING	15	
PB121	Honda	O ring	O RING HONDA 91301-PB9-000	3	
PB146		Rubber	TOYOTA 90480-18180	113	
PB147	Nissan	Copper washer	WASHER NISSAN 11026-01M02	9	
PB150		Alloy washer -drain plug	DRAIN PLUG WASH.HH 94109-20000	44	
PB157			O RING	165	
PB159		Rocker bolt washer?	WASHER	12	
PB183	Toyo	Fuel pipe gsk	FUEL PIPE GSK. TOY.90430-12011	1159	
PB270	Dai	Sump plug gsk	SUMP PLUG GASKET DAIHATSU	218	
PB300	Honda	Copper washer	VALVE HOLDER 14777-PC6-000 HON	341	
PB301	Honda	O ring	O RING 91303-PC6-000 HONDA	20	
PB302		V/seal O	VALVE GUIDE O RING 91301PC6004	460	
PB345	Toyo 4AGE	Rocker bolt seal		2	
PB347	Toyo 2C	Rocker bolt seal	R.C. SEAL TOTOTA 2C	310	
PB355	Honda F22B SOHC	Valve seal		4	
PB356	Honda F22B SOHC	Valve seal		4	
PB382	Mazda	Water pump gsk	WATER PUMP GSK MAZDA	171	
PB449	Suzuki	Sump washer gsk	SUMP WASHER SUZUKI 09168-12007	19	
PM1922E		Collet cover 22 mm pipe		17	
PNZ072	GM	Sump sides LH&RH	L.H & R.H. SUMP SIDES GSKS G.M	11	
PNZ186	Bedford	Inj pump gsk?)	Components of set 91093363	1	
PNZ187	Bedford	Inj pump gsk?)	Components of set 91093363	2	
PNZ195	Ford V4/6	MGI copper disc	SQUARE CENTRE DISC FOR JA747/8	204	\$ 3.00
PNZ196	Ford V4/6	MGI copper disc	COPPER WASHER FOR JA747/8	700	\$ 3.00
PNZ239	Ford Falcon CIH X/F	Mani gsk Exh	See HA048		
PNZ264	Mits	Ex fla gsk	MIT.S.EXH.FLANGE/G JCMB687013/R	12+2	
PNZ266	Chrysler V8 318, 360	Mani gsk Exh	EX.MANIFOLD GASKET V8.	5	\$ 15.00
PNZ267	Ford V8 Cleveland	Mani gsk Exh Extractor	DFS27 or HSM27	11	\$ 10.00
PNZ268	Mazda 626	Baffle gsk	BAFFLE 626/TELSTR F80110229ANZ	268	
PNZ269	Toyo	Fuel pump gsk	FUEL PUMP GSK.TOYOTA	5	
PNZ271		Misc gsk	ON DELETION 2237	91	
PNZ272		Therm gsk	THERMOSTAT GSK SAMPLE H.PAYEN	110	
PNZ326	Mazda F8, FE	Front cover gsk		20	
PNZ330	Mazda FE	Ex fla?		1	
PNZ331	Ford Falcon EA, EB	Ex header tail gsk	EA/EB HEADER TAIL GASKET	64	
PNZ334		Water outlet gsk	Water outlet housing gsk	182	
PNZ337	55mm	Therm gsk	T/STAT GSK BLANK 55mm 1D	10	
PNZ338	53mm	Therm gsk	T/STAT GSK BLANK 53mm 1D	23	
PNZ339	49mm	Therm gsk	T/STAT GSK BLANK 49mm 1D	102	
PNZ340	44mm	Therm gsk	T/STAT GSK BLANK 44mm 1D	53	
PNZ359		Oil pump cover gsk	OIL PUMP GSK	58	
PNZ360	Toyo	Oil pump cover gsk	OIL PUMP GSK TOYOTA	676	
PNZ370	Toyota	Mani gsk		2	
PNZ371		Misc gsk	MISC.GSK	15	
PNZ372		Misc gsk	MISC. GSK. HH16215-PE8-600	38	
PNZ378	Ford V6	MGI part	F 722M-3441-AA (PART OF JA748)	19	\$ 10.00
PNZ379	Ford V4	MGI part	F 702M-9A454-BA (PART OF JA747)	35	\$ 10.00
PNZ389		3 gsk		4	
PNZ390		W/pump gsk?		1	
PNZ391		W/pump gsk?		1	
PNZ392	Honda	Transm gsk	TRANSMISSION GASKET HONDA	2	
PNZ393	Honda	Transm gsk	TRANSMISSION GASKET HONDA	15	
PNZ408		Mani gsk Inlet	plus JC401 = GT252		
PNZ437		Baffle gsk	BAFFLE PLATE GASKET	22	
PNZ439		Carb gsk	CARB GASKET	10	

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

PNZ445	Mazda 626	Water pump gsk	WATER PUMP GSK MAZDA 626 12V	6	
PNZ454		Therm gsk large	WATER OUTLET GASKET	79	
PNZ455	Mazda TC	Misc gsk	MISC GSK. MAZDA TC	7	
PNZ458	Mazda B6	Fuel pump gsk	FUEL PUMP GSK. MAZDA B6	7	
PNZ459	Mazda B6	Misc gsk	MISC GSK. MAZDA B6	4	
PNZ464	Nissan	Carb gsk	CARB GSK.NISSAN	110	
PNZ465	Nissan	Carb gsk	CARB GSK.NISSAN	195	
PNZ487			MISC.GSK.	21	
PR4978	88?x105x10	Oil seal		1	
PR6181	2.062x2.750x.375	Oil seal		1	
PR6234	1.37x2x.437	Oil seal		7	
PR6365		Rear seal -rope		1	
PR6407	1.75x2.35x.25	Oil seal		1	
PR7001		Oil seal	52x68x10?	1	
PR7002		Oil seal	4"x5"x3/8"	1	
PR7081	39x51x7.5	Oil seal		10	
PR7107K	52x68x13	Oil seal		1	
PS-11	3/8" valve seals (.540" guide OD)	Valve seal kit	Hastings 16 x 3/8" seals with installer	23	
PS-2	5/16" valve seals (.502" guide OD)	Valve seal kit	Hastings 12 x 5/16" seals with installer	36	
R71267895		Mani gsk	INDUCTION & EX.MAN.GSK MI 1830	5	
RC0023	Ford V8 EFI	Rocker cover gsk		2	
RC3000	Isuzu G200 DOHC	Rocker cover gsk		2	\$ 18.00
RC3008	Nissan TD42	Rocker cover gsk -rubber		1	
RC3011	Toyo 2C, 3C	Rocker cover gsk -rubber		1	
RC3017	Toyota 1G-EU	Rocker cover gsk -rubber		1	\$ 22.00
RHA60	Grease Nipple	Grease Nipple	1/4 GAS 90 Degree	27	
S32684R	Mits 4DR5	Sump gsk		2	\$ 20.00
S50451	Ford Trader 380 Dover etc	Fuel pump gsk also KS755			\$ 4.00
S62632N	50x68x9	Oil seal		1	
SS318	BMW 318	Valve seal		8	
ST2002BC	Universal -for 3/8" stem, 9/16" guide	Valve seal	-clamp on guide	920	
TC12048	1.125x2.062x.375	Oil seal		1	
TC12058	1.250x1.875x.375	Oil seal		2	
TC12508	32x50x10	Oil seal		1	
TC12577	45x62x8	Seal		1	
TC12631	60x90x8	Oil seal		2	
TC12896	Nissan Patrol 82	Seal for hub		1	
TC4	Holden 4	Front cover set		1	
TC450	Mits	front cover gsk pr	JCM020311/JCM020312	1	
TCS22	Nissan J	Timing cover set		1	
TCS34	BMA	Timing cover set		1	
TG001	Ford Falcon	Timing cover set		1	
TG002	Holden 6	Front cover set		1	
TG005	Mazda	Front cover set		1	
TG006	Nissan A12 etc	Front cover set			\$ 5.00
TG007	Toyota 3K, 4K	Front cover set			\$ 15.00
TG008	Nissan L16, L18	Front cover set			\$ 20.00
TG010	Mits 4G32	Front cover set		12	
TG011	Ford Cortina 2.0	Front cover set		1	
TK013	Mitsubishi 4G63 etc	Front seal set	NJ005,NJ242,NJ255,NJ610,NJ655,JR689,	12	\$ 30.00
V200		Therm gsk	MISC GSK.N.Z.M.C.	9	
VCK427	Mits 4G52, 4G54 narrow block	Rocker cover set		1	\$ 15.00
VSS128	round	Valve seal		36	
VSS218	Umbrella	Valve seal -umbrella		yes	
VSS318	Ford	Valve seal		yes	
WG1	Universal	Therm hsg gsk		228	\$ 1.00
WG2	Universal	Therm hsg gsk		235	\$ 1.00
WG3	Universal	Therm hsg gsk		23	\$ 1.00
WG6	Universal	Therm hsg gsk		358	\$ 1.00
ZD139		Valve seal	VALVE STEM SEAL O.90913-02057	563	
ZD167		O ring	OIL SEAL O RING GSK.9030165002	40	
ZD170		O ring	OIL PUMP O RING 96721-24056	17	
ZD171		Rubber	T/BELT COVER GSK 11328-11040	13	

Taupo Bay Road, R.D.1, Mangonui 0557 (Northland), New Zealand

Phone/Fax: 09-4061388 Mobile: 025 2920461

Email: conrodchris@quicksilver.net.nz

Prepared by Chris Bowden 29/04/2009

BOWDEN ENGINE PARTS

LOOSE GASKETS SEALS

APR 2009

ZD173		Copper washer	SUMP PLUG 90430-13002	29
ZD174		Alloy washer	SUCTION PIPE GSK O 90430-24246	10
ZG174		T/belt cvr rubber strip	T/BELT COVER GSK F8B2-10-512	11
ZG175		Front plate gsk	Front plate gsk F210-10-185	22
ZL150	Honda	Copper washer	MISC GSK HONDA 14777-657-000	189
ZL156	Honda	Rocker bolt seal	ROCKER BOLT SEAL HONDA	23
ZL157		Rubber	RUB/TIM.B/COVER.11109-689-000	9
ZL159		Oil pump gsk	OIL PUMP GSK HH15105-689-010	9
ZL163	Honda??	T/belt cvr rubber	T/BELT COVER GSK HH11831PC0000	12
ZL165		Oil pump cover gsk	OIL PUMP GSK.HH 15105-PA5-000	13
ZL166		Drain plug alloywasher	DRAIN PLUG GSK.HH90443-PA6-003	13
ZL167		Inj seal	INJECTOR SEAL	218
ZL168		Inj seal	INJECTOR SEAL	230
ZL169		Carb gsk	CARB.GSK.HH16105-PG6-000	30
ZL170		O ring -injector	INJECTOR O RING	82
ZL171		O ring	O RING	27
ZQ109		Rubber gsk	INSULATOR BLOCK S 16175-AA020	36
ZQ114		Alloy washer	PLUG 80321-6010	10
ZQ115		Copper washer	PLUG S 80350-6020	9
ZQ116		Alloy washer	PLUG S 80392-6020	8
ZS109	Suzuki	O ring	O RING SUZUKI 09280-16005	20